



# Cisco RF Gateway 1 Software Release Notes, Release 3.00.18

## Overview

### Introduction

The RF Gateway 1 software version 3.00.18 provides higher channel capacity with no hardware changes from its predecessor releases. The RF Gateway 1 remains fully SDV capable and the new 3.00.18 system release is primarily intended for support of SDV applications. Other video deployments can continue to use 2.02.XX and so forth as the preferred release.

### Purpose

The purpose of this document is to notify RF Gateway 1 users of the enhancements included in the current release, and inform users of any special upgrade procedures needed for using Release 3.00.18.

### Audience

This document is intended for system engineers or managers responsible for operating and/or maintaining this product.

### Related Publications

Refer to the following documents for additional information regarding hardware and software.


- *Cisco RF Gateway 1 Configuration Guide*, part number 4025112
- *Cisco RF Gateway 1 System Guide*, part number 4024958

### Safe Operation for Software Controlling Optical Transmission Equipment

If this document discusses software, the software described is used to monitor and/or control ours and other vendors' electrical and optical equipment designed to transmit video, voice, or data signals. Certain safety precautions should be observed when operating equipment of this nature.

For equipment specific safety requirements, refer to the appropriate section of the equipment documentation.

For safe operation of this software, refer to the following warnings.

 **WARNINGS:**

- Ensure that all optical connections are complete or terminated before using this equipment to remotely control a laser device. An optical or laser device can pose a hazard to remotely located personnel when operated without their knowledge.
- Allow only personnel trained in laser safety to operate this software. Otherwise, injuries to personnel may occur.
- Restrict access of this software to authorized personnel only.
- Install this software in equipment that is located in a restricted access area.

### In This Document

- 96 QAM Channels..... 3
- Miscellaneous Improvements ..... 4
- Front Panel Enhancements ..... 5
- Known Issues ..... 6
- Licensing ..... 7
- Upgrade Information ..... 9
- Upgrade Procedure for Customers Running 1.02.09 ..... 10
- IP Port Configuration Changes ..... 12
- IP Port Configuration Parameter Settings ..... 13
- For Information ..... 15

# 96 QAM Channels

The 3.00.18 release provides up to 96 licensed QAM channels or 8 channels per RF port. This feature is fully functional with no hardware changes from the predecessor RF Gateway 1 releases. The new 96 QAM channel capability is enabled by simply applying the 8 channels per port license to the 3.00.18 release.

The RF Gateway 1 continues to operate as earlier 48 QAM versions without applying the 8 channels per port license and upgrading to system release 3.00.18. There is no configuration and/or operational differences operating with system release 3.00.18 in this mode. QAM channel numbering follows the 4 channel per port predecessor.

Full backward compatibility is ensured with RF Gateway 1 configuration databases used under the 1.03.XX and 2.02.XX RF Gateway 1 system release branches. See the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112 for additional information about operating in the 8 channels per port mode.

Card	Port	Ch1	Ch2	Ch3	Ch4	Ch5	Ch6	Ch7	Ch8
1	1	OK	OK	OK	OK	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
2	1	OK	OK	OK	OK	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
3	1	OK	OK	OK	OK	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
4	1	OK	OK	OK	OK	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
5	1	OK	OK	OK	OK	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
6	1	OK	OK	OK	OK	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)

(a) Unlicensed 8 channels per port

Card	Port	Ch1	Ch2	Ch3	Ch4	Ch5	Ch6	Ch7	Ch8
1	1	OK	OK	OK	OK	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
2	1	OK	OK	OK	OK	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
3	1	OK	OK	OK	OK	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
4	1	OK	OK	OK	OK	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
5	1	OK	OK	OK	OK	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)
6	1	OK	OK	OK	OK	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)
	2	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	19.2887 (50%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)	0.0000 (0%)

(b) Licensed 8 channels per port




## Miscellaneous Improvements

- System release file transfers performed over the management network now include enhanced error checking for downloaded release verification.
- The RF Gateway 1 web management user interface for QAMS and Maps now implement faster loading web pages, providing the user with minimal page load times when accessing these configuration pages.
- Clicking Advanced Settings under Maps/Video Stream Map now includes a quaternary source specification capability. See Chapter 4 of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112 for detailed information about configuring the RF Gateway 1.
- Additional monitoring of QAM module health has been added, including monitoring alarms and traps for QAM module voltages. In addition to enhanced monitoring, software version 3.00.18 removes a QAM module from service if a critical failure occurs.

## Front Panel Enhancements

Software Release 1.03.19 provides the operator the ability to view RF port frequency and output power levels of the carriers on the front panel LCD. This allows easy access for users interested in confirming RF port status directly from an RF Gateway 1 unit.

The front panel *Info* submenu now includes an *RF* selection for entry into the RF port/channel display screens. The up and down arrow keys on the front panel keypad can be used to move from one RF port to the next and the left and right arrow keys from one carrier to the next. All carriers on an RF port have the same output level. If a carrier is muted or if the RF port is off, the string *mute* or *off*, respectively will be displayed instead of the power level. To exit these screens, the user must press the middle select button on the front panel keypad from any RF menu screen. Refer to examples below of the front panel display.



## Known Issues

The following list identifies known limitations planned to be resolved as part of an upcoming GA release.

- The RF Gateway 1 web management interface provides no events or alarms informing a user about a missing 8 Channels per Port license. The user can easily observe the Summary page to view greyed out channel frequencies and the System/License Management page to confirm an unlicensed unit.
- Over provisioning an unlicensed QAM channel causes an alarm condition on the RF Gateway 1.
- The RF Gateway 1 web interface is not fully tested with IE-8 and FireFox-3.5.x or newer. The RF Gateway 1 web management interface is tested with IE-6 or FireFox-2.0.0.14 and above. Use of Java 1.6.x is also recommended.
- When using /31 IP addressing, although the RF Gateway 1 allows setting IP addresses and masks that correspond to this point-to-point protocol, the GbE ports will not respond to ICMP echo requests, nor will they properly resolve their link partner's MAC address via ARP. These limitations may adversely affect unicast operations when using /31 subnets.

## Licensing

After an upgrade to 3.00.18, a new system license (8 channels per port) must be installed to access full 96 QAM channel support. For information regarding RF Gateway 1 licensing requirements and procedures, see the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112.

The following features require a system license:

- Third Party Encryption
- Data streams requiring use of the DOCSIS® Timing Interface
- DVB® Encryption
- PowerKEY® Encryption
- 8 channels per port

Most systems delivered with 1.02.20 or later using a data part number included a license file pre-installed at the factory. For these systems, an FTP transfer is not necessary.

All systems delivered prior to 1.02.20 and some systems delivered with release 01.02.20 will require that a license file be obtained from Cisco after an upgrade to 3.00.18. Contact your account representative for details on obtaining your license files.

**Note:** Performing an upgrade without a license file will not affect the configuration of a chassis already operating in release V01.03.XX, V02.02.XX, or V01.02.XX. The unit will continue to function as configured earlier until configuration or any license changes are made. No alarms or warnings are currently present that indicate the absence of the 8 channel per port license.

For systems requiring a license upgrade, a licensing-capable RF Gateway 1 provides the operator with a new tree menu item, *License Management*, located under the **System** tab. See the screen below. It provides an FTP mechanism to transfer license files to the device.

## Licensing

**Note:** In Release 3.00.18, the RF Gateway 1 will not immediately warn the operator if the FTP transfer fails due to an incorrect filename. It is strongly recommended that the operator monitor the file transfer status using feedback from the FTP server.

The screenshot displays the Cisco configuration interface for device **rfgw1**. The top navigation bar includes buttons for **Login**, **Reboot**, **Save**, **Refresh**, and **Help**, along with the Cisco logo and the time **16:08:05**. The main content area is divided into several sections:

- Device Host ID:** A text field containing the value **00000006311020**.
- License Overview:** A table with the following data:

Type	Installed	Count	Usage	Expiration Date	Remaining Time	Expired	Key
DATA	Yes	1	0	00-000-0000	0	No	7E4164E829C42CD5AFEF8EE0CC9A1EA4
DVB_SCRAMBLING	Yes	1	1	00-000-0000	0	No	80EC997598F5FBF00F43BAB4C7B06F2F
@_CHANNELS_PER_PORT	Yes	1	1	00-000-0000	0	No	6S25539400A24111EFB92CA9F518D5E2
- License File Information:** A section with two fields:
  - License File Path:** `/SW_Release/License/`
  - License File Name:** `6311020_AllThree_Ravi_license.dat`

At the bottom of the License File Information section, there are two buttons: **Download License** and **Cancel**.



## Upgrade Information

An RF Gateway 1 unit running release 1.02.20 can be upgraded directly to 1.03.19. See Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112, for more information. The RF Gateway 1 reboots automatically at the end of the upgrade process. However, when upgrading to 1.03.19 from 1.02.09, an intermediate step of using the bridge release 1.02.19 to arrive at 1.02.20 and finally 3.00.18 must be followed. The bridge release designated as 1.02.19 has been created to provide a secure and robust upgrade path. Releases 1.02.19 (bridge) and 1.02.20 (final) have identical user features and functionality. See *Upgrade Procedure for Customers Running 1.02.09* (on page 10).

**WARNING:**

**Upgrading to 1.02.20 or 3.00.18 directly from 1.02.09 must not be attempted. This may cause the RF Gateway 1 to be non-operational.**

## Upgrade Procedure for Customers Running 1.02.09



**WARNING:**

Upgrading to 2.01.09 directly from 1.02.09 must not be attempted. This may cause the RF Gateway 1 to become non-operational.

- 1 Before starting the upgrade, back up the system configuration. See Chapter 3, *General Configuration and Monitoring (Configuration Backup)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. Name the file appropriately to identify it as a configuration that corresponds to 1.02.09. This file will be necessary later if the user decides to revert back to 1.02.09.
- 2 Record the IP port configuration parameters by saving a screen capture of the *System/IP Network* page. See **Recording IP Port Configuration Settings** (on page 14).
- 3 Download and activate 1.02.19. See Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. The RF Gateway 1 reboots automatically at the end of the upgrade process.
- 4 After reboot, display the *System/IP Network* page. See **Displaying IP Port Configuration Settings** (on page 13).
- 5 Verify the IP port configuration parameters by checking them against those recorded in step 2 (prior to the upgrade as done in step 3). The Negotiation Mode, Redundancy Mode, and Revert Mode parameter values are inverted. See **Displaying IP Port Configuration Settings** (on page 13). Change the differing parameter values to match those recorded before download and activation. Be sure to click **Apply** after making your changes.
- 6 Once step 5 is completed, save the configuration which includes the IP port configuration parameters. Going forward, these values will not change.
- 7 Validate/qualify/soak release 1.02.19 in its application to establish confidence the release is operating at the same level as 1.02.09. In the very unlikely event service is impacted by 1.02.19, reverting back to 1.02.09 may be done to re-establish operations. If reverting back to 1.02.09 is necessary, the IP port configuration parameters must be swapped back and the configuration saved in step 2 restored.

- 8 After satisfactory completion of step 7, upgrade from 1.02.19 to 1.02.20. These two releases have identical performance and behavior. Release 1.02.20 includes a boot code upgrade that readily supports future roadmap features/releases without the need for subsequent two-step bridge upgrade processes.
- 9 Download and activate 3.00.18. See Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. The RF Gateway 1 reboots automatically at the end of the upgrade process.

## IP Port Configuration Changes

There is a bug in 1.02.09 that causes the following IP port configuration parameters to have inverted values saved in the configuration file.

- Negotiation Mode (On/Off) - one for each port (total 4)
- Redundancy Mode (Auto/Manual) - one for each port pair (total 2)
- Revert Mode (Enable/Disable) - one for each port pair (total 2)

For details on these parameters, see Chapter 3, *General Configuration and Monitoring* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112.

This bug has been corrected in the configuration file in 1.02.19. Upon upgrade to 1.02.19, these three parameters will appear to have changed value as seen in the *System/IP Network* page of the web GUI. As a result, the IP ports may not be configured properly for operation immediately after upgrade (after the subsequent reboot that follows activation).

See *Upgrade Procedure for Customers Running 1.02.09* (on page 10).


## IP Port Configuration Parameter Settings

The RF Gateway 1 has four physical GbE input ports that receive video and data streams from the upstream network. These ports may be used independently (in software releases 02.02.11 or later) or configured to implement input redundancy. See Chapter 3, *General Configuration and Monitoring of the Cisco RF Gateway 1 Configuration Guide*, part number 4025112 for specific details.

### Displaying IP Port Configuration Settings

Follow these instructions to display the *System/IP Network* page.

- 1 Launch your web browser.
- 2 In the IP Address field, enter the RF Gateway 1 IP address.
- 3 Click **Enter**.
- 4 Click the *System/IP Network* tab and review the IP settings. See the following screen.



The screenshot displays the configuration page for the RF Gateway 1 (rfgw1). The left sidebar shows the navigation menu with 'IP Network' selected. The main content area is divided into two sections: '10/100 Ports' and 'GbE Input Ports'.

**10/100 Ports Configuration:**

	Management	Conditional Access
Port Control		Off
Address Selection Mode	Static	Static
MAC Address	00:50:4b:11:20:90	00:50:4b:11:20:90
IP Address	10.90.149.87	150.158.235.250
Subnet Mask	255.255.255.0	255.255.255.0
Default Gateway	10.90.149.1	150.158.235.254

**GbE Input Ports Configuration:**

	Port 1	Port 2	Port 3	Port 4
MAC Address	00:50:4b:11:20:96	00:50:4b:11:20:9f	00:50:4b:11:20:a0	00:50:4b:11:20:b1
IP Address	76.59.99.139	150.158.233.252	76.59.91.195	150.158.234.250
Subnet Mask	255.255.255.248	255.255.255.252	255.255.255.248	255.255.255.252
Negotiation Mode	On	On	On	On

**Port Pair Configuration:**

	Port Pair 1	Port Pair 2
Video/Data IP	76.59.99.130	76.59.91.194
Redundancy Mode	Manual	Manual
Primary Port	1	3
Current Active Port	1	3
Detection Mode	Ethernet Link	Ethernet Link
LOS Timeout (s)	1	1
Revert To Primary	Enabled	Enabled
Revert Check Time (s)	2	2

## Recording IP Port Configuration Settings

Follow these instructions to record IP port configuration settings.

- 1 Navigate to the *System/IP Network* page.
- 2 Click the **Alt-PrtScrn** keys to copy the IP Network parameter settings to the clipboard.
- 3 Launch Microsoft Word (or WordPad if you don't have Microsoft Word) and paste the clipboard contents to page 1.
- 4 Save the Microsoft Word document as ipsettings.doc.

## For Information

### Support Telephone Numbers

This table lists the Technical Support and Customer Service numbers for your area.

Region	Centers	Telephone and Fax Numbers
North America	Cisco Services Atlanta, Georgia United States	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> <li>■ Toll-free: 1-800-722-2009</li> <li>■ Local: 678-277-1120 (Press <b>2</b> at the prompt)</li> </ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"> <li>■ Toll-free: 1-800-722-2009</li> <li>■ Local: 678-277-1120 (Press <b>3</b> at the prompt)</li> <li>■ Fax: 770-236-5477</li> <li>■ Email: customer-service@cisco.com</li> </ul>
Europe, Middle East, Africa	Belgium	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 32-56-445-197 or 32-56-445-155</li> <li>■ Fax: 32-56-445-061</li> </ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 32-56-445-444</li> <li>■ Fax: 32-56-445-051</li> <li>■ Email: service-elc@cisco.com</li> </ul>
Japan	Japan	<ul style="list-style-type: none"> <li>■ Telephone: 81-3-5908-2153 or +81-3-5908-2154</li> <li>■ Fax: 81-3-5908-2155</li> </ul>
Korea	Korea	<ul style="list-style-type: none"> <li>■ Telephone: 82-2-3429-8800</li> <li>■ Fax: 82-2-3452-9748</li> <li>■ Email: songk@cisco.com</li> </ul>
China (mainland)	China	<ul style="list-style-type: none"> <li>■ Telephone: 86-21-2401-4433</li> <li>■ Fax: 86-21-2401-4455</li> <li>■ Email: xishan@cisco.com</li> </ul>
All other Asia Pacific countries & Australia	Hong Kong	<ul style="list-style-type: none"> <li>■ Telephone: 852-2588-4746</li> <li>■ Fax: 852-2588-3139</li> <li>■ Email: saapac-support@cisco.com</li> </ul>
Brazil	Brazil	<ul style="list-style-type: none"> <li>■ Telephone: 11-55-08-9999</li> <li>■ Fax: 11-55-08-9998</li> <li>■ Email: fattinl@cisco.com or ecavalhe@cisco.com</li> </ul>
Mexico, Central America, Caribbean	Mexico	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 52-3515152599</li> <li>■ Fax: 52-3515152599</li> </ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"> <li>■ Telephone: 52-55-50-81-8425</li> <li>■ Fax: 52-55-52-61-0893</li> <li>■ Email: sa-latam-cs@cisco.com</li> </ul>

## For Information

<b>Region</b>	<b>Centers</b>	<b>Telephone and Fax Numbers</b>
All other Latin America countries	Argentina	For <i>Technical Support</i> , call: <ul style="list-style-type: none"><li>■ Telephone: 54-23-20-403340 ext 109</li><li>■ Fax: 54-23-20-403340 ext 103</li></ul> For <i>Customer Service</i> , call: <ul style="list-style-type: none"><li>■ Telephone: 770-236-5662</li><li>■ Fax: 770-236-5888</li><li>■ Email: keillov@cisco.com</li></ul>







5030 Sugarloaf Parkway, Box 465447  
Lawrenceville, GA 30042

678.277.1000

Cisco, Cisco Systems, the Cisco logo, the Cisco Systems logo, and PowerKEY are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

DOCSIS is a registered trademark of Cable Television Laboratories, Inc.

DVB is a registered trademark of the DVB project.

*All other trademarks mentioned in this document are the property of their respective owners.*

Product and service availability are subject to change without notice.

© 2009 Cisco Systems, Inc. All rights reserved.  
November 2009

Printed in United States of America  
Part Number 7019551 Rev A