

# Troubleshooting Encapsulation Failures with the debug atm errors Command

Document ID: 10436

## Contents

### Introduction

#### Prerequisites

- Requirements

- Components Used

- Conventions

#### Network Diagram

- Notes

#### Configurations

#### Unicast Mapping Problem

Why Does It Fail?

- Solution

#### Broadcast or Multicast Mapping Problem

Why Does It Fail?

- Solution

#### Related Information

## Introduction

When you enable the **debug atm errors** command, encapsulation error messages are sometimes displayed. This document explains what these error messages mean.

## Prerequisites

### Requirements

There are no specific requirements for this document.

### Components Used

This document is not restricted to specific software and hardware versions.

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, make sure that you understand the potential impact of any command.

### Conventions

For more information on document conventions, refer to the Cisco Technical Tips Conventions.

## Network Diagram

This document is based on this network setup:



## Notes

- 0/102 is the virtual path identifier/virtual channel identifier (VPI/VCI) value assigned on both ends of the permanent virtual connection (PVC) between Router 1 and Router 2.
- For the sake of clarity, 0/102 is switched to 0/102 by the ATM switch.
- These PVCs have been created on a multipoint subinterface.

## Configurations

This document uses these PVC configurations:

- Router 1
- Router 2

Router 1
<pre>interface ATM6/0.102 multipoint ip address 11.1.1.1 255.255.255.0 no ip directed-broadcast pvc 0/102   protocol ip 11.1.1.2   encapsulation aal5snap</pre>

Router 2
<pre>interface ATM2/0.102 multipoint ip address 11.1.1.2 255.255.255.0 no ip directed-broadcast pvc 0/102   protocol ip 11.1.1.1   encapsulation aal5snap</pre>

## Unicast Mapping Problem

In this example, a ping to 11.1.1.23 is attempted from Router 2 while the **debug atm error** command is turned on:

```
Router1# ping 11.1.1.23

Type escape sequence to abort.
Sending 5, 100-byte ICMP Echos to 11.1.1.23, timeout is 2 seconds:
 *Jul 12 05:01:26.161: ATM(ATM6/0): Encapsulation error1, link=7, host=B010117.
 *Jul 12 05:01:28.161: ATM(ATM6/0): Encapsulation error1, link=7, host=B010117.
 *Jul 12 05:01:30.161: ATM(ATM6/0): Encapsulation error1, link=7, host=B010117.
 *Jul 12 05:01:32.161: ATM(ATM6/0): Encapsulation error1, link=7, host=B010117.
 *Jul 12 05:01:34.161: ATM(ATM6/0): Encapsulation error1, link=7, host=B010117.
Success rate is 0 percent (0/5)
```

You can see from this output that the ping fails and the encapsulation error message is recorded. The hexadecimal value B010117 is converted to decimal in this manner:

Hexadecimal Value	Decimal Value
B	11
01	1
01	1
17	23

The hexadecimal value displayed is equivalent to 11.1.1.23, which is the address to which the ping is sent.

## Why Does It Fail?

The interface ATM 2/0.102 is configured as a point-to-multipoint interface. Before it can reach a device on the other side of a PVC on this interface, mapping must exist between the IP address and the PVC. This mapping can be obtained using the **inarp** command or by statically configuring it, as shown in this document.

In this example, there is no mapping between 11.1.1.23 and a PVC:

```
Router2# show atm map

Map list ATM2/0.102pvc4 : PERMANENT
ip 11.1.1.1 maps to VC 4, VPI 0, VCI 102, ATM2/0.102
```

The only mapping that exists is between 11.1.1.1 and the PVC 0/102. Since there is no mapping for 11.1.1.23, the router can not send the packet and it therefore records an encapsulation failure.

## Solution

Whenever you see such an error message, decode the hexadecimal value and check why the mapping is not configured for that particular unicast IP address.

## Broadcast or Multicast Mapping Problem

In this example, this routing configuration is added to both routers:

```
router eigrp 1
 network 11.0.0.0
!
router rip
 network 11.0.0.0
```

When you issue the **debug atm error** command, this message is displayed:

```
!--- This timestamped line of output appears on one line:

.Jul 12 14:21:09.408: ATM(ATM2/0.102)
      Send:Error in encapsulation, No VC for address 0xFFFFFFFF
```

This message indicates that the router is not able to send a broadcast on the PVC.

## Why Does It Fail?

If you look closely at this configuration, you can see that the **broadcast** keyword under the PVC configuration is missing. Similar to the previous unicast problem, you must specify this keyword before you

can send a broadcast on the PVC. In this case, the broadcast is generated by the Routing Information Protocol (RIP).

This message is also sometimes displayed:

```
!--- Each of these timestamped lines of output appear on one line:

*Jul 12 06:09:50.945: ATM(ATM2/0.102)
    Send: Error in encapsulation, No VC for address 0xE000000A
*Jul 12 06:09:51.625: ATM(ATM2/0.102)
    Send: Error in encapsulation, No VC for address 0xE0000009

!--- E000000A corresponds to 224.0.0.10.
!--- E0000009 corresponds to 224.0.0.9.
```

Both of these addresses are being used by the Enhanced Interior Gateway Routing Protocol (EIGRP) configured on the routers. Again, these packets can not be sent because the `broadcast` keyword is missing under the PVC configuration.

Whenever you see those messages, they are probably due to a routing protocol not being able to send updates or hello packets across the PVC. They can also be caused by other types of multicast traffic, such as IP/TV.

## Solution

In order to allow broadcast and multicast messaging on the PVC, the configuration should be similar to this example, which is done on Router 2:

```
interface ATM2/0.102 multipoint
 ip address 11.1.1.2 255.255.255.0
 no ip directed-broadcast
 pvc 0/102
   protocol ip 11.1.1.1 broadcast
   encapsulation aal5snap
```

## Related Information

- [ATM \(Asynchronous Transfer Mode\) Support Pages](#)
- [Tools and Utilities – Cisco Systems](#)
- [Technical Support – Cisco Systems](#)

---

[Contacts & Feedback](#) | [Help](#) | [Site Map](#)

© 2014 – 2015 Cisco Systems, Inc. All rights reserved. [Terms & Conditions](#) | [Privacy Statement](#) | [Cookie Policy](#) | [Trademarks of Cisco Systems, Inc.](#)

---

Updated: Nov 15, 2007

Document ID: 10436

---