Upgrade FTD HA Pair on Firepower Appliances

Contents

Introduction

Prerequisites

Requirements

Components Used

Configure

Network Diagram

Task 1. Verify the Prerequisites

Task 2. Upload the Software Images

Task 3. Upgrade the first FXOS chassis

Task 4. Swap the FTD Failover States

Task 5. Upgrade the second FXOS chassis

Task 6. Upgrade the FMC Software

Task 7. Upgrade the FTD HA Pair

Task 8. Deploy a Policy to the FTD HA Pair

Related Information

Introduction

This document describes the upgrade process of Firepower Threat Defense (FTD) in High Availability (HA) mode on Firepower appliances.

Prerequisites

Requirements

Cisco recommends knowledge of these topics:

- Firepower Management Center (FMC)
- FTD
- Firepower appliances (FXOS)

Components Used

- 2 x FPR4150
- 1 x FS4000
- 1 x PC

The software image versions before the upgrade:


- FMC 6.1.0-330
- FTD Primary 6.1.0-330
- FTD Secondary 6.1.0-330

- FXOS Primary 2.0.1-37
- FXOS Secondary 2.0.1-37

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, ensure that you understand the potential impact of any command.

Configure

Network Diagram



Action Plan

- Task 1: Verify the prerequisites
- Task 2: Upload the images to FMC and SSP
- Task 3: Upgrade the first FXOS chassis $(2.0.1-37 \rightarrow 2.0.1-86)$
- Task 4: Swap the FTD failover
- Task 5: Upgrade the second FXOS chassis (2.0.1-37 -> 2.0.1-86)
- Task 6: Upgrade the FMC (6.1.0-330 -> 6.1.0.1)
- Task 7: Upgrade the FTD HA pair (6.1.0-330 -> 6.1.0.1)
- Task 8: Deploy a policy from FMC to the FTD HA pair

Task 1. Verify the Prerequisites

Consult the FXOS Compatibility Guide in order to determine the compatibility between:

• Target FTD software version and FXOS software version

• Firepower HW platform and FXOS software version

Cisco Firepower 4100/9300 FXOS Compatibility



Note: This step is not applicable to FP21xx and earlier platforms.

Check the FXOS Release Notes of the target version in order to determine the FXOS upgrade path:

Cisco Firepower 4100/9300 FXOS Release Notes, 2.0(1)



Note: This step is not applicable to FP21xx and earlier platforms.

Consult the FTD target version Release Notes in order to determine the FTD upgrade path:

Firepower System Release Notes, Version 6.0.1.2

Task 2. Upload the Software Images

On the two FCMs, upload the FXOS images (fxos-k9.2.0.1.86.SPA).

On the FMC, upload the FMC and FTD upgrade packages:

- For the FMC upgrade: Sourcefire 3D Defense Center S3 Patch-6.1.0.1-53.sh
- For the FTD upgrade: Cisco_FTD_SSP_Patch-6.1.0.1-53.sh

Task 3. Upgrade the first FXOS chassis



Note: In case you upgrade FXOS from 1.1.4.x to 2.x, first shut down the FTD logical appliance, upgrade the FXOS, and then re-enable it.




Note: This step is not applicable to FP21xx and earlier platforms.


Before the upgrade:

```
<#root>
FPR4100-4-A /system #
show firmware monitor
FPRM:
    Package-Vers: 2.0(1.37)
    Upgrade-Status: Ready
Fabric Interconnect A:
    Package-Vers: 2.0(1.37)
    Upgrade-Status: Ready
Chassis 1:
    Server 1:
        Package-Vers: 2.0(1.37)
        Upgrade-Status: Ready
```

Start the FXOS upgrade:



The FXOS upgrade requires a chassis reboot:



You can monitor the FXOS upgrade from the FXOS CLI. All three components (FPRM, fabric interconnect, and chassis) have to be upgraded:

```
<#root>
FPR4100-4-A#
scope system
FPR4100-4-A /system #
show firmware monitor
FPRM:
```

```
Package-Vers: 2.0(1.37)
    Upgrade-Status:
Upgrading
Fabric Interconnect A:
    Package-Vers: 2.0(1.37)
    Upgrade-Status: Ready
Chassis 1:
    Server 1:
        Package-Vers: 2.0(1.37)
        Upgrade-Status: Ready
```



Note: A few minutes after you start the FXOS upgrade process, you are disconnected from both the FXOS CLI and the GUI. You must be able to log in again after a few minutes.

After approximately five minutes, the FPRM component upgrade completes:

```
<#root>
FPR4100-4-A /system #
show firmware monitor
FPRM:
    Package-Vers:
2.0(1.86)
    Upgrade-Status:
Ready
Fabric Interconnect A:
    Package-Vers: 2.0(1.37)
    Upgrade-Status:
Upgrading
Chassis 1:
    Server 1:
        Package-Vers: 2.0(1.37)
        Upgrade-Status:
Upgrading
```

After approximately 10 minutes, and as a part of the FXOS upgrade process, the Firepower device restarts:

```
<#root>
Please stand by while rebooting the system...
Restarting system.
```

After the restart the upgrade process resumes:

```
<#root>
FPR4100-4-A /system #
show firmware monitor
FPRM:
    Package-Vers:
2.0(1.86)
    Upgrade-Status:
Ready
Fabric Interconnect A:
    Package-Vers: 2.0(1.37)
    Upgrade-Status:
Upgrading
Chassis 1:
    Server 1:
        Package-Vers: 2.0(1.37)
        Upgrade-Status:
Upgrading
After a total of approximately 30 minutes the FXOS upgrade completes:
<#root>
FPR4100-4-A /system #
show firmware monitor
FPRM:
    Package-Vers:
2.0(1.86)
    Upgrade-Status:
Ready
Fabric Interconnect A:
    Package-Vers:
2.0(1.86)
    Upgrade-Status:
```

Ready

```
Chassis 1:
    Server 1:
        Package-Vers:
2.0(1.86)
,2.0(1.37)
        Upgrade-Status:
Ready
```

Task 4. Swap the FTD Failover States



Note: This step is not applicable to FP21xx and earlier platforms.

Before you swap the failover states, ensure that the FTD module on the chassis is fully UP:

```
<#root>
FPR4100-4-A#
connect module 1 console
Firepower-module1>
connect ftd
Connecting to ftd console... enter exit to return to bootCLI
show high-availability config
Failover On
Failover unit Secondary
Failover LAN Interface: FOVER Ethernet1/8 (up)
Reconnect timeout 0:00:00
Unit Poll frequency 1 seconds, holdtime 15 seconds
Interface Poll frequency 5 seconds, holdtime 25 seconds
Interface Policy 1
Monitored Interfaces 3 of 1041 maximum
MAC Address Move Notification Interval not set
failover replication http
Version: Ours 9.6(2), Mate 9.6(2)
Serial Number: Ours FLM2006EQFW, Mate FLM2006EN9U
Last Failover at: 15:08:47 UTC Dec 17 2016
 This host: Secondary - Standby Ready
                Active time: 0 (sec)
                slot 0: UCSB-B200-M3-U hw/sw rev (0.0/9.6(2)) status (Up Sys)
                  Interface inside (192.168.75.112):
Normal
 (Monitored)
                  Interface outside (192.168.76.112):
```

```
Normal
 (Monitored)
                   Interface diagnostic (0.0.0.0): Normal (Waiting)
                slot 1: snort rev (1.0)
status
 (
up
)
                slot 2: diskstatus rev (1.0)
status
 (
up
)
      Other host: Primary - Active
                Active time: 5163 (sec)
                  Interface inside (192.168.75.111):
Normal
 (Monitored)
                   Interface outside (192.168.76.111):
Normal
 (Monitored)
                   Interface diagnostic (0.0.0.0): Normal (Waiting)
                 slot 1: snort rev (1.0)
status
 (
up
)
                slot 2: diskstatus rev (1.0)
status
 (
up
)
Stateful Failover Logical Update Statistics
        Link : FOVER Ethernet1/8 (up)
        Stateful Obj
                         xmit
                                    xerr
                                                rcv
                                                           rerr
        General
                         65
                                    0
                                                68
        sys cmd
                         65
                                    0
                                                65
                                                           0
      ...
```

```
<#root>
no failover active
      Switching to Standby
```

Task 5. Upgrade the second FXOS chassis

Similar to Task 2, upgrade the FXOS appliance where the new Standby FTD is installed. This can take approximately 30 minutes or more to complete.



Note: This step is not applicable to FP21xx and earlier platforms.

Task 6. Upgrade the FMC Software

Upgrade the FMC, in this scenario from 6.1.0-330 to 6.1.0.1.


Task 7. Upgrade the FTD HA Pair

Before the upgrade:

```
<#root>
show high-availability config
Failover On
Failover unit Primary
Failover LAN Interface: FOVER Ethernet1/8 (up)
Reconnect timeout 0:00:00
Unit Poll frequency 1 seconds, holdtime 15 seconds
Interface Poll frequency 5 seconds, holdtime 25 seconds
Interface Policy 1
Monitored Interfaces 3 of 1041 maximum
MAC Address Move Notification Interval not set
failover replication http
Version: Ours 9.6(2), Mate 9.6(2)
Serial Number: Ours FLM2006EN9U, Mate FLM2006EQFW
Last Failover at: 15:51:08 UTC Dec 17 2016
        This host: Primary - Standby Ready
                Active time: 0 (sec)
                slot 0: UCSB-B200-M3-U hw/sw rev (0.0/9.6(2)) status (Up Sys)
                  Interface inside (192.168.75.112): Normal (Monitored)
                  Interface outside (192.168.76.112): Normal (Monitored)
```


```
Interface diagnostic (0.0.0.0): Normal (Waiting)
                slot 1: snort rev (1.0) status (up)
                slot 2: diskstatus rev (1.0) status (up)
       Other host: Secondary - Active
                Active time: 1724 (sec)
                  Interface inside (192.168.75.111): Normal (Monitored)
                  Interface outside (192.168.76.111): Normal (Monitored)
                  Interface diagnostic (0.0.0.0): Normal (Waiting)
                slot 1: snort rev (1.0) status (up)
                slot 2: diskstatus rev (1.0) status (up)
Stateful Failover Logical Update Statistics
        Link: FOVER Ethernet1/8 (up)
        Stateful Obj
                        xmit
                                   xerr
                                                         rerr
                                              rcv
       General
                                   0
                                              9
                                                         0
                        6
                        6
                                   0
                                              6
                                                         0
        sys cmd
```

From the FMC **System > Updates** menu, initiate the FTD HA upgrade process:






First, the Primary/Standby FTD is upgraded:




The Standby FTD module reboots with the new image:



You can verify the FTD status from the FXOS BootCLI mode:


The Secondary/Active FTD CLI shows a warning message due to a software version mismatch between the FTD modules:

The FMC shows that the FTD device was successfully upgraded:




The upgrade of the second FTD module starts:

' command.



At the end of the process the FTD boots with the new image:



In the background, the FMC uses the internal user **enable_1**, swaps the FTD failover states, and temporarily removes the failover configuration from the FTD:

```
firepower#
show logging

Dec 17 2016 16:40:14: %ASA-5-111008: User 'enable_1' executed the '
no failover active
' command.
Dec 17 2016 16:40:14: %ASA-5-111010: User 'enable_1', running 'N/A' from IP 0.0.0.0, executed 'no failo Dec 17 2016 16:41:19: %ASA-5-111008: User 'enable_1' executed the '
clear configure failover
```

```
Dec 17 2016 16:41:19: %ASA-5-111010: User 'enable_1', running 'N/A' from IP 0.0.0.0, executed 'clear co Dec 17 2016 16:41:19: %ASA-5-111008: User 'enable_1' executed the 'copy /noconfirm running-config disk0 Dec 17 2016 16:41:19: %ASA-5-111010: User 'enable_1', running 'N/A' from IP 0.0.0.0, executed 'copy /no disk0:/modified-config.cfg'

firepower#

Switching to Standby
```

In this case the whole FTD upgrade (both units) took approximately 30 minutes.

Verification

firepower#


This example shows FTD CLI verification from the Primary FTD device:

```
<#root>
show high-availability config
Failover On
Failover unit Primary
Failover LAN Interface: FOVER Ethernet1/8 (up)
Reconnect timeout 0:00:00
Unit Poll frequency 1 seconds, holdtime 15 seconds
Interface Poll frequency 5 seconds, holdtime 25 seconds
Interface Policy 1
Monitored Interfaces 3 of 1041 maximum
MAC Address Move Notification Interval not set
failover replication http
Version: Ours 9.6(2)4, Mate 9.6(2)4
Serial Number: Ours FLM2006EN9U, Mate FLM2006EQFW
Last Failover at: 16:40:14 UTC Dec 17 2016
        This host: Primary - Active
                Active time: 1159 (sec)
                slot 0: UCSB-B200-M3-U hw/sw rev (0.0/9.6(2)4) status (Up Sys)
                  Interface inside (192.168.75.111): Normal (Monitored)
                  Interface outside (192.168.76.111): Normal (Monitored)
                  Interface diagnostic (0.0.0.0): Normal (Waiting)
                slot 1: snort rev (1.0) status (up)
                slot 2: diskstatus rev (1.0) status (up)
       Other host: Secondary - Standby Ready
                Active time: 0 (sec)
                slot 0: UCSB-B200-M3-U hw/sw rev (0.0/9.6(2)4) status (Up Sys)
                  Interface inside (192.168.75.112): Normal (Monitored)
                  Interface outside (192.168.76.112): Normal (Monitored)
                  Interface diagnostic (0.0.0.0): Normal (Waiting)
                slot 1: snort rev (1.0) status (up)
                slot 2: diskstatus rev (1.0) status (up)
```


```
Stateful Failover Logical Update Statistics
       Link : FOVER Ethernet1/8 (up)
       Stateful Obj xmit xerr
                                            rcv
                                                      rerr
       General
                       68
                                 0
                                            67
This example shows FTD CLI verification from the Secondary/Standby FTD device:
<#root>
show high-availability config
Failover On
Failover unit Secondary
Failover LAN Interface: FOVER Ethernet1/8 (up)
Reconnect timeout 0:00:00
Unit Poll frequency 1 seconds, holdtime 15 seconds
Interface Poll frequency 5 seconds, holdtime 25 seconds
Interface Policy 1
Monitored Interfaces 3 of 1041 maximum
MAC Address Move Notification Interval not set
failover replication http
Version: Ours 9.6(2)4, Mate 9.6(2)4
Serial Number: Ours FLM2006EQFW, Mate FLM2006EN9U
Last Failover at: 16:52:43 UTC Dec 17 2016
       This host: Secondary - Standby Ready
               Active time: 0 (sec)
               slot 0: UCSB-B200-M3-U hw/sw rev (0.0/9.6(2)4) status (Up Sys)
                 Interface inside (192.168.75.112): Normal (Monitored)
                 Interface outside (192.168.76.112): Normal (Monitored)
                 Interface diagnostic (0.0.0.0): Normal (Waiting)
               slot 1: snort rev (1.0) status (up)
               slot 2: diskstatus rev (1.0) status (up)
       Other host: Primary - Active
               Active time: 1169 (sec)
                 Interface inside (192.168.75.111): Normal (Monitored)
                 Interface outside (192.168.76.111): Normal (Monitored)
                 Interface diagnostic (0.0.0.0): Normal (Waiting)
               slot 1: snort rev (1.0) status (up)
               slot 2: diskstatus rev (1.0) status (up)
Stateful Failover Logical Update Statistics
       Link: FOVER Ethernet1/8 (up)
                                       rcv
       Stateful Obj xmit xerr
                                                      rerr
       General
                       38
                                 0
                                            41
. . .
```

Task 8. Deploy a Policy to the FTD HA Pair

After the upgrade is completed, you need to deploy a policy to the HA pair. This is shown in the FMC UI:



Deploy the policies:



Verification

The upgraded FTD HA pair as it seen from the FMC UI:



The upgraded FTD HA pair as it seen from the FCM UI:



Related Information

- Cisco Firepower NGFW
- Technical Support & Documentation Cisco Systems