

Release Notes for Cisco 4000 Series ISRs, Cisco IOS XE Everest 16.6

First Published: 2017-07-28

Last Modified: 2017-07-28

Cisco 4000 Series Integrated Services Routers Overview



Note Explore the [Content Hub](#), the all new portal that offers an enhanced product documentation experience.

- Use faceted search to locate content that is most relevant to you.
- Create customized PDFs for ready reference.
- Benefit from context-based recommendations.

Get started with the Content Hub at content.cisco.com to craft a personalized documentation experience.

Do provide feedback about your experience with the Content Hub.

The Cisco 4000 Series ISRs are modular routers with LAN and WAN connections that can be configured by means of interface modules, including Cisco Enhanced Service Modules (SM-Xs), and Network Interface Modules (NIMs).



Note The Cisco IOS XE Bengaluru 17.4.1a is the first release for Cisco 4000 Series Integrated Services Routers in the Cisco IOS XE Bengaluru 17.4.1 release series.

The following table lists the router models that belong to the Cisco 4000 Series ISRs.

Cisco 4400 Series ISR	Cisco 4300 Series ISR	Cisco 4200 Series ISR
Cisco 4431 ISR	Cisco 4321 ISR	Cisco 4221 ISR
Cisco 4451 ISR	Cisco 4331 ISR	
Cisco 4461 ISR	Cisco 4351 ISR	

System Requirements

The following are the minimum system requirements:



Note There is no change in the system requirements from the earlier releases.

- Memory: 4GB DDR3 up to 16GB
- Hard Drive: 200GB or higher (Optional). (The hard drive is only required for running services such as Cisco ISR-WAAS.)
- Flash Storage: 4GB to 32GB



Note There is no change in the flash storage size from the earlier releases. The flash storage size must be equal to the system memory size.

- NIMs and SM-Xs: Modules (Optional)
- NIM SSD (Optional)

For more information, see the [Cisco 4000 Series ISRs Data Sheet](#).

Determining the Software Version

You can use the following commands to verify your software version:

- For a consolidated package, use the **show version** command
- For individual sub-packages, use the **show version installed** command

Upgrading to a New Software Release

To install or upgrade, obtain a Cisco IOS XE Gibraltar 16.12.1a consolidated package (image) from Cisco.com. You can find software images at <http://software.cisco.com/download/navigator.html>. To run the router using individual sub-packages, you also must first download the consolidated package and extract the individual sub-packages from a consolidated package.



Note When you upgrade from one Cisco IOS XE release to another, you may see *%Invalid IPV6 address* error in the console log file. To rectify this error, enter global configuration mode, and re-enter the missing IPv6 alias commands and save the configuration. The commands will be persistent on subsequent reloads.

For more information on upgrading the software, see the [How to Install and Upgrade the Software](#) section of the Software Configuration Guide for the Cisco 4000 Series ISRs.

Recommended Firmware Versions

[Table 1: Recommended Firmware Versions, on page 3](#) provides information about the recommended Rommon and CPLD versions for releases prior to Cisco IOS XE Everest 16.4.1.

Table 1: Recommended Firmware Versions

Cisco 4000 Series ISRs	Existing RoMmon	Cisco Field-Programmable Devices
Cisco 4451 ISR	16.7(4r)	15010638 Note Upgrade CLI output has a typo and it would show the version incorrectly as 15010738 instead of 15010638. This does not impact the upgrade.
Cisco 4431 ISR	16.7(4r)	15010638 Note Upgrade CLI output has a typo and it would show the version incorrectly as 15010738 instead of 15010638. This does not impact the upgrade.
Cisco 4351 ISR	16.7(5r)	14101324
Cisco 4331 ISR	16.7(5r)	14101324
Cisco 4321 ISR	16.7(5r)	14101324
Cisco 4221 ISR	16.7(5r)	14101324

Upgrading the ROMMON Version on the Cisco 4000 Series ISR

For information about ROMMON compatibility matrix, and ROMMON upgrading procedure, see the ROMMON Compatibility Matrix and "ROMMON Overview and Basic Procedures" sections in the [Upgrading Field-Programmable Hardware Devices for Cisco 4000 Series ISRs](#).

Upgrading Field-Programmable Hardware Devices

The hardware-programmable firmware is upgraded when Cisco 4000 Series ISR contains an incompatible version of the hardware-programmable firmware. To do this upgrade, a hardware-programmable firmware package is released to customers.

Generally, an upgrade is necessary only when a system message indicates one of the field-programmable devices on the Cisco 4000 Series ISR needs an upgrade, or a Cisco technical support representative suggests an upgrade.

From Cisco IOS XE Release 3.10S onwards, you must upgrade the CPLD firmware to support the incompatible versions of the firmware on the Cisco 4000 Series ISR. For upgrade procedures, see the [Upgrading Field-Programmable Hardware Devices for Cisco 4000 Series ISRs](#).

Feature Navigator

You can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.

Limitations and Restrictions

The following limitations and restrictions apply to all releases:

- [Cisco Unified Threat Defense](#) , on page 4

- Cisco ISR-WAAS and AppNav-XE Service, on page 4
- USB Etoken, on page 5

Acessing RSA Key and SSH

When you downgrade the Cisco 4000 Series ISR from IOS XE version 16.6.1 or a later release to a pre-16.6.1 release, including 16.3.X, the RSA key-pairs that are stored in private configuration storage are not accessible, and as a result, the SSH access is lost. This occurs because a secure storage feature was introduced and enabled by default starting with IOS XE version 16.6.1 which is not supported in pre-16.6.1 releases. After you downgrade, if you want to retain the access to RSA key-pair and SSH, use the **no service private-config-encryption** command in global configuration mode.

Smart Licensing

Ensure that the device is running the Cisco IOS XE Everest 16.6.1 version that supports the Smart Licensing mode.

For a more detailed overview on Cisco Licensing, go to <https://cisco.com/go/licensingguide>.

Cisco Unified Threat Defense

The Cisco Unified Threat Defense (UTD) service requires a minimum of 1 to 4 GB of DRAM.

Cisco ISR-WAAS and AppNav-XE Service

The Cisco ISR-WAAS/AppNav service requires a system to be configured with a minimum of 8GB of DRAM and 16GB flash storage. For large service profiles, 16GB of DRAM and 32GB flash storage is required. Also, Cisco ISR-WAAS requires a minimum of 200GB SSD.

IPsec Traffic

IPsec traffic is restricted on the Cisco ISR 4451-X. The router has the same IPsec functionality as a Cisco ISR G2. The default behavior of the router will be as follows (unless an HSECK9 license is installed):

- If the limit of 1000 concurrent IPsec tunnels is exceeded, no more tunnels are allowed and the following error message appears:

%CERM-4-TUNNEL_LIMIT: Maximum tunnel limit of 225 reached for Crypto functionality with securityk9 technology package license.

- The throughput encrypted traffic supports 85 Mbps.
- The Cisco 4000 Series ISR does not currently support nested SA transformation such as:

```
crypto ipsec transform-set transform-1 ah-sha-hmac esp-3des esp-md5-hmac  
crypto ipsec transform-set transform-1 ah-md5-hmac esp-3des esp-md5-hmac
```

- The Cisco 4000 Series ISR does not currently support COMP-LZS configuration.

CUBE-SRTP Calls

Cisco IOS XE Everest release 16.5.1 is not recommended for Cisco Unified Border Element deployment involving SRTP calls.

USB Etoken

USB Etoken is not supported on Cisco IOS XE Denali 16.2.1.

Unified Communication on Cisco 4000 Series ISR

- For T1/E1 clocking design and configuration changes, For detailed information, see the following Cisco document: [T1/E1 Voice and WAN Configuration Guide](#).
- For Cisco ISR 4000 Series UC features interpretation with CUCM versions, For detailed information, see the following Cisco document: [Compatibility Matrix](#).
- For High density DSPfarm PVDM (SM-X-PVDM) and PVDM4 DSP planning, For detailed information, see the following Cisco document: [DSP Calculator for DSP planning](#).

Yang Data Models

Effective with Cisco IOS XE Everest 16.5.1b, the Cisco IOS XE YANG models are available in the form of individual feature modules with new module names, namespaces and prefixes. Revision statements embedded in the YANG files indicate if there has been a model revision.

Navigate to [<https://github.com/YangModels/yang>](https://github.com/YangModels/yang) > vendor > cisco > xe > 1651, to see the new, main cisco-IOS-XE-native module and individual feature modules attached to this node.

There are also XPATH changes for the access-list in the *Cisco-IOS-XE-acl.yang* schema.

The *README.md* file in the above Github location highlights these and other changes with examples.

New Features and Important Notes About Cisco 4000 Series ISRs Release Everest 16.6

This section describes new features in Cisco IOS XE Everest 16.6 that are supported on the Cisco 4000 Series ISRs.

New and Changed Information

New Software Features in Cisco 4000 Series ISR Release Cisco IOS XE Everest 16.6.2

The following features are supported by the Cisco 4000 Series Integrated Services Routers for Cisco IOS XE Everest 16.6.2:

- Dying Gasp Support on Cisco 4000 Series ISRs—For detailed information, see the following Cisco document: [Carrier Ethernet Configuration Guide](#).
- Encrypted Traffic Analytics—For detailed information, see the following Cisco document: https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_data_eta/configuration/xe-16-6/sec-data-encrypted-traffic-analytics-xe-16-6-book.html and <https://www.cisco.com/c/dam/en/us/td/docs/solutions/CVD/Campus/CVD-Encrypted-Traffic-Analytics-Deployment-Guide-2017DEC.pdf>.
- Enable Allowedlist Support for Encrypted Traffic Analytics—For detailed information, see the following Cisco document: <https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/netflow/configuration/xe-16-6/nf-xe-16-6-book/encrypted-traffic-analytics.html>.
- Enable TLS Labels, App ID, and Multi Destination Support—For detailed information, see the following Cisco document: <https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/netflow/configuration/xe-16-6/nf-xe-16-6-book/encrypted-traffic-analytics.html>.

New Hardware Features in Cisco IOS XE Everest 16.6.1

There are no new hardware features in this release.

New Software Features in Cisco 4000 Series ISR Release Cisco IOS XE Everest 16.6.1

The following features are supported by the Cisco 4000 Series Integrated Services Routers for Cisco IOS XE Everest 16.6.1:

- For information on migrating from existing Cisco IOS XE 3S releases to the Cisco IOS XE Everest 16.6.1 release, see [Cisco IOS XE Everest 16.4.1 Migration Guide for Access and Edge Routers](#).
- Supported Technology Configuration Guides—When a technology is supported on Cisco 4000 series ISR, the corresponding technology configuration guide is displayed on the product landing page.
- BGP Feature Monitoring—for detailed information, see the following Cisco document:
<http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/datamodels/configuration/xe-16/data-models-xe-16-book.html>.
- Caller-ID and Directory Lookup for SIP Phones on Unified CME—for detailed information, see the following Cisco document:
http://www.cisco.com/c/en/us/td/docs/voice_ip_comm/cucme/admin/configuration/manual/cmeadm/cmadirss.html.
- HTTPS: UC Gateway Services API—for detailed information, see the following Cisco document:
http://www.cisco.com/c/en/us/td/docs/voice_ip_comm/cucme/CUCIS_API/CUCIS_API_Guide.html.
- IPv6 Support for Cisco Unified SIP SRST—for detailed information, see the following Cisco document:
http://www.cisco.com/c/en/us/td/docs/voice_ip_comm/admin/sip_sst/configuration/guideSCCP_and_SIP_SRST_Admin_Guide/sst_overview.html
- ISIS - SR OAM: ISIS FEC—for detailed information, see the following Cisco document:
https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/seg_routing/configuration/xe-16-6/xe-16-6-book/oam-entropy-label-support.html
- MLPPPoe on PPP Termination and Aggregation Router—for detailed information, see the following Cisco document:
http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/wan_mlp/configuration/xe-16/wan-mlp-xe-16-book/wan-mlppp-eht-ptx.html.
- NID Support—for detailed information, see the following Cisco document:
<https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/cether/configuration/xe-16-6/ce-xe-16-6-book/ce-nid-support.html>.
- NTT for NIM-BRI on Cisco 4000 Series ISR—Effective with Cisco IOS XE Everest 16.6.1 release, the ISDN switch type NTT on BRI network interface modules is supported on Cisco 4000 Series Integrated Services Routers, to enable seamless migration from Cisco G2 Series Integrated Services Routers.
- NGE TDM-IP (SIP) Support on Cisco 4000 Series ISR—Effective with Cisco IOS XE Everest 16.6.1, Next Generation Encryption (NGE) support is added for TDM-IP SIP in Cisco 4000 Series ISRs. NGE provides stronger encryption algorithm. With NGE, both signaling and media can be protected by the next generation cipher suites.
- QoS on GEC Portchannel on Cisco 4000 Series ISR—for detailed information, see the following Cisco document:
https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_mqc/configuration/xe-16-6/qos-mqc-xe-16-6-book/aggregate-etherchannel-quality-of-service.html.
- Report Client-IP to Umbrella Cloud—for detailed information, see the following Cisco document:
http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/sec_data/utl/configuration/xe-16/sec-data-umbrella-branch-xe-16-book/sec-data-umbrella-branch.html
- RESTCONF Programmability Interface Feature—for detailed information, see the following Cisco document:
https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/prog/configuration/166/b_166_programmability_cg.html

- Radio Aware Routing—For detailed information, see the following Cisco document:
http://www.cisco.com/c/en/us/td/docs/routers/access/4400/software/configuration/guide/ir4400swcfg/ir4400swcfg_chapter_010010.html
- SD-AVC Auto-update Capability—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_nbar/configuration/xe-16-6/qos-nbar-xe-16-6-book.html
- SD-AVC NBAR Export Capability—For detailed information, see the following Cisco document:https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/qos_nbar/configuration/xe-16-6/qos-nbar-xe-16-6-book.html
- Software Maintenance Upgrade—For detailed information, see the following Cisco document:
<https://www.cisco.com/c/en/us/td/docs/ios-xml/ios/config-mgmt/configuration/xe-16-6/config-mgmt-xe-16-6-book.html>
- Support for Idle URL for SIP Phones on Unified CME—For detailed information, see the following Cisco document:
http://www.cisco.com/c/en/us/td/docs/voice_ip_comm/cucme/admin/configuration/manual/cmeadm/cmelabel.html
- Umbrella Connector on Cisco 4000 Series ISR/Interoperability of OpenDNS with IWAN—For detailed information, see the following Cisco document:
http://www.cisco.com/c/en/ustd/docs/ios-xml/ios/sec_data_udt/configuration/xe-16sec-data-umbrella-branch-xe-16-book/sec-data-umbrella-branhtml
- UDF-ACL-Enhancement—For detailed information, see the following Cisco document:
<http://www.cisco.com/c/en/us/td/docs/ios-xml/ios/lanswitch/configuration/xe-16-lanswitch-xe-16-6-book/lnsw-conferspan.html>
- Web User Interface—Supports an embedded GUI-based device-management tool that provides the ability to provision the router, simplifies device deployment and manageability, and enhances user experience. The following features are supported on Web User Interface from Cisco IOS XE Everest 16.6.1:
 - Cisco Umbrella Branch—The Cisco Umbrella Branch feature enables cloud-based security service by inspecting the Domain Name System (DNS) query that is sent to the enterprise DNS server through the Cisco 4000 Series Integrated Services Routers (ISR). The security administrator configures policies on the Cisco Umbrella Branch cloud to either allow or deny traffic towards the fully qualified domain name (FQDN). Cisco 4000 Series ISR acts as a DNS forwarder on the network edge, transparently intercepts DNS traffic, and forwards the DNS queries to the Cisco Umbrella Branch cloud.
 - Dynamic Multipoint VPN—The Dynamic Multipoint VPN feature allows users to better scale large and small IP Security (IPsec) Virtual Private Networks (VPNs) by combining generic routing encapsulation (GRE) tunnels, IPsec encryption, and Next Hop Resolution Protocol (NHRP).
 - USB-LTE modem is supported on Web UI.
 - Snort IPS/IDS—The Snort IPS feature enables Intrusion Prevention System (IPS) or Intrusion Detection System (IDS) for branch offices on Cisco 4000 Series Integrated Services Routers and Cisco Cloud Services Router 1000v Series. This feature uses the open source Snort solution to enable IPS and IDS.
 - Zone-Based Firewall—Allows you to easily manage Cisco IOS unidirectional firewall policy between groups of interfaces known as zones.

For information on how to access the Web User Interface, see Configure the Router for Web User Interface section.

- YANG Data Models—For the list of Cisco IOS XE YANG models available with this release, navigate to <https://github.com/YangModels/yang/tree/master/vendor/cisco/xe/1661>.

Revision statements embedded in the YANG files indicate if there has been a model revision. The README.md file in the same github location highlights changes that have been made in the release

- Zero-Touch Provisioning (ZTP) —Supports HTTP file download along with TFTP file download

Configure the Router for Web User Interface

This section explains how to configure the router to access Web User Interface. Web User Interface require the following basic configuration to connect to the router and manage it.

- An HTTP or HTTPs server must be enabled with local authentication.
- A local user account with privilege level 15 and accompanying password must be configured.
- Vty line with protocol ssh/telnet must be enabled with local authentication. This is needed for interactive commands.
- For more information on how to configure the router for Web User Interface, see [Cisco 4000 Series ISRs Software Configuration Guide, Cisco IOS XE 17](#).

Entering the Configuration Commands Manually

To enter the Cisco IOS commands manually, complete the following steps:

Before you begin

If you do not want to use the factory default configuration because the router already has a configuration, or for any other reason, you can use the procedure in this section to add each required command to the configuration.

Procedure

-
- Step 1** Log on to the router through the Console port or through an Ethernet port.
- Step 2** If you use the Console port, and no running configuration is present in the router, the Setup command Facility starts automatically, and displays the following text:
- ```
--- System Configuration Dialog ---
Continue with configuration dialog? [yes/no] :
```
- Enter no so that you can enter Cisco IOS CLI commands directly.
- If the Setup Command Facility does not start automatically, a running configuration is present, and you should go to the next step.
- Step 3** When the router displays the user EXEC mode prompt, enter the **enable** command, and the enable password, if one is configured, as shown in the following example:
- ```
Router> enable  
password password
```
- Step 4** Enter config mode by entering the **configure terminal** command, as shown in the following example.
- ```
Router> config terminal
Router(config)#
```
- Step 5** Using the command syntax shown, create a user account with privilege level 15.

- Step 6** If no router interface is configured with an IP address, configure one so that you can access the router over the network. The following example shows the interface GigabitEthernet 0/0/0 configured.

```
Router(config)# interface gigabitethernet 0/0/0
Router(config-if)# ip address 10.10.10.1 255.255.255.248
Router(config-if)# no shutdown
Router(config-if)# exit
```

- Step 7** Configure the router as an http server for nonsecure communication, or as an https server for secure communication. To configure the router as an http server, enter the **ip http server** command shown in the example:

```
Router(config)# ip http secure-server
```

- Step 8** Configure the router for local authentication, by entering the **ip http authentication local** command, as shown in the example:

```
Router(config)# ip http authentication local
```

- Step 9** Configure the vty lines for privilege level 15. For nonsecure access, enter the **transport input telnet** command. For secure access, enter the **transport input telnet ssh** command. An example of these commands follows:

```
Router(config)# line vty 0 4
Router(config-line)# privilege level 15
Router(config-line)# login local
Router(config-line)# transport input telnet
Router(config-line)# transport output telnet
Router(config-line)# transport input telnet ssh
Router(config-line)# transport output telnet ssh
Router(config-line)# exit
Router(config)# line vty 5 15
Router(config-line)# privilege level 15
Router(config-line)# login local
Router(config-line)# transport input telnet
Router(config-line)# transport output telnet
Router(config-line)# transport input telnet ssh
Router(config-line)# transport output telnet ssh
Router(config-line)# end
```

## Resolved and Open Bugs

This section provides information about the caveats in Cisco 4000 Series Integrated Services Routers and describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats. This section includes severity 1, severity 2, and selected severity 3 caveats.

The open and resolved bugs for this release are accessible through the [Cisco Bug Search Tool](#). This web-based tool provides you with access to the Cisco bug tracking system, which maintains information about bugs and vulnerabilities in this product and other Cisco hardware and software products. Within the [Cisco Bug Search Tool](#), each bug is given a unique identifier (ID) with a pattern of CSCxxNNNNN, where x is any letter (a-z) and N is any number (0-9). The bug IDs are frequently referenced in Cisco documentation, such as Security Advisories, Field Notices and other Cisco support documents. Technical Assistance Center (TAC) engineers or other Cisco staff can also provide you with the ID for a specific bug. The [Cisco Bug Search Tool](#) enables you to filter the bugs so that you only see those in which you are interested.

In addition to being able to search for a specific bug ID, or for all bugs in a product and release, you can filter the open and/or resolved bugs by one or more of the following criteria:

- Last modified date
- Status, such as fixed (resolved) or open
- Severity
- Support cases

You can save searches that you perform frequently. You can also bookmark the URL for a search and email the URL for those search results.



**Note** If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access the field notices from the following location:

[http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html)

## Using the Cisco Bug Search Tool

For more information about how to use the [Cisco Bug Search Tool](#), including how to set email alerts for bugs and to save bugs and searches, see [Bug Search Tool Help & FAQ](#).

### Before You Begin



**Note** You must have a Cisco.com account to log in and access the [Cisco Bug Search Tool](#). If you do not have one, you can register for an account.

### Procedure

**Step 1** In your browser, navigate to the [Cisco Bug Search Tool](#).

**Step 2** If you are redirected to a Log In page, enter your registered Cisco.com username and password and then, click Log In.

**Step 3** To search for a specific bug, enter the bug ID in the Search For field and press Enter.

**Step 4** To search for bugs related to a specific software release, do the following:

- a) In the Product field, choose Series/Model from the drop-down list and then enter the product name in the text field. If you begin to type the product name, the [Cisco Bug Search Tool](#) provides you with a drop-down list of the top ten matches. If you do not see this product listed, continue typing to narrow the search results.

- b) In the Releases field, enter the release for which you want to see bugs.

The [Cisco Bug Search Tool](#) displays a preview of the results of your search below your search criteria.

**Step 5** To see more content about a specific bug, you can do the following:

- Mouse over a bug in the preview to display a pop-up with more information about that bug.

- Click on the hyperlinked bug headline to open a page with the detailed bug information.

**Step 6** To restrict the results of a search, choose from one or more of the following filters:

| Filter        | Description                                                                                                                                  |
|---------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| Modified Date | A predefined date range, such as last week or last six months.                                                                               |
| Status        | A specific type of bug, such as open or fixed.                                                                                               |
| Severity      | The bug severity level as defined by Cisco. For definitions of the bug severity levels, see <a href="#">Bug Search Tool Help &amp; FAQ</a> . |
| Rating        | The rating assigned to the bug by users of the <a href="#">Cisco Bug Search Tool</a> .                                                       |
| Support Cases | Whether a support case has been opened or not.                                                                                               |

Your search results update when you choose a filter.

---

## Resolved and Open Bugs in Cisco 4000 Series Integrated Services Routers

This section contains the following topics:

### Open Caveats - Cisco IOS XE Everest 16.6.9

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                            |
|----------------------------|------------------------------------------------------------------------|
| <a href="#">CSCvf86185</a> | NIM-SSD: Inventory of disk0 and disk1 are interchanged on Polaris 16.x |
| <a href="#">CSCvt35331</a> | Console port goes unresponsive, reboot required to restore it.         |

### Resolved Caveats - Cisco IOS XE Everest 16.6.9

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                  |
|----------------------------|------------------------------------------------------------------------------|
| <a href="#">CSCvs48300</a> | Arkenstone boot fail in Cisco 4221 ISR                                       |
| <a href="#">CSCvv98528</a> | Cisco 4000 Series ISR SER parity error checks continuing till router crashes |
| <a href="#">CSCvw56517</a> | LMR Unable to hear first seconds of audio                                    |
| <a href="#">CSCvw57860</a> | Duplicate entries seen in MAC filter table.                                  |

### Open Caveats - Cisco IOS XE Everest 16.6.8

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                  |
|----------------------------|----------------------------------------------------------------------------------------------|
| <a href="#">CSCve01479</a> | The e2e ping fails after configuring profiles qos-de and aaaauth1.                           |
| <a href="#">CSCvf50723</a> | Packet-tracer error message % Error: Failed to collect packet information.                   |
| <a href="#">CSCvf86185</a> | NIM-SSD: Inventory of disk0 and disk1 are interchanged on Polaris 16.x.                      |
| <a href="#">CSCvg62139</a> | The "show voice lmr port_number" on Cisco 4000 Series ISRs do not show m-lead status         |
| <a href="#">CSCvi37580</a> | There is unexpected packets lost TCA reported on ISR4331 platform.                           |
| <a href="#">CSCvj17326</a> | Cisco 4000 Series ISRs crashes in o2_cavm_pci_unlock when forwarding large packets for VPLS. |
| <a href="#">CSCvn22199</a> | Cisco 4000 Series ISRs fails to authenticate users via dot1x following interface flap.       |
| <a href="#">CSCvo84147</a> | Cisco 4000 Series ISRTCP SEQ/ACK number wrongly inserted after OUT to IN NAT translation.    |
| <a href="#">CSCvp49863</a> | Incomplete arp in management interface.                                                      |
| <a href="#">CSCvp68166</a> | The P-bit Sev Err Secs" increasing in patterns of 256 in SM-X-1T3/E3 on Cisco 4451 ISR.      |
| <a href="#">CSCvr89973</a> | NIM interfaces go into shutdown after router bootup.                                         |
| <a href="#">CSCvt35331</a> | Console port goes unresponsive, reboot required to restore it.                               |
| <a href="#">CSCvt55347</a> | Cisco 4000 Series ISRs OID cwceLteCurrRsrq returning the wrong values.                       |

**Resolved Caveats - Cisco IOS XE Everest 16.6.8**

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                               |
|----------------------------|-------------------------------------------------------------------------------------------|
| <a href="#">CSCvo97985</a> | The path-id discovery failure with "CENT throttle check fails, throttle type:0.           |
| <a href="#">CSCvp23112</a> | OBS: ping stop working on replacing MIP100 ->SIP40 >MIP100                                |
| <a href="#">CSCvp94050</a> | cpp_bqs_srt_yoda_csr_tree_seid_initialize:1744 is not in "placed" state                   |
| <a href="#">CSCvq81620</a> | Router crashes with ZBF HA sync.                                                          |
| <a href="#">CSCvq93850</a> | Passive FTP will fail when going over NAT and either client or server are off a SM-X-ES3. |
| <a href="#">CSCvr00983</a> | Unrecoverable Error with PVDM in 0/4 and Thule+dreamliner in 1/0 on Cisco 4300 ISR.       |
| <a href="#">CSCvr01454</a> | Punt fragment crash when receive EoGRE packets which have many fragments.                 |

| Caveat ID Number           | Description                                                                                                          |
|----------------------------|----------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvr15127</a> | Cisco 4000 Series ISRs Calls fade to no-way audio due to media inactivity detection after 20 minutes.                |
| <a href="#">CSCvr43037</a> | The show macsec statistics interface and show macsec status interface does not show output                           |
| <a href="#">CSCvr58352</a> | Prince: Keepalive pkts dropped when serial link congested with data traffic                                          |
| <a href="#">CSCvr76534</a> | Cisco 4000 Series ISRs : Crash seen at Process Exec.                                                                 |
| <a href="#">CSCvr79751</a> | Cisco 4331 ISR with BOOST License, the order of multicast packets reversed.                                          |
| <a href="#">CSCvr89957</a> | CFT crashed frequently.                                                                                              |
| <a href="#">CSCvs07447</a> | Cisco 4000 Series ISRs Mgmt Gi0 up with speed 100Mbps                                                                |
| <a href="#">CSCvs28073</a> | IOS-XE memory leak seen in 16.3.7 in IOSd due to update_sn_ao_state not deleting TDL bucket.                         |
| <a href="#">CSCvs53749</a> | EVPN RMAC stale routes seen.                                                                                         |
| <a href="#">CSCvs55066</a> | Cisco 4000 Series ISRs only: MGCP status remains Down and does not register with CUCM after a reboot or power cycle. |
| <a href="#">CSCvs75958</a> | Cisco 4331 ISR/K9 Dialer cannot make calls suddenly.                                                                 |
| <a href="#">CSCvs86573</a> | Connect message is never forwarded to the calling side.                                                              |

## Open Caveats - Cisco IOS XE Everest 16.6.7

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                   |
|----------------------------|-----------------------------------------------------------------------------------------------|
| <a href="#">CSCvd65197</a> | IOSd crashed when dialer disconnect the ISDN call.                                            |
| <a href="#">CSCvf86185</a> | NIM-SSD: Inventory of disk0 and disk1 are interchanged on XE 16.x.                            |
| <a href="#">CSCvg62139</a> | "show voice lmr port_number " on Cisco 4000 Series ISRs do not show m-lead status.            |
| <a href="#">CSCvi37580</a> | There is unexpected packets lost TCA reported on Cisco 4331 ISR platform                      |
| <a href="#">CSCvj17326</a> | Cisco 4400 ISR crashes in o2_cavm_pci_unlock when forwarding large packets for VPLS.          |
| <a href="#">CSCvj55210</a> | Memory leaks at __be_PKI_keypair_name_get.                                                    |
| <a href="#">CSCvo70549</a> | CME SIP: BE4000 Smart Licensing - Extension Assigner temp registration uses endpoint license. |
| <a href="#">CSCvo84147</a> | Cisco 4000 Series ISRs TCP SEQ/ACK number wrongly inserted after OUT to IN NAT translation.   |

## Resolved Caveats - Cisco IOS XE Everest 16.6.7

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvp31671</a> | Router crashes due to a call loop.                                                                    |
| <a href="#">CSCvp49863</a> | Incomplete arp in management interface.                                                               |
| <a href="#">CSCvp68166</a> | "P-bit Sev Err Secs" increasing in patterns of 256 in SM-X-1T3/E3 on Cisco 4451 ISR.                  |
| <a href="#">CSCvp70211</a> | Crash when running show crypto map.                                                                   |
| <a href="#">CSCvp98673</a> | Inband to OOB DTMF Fails to Be Passed On CUBE If Media Inactive Comes During Digit Processing         |
| <a href="#">CSCvq43004</a> | Need to check qfp ucode crash with RTCP traffic - chunk memory corruption in RTCP path.               |
| <a href="#">CSCvq73281</a> | TLS connections in WebEx between CUBE and iCP/CUSP breaks intermittently.                             |
| <a href="#">CSCvq75307</a> | Crash due to watchdog after adding a prefix-list/ Route-map entry to existing route map.              |
| <a href="#">CSCvq78692</a> | mGRE L3VPN broken after reload.                                                                       |
| <a href="#">CSCvq81620</a> | Router crashes with ZBF HA sync.                                                                      |
| <a href="#">CSCvq85913</a> | FlexVPN with password encryption -- after MasterKey change password in profile is not working.        |
| <a href="#">CSCvq90361</a> | NHRP process crash on using same tunnel address on multiple spokes.                                   |
| <a href="#">CSCvr00983</a> | Unrecoverable Error with PVDM in 0/4 and Thule+dreamliner in 1/0 on Cisco 4300 Series ISRs.           |
| <a href="#">CSCvr15127</a> | Cisco 4000 Series ISRs Calls fade to no-way audio due to media inactivity detection after 20 minutes. |
| <a href="#">CSCvr15253</a> | Router Crashes while Parsing and Printing Voice Packet IEs.                                           |
| <a href="#">CSCvr17169</a> | qfp ucode crash with media monitor.                                                                   |
| <a href="#">CSCvr17670</a> | The Cisco 4331 ISR crash and lost all config files.                                                   |

## Resolved Caveats - Cisco IOS XE Everest 16.6.7

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCvd67904</a> | Cisco 4000 Series ISRs does not run dot1x when a laptop wakes from sleep mode.                    |
| <a href="#">CSCve57810</a> | Amur failing over w/o fail next-method or no-response next method.                                |
| <a href="#">CSCvg32153</a> | "show interface port-channel" falsely reports output drops when there are no actual output drops. |

| Caveat ID Number           | Description                                                                                    |
|----------------------------|------------------------------------------------------------------------------------------------|
| <a href="#">CSCvh49874</a> | FNF monitor download to DP failed after changing netflow record.                               |
| <a href="#">CSCvh79264</a> | Change the punt cause of packets whose destination is virtual IP from SUBNET_BCAST to FOR_US.  |
| <a href="#">CSCvh92659</a> | BFD flaps everytime with dynamic tunnel creation in DMVPN.                                     |
| <a href="#">CSCvi04907</a> | T38 Packets are dropped by CUBE on ISR G2 in Multi VRF Scenario.                               |
| <a href="#">CSCvi22263</a> | Crash when IOS is adapting shaping with Adaptive QoS over DMVPN configured.                    |
| <a href="#">CSCvj00317</a> | Memory leak VOIP *MallocLite*.                                                                 |
| <a href="#">CSCvj28921</a> | High CPU due to Alignment Corrections - SMEF & IWAN.                                           |
| <a href="#">CSCvj72294</a> | memory leak @ CCSIP_SPI_CONTR.                                                                 |
| <a href="#">CSCvj76866</a> | Partial Power Failure in Stack Causes Interfaces to Become "shutdown".                         |
| <a href="#">CSCvk17998</a> | Rekey Timer are same for both the Server and Client.                                           |
| <a href="#">CSCvk47271</a> | ICisco 4000 Series ISRs crashed in FXS-FXS non-hairpin call.                                   |
| <a href="#">CSCvk51939</a> | SSS Manager Traceback observer when test MLPPP.                                                |
| <a href="#">CSCvm10850</a> | Crash after CPUHOG in ISDN L2D SRQ Process.                                                    |
| <a href="#">CSCvm47690</a> | Addition/Edits to numbered OG ACL using "access-list <>" command does not re-expand the ACL.   |
| <a href="#">CSCvn00104</a> | Software crash due to memory corruption after packet trace was enabled.                        |
| <a href="#">CSCvn01507</a> | ISR not re-calculating the hash value correctly after payload change.                          |
| <a href="#">CSCvn02456</a> | Router crashes when the calls doesn't establish after making 2 calls when we set "max-conn 2". |
| <a href="#">CSCvn03502</a> | SR: CFLOW input intf index is 0xffffffff for Service-engine DSP module interface.              |
| <a href="#">CSCvn23906</a> | DHCP Server sends Renew ACKs to Clients with 00:00:00:00:00:00 MAC in L2 frame.                |
| <a href="#">CSCvn45732</a> | Device crashing if we unconfigure the NTP on the device.                                       |
| <a href="#">CSCvn57892</a> | High Memory utilization due to Wireless Manager IOSD process.                                  |
| <a href="#">CSCvn61039</a> | Cisco 4000 Series ISRs - control-plane host' feature was moved to APPX feature set.            |
| <a href="#">CSCvn78961</a> | Subscribers cannot re-login due to CoA time-out (lite-sessions in routed mode)                 |
| <a href="#">CSCvo03458</a> | PKI "revocation check crl none" does not fallback if CRL not reachable.                        |
| <a href="#">CSCvo04856</a> | DataPlane (DP) crash observed in MMOH call flow.                                               |

| Caveat ID Number           | Description                                                                                         |
|----------------------------|-----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvo06817</a> | Router crash while executing show commands using " " (pipe) to filter the output.                   |
| <a href="#">CSCvo10145</a> | Memory overlay crash when using include-cui.                                                        |
| <a href="#">CSCvo10491</a> | PnP Agent should detect image upgrade scenario and configure dialer to bring up cellular interface. |
| <a href="#">CSCvo11786</a> | SCCP Application does not clear failed sockets leading to leak and socket pool exhaustion.          |
| <a href="#">CSCvo12745</a> | Packet drop occurs after acl permit configurations.                                                 |
| <a href="#">CSCvo12799</a> | Call is not getting connected in Forking Re-INVITE scenario.                                        |
| <a href="#">CSCvo21122</a> | Memory leak at hman process.                                                                        |
| <a href="#">CSCvo36031</a> | WSMA crash formatting show command output.                                                          |
| <a href="#">CSCvo46138</a> | Stuck CPP Thread while processing H323 packet.                                                      |
| <a href="#">CSCvo46405</a> | QFP ucode crashed with sRTP traffic - chunk memory corruption.                                      |
| <a href="#">CSCvo47376</a> | Cisco REST API Container for IOS XE Software Authentication Bypass Vulnerability.                   |
| <a href="#">CSCvo55194</a> | After RSP switchover label imposition was not programmed in Software on APS standby router.         |
| <a href="#">CSCvo58098</a> | CTS PACS not downloading to the devices.                                                            |
| <a href="#">CSCvo61610</a> | FXS - no busy tone is generated on remote-onhook condition with call pickup scenario.               |
| <a href="#">CSCvo66216</a> | IPSec-Session count in "show crypto eli" reaches max causing VPN failure.                           |
| <a href="#">CSCvo71721</a> | When sending account-logon ISG do not reply with ACK nor NACK.                                      |
| <a href="#">CSCvo74486</a> | IOS-XE ACL port information preserved after encapsulation.                                          |
| <a href="#">CSCvo87827</a> | Crash when polling IPForwarding MIB.                                                                |
| <a href="#">CSCvo90060</a> | Wrong label programming leading to traffic drop.                                                    |
| <a href="#">CSCvo92514</a> | SDP attribute list corruption causes voice gateway crash.                                           |
| <a href="#">CSCvp24911</a> | SRTPE ROC Stress: CPP crash with 6000+ concurrent calls - g729.                                     |
| <a href="#">CSCvp24981</a> | When FQDN used for APN, IOS DNS resolves FQDN to IP, but GTP stays in DNS pending and IP 0.0.0.0.   |
| <a href="#">CSCvp25052</a> | Cisco 4000 Series ISRs: Router crash due to twice memory release.                                   |
| <a href="#">CSCvp27220</a> | Tail drops on IPSLA sender when using scaled udp-jitter probes.                                     |
| <a href="#">CSCvp31779</a> | Router Running IOS-XE 16 Crashes when Stopping EPC with ACL.                                        |

| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCvp33578</a> | Crash at the moment of deleting a DVTI.                                                           |
| <a href="#">CSCvp34230</a> | CUBE HA - Global bind is removed during interface flap.                                           |
| <a href="#">CSCvp38317</a> | MGCP GW does not reset SSRC/ROC on receiving MDCX with new IP/port/SDP parameter for SRTP call.   |
| <a href="#">CSCvp39597</a> | Crashes with GRE tunnels configured with QOS over Multilink Frame-relay interfaces.               |
| <a href="#">CSCvp42709</a> | Cisco 4000 Series ISRs NO_PUNT_KEEPALIVE kernel crash due to CP drivers stuck punt and IPC rings. |
| <a href="#">CSCvp47723</a> | Cisco 4000 Series ISRs CME no way audio on calls across E1/PRI, reboot resolves for sometime.     |
| <a href="#">CSCvp56596</a> | Cisco 4000 Series ISRs crashes after voice register reset command is applied.                     |
| <a href="#">CSCvp63616</a> | Crash due to too many DSPs.                                                                       |
| <a href="#">CSCvp65151</a> | CPP Stuck thread when processing IPv6 traffic.                                                    |
| <a href="#">CSCvp67530</a> | Corrupt free block of memory with high availability config for Session Initiation Protocol.       |
| <a href="#">CSCvp69393</a> | Router crashes after snmpget to OID related to NHRP.                                              |
| <a href="#">CSCvp70443</a> | ISDN cause-location command support for switch-type primary-ntt.                                  |
| <a href="#">CSCvp72220</a> | Crash at sisf_show_counters after entering show device-tracking counters command.                 |
| <a href="#">CSCvp72379</a> | IP dns primary command does not get removed.                                                      |
| <a href="#">CSCvp74674</a> | QoS fails to apply to tunnel2 when underlying tunnell1 reachability change.                       |
| <a href="#">CSCvp86216</a> | Router ucode crash with NAT with interface flap.                                                  |
| <a href="#">CSCvp87488</a> | No login on-success log CLI does not persist across device reloads.                               |
| <a href="#">CSCvp92334</a> | Crash after Media monitor look up.                                                                |
| <a href="#">CSCvp99884</a> | CUBE not passing History-Info header in 181 Call is being forwarded.                              |
| <a href="#">CSCvq00263</a> | Device crashed @ radius_io_stats_timer_handler due to dynamic-author.                             |
| <a href="#">CSCvq04828</a> | VRF aware reverse DNS lookup not working.                                                         |
| <a href="#">CSCvq12723</a> | DPDK: Performing Shut/No-Shut with traffic running can cause packets to silently drop on TX.      |
| <a href="#">CSCvq18793</a> | NIM-2FXS/4FXOP crashing due to DSP failed to reply properly.                                      |
| <a href="#">CSCvq29575</a> | Voice gateway crash due to segmentation fault in process CCSIP_DNS.                               |
| <a href="#">CSCvq39121</a> | Cisco 4000 Series ISRs crash during packet inspection due to stuck thread.                        |

| Caveat ID Number           | Description                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvq50202</a> | Class-attributes duplicated after EAP reauthen. in ISG radius proxy scenario.                      |
| <a href="#">CSCvq57205</a> | Recording failures with XM福 media forking and SIP preservation timer.                              |
| <a href="#">CSCvq57862</a> | Cable-detect command not reflecting proper status in Analog ports on IOS-XE platforms.             |
| <a href="#">CSCvq58520</a> | After reload dial-peers with ports that have the 'signal did' command show operational state none. |
| <a href="#">CSCvq72560</a> | More connections are getting passthrough with reason SNG_OVERLOAD.                                 |
| <a href="#">CSCvq75610</a> | IWAN router crash after upgrading to 16.3.8.                                                       |
| <a href="#">CSCvq92102</a> | VG450: SCCP crashing router while shutdown the process.                                            |

## Open Caveats - Cisco IOS XE Everest 16.6.6

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj72294</a> | Memory leak happens at CCSIP_SPI_CONTR process for every trunk out-of-dialog message with "contact" header in it. |
| <a href="#">CSCvj56471</a> | Memory leak under CCSIP_UDP_SOCKET / MallocLite                                                                   |
| <a href="#">CSCvk51939</a> | SSS Manager Traceback observer when test MLPPP                                                                    |
| <a href="#">CSCvn01507</a> | ISR not re-calculating the hash value correctly after payload change                                              |
| <a href="#">CSCvo60849</a> | Crash noticed when routes are getting imported twice(from vpnv4 to vrf to evpn) with route churn                  |
| <a href="#">CSCvo62122</a> | IOS-XE Router may crash when attempting to Fragment Corrupted IPv4 Packet                                         |
| <a href="#">CSCvo66216</a> | IPSec-Session count in "show crypto eli" reaches max causing VPN failure                                          |
| <a href="#">CSCvo74486</a> | IOS-XE ACL port information preserved after encapsulation                                                         |
| <a href="#">CSCvo87827</a> | Crash when polling IPForwarding MIB                                                                               |
| <a href="#">CSCvp03110</a> | After Configuring a New VRF Routes Are Not Imported From WAN Into l2vpn EVPN For Unrelated VRF                    |

## Resolved Caveats - Cisco IOS XE Everest 16.6.6

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description             |
|----------------------------|-------------------------|
| <a href="#">CSCuw36080</a> | SNMP with Extended ACL. |

| Caveat ID Number           | Description                                                                                                 |
|----------------------------|-------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvg40746</a> | mka policy MKA_POLICY" config lost after reload.                                                            |
| <a href="#">CSCvh57657</a> | NAT MIB not populated when using traditional NAT.                                                           |
| <a href="#">CSCvj86876</a> | Cisco 4000 Series ISR- IOS 16.8 - crypto-related issues seen with a single AF configured in VRF definition. |
| <a href="#">CSCvk32822</a> | QoS stats process crash.                                                                                    |
| <a href="#">CSCvk62792</a> | IKE Fragmentation payload incorrectly marked as critical.                                                   |
| <a href="#">CSCvm56670</a> | ACL dropping packets after updating it - %CPPEXMEM-3-NOMEM.                                                 |
| <a href="#">CSCvm70471</a> | hw-module subslot 0/2 reload' CLI does not activate the container after harddisk format.                    |
| <a href="#">CSCvm75066</a> | MPLSoVPN: Change behavior of default route in NHRP. Must insert 0.0.0.0/0 instead of /32.                   |
| <a href="#">CSCvm94891</a> | Crash caused by a "TLB Modification exception" after processing a null chunk in "IP Input" process.         |
| <a href="#">CSCvn02419</a> | Device running IOS-XE 16 Polaris Sees Crash When Performing NAT ALG on FTP Packet.                          |
| <a href="#">CSCvn14737</a> | Crash with SIP call.                                                                                        |
| <a href="#">CSCvn17062</a> | Cisco 4000 Series ISRs add SCCP MTP single-VRF support with a limitation no traffic from/to other VRF       |
| <a href="#">CSCvn17530</a> | Router Crashes When PKI-CRL-IO_0 Runs out of Stack Space During Failed DNS Lookup for CA Server.            |
| <a href="#">CSCvn23226</a> | NHRP process is crashing.                                                                                   |
| <a href="#">CSCvn27449</a> | PBR does not work for dialer intf when it does not have fixed ip address.                                   |
| <a href="#">CSCvn56017</a> | Crash while processing ISIS updates when DiffServ-TE is enabled.                                            |
| <a href="#">CSCvn78203</a> | Router crashed when printing logs while constructing rekey packets (GETVPN).                                |
| <a href="#">CSCvn78349</a> | FlexVPN with password encryption - keyring aaa LIST password 6 xxxxx encrypted again upon reload.           |
| <a href="#">CSCvn82245</a> | EIGRP session is not coming up if the dynamic PBR is applied on interface.                                  |
| <a href="#">CSCvo09246</a> | Cisco 4351 ISR communication down few minute after shutdown/no shutdown interface.                          |
| <a href="#">CSCvo19234</a> | Memory corruption while freeing memory.                                                                     |
| <a href="#">CSCvo22398</a> | Cisco 4000 Series ISR with NIM-ES2 do not forward STP Uplink Fast dummy packet.                             |
| <a href="#">CSCvo24170</a> | Crash due to chunk corruption in ISIS code.                                                                 |

| Caveat ID Number           | Description                                                     |
|----------------------------|-----------------------------------------------------------------|
| <a href="#">CSCvo27553</a> | PKI incorrect fingerprint calculation during CA authentication. |
| <a href="#">CSCvo47866</a> | Crash at Process = SCCP Auto Config.                            |

**Open Caveats - Cisco IOS XE Everest 16.6.5**

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                               |
|----------------------------|-----------------------------------------------------------------------------------------------------------|
| <a href="#">CSCus13106</a> | IOS-XE - RSA key-gen: Error in generating keys: no available resources.                                   |
| <a href="#">CSCvj89047</a> | Quake-sessmgrd Huge Mem Leak After Master switchover.                                                     |
| <a href="#">CSCvk15062</a> | Modification to ZBFW access-lists do not reflect in TCAM.                                                 |
| <a href="#">CSCvk22449</a> | BGP Traceback/Crash seen with 20k IPv4 BGP scale after reload/clearing bgp.                               |
| <a href="#">CSCvk32822</a> | QoS stats process crash                                                                                   |
| <a href="#">CSCvm25921</a> | Signaling interface inactive on "show snmp mib ifmib ifindex de" on Cisco IOS 16.6.3.                     |
| <a href="#">CSCvm51112</a> | The "clear crypto sa vrf MyVrf" triggers crash after updating pre-shared-keys.                            |
| <a href="#">CSCvm57021</a> | Crash in CENT-MC-0 process after Doubly-linked list corruption.                                           |
| <a href="#">CSCvm61279</a> | Crash under AFW_application_process with shared-line configuration.                                       |
| <a href="#">CSCvm70471</a> | The hw-module subslot 0/2 reload CLI does not activate the container after harddisk format.               |
| <a href="#">CSCvm76452</a> | IPSec background crash while sending SNMP trap.                                                           |
| <a href="#">CSCvm78822</a> | The config-sync failure aaa authorization commands.                                                       |
| <a href="#">CSCvm84742</a> | Crash after issuing "no ip dhcp snooping VLAN <VLAN #>" command.                                          |
| <a href="#">CSCvm91837</a> | IOS and IOS-XE STCAPP service not updating DTMF RFC2833 payload when there is SCCP renegotiation.         |
| <a href="#">CSCvn01507</a> | Cisco 4000 Series ISR not re-calculating the hash value correctly after payload change.                   |
| <a href="#">CSCvn02419</a> | Router crashes while running Dell software update.                                                        |
| <a href="#">CSCvn06127</a> | Oneway audio issue is seen when CUBE use loopback interface for voice traffic that is coming on Multivrf. |
| <a href="#">CSCvn08136</a> | Removing FNF config using the command "no vlan config 1-4094" causes watchdog forced crash.               |
| <a href="#">CSCvn14454</a> | iWAN router PDP crash.                                                                                    |

| Caveat ID Number           | Description                                                                            |
|----------------------------|----------------------------------------------------------------------------------------|
| <a href="#">CSCvn23906</a> | DHCP Server sends Renew ACKs to Clients with 00:00:00:00:00:00 MAC in L2 frame.        |
| <a href="#">CSCvn28017</a> | Cisco 4331 ISR Routers may crash when "eigrp default-route-tag" Configured on IPv4 AF. |
| <a href="#">CSCvn49911</a> | Stuck thread crash after executing 'clear ip nat translation vrf <VRFNAME>.            |

## Resolved Caveats - Cisco IOS XE Everest 16.6.5

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------------------|
| <a href="#">CSCty35807</a> | INFO-2833 DTMF interoperability issue when Remote-Party-ID is configured.                          |
| <a href="#">CSCuy44786</a> | Meet crypto recommendations in IKEv2 defaults.                                                     |
| <a href="#">CSCuz14861</a> | IOS-XE Fails to correctly populate RTCP SSRC Field.                                                |
| <a href="#">CSCvb03610</a> | Watchdog crash after "% AAA/AUTHEN/CONT: Bad state in aaa_cont_login()."                           |
| <a href="#">CSCve31475</a> | SNMP Error: OID not increasing: @ipAddressIfIndex.ipv6z.                                           |
| <a href="#">CSCve76160</a> | Transfer to voicemail not working because ephone-dn virtual/internal dial-peer is down.            |
| <a href="#">CSCvf37923</a> | Crash due to stack overflow.                                                                       |
| <a href="#">CSCvf65079</a> | CUBE reloaded with reason: RG-application reload on voice-b2bha RG.                                |
| <a href="#">CSCvf67313</a> | CUBE does not honor codec under dialpeer when LTI and midcall-signaling block configured together. |
| <a href="#">CSCvg04712</a> | ESP crash with cpp-mcplo-ucode core file.                                                          |
| <a href="#">CSCvg29037</a> | Traceback is observed during mid-call media IP and port change.                                    |
| <a href="#">CSCvg40893</a> | Registration failed for REGISTER matching wrong voip dial-peer.                                    |
| <a href="#">CSCvg42218</a> | VRF failed to associate if binding is used in tenant.                                              |
| <a href="#">CSCvg68773</a> | Global bind disappears when bind interface flaps during an active call.                            |
| <a href="#">CSCvg69229</a> | TAMS process crashes on Cat3k running 16.6.x code.                                                 |
| <a href="#">CSCvh49380</a> | PFRv3 Incorrect reported value of TCA threshold in traffic-class router change history.            |
| <a href="#">CSCvh77310</a> | Wrong initial number of DPD incrementing error counter.                                            |
| <a href="#">CSCvh84873</a> | High CPU when enabling GETVPN Routing Awareness for BGP (crypto engine pr).                        |
| <a href="#">CSCvh92275</a> | QoS Overrides loadbalancing to per prefix even with only session level policing applied.           |

| Caveat ID Number           | Description                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvh97101</a> | NAT-HA on Cisco 2900s breaks if it is asymmetric routing.                                          |
| <a href="#">CSCvi08303</a> | Standby RP Reloads due to Config Sync Failure When Applied Service-insertion WAAS on Physical Int. |
| <a href="#">CSCvi52608</a> | CLI show aaa clients detailed command triggered SSH to crash.                                      |
| <a href="#">CSCvi65958</a> | Standby RP crashes due to shortage of memory when running OSPF.                                    |
| <a href="#">CSCvi83306</a> | Crash with IOSXE-WATCHDOG: Process = IPv6 RIB Event Handler.                                       |
| <a href="#">CSCvi83419</a> | Router crash when removing route-target and with hard clear.                                       |
| <a href="#">CSCvi92528</a> | ZBFW HA: Configuring redundancy RII on virtual template auto-tunnel does not take effect.          |
| <a href="#">CSCvi96450</a> | Router crashed when lsp-mtu is changed.                                                            |
| <a href="#">CSCvi96965</a> | Radius Automate Tester probe on feature is not working as expected.                                |
| <a href="#">CSCvj02910</a> | Reload removing ipv6 VRRP group.                                                                   |
| <a href="#">CSCvj22537</a> | Standby switch crashes when flow-exporter destination configured with Hostname.                    |
| <a href="#">CSCvj25678</a> | Crash after failing to modify xcode.                                                               |
| <a href="#">CSCvj43156</a> | Crash in XDR process: "fib_rp_table_broker_encode_buf.size <= FIB_RP_TABLE_BROKER_ENC_BUF_SZ"      |
| <a href="#">CSCvj45781</a> | QFP CGM Memory depletion during ISG session churn.                                                 |
| <a href="#">CSCvj50005</a> | Cisco 4000 Series ISR PPE ucode crash when processing ipsec traffic on CWS tunnel.                 |
| <a href="#">CSCvj60825</a> | Redzone overlay copying SIP SDP data.                                                              |
| <a href="#">CSCvj67623</a> | DNS ALG will not work when trying to match specific destination hosts.                             |
| <a href="#">CSCvj70568</a> | FlexVPN / DHCP entries not flushing for ikev2 timed out reconnect sessions.                        |
| <a href="#">CSCvj71845</a> | Backup path incorrect for ring topology where high ISIS cost is configured on 1 link.              |
| <a href="#">CSCvj76285</a> | Snmp v2 breaks due to Authentication failure, bad community string, 16.03.06.                      |
| <a href="#">CSCvj76316</a> | subscriber template not cleared after idle time exceed as well as traceback generation             |
| <a href="#">CSCvj76662</a> | GetVPN TBAR failure does not generate syslogs.                                                     |
| <a href="#">CSCvj77688</a> | Shimming have some issue over selecting idb.                                                       |
| <a href="#">CSCvj78083</a> | Path of Last Resort Sending Probes in Standby State.                                               |
| <a href="#">CSCvj78647</a> | MTU cli is disappeared from show run when interface dialer shut/no shut.                           |
| <a href="#">CSCvj79542</a> | Missing interface source template model.                                                           |

| Caveat ID Number           | Description                                                                                         |
|----------------------------|-----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj79694</a> | sgt-map gets cleared for some of the end points for unknown reason.                                 |
| <a href="#">CSCvj83551</a> | SISF crash in IPV6 neighbor discovery packets.                                                      |
| <a href="#">CSCvj84104</a> | PLR channel is not muted for some time.                                                             |
| <a href="#">CSCvj88138</a> | VASI NAT: FTP ALG translation is sometimes failed.                                                  |
| <a href="#">CSCvj90089</a> | Crashes while doing a conference call.                                                              |
| <a href="#">CSCvj90145</a> | Zero Touch Provisioning (ZTP) fails to apply certain service instance configuration.                |
| <a href="#">CSCvj90814</a> | Crashes due to memory corruption in Cisco 4000 Series ISR.                                          |
| <a href="#">CSCvj91448</a> | PKI:-IP address parsing issue while printing the subject name if classless IP is used in Trustpoint |
| <a href="#">CSCvj94863</a> | Channel with wrong label may be created on hub border.                                              |
| <a href="#">CSCvj95361</a> | Crashed due to process = IPSec background proc.                                                     |
| <a href="#">CSCvk20272</a> | Hoot-n-holler multicast traffic marked with DSCP 0.                                                 |
| <a href="#">CSCvk07070</a> | Observing bmalloc smd leaks at OBJ_WEBAUTH_LOGOUT_URL with webauth.                                 |
| <a href="#">CSCvk07838</a> | CUBE is using wrong source IP address to send SIP error.                                            |
| <a href="#">CSCvk10633</a> | BGP crashes while running show command and same time bgp peer reset.                                |
| <a href="#">CSCvk10909</a> | ISRv: ONEP process crash during day0 bringup.                                                       |
| <a href="#">CSCvk12152</a> | Unable to remove command ip nat inside destination.                                                 |
| <a href="#">CSCvk16771</a> | ISIS for IP is enabled/installing routes in the RIB while IP routing is disabled.                   |
| <a href="#">CSCvk20003</a> | Host limit of 32 for session monitoring sessions.                                                   |
| <a href="#">CSCvk20560</a> | 491 not sent in a multiple re-invites in DO2EO scenario.                                            |
| <a href="#">CSCvk20589</a> | SSH V2 crashes.                                                                                     |
| <a href="#">CSCvk27007</a> | MGCP status remains Down after IOS upgrade caused by CSCvh70570.                                    |
| <a href="#">CSCvk30939</a> | Memory corruption at PKI session end.                                                               |
| <a href="#">CSCvk31115</a> | Device-sensor does not send data off initial boot.                                                  |
| <a href="#">CSCvk37875</a> | High Availability system with two Voice Gateways crashes.                                           |
| <a href="#">CSCvk39041</a> | SDA: IP phone latency in fabric is close to 4 secs.                                                 |
| <a href="#">CSCvk46664</a> | DNA Center SWIM Upgrade fails and unable to upgrade manually.                                       |
| <a href="#">CSCvk50734</a> | Device Tracking - Memory leak observed with IPv6 NS/NA Packets.                                     |

| Caveat ID Number           | Description                                                                                                        |
|----------------------------|--------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvk52495</a> | IP SLA multicast appear as "Unknown".                                                                              |
| <a href="#">CSCvk53405</a> | Router crash - AFW_application_process.                                                                            |
| <a href="#">CSCvk56331</a> | Initial contact in IKEv1 phase 2 rekey (QM1) causes all crypto sessions to drop.                                   |
| <a href="#">CSCvk58143</a> | 500~600 secs Increase in boot time when "ip domain lookup" configured.                                             |
| <a href="#">CSCvk59419</a> | Crash in xoslib code for onepk process when using yang-netconf.                                                    |
| <a href="#">CSCvk60184</a> | Random crash of data plane with SRTP-SRTP / SRTP-RTP load tests.                                                   |
| <a href="#">CSCvk65072</a> | Crash due ZBF + NAT.                                                                                               |
| <a href="#">CSCvk65354</a> | Extension Mobility Not working when used with Greek locale on SIP CME.                                             |
| <a href="#">CSCvk66880</a> | CUBE incorrectly formats SIP SDP.                                                                                  |
| <a href="#">CSCvk69075</a> | No calls shown in output "show call active voice brief" on CUBE & stale entries are present.                       |
| <a href="#">CSCvk69093</a> | CUBE is not responding to SIP INFO.                                                                                |
| <a href="#">CSCvm00765</a> | BFD crash on imitating traffic loss.                                                                               |
| <a href="#">CSCvm01420</a> | CUBE crashes at sipSPI_ipip_vcc_CheckCodecSetType.                                                                 |
| <a href="#">CSCvm02627</a> | Incorrect Contact port 5060 used instead of 5061 by CUBE in "302 Moved Temporarily" message.                       |
| <a href="#">CSCvm03744</a> | "%FMFP-3-OBJ_DWNLD_TO_DP_FAILED:fman_fp_image:xxx" appears when configured "ip port-map" on Cisco 4000 Series ISR. |
| <a href="#">CSCvm08571</a> | Rework need on CSCvj59170 to support SDP parsing.                                                                  |
| <a href="#">CSCvm12196</a> | Memleak (IP: RIB Alternate Preference): provides fix for CSCvk68355.                                               |
| <a href="#">CSCvm19399</a> | CRL file is getting overwritten when PKI server turns up after reload.                                             |
| <a href="#">CSCvm21219</a> | Crash is seen on Running "show vpdn tunnel summary" command.                                                       |
| <a href="#">CSCvm24689</a> | One-way audio to IP phone if phone does hold/resume after 20 minutes on secure SIP gateway.                        |
| <a href="#">CSCvm32047</a> | Device crashed when call-home is enabled and non-ascii characters in use in login banner.                          |
| <a href="#">CSCvm38891</a> | PKI disabled stripping of trailing dot during server-id check.                                                     |
| <a href="#">CSCvm39894</a> | False authorizations and authentications even without radius server for dot1x/mab.                                 |
| <a href="#">CSCvm40441</a> | CFD: PNP DNS discovery with trust pool flow uses IP address in PNP profile instead of FQDN.                        |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvm43071</a> | [IBNS 2.0] aaa-available event is not being triggered when using authentication/authorization list.   |
| <a href="#">CSCvm45068</a> | IOS CUBE Ent does not show media anti-trombone in configuration.                                      |
| <a href="#">CSCvm46814</a> | cts_sga on 16.3.6 crashes.                                                                            |
| <a href="#">CSCvm51739</a> | SNMP v3 discloses password in the parser warning syslog trap.                                         |
| <a href="#">CSCvm53491</a> | SIP CME Crashes when Calling Shared Line.                                                             |
| <a href="#">CSCvm55465</a> | BGP updates missing ISIS advertising-bits led to LDP label purge on peer.                             |
| <a href="#">CSCvm56592</a> | Cisco CME: Corrupted config file for Auto Registered IP Phones after reload.                          |
| <a href="#">CSCvm58960</a> | "VoIP dial-Peer <XX> is Busied out" printed in log every 2 minutes when destination is not reachable. |
| <a href="#">CSCvm59172</a> | The "autoroute announce" and "loose" path not working on intra-area TE tunnel.                        |
| <a href="#">CSCvm59483</a> | Host crashes the DSP if ipv6 commands are configured under Service-Engine [Purge ipv6 config option]. |
| <a href="#">CSCvm63651</a> | Memory leak due to authentication mac-move permit.                                                    |
| <a href="#">CSCvm65384</a> | SNMP OID conflict.Trap being generated with wrong oid 6999.it should be 854.                          |
| <a href="#">CSCvm66103</a> | Crash due to communication failure - IPC (Inter-Procedure Call) messages between DSP and RP.          |
| <a href="#">CSCvm74894</a> | PKI authentication should proceed even if GetCACaps return any http failure.                          |
| <a href="#">CSCvm76590</a> | CUBE doesn't forward 200 OK in SRTP-RTP scenario with TCL script on Dial-peer.                        |
| <a href="#">CSCvm83720</a> | Cisco 4431 ISRGateway crashed due to flex_dsprm_vtsp_close.                                           |
| <a href="#">CSCvm86135</a> | SMD crash after removing access-session attributes filter-list.                                       |
| <a href="#">CSCvm91422</a> | [MiFID] [Inbox-HA] VRF-ID is set to 65535 after switchover, call fails.                               |
| <a href="#">CSCvm92019</a> | Media Ant-Trombone does not properly handle a Re-Invite utilizing a Replaces Header.                  |
| <a href="#">CSCvm93603</a> | IP change on dialer-int does not trigger a correct "local crypto entpt" in DMVPN.                     |
| <a href="#">CSCvm96663</a> | An IOS-XE router crashes after umbrella is configured.                                                |
| <a href="#">CSCvm99036</a> | CUBE Crash in CCSIP_SPI_CONTROL process.                                                              |
| <a href="#">CSCvm99045</a> | IOS-XE PKI: Certificate with 4 dashes imported in trustpool gets lost after reboot.                   |
| <a href="#">CSCvn02171</a> | Cisco IOS XE :HOLE is not created when acl default passthrough configured.                            |
| <a href="#">CSCvn07614</a> | Out of Band DTMF Events Not Passing to CUCM via SCCP When Using IOS MTP.                              |

| Caveat ID Number           | Description                                                                            |
|----------------------------|----------------------------------------------------------------------------------------|
| <a href="#">CSCvn18712</a> | CUBE incorrectly formats SIP SDP with Content-Length > 1024.                           |
| <a href="#">CSCvn33961</a> | SSRC-field in RTCP gets changes to 0 when going through TRP present in the media path. |

## Open Caveats - Cisco IOS XE Everest 16.6.4

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCuy75886</a> | Chunk memory leak about SNMP SMALL CHUN and SNMP MEDIUM CHU.                                          |
| <a href="#">CSCvb72829</a> | The <b>sh ipv6 neigh statistics</b> not updated post RPSO for entries synced.                         |
| <a href="#">CSCvc73961</a> | OSPF BGP LS: When seg mpls is disabled on the NBR, the unnumbered links not withdrawn from LSLIB.     |
| <a href="#">CSCvd20054</a> | Traceback @mpls_ldp_cfg_interface while enabling ISIS.                                                |
| <a href="#">CSCvd65197</a> | IOSd crashed when dialer disconnects the ISDN call.                                                   |
| <a href="#">CSCve05486</a> | ISDN switch-type configure issue for BRI leased-line.                                                 |
| <a href="#">CSCve12319</a> | ISIS SRTE: When one of ECMP path for prefix is not enabled for SR, SRTE tunnel does not come up.      |
| <a href="#">CSCve16269</a> | IKEv2 CoA does not work with ISE.                                                                     |
| <a href="#">CSCve32648</a> | Traceback@cpp_mlp_bundle_stats_query_all_cmn on fp reload.                                            |
| <a href="#">CSCve39101</a> | OSPF SROAM: "%ARP-3-ARPADJ: Internal software error during updating CEF Adjacency" when box comes up. |
| <a href="#">CSCve39572</a> | BGP net should have inlabel if bgp mpls-local-label is configured.                                    |
| <a href="#">CSCve54914</a> | NDSSO vrf ha table to be populated correctly.                                                         |
| <a href="#">CSCve96308</a> | Observing memory leak in AAA_MALLOC_LITE.                                                             |
| <a href="#">CSCvf21341</a> | CME: Pushing call from desk phone to SNR phone failing if media-renegotiate CLI is configured         |
| <a href="#">CSCvf22725</a> | OSPF SR/SIDredistribute: when SID configured > avbl SRGB, that sid should not be advertised in EPL.   |
| <a href="#">CSCvf28564</a> | Show details soft key is not functioning in a conference call.                                        |
| <a href="#">CSCvf34848</a> | License synchronized to SSMS despite being removed from SL Portal.                                    |
| <a href="#">CSCvf37923</a> | Crash due to Stack overflow.                                                                          |
| <a href="#">CSCvf51917</a> | The <b>dns-a-override</b> CLI not working due to breakage since 16.4 IOS.                             |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvf76436</a> | Combination of add-path, backup path and advertised-to leaves is not giving expected netconf values. |
| <a href="#">CSCvf86185</a> | NIM-SSD: Inventory of disk0 and disk1 are interchanged on Cisco IOS XE 16.x.                         |
| <a href="#">CSCvf95739</a> | Remove "dns-vrf-aware" CLI and make DNS vrf aware by default.                                        |
| <a href="#">CSCvg06563</a> | BE4K memory leak during bulk register request from portal.                                           |
| <a href="#">CSCvg23363</a> | Virtual-access interface MTU wrongly set when using ipsec ipv4.                                      |
| <a href="#">CSCvg23820</a> | CTS PAC download fails with VRF config on non-managenent interface.                                  |
| <a href="#">CSCvg40893</a> | BE4K Registration failed for REGISTER matching wrong voip dial-peer.                                 |
| <a href="#">CSCvg42218</a> | BE4K VRF failed to associate if binding is used in tenant.                                           |
| <a href="#">CSCvg49910</a> | BE4K OPTION messages not sent out with VRF+DNS.                                                      |
| <a href="#">CSCvg62139</a> | The "show voice lmr port_number" on ISR4K do not show m-lead status.                                 |
| <a href="#">CSCvg63956</a> | BE4K Call failed to answer if SNr configured with no matching dial-peer.                             |
| <a href="#">CSCvg81772</a> | VRF import config missing ipv4 unicast after no router bgp                                           |
| <a href="#">CSCvg87102</a> | BE4K group pickup failed when call xferred by AA with cause code 47.                                 |
| <a href="#">CSCvh17679</a> | BE4000/CME SNR call fails due to the extension COR list configuration.                               |
| <a href="#">CSCvh49364</a> | PFRv3 Incorrect time-stamp in traffic-class router change history.                                   |
| <a href="#">CSCvh57657</a> | NAT MIB not populated when using traditional NAT.                                                    |
| <a href="#">CSCvh65955</a> | CME: SIP Notify to clear NightService display message not sent to phones during de-activation.       |
| <a href="#">CSCvh67422</a> | IPSLA ICMP-jitter stats reporting some of the received packets as lost.                              |
| <a href="#">CSCvh67788</a> | CME: COR functionality impacts CallFwd and SNR call flow scenarios.                                  |
| <a href="#">CSCvh85031</a> | Branch MC crashed@cent_send_syslog_on_violated_policies under stress test.                           |
| <a href="#">CSCvh93960</a> | CME SIP: One way audio on consult transfer when SNR enabled on transfer target.                      |
| <a href="#">CSCvi06417</a> | SIP stack matching the dial-peer when processing NOTIFY message causing call routing issues.         |
| <a href="#">CSCvi10089</a> | EXEC process stuck vty line where no exec is set.                                                    |
| <a href="#">CSCvi15955</a> | Call failure after Bye-Also blind transfer from CUE requires failure indication.                     |
| <a href="#">CSCvi36351</a> | The standby rp crash on removing member link from port-channel.                                      |
| <a href="#">CSCvi37580</a> | There is unexpected packets lost TCA reported on Cisco 4331 ISR platform.                            |

| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCvi54372</a> | %NHRP-3-PAKERROR   loop detected   Pak sanity failure.                                            |
| <a href="#">CSCvi63425</a> | Cisco 4400 ISR router cpp crashed when configured HSRP with PMIPv6.                               |
| <a href="#">CSCvi83419</a> | Router crash when removing route-target and with hard clear.                                      |
| <a href="#">CSCvi90729</a> | IKEv2 CoA does not work with ISE (coa-push=TRUE instead of true).                                 |
| <a href="#">CSCvi90964</a> | Cisco 4331 ISR : Crash due to Segmentation fault(11), Process = Tunnel Security.                  |
| <a href="#">CSCvi92505</a> | MWI info is not preserved on CME SIP phone after a reboot for unsolicited method.                 |
| <a href="#">CSCvi93431</a> | CME/BE4k: Adding Support to allow whisper paging as a configurable option on SIP phones.          |
| <a href="#">CSCvi93972</a> | IWAN versions with prefix tracking only allow prefix splitting for internet and not enterprise.   |
| <a href="#">CSCvi97233</a> | CME radius accounting does not generate complete called number for EA.                            |
| <a href="#">CSCvj08942</a> | SNMPwalk of cipslaPercentileLatestStatsTable does not give all the cipslaPercentileTypeVar types. |
| <a href="#">CSCvj09305</a> | Slow convergence when configuring ha-mode sso for IPv6 peers.                                     |
| <a href="#">CSCvj11263</a> | NBAR: resource exhaustion might occur in FNF with vmware-vsphere and flow monitors.               |
| <a href="#">CSCvj22081</a> | Cisco 4331 ISR: Memory lock occurs when archive config and "wr" are executed at the same time     |
| <a href="#">CSCvj25236</a> | IPDT flapping after upgrade to 15.2(2)E7.                                                         |
| <a href="#">CSCvj26944</a> | Cisco-IOS-XE-policy yang model does not support "set precedence"                                  |
| <a href="#">CSCvj29514</a> | CME: Toll fraud app not automatically trusting traffic from phones.                               |
| <a href="#">CSCvj35317</a> | Ti-LFA Repair Path is not Loop-Free.                                                              |
| <a href="#">CSCvj44615</a> | Ringback stops on REFER based xfer when CUBE receives 180 followed by 183 w/SDP media change.     |
| <a href="#">CSCvj45781</a> | QFP CGM Memory depletion during ISG session churn                                                 |
| <a href="#">CSCvj47270</a> | IKEv2 sessions cannot establish due to CAC leakage.                                               |
| <a href="#">CSCvj50644</a> | Barge and cBarge failure on Incoming SIP trunk calls to BE4K.                                     |
| <a href="#">CSCvj51929</a> | Out of order ESP packets triggering IPSEC replay error message.                                   |
| <a href="#">CSCvj57453</a> | OSPF TILFA: tilfa repair path computation ALGORITHM fails with reason code BAD FH NBR.            |

| Caveat ID Number           | Description                                                                                                      |
|----------------------------|------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj57487</a> | OSPF TILFA: tilfa repair path computation ALGORITHM uses incorrect firsthop router-id.                           |
| <a href="#">CSCvj58359</a> | SIP packets not sent out by BE4K when gig0/0/1 has vrf forwarding enabled.                                       |
| <a href="#">CSCvj59152</a> | Evaluation of all for May CPU Side-Channel Information Disclosure Vulnerabilities.                               |
| <a href="#">CSCvj60144</a> | OSPF TILFA: tilfa ALGORITHM fails to get repair node n-sid label when vertex is beyond PGW node                  |
| <a href="#">CSCvj60749</a> | Cisco 4000 Series ISRs handles MTU on Virtual-PPP interface differently and doesn't respect DF-bit on QFP level. |
| <a href="#">CSCvj64493</a> | Standby switch crash whem removing kron scheduler command.                                                       |
| <a href="#">CSCvj66204</a> | Initial SNMP traps take agent-addr from shutdown interface.                                                      |
| <a href="#">CSCvj67623</a> | DNS ALG will not work when trying to match specific destination hosts.                                           |
| <a href="#">CSCvj70568</a> | FlexVPN    DHCP entries not flushing for ikev2 timed out reconnect sessions.                                     |
| <a href="#">CSCvj72854</a> | Router crash due to NHRP process Segmentation fault(11).                                                         |
| <a href="#">CSCvj74888</a> | Kernel OOPS reporting ECC error.                                                                                 |
| <a href="#">CSCvj75853</a> | Device crash after execute command " <b>show lldp neighbor [int] detail</b> ".                                   |
| <a href="#">CSCvj76285</a> | Snmp v2 breaks due to Authentication failure, bad community string, 16.03.06.                                    |
| <a href="#">CSCvj76316</a> | Subscriber template not cleared after idle time exceed as well as traceback generation.                          |
| <a href="#">CSCvj76662</a> | GetVPN TBAR failure does not generate syslogs.                                                                   |
| <a href="#">CSCvj78876</a> | CUBE: FPI Hung Sessions and Provisioning Failures observed in Standby CUBE.                                      |
| <a href="#">CSCvj81382</a> | IPv6 AAA Prefix Support for 3rd party PPP clients no password for -dhcpv6 Access-Request.                        |
| <a href="#">CSCvj82095</a> | NBAR mismatch cisco video traffic.                                                                               |
| <a href="#">CSCvj83551</a> | SISF crash in IPV6 neighbor discovery packets.                                                                   |
| <a href="#">CSCvj84104</a> | PLR channel is not muted for some time.                                                                          |
| <a href="#">CSCvj84121</a> | Cisco 4321 ISR Radius Chap authentication does not work.                                                         |
| <a href="#">CSCvj84158</a> | PfRv3: BR May Crash due to Channel Creation/Modification and Next-Hop State.                                     |
| <a href="#">CSCvj88265</a> | CBR8 After SUP failover, some BSOD clients have no service, L2VPN                                                |
| <a href="#">CSCvj89345</a> | AVC license should be activated only in case of smart licensing model.                                           |
| <a href="#">CSCvj90089</a> | Device crashes while doing a conference call.                                                                    |

| Caveat ID Number           | Description                                                                              |
|----------------------------|------------------------------------------------------------------------------------------|
| <a href="#">CSCvj90814</a> | Crash due to Memory corruption in Cisco 4000 Series ISRs.                                |
| <a href="#">CSCvj92548</a> | FlexVPN: Spoke to Spoke: Implicit NHRP entry due to expired resolution request handling. |

**Resolved Caveats - Cisco IOS XE Everest 16.6.4**

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCsd58148</a> | %SEC_LOGIN-4-LOGIN_FAILED does not show username in [user: ].                                        |
| <a href="#">CSCuv14856</a> | WATCHDOG timeout crash during IPSEC phase 2.                                                         |
| <a href="#">CSCuv90519</a> | Map does not get updated with socket change on local address change.                                 |
| <a href="#">CSCuw90084</a> | DS: Download should print alerts in case of unresolved variables.                                    |
| <a href="#">CSCvb34443</a> | The ikev2 fragmentation not working with aes-gcm encryption - hmac failure.                          |
| <a href="#">CSCvb69966</a> | Memory leak under LLDP Protocol process.                                                             |
| <a href="#">CSCvb88867</a> | Excess BGP Traps Generated just after upgrade.                                                       |
| <a href="#">CSCvd14310</a> | IP TUNNELS: Overlapping Loopback Interface Causes Incorrect Forwarding Decision with AppNav and PfR. |
| <a href="#">CSCvd47657</a> | Cisco 4000 Series ISRs routers may crashed with Segmentation Fault in AFW Application Process.       |
| <a href="#">CSCvd50613</a> | Cisco 4431 ISR crashes with UNIX-EXT-SIGNAL: Segmentation fault(11), Process = HTTP CP.              |
| <a href="#">CSCvd90410</a> | Router loses RSA keys upon boot with private-config encryption and config archive enabled.           |
| <a href="#">CSCve11959</a> | Memory leak occurs on DHCP client.                                                                   |
| <a href="#">CSCve41775</a> | Crash over CCSIP_SPI_CONTROL process due to null pointer / segmentation fault.                       |
| <a href="#">CSCve55004</a> | OSPF GIR BASE: not all repair paths calculated for AS ext routes when routes rxed with maxmetric.    |
| <a href="#">CSCve61143</a> | CME SIP sip-ua do not send registration request when vrf forwarding is enabled.                      |
| <a href="#">CSCvf05864</a> | BGP RR changes tunnel parameters for bgp evpn route type 3.                                          |
| <a href="#">CSCvf06123</a> | Route-map not checked when packet is flowing from OUT to IN with Static NAT.                         |
| <a href="#">CSCvf07153</a> | SIP Date header format not in GMT Format.                                                            |
| <a href="#">CSCvf07576</a> | Router reloaded when doing show BGP RT filter routes.                                                |

| Caveat ID Number           | Description                                                                                    |
|----------------------------|------------------------------------------------------------------------------------------------|
| <a href="#">CSCvf16374</a> | CME SNR Does not get ringback for PRI calls.                                                   |
| <a href="#">CSCvf19460</a> | CTS Pac download fails with ISE reachability through loopback interface over vrf.              |
| <a href="#">CSCvf23485</a> | DS: Increase the size of command and prompt strings.                                           |
| <a href="#">CSCvf26916</a> | RTCP/RTP based Media Inactivity timers for MGCP GW do not work in newer releases.              |
| <a href="#">CSCvf38050</a> | Voice Gateway crash due to memory corruption while finding DN index during redirect.           |
| <a href="#">CSCvf49126</a> | Stub is not leaking the network as expected.                                                   |
| <a href="#">CSCvf51773</a> | NHRP redirect overriding routing table.                                                        |
| <a href="#">CSCvf52766</a> | Dual Ringback in Semi-consult transfer on CME.                                                 |
| <a href="#">CSCvf53053</a> | Crash when issuing no dspfarm profile x stuck on DOWN_PENDING state.                           |
| <a href="#">CSCvf57090</a> | CUBE automatically considers re-INVITE with a=silenceSupp:off - - - as fax call.               |
| <a href="#">CSCvf66030</a> | OSPF SR: When SRGB range is changed, mapping server entries do not get re-installed.           |
| <a href="#">CSCvf66860</a> | IOS crash in SOCK TCP Test Server process.                                                     |
| <a href="#">CSCvf70383</a> | Crash in SDP Passthru when T.38 as 1st mline in mid-call SDP.                                  |
| <a href="#">CSCvf73693</a> | Cisco 4321 ISR crash @ BGP Router for bfd bgp when sending traffic.                            |
| <a href="#">CSCvf80363</a> | Rotate nginx access/error log files.                                                           |
| <a href="#">CSCvf81931</a> | Loopback interface not appearing in RIB after upgrade.                                         |
| <a href="#">CSCvf84528</a> | False "voip_rtp_allocate_port:Possible port leak" errors.                                      |
| <a href="#">CSCvf88705</a> | Malformed GETVPN message %GDOI-4-COOP_KS_UNAUTH.                                               |
| <a href="#">CSCvf89894</a> | GETVPN // Primary KS sending rekey first to GM's and then to Secondary KS via scheduled rekey. |
| <a href="#">CSCvf96009</a> | OSPF SR: When loopback isconfigured with prefix suppression, EPL should be withdrawn.          |
| <a href="#">CSCvf96294</a> | MIB counter for IPSec tunnels does not decrement under high tunnel scale and churn.            |
| <a href="#">CSCvf97908</a> | When NSSA ASBR is reloaded, ECMP to ext routes not installed in other routers.                 |
| <a href="#">CSCvf98378</a> | IOSXE_INFRA-6-PROCPATH_CLIENT_HOG: IOS shim client fman stats bipc has taken xx msec.          |
| <a href="#">CSCvg01774</a> | OSPF SSPF: when seg area is disabled and enabled, mapping server EPL entries not re-generated. |
| <a href="#">CSCvg03444</a> | Hub MC continues to send EIGRP SAF hellos after adjacency removed.                             |

| Caveat ID Number           | Description                                                                                            |
|----------------------------|--------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvg05172</a> | Crash in VOIP media loop detection.                                                                    |
| <a href="#">CSCvg05452</a> | IOS-XE router crash from memory corruption during CCB cleanup.                                         |
| <a href="#">CSCvg06142</a> | IPSM Tunnel Entry and Crypto IKMP memory leak due to IKE tunnel entry not deleted.                     |
| <a href="#">CSCvg08471</a> | OSPF; process ospf segmentation fault when shut and no shut is performed in active RP.                 |
| <a href="#">CSCvg08768</a> | OSPF BGP LS: After fail over, error msg seen: %LSLIB-4-EOD: Producer OSPF-0x0 did not send EOD.        |
| <a href="#">CSCvg12605</a> | Corrupted NOTIFY leads to %CRYPTO-4-IKMP_BAD_MESSAGE, stale ISAKMP SA and traffic failure.             |
| <a href="#">CSCvg16234</a> | ISR receives a control packet (CDP) with a CMD tag it should process it, not drop it                   |
| <a href="#">CSCvg18094</a> | GETVPN: show crypto gdoi ks member summary missing last octet in IP address                            |
| <a href="#">CSCvg19259</a> | MPLSoFlexVPN: Hub doesn't forward resolution req when default route is advertised to spokes            |
| <a href="#">CSCvg25874</a> | Toggling the switchport then default the interface, load-interval config reapplied                     |
| <a href="#">CSCvg30991</a> | IOS-XE routers: Memory leak observed on process ivr: peer_item_t in AFW_application_process            |
| <a href="#">CSCvg32701</a> | Night-Service fails if it overlaps with FAC codes.                                                     |
| <a href="#">CSCvg32858</a> | Snort control plane connectivity with Mgmt-intf is broken.                                             |
| <a href="#">CSCvg33454</a> | Pass load balancing information in IP header to container.                                             |
| <a href="#">CSCvg34167</a> | Unexpected reboot of voice gateway Cisco 4400 ISR.                                                     |
| <a href="#">CSCvg34986</a> | Media recording on IOS-XE does not work if a refer is received immediately after the call is answered. |
| <a href="#">CSCvg36598</a> | ISAKMP Fails When Multiple HSRP tunnel/SVTI Interfaces Configured.                                     |
| <a href="#">CSCvg39082</a> | Crash after TCP session timeout.                                                                       |
| <a href="#">CSCvg41950</a> | Cisco IOS XE Software Diagnostic Shell Path Traversal Vulnerability.                                   |
| <a href="#">CSCvg43263</a> | when shutting interface with no isis adjacency, local micro-loop avoidance blocks FRR recalculation    |
| <a href="#">CSCvg44135</a> | OSPF SRTE: prefix information is not provided to SRTE when it is learnt via mapping server.            |
| <a href="#">CSCvg45950</a> | packet drop seen intermittently if 40G traffic sent via cts interface                                  |
| <a href="#">CSCvg47453</a> | Default route redistributed into RIP from EIGRP is not removed from RIP database                       |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvg48470</a> | ISIS I1-I2 redistribution prefix doesn't get redistributed till clear isis rib redistribution is done |
| <a href="#">CSCvg48492</a> | BE4000 one way audio seen line to trunk side call with VRF enabled                                    |
| <a href="#">CSCvg51358</a> | DHCPNAK is not sent in roaming scenario.                                                              |
| <a href="#">CSCvg53159</a> | %SNMP-3-RESPONSE_DELAYED: processing GetNext of cafSessionEntry.2 seen on catalyst switch             |
| <a href="#">CSCvg54267</a> | CDP Protocol can run device out of memory                                                             |
| <a href="#">CSCvg56088</a> | Getting "HA Module DSP_MSP reported CALL_MODIFY RECREATE failure" in CUBE HA.                         |
| <a href="#">CSCvg56110</a> | Error and pending objects when mma policy flap with egress monitor for multi-VRF case.                |
| <a href="#">CSCvg58096</a> | Increase of dampening penalty on route refresh.                                                       |
| <a href="#">CSCvg58599</a> | Syslog: Logging host is truncating lines causing debug output to be cutoff in the middle of a msg.    |
| <a href="#">CSCvg59604</a> | Cube crashes intermittently multiple times within every two days.                                     |
| <a href="#">CSCvg61219</a> | Crash seen during Blind Transfer in CME video call                                                    |
| <a href="#">CSCvg67028</a> | VRF deletion status <being deleted> after removing the RD                                             |
| <a href="#">CSCvg67820</a> | HIGH CPU observation on FMAN RP ESS EVENT TRACING                                                     |
| <a href="#">CSCvg68391</a> | ISIS SR: When seg mpls is shut globally, ISIS SID entries not withdrawn from the entire network.      |
| <a href="#">CSCvg71944</a> | OSPF SR: When loopback is defined as /24 address, EPL should not be sent for the prefix.              |
| <a href="#">CSCvg75315</a> | ASR1K BGP scanner crash when change VRF and BGP configuration                                         |
| <a href="#">CSCvg75419</a> | ISIS SRTE: Explicit SRTE keeps flapping when ISIS is not the winning route in the RIB                 |
| <a href="#">CSCvg76664</a> | OSPF SSPF: With SRTE tunnel, constrained bind of SID0 uses invalid old repair path in some cases      |
| <a href="#">CSCvg76990</a> | Missing LSP sending after configuration change                                                        |
| <a href="#">CSCvg78770</a> | Router resets while processing fragmented/encrypted packet                                            |
| <a href="#">CSCvg82855</a> | OSPF SSPF: mapping-server strict SID is processed by images which are not strict spf capable          |
| <a href="#">CSCvg84181</a> | "CLID restrict" on outbound leg is setting "Privacy=Full" on inbound leg.                             |

| Caveat ID Number           | Description                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvg85146</a> | OSPFv2 Encoding for local-id in LLS needs to be fixed.                                             |
| <a href="#">CSCvg85879</a> | BGP sets the wrong Local Preference for routes validated by RPKI server.                           |
| <a href="#">CSCvg89163</a> | CUBE does not acknowledge Session-Expires header in UPDATE.                                        |
| <a href="#">CSCvg91126</a> | BE4K Group pickup failed if agent configured for cfwd no answer                                    |
| <a href="#">CSCvg91169</a> | 3850 standby switch reloads due to configuration-mismatch after use "exception crashinfo" command  |
| <a href="#">CSCvg94978</a> | CUBE Router crashed - Critical software exception, Process = CCH323_CT                             |
| <a href="#">CSCvg95213</a> | ISR4k: speed/duplex disappear from 'show run' after shut down & reload.                            |
| <a href="#">CSCvg96936</a> | IOS-XE : PAT entry using the same port which is configured for static NAT                          |
| <a href="#">CSCvg97010</a> | load-balance advanced moving traffic to fallback path when primary path are not over utilized      |
| <a href="#">CSCvg97824</a> | service-controller - mDNS API's did not free the ID's for mDNS SD HANDLES process.                 |
| <a href="#">CSCvg99559</a> | OSPF SSPF/TILFA: TILFA ECMP tunnels are not created when the last segment is adjacency sid.        |
| <a href="#">CSCvh00630</a> | ISRv/QOS - service-policy defined in bootstrap config may not be applied                           |
| <a href="#">CSCvh01652</a> | Multicast IPSLA UDP Jitter throws Socket open error if vrf interface is configured on responder    |
| <a href="#">CSCvh02109</a> | WSMA: Server responds with HTTP 404 on wsma-exec with http transport profile                       |
| <a href="#">CSCvh03359</a> | EIGRP network statement reappearing after reboot                                                   |
| <a href="#">CSCvh03788</a> | EIGRP Name mode Summary route is not being apply on Virtual-Access on HUB                          |
| <a href="#">CSCvh05611</a> | IOSd crash while applying dial peer configuration                                                  |
| <a href="#">CSCvh06249</a> | Crash when receiving EVPN NLRI with incorrect NLRI length field value                              |
| <a href="#">CSCvh09334</a> | SDA-IPV6::SISF traceback @ar_relay_create_entry - L2 Binding tbl entry insertion failed            |
| <a href="#">CSCvh09525</a> | CME: BLF monitor function fails intermittently with TCP connection                                 |
| <a href="#">CSCvh10607</a> | ISG : IETF-Disc-Cause = 0 if DHCP SIP disconnect.                                                  |
| <a href="#">CSCvh15336</a> | OSPF SSPF: ECMP combination of SRTE tunnels and MPLS-TE tunnels does not work properly sometimes.  |
| <a href="#">CSCvh15484</a> | ISIS SR: When the SRGB range is increased, the local SIDs which are in new range are re-installed. |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvh18001</a> | Crash due to race condition caused by IOS radioactive trace code.                                    |
| <a href="#">CSCvh18015</a> | AppNav-XE cluster may cause router crash and reload.                                                 |
| <a href="#">CSCvh21564</a> | AAA Attrbute list leak in Polaris 16.6.2                                                             |
| <a href="#">CSCvh21909</a> | LISP: Overlapping prefix causes "probe-down" for map-cache entry                                     |
| <a href="#">CSCvh21973</a> | QFP crashed to while sending oversubscribe traffic.                                                  |
| <a href="#">CSCvh22278</a> | OSPF Hello timer 10sec is not applied in network type non-broadcast                                  |
| <a href="#">CSCvh22300</a> | Update IOS XE OSPFv2 ELL private TLVs to IANA codepoints                                             |
| <a href="#">CSCvh24315</a> | Memory leak for CCSIP_TCP_SOCKET and CCSIP_UDP_SOCKET on CUBE                                        |
| <a href="#">CSCvh25624</a> | ISIS SR: When seg mpls is shut under ISIS, sid entries not cleared in the local router.              |
| <a href="#">CSCvh26072</a> | EIGRP SAF Adjacency doesn't form with /31 mask                                                       |
| <a href="#">CSCvh28323</a> | ASR1002HX FP Crash post LNS path switchover                                                          |
| <a href="#">CSCvh29821</a> | CME should send out a refer with notify_clear when night-service is manually disabled                |
| <a href="#">CSCvh30968</a> | ISIS BGP LS: When distribute link state changed from level 1 to level 2, entries not given to BGP LS |
| <a href="#">CSCvh32216</a> | Sporadic Crashes Due to IPSec (during ISAKMP AAA interaction)                                        |
| <a href="#">CSCvh32224</a> | 8800 KEM module not getting detected on 88XX phones with CME 12,11.6                                 |
| <a href="#">CSCvh45744</a> | CME Call Park: Dead air experienced on parked PSTN (TDM/FXO) calls                                   |
| <a href="#">CSCvh48085</a> | OSPF SSPF/SRTE: when we have ABR with multiple interfaces to backbone area, SPF keeps running.       |
| <a href="#">CSCvh48610</a> | IWAN router crash while updating pmi policy.                                                         |
| <a href="#">CSCvh49600</a> | Output "sh sip-ua connections tcp tls detail" shows that CUBE has stuck connection ids.              |
| <a href="#">CSCvh51038</a> | [168] OSPF process crash on P router when router ospf<> is unconfigured on another PE or P router.   |
| <a href="#">CSCvh53691</a> | FP reload with IMGR deregister interface.                                                            |
| <a href="#">CSCvh53764</a> | RP Unexpected reboot when using conditional debugging with CCSIP debug.                              |
| <a href="#">CSCvh54672</a> | VRRP doesnt work over Port-channel L3 interface.                                                     |
| <a href="#">CSCvh56594</a> | EIGRP offset-list still active if ACL used in offset-list is removed before offset-list.             |
| <a href="#">CSCvh57061</a> | Cisco 4000 Series ISRs-PPTP passthrough traffic not working with PAT, GRE packet consumed by router. |

| Caveat ID Number           | Description                                                                                   |
|----------------------------|-----------------------------------------------------------------------------------------------|
| <a href="#">CSCvh57108</a> | CPUHOG on QoS statistics collection for DMVPN. QoS crash with DMVPN/NHRP.                     |
| <a href="#">CSCvh57340</a> | DMVPN: Crypto session stuck into UP-IDLE status after reconfiguring tunnel.                   |
| <a href="#">CSCvh57402</a> | Ciso 4451-X ISR sometime drop the packet when volume -based rekey occurred.                   |
| <a href="#">CSCvh58909</a> | OSPFv3 cost calculation not correct in some specific topology.                                |
| <a href="#">CSCvh61453</a> | NULL remote_hostname from LAC.                                                                |
| <a href="#">CSCvh62532</a> | System reload when clearing cts pac.                                                          |
| <a href="#">CSCvh62615</a> | There is junk entry in route-import table on branch when shutdown/no shutdown WAN interface.  |
| <a href="#">CSCvh63932</a> | Noisy debugs in "periodic" tracelog.                                                          |
| <a href="#">CSCvh66033</a> | IKEv2 - Crash with segmentation fault when debugs crypto ikev2 are enabled.                   |
| <a href="#">CSCvh66642</a> | uIDB leaks at the DMVPN hub if the route to remote NBMA is not learned                        |
| <a href="#">CSCvh68228</a> | CUBE Unsolicited NOTIFY returns 481 Subscription does not exist                               |
| <a href="#">CSCvh70297</a> | Redundancy Mode None does not Sync.                                                           |
| <a href="#">CSCvh70557</a> | CPP crash in MMA.                                                                             |
| <a href="#">CSCvh70570</a> | MGCP fallback mode remains ON after CUCM registered.                                          |
| <a href="#">CSCvh71856</a> | IOSd crash when enabling dot1q in a port-channel sub-interface.                               |
| <a href="#">CSCvh72700</a> | CME: GUI user page doesn't load correctly. It is showing "View Window".                       |
| <a href="#">CSCvh73805</a> | Explicit SRTE tunnels are not come up when a prefix is redistributed between levels.          |
| <a href="#">CSCvh75132</a> | CPP crash stuck thread detected multikey_hash_replace_int.                                    |
| <a href="#">CSCvh77733</a> | RR does not send VPNv4 routes to peer.                                                        |
| <a href="#">CSCvh79067</a> | Call Park with standard FAC fails if phones extensions overlap with FAC codes.                |
| <a href="#">CSCvh79640</a> | Cisco 4000 Series ISRs: BDI unreachable when interface has HSRP-enabled subinterfaces.        |
| <a href="#">CSCvh79942</a> | Chunk corruption crash related to PNP or Guestshell.                                          |
| <a href="#">CSCvh82112</a> | Routers - Memory leak under process RECMSPAPP in IOSd.                                        |
| <a href="#">CSCvh83215</a> | IOS-XE Voice NIM/PVDM Service-Engine Admin Down leads to one-way audio.                       |
| <a href="#">CSCvh85788</a> | Local LAN-only prefix present in master route-import table but not present in site prefix DB. |
| <a href="#">CSCvh88330</a> | VAI Leaks with IKEv1 DVTI.                                                                    |

| Caveat ID Number           | Description                                                                                  |
|----------------------------|----------------------------------------------------------------------------------------------|
| <a href="#">CSCvh88975</a> | Performance-monitor does not report classification after tunnel shutdown.                    |
| <a href="#">CSCvh92130</a> | Downloaded policies hit by traffics were all gone after the second SSO.                      |
| <a href="#">CSCvh92378</a> | High CPU utilization with presence feature when reset is issued under voice register global. |
| <a href="#">CSCvh93071</a> | Redistributing connected route with AIGP attribute is being continuously readvertised.       |
| <a href="#">CSCvh96542</a> | CCSIP_SPI_CONTROL holding memory increasing.                                                 |
| <a href="#">CSCvh96670</a> | Cisco 4000 Series ISRs packet drop when shutdown or no shutdown interface.                   |
| <a href="#">CSCvh97246</a> | Cisco 4000 Series ISRs - ucode crash with fw_base_flow_create.                               |
| <a href="#">CSCvh97691</a> | Tacacs-server is missing keyword "key" in argument	option available.                         |
| <a href="#">CSCvh97818</a> | The "show voice call <x/y/z>" missing print out dsp statistics in Cisco 4000 Series ISRs.    |
| <a href="#">CSCvh99576</a> | LACP Rate defaults to fast with no way to change it to normal.                               |
| <a href="#">CSCvh99651</a> | AAA-Proxy errors in dmiauthd tracelogs.                                                      |
| <a href="#">CSCvh99949</a> | Options Keepalive not triggered on applying profile to dial-peer.                            |
| <a href="#">CSCvi01558</a> | iBGP dynamic peer using TTL 1.                                                               |
| <a href="#">CSCvi01650</a> | SIP Out-of-Dialog OPTIONS Ping Group Shows Dial-Peers Marked as None.                        |
| <a href="#">CSCvi01805</a> | Router with SIP traffic crashes at ccsip_free_kpml_info.                                     |
| <a href="#">CSCvi02816</a> | ZBF not able to identify the WAAS optimized flow and drops ACK.                              |
| <a href="#">CSCvi03339</a> | [ECA-SIT] IOSd crash seen on xTR with baseline @ sisf_macdb_get_vlanid.                      |
| <a href="#">CSCvi04666</a> | ISIS SRTE: SRTE tunnel not created due to R-flag set.                                        |
| <a href="#">CSCvi05126</a> | ISAKMP Notification messages carry unnecessary data.                                         |
| <a href="#">CSCvi05408</a> | Memory leak due to asnl.                                                                     |
| <a href="#">CSCvi06312</a> | Subsystem stopped: ios-emul-oper-db due to bgp table issue.                                  |
| <a href="#">CSCvi06480</a> | OSPF SSPF: EPL not sent for secondary addresses on loopback interfaces.                      |
| <a href="#">CSCvi06897</a> | The dialpeer matching for inbound SIP profile fails with VRFs.                               |
| <a href="#">CSCvi07387</a> | The ip dhcp excluded-address deletion issues via netconf.                                    |
| <a href="#">CSCvi11123</a> | FMFP-3-OBJ_DWNLD_TO_DP_FAILED error after modifying QoS policy.                              |
| <a href="#">CSCvi11665</a> | Virtual-service guest IP accepts broadcast address.                                          |
| <a href="#">CSCvi11970</a> | Abnormal output for show pnp tech-support.                                                   |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvi13686</a> | Cisco 4000 Series ISR - Outbound faxes originating from certain fax servers may fail to send.         |
| <a href="#">CSCvi14656</a> | Loss TCA is not generated for traffic with DSCP0 when 0-SLA enabled.                                  |
| <a href="#">CSCvi15772</a> | The ephone-dn with shared line sip in ESRST GW causing call incoming failure.                         |
| <a href="#">CSCvi15950</a> | DTMF fails when mid-call renegotiation changes DTMF method.                                           |
| <a href="#">CSCvi16306</a> | Cube sends reinvite with annexb=yes even when it receives annexb=no.                                  |
| <a href="#">CSCvi16454</a> | Router crash due to PuntInject Keepalive Process - kmalloc failures.                                  |
| <a href="#">CSCvi19685</a> | ISDN - BRI - 'progress_ind command does not work.                                                     |
| <a href="#">CSCvi20882</a> | Netconf IP-SLA udp-jitter case missing leaf codec.                                                    |
| <a href="#">CSCvi21288</a> | PFRv3 RC FIA is not enabled on interfaces with one of sub-interface with xconnect configuration.      |
| <a href="#">CSCvi24515</a> | IOS-XE - FTP closing connection as NAT device does not process the 230 reply message.                 |
| <a href="#">CSCvi26061</a> | RP crash @ policymap_associated_to_multiple_instances.                                                |
| <a href="#">CSCvi26398</a> | "%LISP-4-LOCAL_EID_RLOC_INCONSISTENCY" should be suppressed in SDA context.                           |
| <a href="#">CSCvi28362</a> | Unexpected metric value for route redistribution from BGP to OSPF.                                    |
| <a href="#">CSCvi34260</a> | 16.8.1:dot1x Clients stops responding ( ping to client IP fails) after SSO (CSCvh68810) (PD changes). |
| <a href="#">CSCvi34314</a> | Cisco ISR:interface down/up does not renew dhcp assigned ip address.                                  |
| <a href="#">CSCvi35143</a> | Repeatedly Tracebacks seen : %INFRA-3-INVALID_GPM_ACCESS: Invalid GPM Load.                           |
| <a href="#">CSCvi35232</a> | CME/BE4K crashes when trying to check help command for new device type BEKEM.                         |
| <a href="#">CSCvi35960</a> | VRF aware CUBE fails to send OOB OPTIONS pings.                                                       |
| <a href="#">CSCvi36290</a> | Incorrect BDI configuration state shown by NETCONF on interface creation.                             |
| <a href="#">CSCvi38244</a> | IPv6 VRRP Master is using using vlan BIA MAC while sending Neighbor advertisements (NA).              |
| <a href="#">CSCvi38391</a> | H.245 messages are not translated by NAT outside when H.323 video call is initiated from Out-2-In.    |
| <a href="#">CSCvi38916</a> | Persistent Telnet and SSH crashes when configured in 16.6.2.                                          |
| <a href="#">CSCvi40033</a> | 802.1x authentications are failing if there was interface template config applied before.             |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvi41050</a> | PFRv3 route-control is inconsistently set to "Disabled" on BR devices.                               |
| <a href="#">CSCvi41465</a> | All router mcast is removed by "no ipv6 mld router" in specific timing.                              |
| <a href="#">CSCvi42002</a> | CDP packets not getting encapsulated over multipoint GRE tunnel.                                     |
| <a href="#">CSCvi44298</a> | Cisco 4451 ISR Installs 2 IPsec SAs with different peers having same proxy identities.               |
| <a href="#">CSCvi44476</a> | IS-IS unnecessarily updates RIB when in metric-style narrow.                                         |
| <a href="#">CSCvi48837</a> | Ensure load-balance internet TCs do not match class DEFAULT if configured.                           |
| <a href="#">CSCvi50061</a> | Evaluate NTP February 2018 Vulnerabilities.                                                          |
| <a href="#">CSCvi52659</a> | Incorrect "Hop count" obsearbed in IPv6 EIGRP                                                        |
| <a href="#">CSCvi54878</a> | Memory leaks seen at PKI_name_list_add(0xa139cc0)+0x3e                                               |
| <a href="#">CSCvi55920</a> | ISR 4K Crashes issuing "show call active voice"                                                      |
| <a href="#">CSCvi56463</a> | Unexpected Reset, Crypto IKMP Segmentation fault with IPSec AAA Configuration                        |
| <a href="#">CSCvi56919</a> | Radius source interface command is not taking effect on ISR 4k                                       |
| <a href="#">CSCvi57096</a> | MATM RP Shim Process memory leak @aaa_attr_list_alloc make_a_sublist_max                             |
| <a href="#">CSCvi58526</a> | CPUHog and crash on DNS-SRV-1 process                                                                |
| <a href="#">CSCvi61745</a> | Crash when running MPLS Tunnel protection command                                                    |
| <a href="#">CSCvi64534</a> | Remove stack 1+1 CLI for WS-C3850-48XS                                                               |
| <a href="#">CSCvi67613</a> | Protocol type for GRE header doesn't work consistently with "cts sgt inline" enable over auto-tunnel |
| <a href="#">CSCvi71376</a> | OSPF SSPF: tilfa ALGORITHM fails to compute repair path, reports incorrect reason of too many labels |
| <a href="#">CSCvi72996</a> | NMR TTL is wrongly considering eid-record of 0.0.0.0/0 for its calculation                           |
| <a href="#">CSCvi74088</a> | link local multicast packets are received when the SVI is in down state                              |
| <a href="#">CSCvi75086</a> | Rapid TDL memory leak in SMD process leads to crash of active switch in stack for ipv6 clients       |
| <a href="#">CSCvi76084</a> | Device-tracking entry stuck in TENTATIVE for certain Mac Pro hosts configured with static IP         |
| <a href="#">CSCvi77760</a> | SNMP cafSessionMethodState not unsupported after Denali 16.3.3 upgrade on 3850                       |
| <a href="#">CSCvi79948</a> | OSPF TILFA: tilfa ALGORITHM preference rules does not pick repair path with lowest number of labels  |
| <a href="#">CSCvi86983</a> | ZBFW HA: active router stuck in cold standby state after shut no shut the wan interface              |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvi91714</a> | IPv6 address not assigned or delayed when RA Guard is enabled                                        |
| <a href="#">CSCvi92571</a> | On IOSXE neighbor command under pseudowire interface is rejected                                     |
| <a href="#">CSCvi93967</a> | EEM: event mat mac-address not triggered on router with NIM-ES2-8-P                                  |
| <a href="#">CSCvi94425</a> | TBAR issues on KS after running "clear crypto gdoi ks coop role"                                     |
| <a href="#">CSCvi95775</a> | Reverse-tunnel routes under PMIPv6 MAG config not using configured distance metric                   |
| <a href="#">CSCvi96874</a> | ASR1001 has crashed with cgm_avlmgm_find_node                                                        |
| <a href="#">CSCvi96933</a> | mac-move doesn't work on IBNS 2.0 unless you disable it then enable it back                          |
| <a href="#">CSCvi97411</a> | Average queue depth calculation tops out prematurely                                                 |
| <a href="#">CSCvi97590</a> | AppNav-XE cause delays for locally source traffic on router                                          |
| <a href="#">CSCvj00858</a> | CPP Microcode Crash during sRTP Call Encryption                                                      |
| <a href="#">CSCvj01098</a> | Evaluation of IOS-XE and IOS for OpenSSL CVE-2018-0739 and CVE-2018-0733                             |
| <a href="#">CSCvj02955</a> | ISR4221 16.6.2 - SIP NAT ALG not sending packets out of WAN interface                                |
| <a href="#">CSCvj03263</a> | H225 gatekeeper request dropping under "ALG PARSER" with ZBF                                         |
| <a href="#">CSCvj04717</a> | OSPF SSPF: With SRTE tunnel scale, SRTE SID0 constraint Label Bind fails with LABEL_BROKER error msg |
| <a href="#">CSCvj05446</a> | Initial Trustpool installation not successful before PKI is ready                                    |
| <a href="#">CSCvj06388</a> | Type 7 password parsed incorrectly in dot1x credentials causing auth failure.                        |
| <a href="#">CSCvj06909</a> | Reverse-route configuration is unsupported under gdoi crypto map.                                    |
| <a href="#">CSCvj09541</a> | Cisco 4000 Series ISR IOS-XE PBR fails when next hop is recursive over tunnel.                       |
| <a href="#">CSCvj14521</a> | Web redirect clients do not get redirected, Create IO ctx, too many intercepted connections.         |
| <a href="#">CSCvj16818</a> | Cisco 4431 ISR crashing immediately following auto-CA certificate renewal.                           |
| <a href="#">CSCvj16825</a> | "VoIP dial-Peer is Up" incorrectly log prints at every up interval when server-group is configured.  |
| <a href="#">CSCvj20302</a> | Cisco 4000 Series ISR MTP not performing RFC2833 payload type conversion.                            |
| <a href="#">CSCvj21692</a> | UNIX-EXT-SIGNAL: Segmentation fault(11), Process = ACCT Periodic Proc.                               |
| <a href="#">CSCvj23301</a> | IOS: Crypto Ruleset fails to get deleted.                                                            |
| <a href="#">CSCvj24940</a> | Voice VRF with No Bind OPTIONS Ping response not sent.                                               |
| <a href="#">CSCvj27172</a> | Crash during Generic Call Filter Module cleanup                                                      |

| Caveat ID Number           | Description                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------------------|
| <a href="#">CSCvj27526</a> | BGP attribute map for aggre address can not set attribute.                                         |
| <a href="#">CSCvj29126</a> | RADIUS client on network fails to solicit PAC key from CTS even though the device has a valid PAC. |
| <a href="#">CSCvj30023</a> | DNS Debug seen without enabling any debug.                                                         |
| <a href="#">CSCvj38384</a> | %PMIPV6-5-TUNNELDELETE:                                                                            |
| <a href="#">CSCvj39346</a> | OSPF SSPF: When sid 0 is removed, wrong implicit-null label used for inter-area prefix.            |
| <a href="#">CSCvj41224</a> | Crash when doing SNMP walk and applying QOS over a GRE tunnel.                                     |
| <a href="#">CSCvj41550</a> | Default channel operation state changing from I/O to D/O failed when zero-sla enabled.             |
| <a href="#">CSCvj42152</a> | No Audio for SRTP enabled calls in Cisco 4000 Series ISRs.                                         |
| <a href="#">CSCvj49476</a> | Telnet Sessions Hang/Become unavailable at execution of "show run".                                |
| <a href="#">CSCvj50410</a> | Cisco 4331 ISR no collisions count up on duplex mismatch condition.                                |
| <a href="#">CSCvj52231</a> | ACEs after an object-group reference not being processed in software if ACL has more than 13 ACEs. |
| <a href="#">CSCvj52681</a> | Dynamic VLAN assignment causes all sisf entires under the port to be deleted.                      |
| <a href="#">CSCvj57502</a> | Memory leak@CENT-BR-0 when change the path label frequently.                                       |
| <a href="#">CSCvj61603</a> | "dtmf-interworking rtp-nte" command breaking software MTP.                                         |
| <a href="#">CSCvj65296</a> | "ip rsvp bandwidth" max value llimitation to 10GE                                                  |

## Open Caveats - Cisco IOS XE Everest 16.6.3

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                    |
|----------------------------|------------------------------------------------------------------------------------------------|
| <a href="#">CSCvf84528</a> | False indication of RTP port leak on Cisco 4000 Series ISRs.                                   |
| <a href="#">CSCvf89894</a> | GETVPN/Primary KS sending rekey first to GM's and then to Secondary KS via scheduled rekey.    |
| <a href="#">CSCvf96294</a> | MIB counter for IPSec tunnels does not decrement under high tunnel scale and churn.            |
| <a href="#">CSCvg16234</a> | Cisco ISR receives a control packet (CDP) with a CMD tag it should process it, not drop it.    |
| <a href="#">CSCvg43408</a> | IOS-XE Router crashed unexpectedly with critical process fault, fman_fp_image, fp_0_0, rc=134. |

| Caveat ID Number           | Description                                                                                   |
|----------------------------|-----------------------------------------------------------------------------------------------|
| <a href="#">CSCvg60185</a> | Cisco 4000 Series ISR discards private RSA key after upgrade and reload with WAAS module.     |
| <a href="#">CSCvg79608</a> | PFR: Overlapping Loopback Interface Causes Incorrect Forwarding Decision with AppNav and PfR. |
| <a href="#">CSCvh05611</a> | IOSd crash while applying dial peer configuration.                                            |
| <a href="#">CSCvh09525</a> | CME: BLF monitor function fails intermittently with TCP connection.                           |
| <a href="#">CSCvh09620</a> | Continuous crash in "/kernel/mki/src/free" after upgrade to version 15.5(3)S6.                |
| <a href="#">CSCvh24730</a> | PfRv3: Crash while Printing the Same TCA message.                                             |
| <a href="#">CSCvh26241</a> | Crash after crypto map removal.                                                               |
| <a href="#">CSCvh32216</a> | Sporadic Crashes Due to IPSec (during ISAKMP AAA interaction).                                |
| <a href="#">CSCvh32224</a> | 8800 KEM module not getting detected on 88XX phones with CME 12,11.6.                         |
| <a href="#">CSCvh48610</a> | IWAN router crash while updating pmi policy.                                                  |
| <a href="#">CSCvh49600</a> | Output "sh sip-ua connections tcp tls detail" shows that CUBE has stuck connection ids.       |
| <a href="#">CSCvh50515</a> | Cisoc 4331 ISR crashed due to SA creation failure                                             |
| <a href="#">CSCvh52882</a> | Memory Leak due to nbar configuration.                                                        |
| <a href="#">CSCvh53691</a> | FP crash with scaled IKE sessions.                                                            |
| <a href="#">CSCvh57108</a> | CPUHOG on QoS statistics collection for DMVPN. QoS crash with DMVPN/NHRP.                     |
| <a href="#">CSCvh59195</a> | Ciosc 4000 Series ISR: QFP crashed due to NAT memory leak.                                    |
| <a href="#">CSCvh66445</a> | Cisco 4000 Series ISR router crashes during status check on WAAS Express.                     |

**Resolved Caveats - Cisco IOS XE Everest 16.6.3**

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                              |
|----------------------------|--------------------------------------------------------------------------|
| <a href="#">CSCua00661</a> | Memory leak seen while creating vlans using Tclsh.                       |
| <a href="#">CSCvc60745</a> | Memory leak - refcount not reduced when packet dropped.                  |
| <a href="#">CSCvd04871</a> | Crash after IWAN does a recalculation in the RIB.                        |
| <a href="#">CSCvd64670</a> | SCEP enrollment failing with HTTP/1.1 500.                               |
| <a href="#">CSCvd97768</a> | Cisco 4000 ISR crashes at sstrncpy using voice.                          |
| <a href="#">CSCve08418</a> | IPsec/IKEv2 Installation sometimes fails with simultaneous negotiations. |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCve32330</a> | A pseudo-random number was generated twice in succession.                                             |
| <a href="#">CSCve55089</a> | BGP crashes at bgp_ha_sso_enable_ssomode.                                                             |
| <a href="#">CSCve64341</a> | Mid Point LSP creation failure after reload with latest polaris Image.                                |
| <a href="#">CSCve66601</a> | Crash is seen in CISCO-SLB-EXT-MIB code.                                                              |
| <a href="#">CSCve75919</a> | In-dialog options ping received post ACK (call completion) cause cube to change codec and no audio.   |
| <a href="#">CSCvf31368</a> | Router crash after EEM-wanfailover script triggered.                                                  |
| <a href="#">CSCvf36269</a> | Cisco IOS and IOS XE Software Plug-and-Play PKI API Certificate Validation Vulnerability.             |
| <a href="#">CSCvf39474</a> | GETVPN: TBAR sync "timer is not running" after KS upgrade causing anti-reply drops and GM outages.    |
| <a href="#">CSCvf48159</a> | Router crash during T38 fax bitrate negotiation.                                                      |
| <a href="#">CSCvf60862</a> | Cisco IOS and IOS XE software IOS daemon Cross-Site scripting vulnerability.                          |
| <a href="#">CSCvf68261</a> | Crash when printing IPSEC anti-replay error.                                                          |
| <a href="#">CSCvf84349</a> | Router crash on polling cEigrpPeerEntry.                                                              |
| <a href="#">CSCvg05896</a> | IWAN EIGRP SAF - seq number mismatch after branch reload.                                             |
| <a href="#">CSCvg07428</a> | PfRv3 triggers List Header leak in FN.F                                                               |
| <a href="#">CSCvg09010</a> | KS merge fails for groups with TBAR due to PST update failure on primary KS.                          |
| <a href="#">CSCvg14256</a> | Crash at cc_detect_mute_call.                                                                         |
| <a href="#">CSCvg22515</a> | After upgrade of IOS, SSH passwords longer than 25 characters do not work.                            |
| <a href="#">CSCvg29183</a> | Cisco 4000 Sereis ISR: XE 16.3.4 - SIP-TDM GW - FLEXDSPRM-3-TDM_CONNECT errors and unexpected reboot. |
| <a href="#">CSCvg30722</a> | EAPTLS:- Session manger crashing with MKA/EAPTLS session bring up with newly installed certificates.  |
| <a href="#">CSCvg31607</a> | IPv4 PLU mtrie lookup return invalid oce_chain_p.                                                     |
| <a href="#">CSCvg34731</a> | IOS-XE MOS scores always show 4.x even with massive packet loss.                                      |
| <a href="#">CSCvg38307</a> | CME/BE4000 crash occurs when call is made to invalid SNR destination.                                 |
| <a href="#">CSCvg40430</a> | Cisco 4431 ISR QFP crashes by a LLC packet received in a serial interface.                            |
| <a href="#">CSCvg40784</a> | Session not comming up after certificate expired.                                                     |
| <a href="#">CSCvg52560</a> | Traceback: OCSP creates a large number of lists and triggers a memory problem.                        |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvg60288</a> | Device IP address AV pair replaced with 192.168.1.5                                                   |
| <a href="#">CSCvg71566</a> | "no cdp enable" is rewritten to "no cdp tlv app" after reload.                                        |
| <a href="#">CSCvg74048</a> | PKI: All SCEP requests fail with "Failed to send the request. There is another request in progress".  |
| <a href="#">CSCvg76912</a> | PnP configuration upgrade failed when IFS returns size 0 for all TFTP files.                          |
| <a href="#">CSCvg84039</a> | Traceback: Crash on WAAS menu prompt for WAN Interface.                                               |
| <a href="#">CSCvg84989</a> | List Header leak with PfR enabled.                                                                    |
| <a href="#">CSCvg90226</a> | Crypto Traceback: Router crash at 'Crypto Support' segmentation fault.                                |
| <a href="#">CSCvg94908</a> | Mgig stack keeps crashing while configuring with Radius commands                                      |
| <a href="#">CSCvg98890</a> | IOS-XE GM router might crash after the rekey method is changed from unicast to multicast.             |
| <a href="#">CSCvh00038</a> | Device IP address AV pair replaced with 192.16X.1.X.                                                  |
| <a href="#">CSCvh17481</a> | PKI: Device crash during crl download with multiple CDP URI.                                          |
| <a href="#">CSCvh32416</a> | Evaluation of all for CPU Side-Channel Information Disclosure Vulnerability                           |
| <a href="#">CSCvh54813</a> | Output Qos policy is removed from Dialer interface after reloading the device if input policy exists. |
| <a href="#">CSCvh60525</a> | CLI 'aaa common-criteria' not available on IPBASEK9 license.                                          |

## Open Caveats - Cisco IOS XE Everest 16.6.2

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCve23012</a> | Cisco 4300 and 4400 ISR Silently Crashes with "Reload Reason:Localsoft" and No Core / Crashinfo File. |
| <a href="#">CSCvd65197</a> | IOSd crashed when dialer disconnect the ISDN call.                                                    |
| <a href="#">CSCve18549</a> | CME/BE4000 Intermittently Crash when making configuration changes.                                    |
| <a href="#">CSCve54914</a> | NDSSO vrf ha table to be populated correctly.                                                         |
| <a href="#">CSCve78446</a> | [1661]- Switch number is missing in stack merged logs.                                                |
| <a href="#">CSCvf33947</a> | CUBE cannot handle mid-call re-invite when midcall-signalling passthrough mediachange is configured.  |
| <a href="#">CSCvf39868</a> | Cisco 4431 ISR crashes while verifying IPv6 CEF scalability.                                          |
| <a href="#">CSCvf65079</a> | CUBE 1K reloaded with reason: RG-application reload on voice-b2bha RG.                                |

| Caveat ID Number           | Description                                                                                       |
|----------------------------|---------------------------------------------------------------------------------------------------|
| <a href="#">CSCvf68261</a> | Crashes when printing IPSEC anti-replay error.                                                    |
| <a href="#">CSCvf70383</a> | Crashes in SDP Passthru when T.38 as 1st mline in mid-call SDP.                                   |
| <a href="#">CSCvf71066</a> | Router crash due to memory corruption in PKI.                                                     |
| <a href="#">CSCvf84349</a> | Router crashes on polling cEigrpPeerEntry.                                                        |
| <a href="#">CSCvf89399</a> | Flexible NetFlow crash.                                                                           |
| <a href="#">CSCvf93129</a> | Mid-call failure because all available Crypto is not Offered in SDP.                              |
| <a href="#">CSCvg05452</a> | IOS-XE router crash from memory corruption during CCB cleanup.                                    |
| <a href="#">CSCvg09010</a> | KS merge fails for groups with TBAR due to PST update failure on primary KS.                      |
| <a href="#">CSCvg15158</a> | DMVPN session get stuck in NHRP and UP-NO-IKE state without active IKEv2 session until rekey.     |
| <a href="#">CSCvg16357</a> | Copying file larger than 2GB to FTP destination fails with "Invalid argument."                    |
| <a href="#">CSCvg19259</a> | MPLSoFlexVPN: Hub doesn't forward resolution req when default route is advertised to spokes.      |
| <a href="#">CSCvg28614</a> | Cisco 4000 Series ISR traceroute is abnormal although communication is OK.                        |
| <a href="#">CSCvg29183</a> | Cisco 4000 Series ISRs - XE 16.3.4 - SIP-TDM GW - FLEXDSPRM-3-TDM_CONNECT errors and crash.       |
| <a href="#">CSCvg30928</a> | Management ARP entry disappears after a period of time.                                           |
| <a href="#">CSCvg33403</a> | Incoming call fails with 'Lower layer disconnected call cause=47' error.                          |
| <a href="#">CSCvg34685</a> | IKEv1 Stuck Virtual-access interface&RRI 15.4(3)s6.                                               |
| <a href="#">CSCvg34889</a> | IKEv2 VPN tunnel does not establish when destination ip address changes during the AUTH exchange. |
| <a href="#">CSCvg38307</a> | BE4K crashed @ContactingDest_SnrOtherDestroyDone                                                  |
| <a href="#">CSCvg40430</a> | 4431 QFP crashes by a LLC packet received in a Serial Interface                                   |

## Resolved Caveats - Cisco IOS XE Everest 16.6.2

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                   |
|----------------------------|---------------------------------------------------------------|
| <a href="#">CSCuv47069</a> | DHCP crashed when configure a manual binding in an interface. |
| <a href="#">CSCux22473</a> | IPv6 Tracking for route learned from IBGP Neighbor is Down.   |
| <a href="#">CSCuy09470</a> | ISIS hello stops to be sent after RSP switchover.             |

| Caveat ID Number           | Description                                                                                           |
|----------------------------|-------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvc78492</a> | DMVPN : IOS-XE - Unable to pass traffic if spoke to spoke fails to build in phase 2.                  |
| <a href="#">CSCvd16501</a> | High CPU due to SNMP ENGINE when polling mplsTunnelHopEntry.                                          |
| <a href="#">CSCve00909</a> | 16.6 : Ping failure on re-add of ip address to Dialer Interface.                                      |
| <a href="#">CSCve07263</a> | IPSec Tunnel stuck in Up/Down state after shut/no-shut - VPN Interop.                                 |
| <a href="#">CSCve09104</a> | Command "segment-routing mpls" under router isis 1 not getting NVGEN'd.                               |
| <a href="#">CSCve13491</a> | Router might crash due watchdog when creating a new swidb at if_index_allocate_index.                 |
| <a href="#">CSCve15722</a> | The second and later PfRv3 VRF configs are missing after reload.                                      |
| <a href="#">CSCve23090</a> | 16.6 OBS: Local LFA is used incorrectly when TI-LFA Node Protection enabled.                          |
| <a href="#">CSCve35209</a> | 16.6:Kignpin @ Kernal errors kernel-source/kernel/softirq.c:150 __local_bh_enable_ip+0x3b/0x9c().     |
| <a href="#">CSCve47826</a> | Memory leak Crypto IKEv2 at ikev2_ios_psh_set_route_info.                                             |
| <a href="#">CSCve51657</a> | Slow convergence with scale after a core link flaps.                                                  |
| <a href="#">CSCve53984</a> | Cisco 4300 ISR crashed while importing certificate.                                                   |
| <a href="#">CSCve54486</a> | Crash when attempting to assign nonexistent/shutdown VLAN to 802.1x port.                             |
| <a href="#">CSCve57788</a> | Web authentication clients do not receive redirect URL and HTTP Intercept, Invalid appl_id error smd. |
| <a href="#">CSCve62353</a> | Startup-config missing after power outage.                                                            |
| <a href="#">CSCve64336</a> | RSP1-Continous ESMC tracebacks observed after IMA8T OIR followed by SSO.                              |
| <a href="#">CSCve66119</a> | Router crash due to process "Crypto Support" segmentation fault.                                      |
| <a href="#">CSCve68911</a> | Nested Enhanced Route Refresh requests triggers Stale Prefixes.                                       |
| <a href="#">CSCve76827</a> | NAT policy-map that is large takes long time to download.                                             |
| <a href="#">CSCve76945</a> | :Router crashed when a sh bgp command was executed.                                                   |
| <a href="#">CSCve77011</a> | SSL handshake failure when validating certification with name-constraints.                            |
| <a href="#">CSCve78101</a> | Inconsistent Behavior on Link states with different SFP's plugged into the module.                    |
| <a href="#">CSCve81985</a> | Subscriber session not syncd to standby while assigning static ip in DHCP.                            |
| <a href="#">CSCve89668</a> | Router crashed when "clear ip bgp vpng4 u update-group <nei>.                                         |
| <a href="#">CSCve90812</a> | Cisco 4431 ISR drops all received packets due to CRC error after power off/on.                        |
| <a href="#">CSCve94399</a> | Router crash when importing BGP routes - EVPN.                                                        |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCve95243</a> | Internal interface missing from L2FIB output list.                                                   |
| <a href="#">CSCve97061</a> | Unable to remove 'mpls tp' configuration from Router.                                                |
| <a href="#">CSCve98056</a> | ESP ucode crash with ALG for PPTP traffic and PAP is enabled.                                        |
| <a href="#">CSCve98223</a> | Two PW-Group switchover notifications are triggered from PI to PD for a single event.                |
| <a href="#">CSCvf02131</a> | IP SLA can trigger crash when used with MPLS probe.                                                  |
| <a href="#">CSCvf03810</a> | Cisco 4221 ISR boot loop when Gig0/0/0 up                                                            |
| <a href="#">CSCvf05616</a> | Traffic drop, on reconfiguring l2vpn sessions after sso on peer.                                     |
| <a href="#">CSCvf11237</a> | Memory leak seen@crypto_init_show_instance.                                                          |
| <a href="#">CSCvf11776</a> | VRRPv3 with VRRS remains NOT READY after shutdown Port-channel IF.                                   |
| <a href="#">CSCvf12746</a> | Cisco 4331 ISR packet drop when shut/no shut interface that not transport traffic.                   |
| <a href="#">CSCvf16448</a> | No all IPv6 GRE crypto tunnels may come up or recover from flapping at scale.                        |
| <a href="#">CSCvf18162</a> | Crash observed in Mlpp-Bacd scenario.                                                                |
| <a href="#">CSCvf18470</a> | IOS-XE CUBE HA crash.                                                                                |
| <a href="#">CSCvf19607</a> | Cisco 4000 Series ISR not correctly handling forked 18X responses with SDP.                          |
| <a href="#">CSCvf24607</a> | Ipsec Session Fail After Up/down Link Between Dmvpn Tunnel.                                          |
| <a href="#">CSCvf24713</a> | Stale path message for that prefix is noticed when dampening is configured.                          |
| <a href="#">CSCvf27072</a> | NBAR not working on 16.5.1a in switch if name-server is configured.                                  |
| <a href="#">CSCvf29213</a> | PFRV3: Site Prefix shows unreachable after removing and adding the specific route for the prefix.    |
| <a href="#">CSCvf30703</a> | Watchdog crash at sla_resp_config_command when executing the "show run" command.                     |
| <a href="#">CSCvf30772</a> | Cisco 4331 ISR - ATM - T1 CAS - One Way Audio: Dropping Packets due to Tail Drop                     |
| <a href="#">CSCvf33443</a> | FEW Inter xTR roam scale 400/sec hit on CSR1KV-Map server causes delay in L2&L3 lisp updates to xTR. |
| <a href="#">CSCvf33570</a> | Crash while BGP-RR Unconfiguration.                                                                  |
| <a href="#">CSCvf34835</a> | IOS-XE GETVPN KS crashes while sending cgmGdoiKeyServerRegistrationComplete trap after GM reg.       |
| <a href="#">CSCvf35507</a> | Crash in SSH Process due to SCP memory corruption.                                                   |
| <a href="#">CSCvf40147</a> | C9300: ASIC Ballot failed message seen on during bootup in overnight reload test                     |

| Caveat ID Number           | Description                                                                                                |
|----------------------------|------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvf40983</a> | TSN-H: Sometimes boot C1111-8PLTEW and see the DHCPD receive traceback in the log                          |
| <a href="#">CSCvf41539</a> | CAT3K SDA border/LISP crashed with segmentation fault                                                      |
| <a href="#">CSCvf42300</a> | ISIS SR: segmentation fault in ISIS when "no seg mpls" command is given.                                   |
| <a href="#">CSCvf44501</a> | ISR4K slow responsiveness when interface state goes from UP to DOWN compared to Cat6880X                   |
| <a href="#">CSCvf44638</a> | Numbered extended IP ACLs break config sync                                                                |
| <a href="#">CSCvf51341</a> | Crash after show ip ospf database summary command                                                          |
| <a href="#">CSCvf54314</a> | Crashes due to a null pointer dereference on htsp structure.                                               |
| <a href="#">CSCvf59923</a> | DNS : Split DNS reg-expression issue in IOS-XE (16.x).                                                     |
| <a href="#">CSCvf62916</a> | Router crashes when doing "show ip bgp neighbor" on a flapping BGP neighborship.                           |
| <a href="#">CSCvf63541</a> | BGP with global import/export crashes when several nbrs deleted simultaneously.                            |
| <a href="#">CSCvf64377</a> | Ping fail with many ACL rules and dialer profiles configured when using ISDN DDR on Cisco 4000 Series ISR. |
| <a href="#">CSCvf65643</a> | Unicast ping stops working when "ip pim sparse-mode" removed from SVI.                                     |
| <a href="#">CSCvf68602</a> | E1r2-Cas is not working when adding "invert-abcd 1 0 0 0"                                                  |
| <a href="#">CSCvf69272</a> | SNMP ENGINE high CPU usage observed with 1.3.6.1.2.1.185.1.1.1(mgmdHostInterfaceEntry).                    |
| <a href="#">CSCvf73320</a> | Cisco 4431 ISR crashes while finding NDR with max oif number per multicast grp at scale.                   |
| <a href="#">CSCvf74154</a> | SGACL: cpp_sp_svr crash during CFM EDIT request with reseq_enable = TRUE.                                  |
| <a href="#">CSCvf74829</a> | CRL download fails due to "failed to create getcacert message".                                            |
| <a href="#">CSCvf76512</a> | Option 82 circuit-id-tag restricted by 6 bytes.                                                            |
| <a href="#">CSCvf76535</a> | B2B NAT HA: Stale NAT translations stuck on primary router after communication loss with standby.          |
| <a href="#">CSCvf80495</a> | IPv6 BGP network advertized not seen in the peer.                                                          |
| <a href="#">CSCvf80757</a> | NETCONF-YANG/RESTCONF edit config fails silently, subsequent get config reports false-positive.            |
| <a href="#">CSCvf88590</a> | After disabling http server/https server on netconf, IP-Adm-V4-Int-ACL-global delete.                      |
| <a href="#">CSCvf89608</a> | Missing ip route to cellular interface after router reload or modem power cycle.                           |
| <a href="#">CSCvf92057</a> | CUBE is unable to send PRACK to Skype server for inbound calls.                                            |

| Caveat ID Number           | Description                                                            |
|----------------------------|------------------------------------------------------------------------|
| <a href="#">CSCvf94948</a> | Cisco 4331 ISR: Input policy-map classify traffic incorrectly.         |
| <a href="#">CSCvf95077</a> | Stale Mac entry in MLRIB.                                              |
| <a href="#">CSCvf95141</a> | ZBF crashes on standby.                                                |
| <a href="#">CSCvf96035</a> | ISIS redistribute connected not working for IPV6 routes.               |
| <a href="#">CSCvg03498</a> | The "copy run start all" makes the router stuck.                       |
| <a href="#">CSCvg06514</a> | BE4K crashed due to CS_Placecall_SharedIn.                             |
| <a href="#">CSCvg08979</a> | Martian check for distance command needs to be removed.                |
| <a href="#">CSCvg13049</a> | ISR G2: dot1p marking fails if service-policy applied on the Dialer.   |
| <a href="#">CSCvg31493</a> | Stale Mac entry in MLRIB.                                              |
| <a href="#">CSCvg31495</a> | NMR calculation is wrongly considering eid-record of 0.0.0.0/0 in SDA. |

## Open Caveats - Cisco IOS XE Everest 16.6.1

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                                  |
|----------------------------|--------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCve95037</a> | Traceback found for PLATFORM_INFRA-5-IOS_INTR_OVER_LIMIT part 2                                              |
| <a href="#">CSCvf23190</a> | IPSec install failing with dynamic crypto map scale.                                                         |
| <a href="#">CSCve90812</a> | Cisco 4431 ISR drops all received packets due to CRC error after power <b>OFF</b> and <b>ON</b> .            |
| <a href="#">CSCvf12746</a> | Cisco 4331 ISR packet drops when the <b>shut/no shut</b> interface does not transport traffic.               |
| <a href="#">CSCve92165</a> | Packet drop issue is seen on Cisco 4000 Series ISR with EVC configuration.                                   |
| <a href="#">CSCve62353</a> | Startup configuration is missing after the power outage.                                                     |
| <a href="#">CSCvf24588</a> | Cisco 4331 ISR Fman_Fp crashes with just a single tunnel configured.                                         |
| <a href="#">CSCvf27563</a> | Cisco 4000 Sereies ISR crashes in fman_fp during IPSec flow deletion.                                        |
| <a href="#">CSCvf02875</a> | Reducing the memory utilized by ISR-WAAS-200.                                                                |
| <a href="#">CSCve45274</a> | A Cisco router may crash when issuing the <b>'show dmvpn detail   in Virtual-Access with up/down INTF'</b> . |
| <a href="#">CSCuv90519</a> | Map doesn't get updated with socket change on local address change.                                          |
| <a href="#">CSCvf16626</a> | IWAN router crash while updating pmi policy.                                                                 |
| <a href="#">CSCvc46230</a> | PfRv3: Unexpected reload while evaluating/moving TC's between channels.                                      |

| Caveat ID Number           | Description                                                                                          |
|----------------------------|------------------------------------------------------------------------------------------------------|
| <a href="#">CSCvf18856</a> | Cisco 4000 Series ISR with SM-X - Switch module does not recover gracefully following bcm crash.     |
| <a href="#">CSCve99492</a> | DMVPN Ph-2: spoke to spoke traffic drops, NHRP entry incomplete, if crypto session fails to come up. |
| <a href="#">CSCve89095</a> | Cisco 4221 ISR router crashed on fw_icmp6_get_ntuple.                                                |
| <a href="#">CSCve69182</a> | Logs filled with conn_array_empty messages                                                           |
| <a href="#">CSCvc89226</a> | Connection goes down randomly on Cisco 4321 ISR/K9.                                                  |
| <a href="#">CSCvf27566</a> | OpenDNS local-domain bypass on Cisco 4000 Series ISR stop working after reboot.                      |

**Resolved Caveats - Cisco IOS XE Everest 16.6.1**

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

| Caveat ID Number           | Description                                                                                              |
|----------------------------|----------------------------------------------------------------------------------------------------------|
| <a href="#">CSCuu68879</a> | Cisco 4300 ISR shows abnormal large RTT/jitter value in IP SLA udp-jitter v2/v3.                         |
| <a href="#">CSCvd19860</a> | OSPFv3 AUTH breaks IPv6 traffic intermittently                                                           |
| <a href="#">CSCve71068</a> | The <b>show platform software cerm-information</b> command is not displaying the statistics information. |
| <a href="#">CSCve47826</a> | Memory leak Crypto IKEv2 at ikev2_ios_psh_set_route_info.                                                |
| <a href="#">CSCve20522</a> | The <b>show crypto map</b> command displays incorrect wildcard mask for crypto access-list.              |
| <a href="#">CSCvf11237</a> | Memory leak is seen at crypto_init_show_instance.                                                        |
| <a href="#">CSCve63482</a> | Phase1 comes up and DPDs being exchanged even if the tunnel interface is shut down.                      |
| <a href="#">CSCvc79296</a> | Redundancy inter-device is not working with security ipsec.                                              |
| <a href="#">CSCve66119</a> | Router crash due to process Crypto Support segmentation fault.                                           |
| <a href="#">CSCvd97524</a> | Fixed versions for CSCuz15131 crash when traffic with maximum size is on wire.                           |
| <a href="#">CSCve14080</a> | Error message "LID: Handle 0x0 is invalid" filling console logs                                          |
| <a href="#">CSCve77011</a> | SSL handshake failure when validating certification with name-constraints                                |
| <a href="#">CSCve74862</a> | Crash due to memory corruption when using PNP feature                                                    |
| <a href="#">CSCve76827</a> | large NAT policy-map takes long time to download                                                         |

## Related Documentation

### Platform-Specific Documentation

For information about the Cisco 4000 Series ISRs and associated services and modules, see:

[Documentation Roadmap for the Cisco 4000 Series ISRs,Cisco IOS XE 16.x](#).

### Cisco IOS Software Documentation

The Cisco IOS XE Everest 16.x software documentation set consists of Cisco IOS XE Everest 16.x configuration guides and Cisco IOS command references. The configuration guides are consolidated platform-independent configuration guides organized and presented by technology. There is one set of configuration guides and command references for the Cisco IOS XE Everest 16.x release train. These Cisco IOS command references support all Cisco platforms that are running any Cisco IOS XE Everest 16.x software image.

See [http://www.cisco.com/en/US/products/ps11174/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps11174/tsd_products_support_series_home.html)

Information in the configuration guides often includes related content that is shared across software releases and platforms.

Additionally, you can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.

### Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco Marketplace](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

### Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

---

© 2017 Cisco Systems, Inc. All rights reserved.