



Release Notes for Cisco 4000 Series ISRs, Cisco IOS XE Cupertino 17.8.x

First Published: 2022-04-22

Full Cisco Trademarks with Software License

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Cisco 4000 Series Integrated Services Routers Overview



Note Cisco IOS XE Cupertino 17.8.1a is the first release for Cisco 4000 Series Integrated Services Routers in the Cisco IOS XE 17.8.x release series.

The Cisco 4000 Series ISRs are modular routers with LAN and WAN connections that can be configured by means of interface modules, including Cisco Enhanced Service Modules (SM-Xs), and Network Interface Modules (NIMs).

The following table lists the router models that belong to the Cisco 4000 Series ISRs.

Cisco 4400 Series ISR	Cisco 4300 Series ISR	Cisco 4200 Series ISR
Cisco 4431 ISR	Cisco 4321 ISR	Cisco 4221 ISR
Cisco 4451-X ISR	Cisco 4331 ISR	
Cisco 4461 ISR	Cisco 4351 ISR	



Note Starting with Cisco IOS XE Amsterdam 17.3.2 release, with the introduction of Smart Licensing Using Policy, even if you configure a hostname for a product instance or device, only the Unique Device Identifier (UDI) is displayed. This change in the display can be observed in all licensing utilities and user interfaces where the hostname was displayed in earlier releases. It does not affect any licensing functionality. There is no workaround for this limitation.

The licensing utilities and user interfaces that are affected by this limitation include only the following:

- Cisco Smart Software Manager (CSSM),
- Cisco Smart License Utility (CSLU), and
- Smart Software Manager On-Prem (SSM On-Prem).

Product Field Notice

Cisco publishes Field Notices to notify customers and partners about significant issues in Cisco products that typically require an upgrade, workaround or other user action. For more information, see <https://www.cisco.com/c/en/us/support/web/field-notice-overview.html>.

We recommend that you review the field notices to determine whether your software or hardware platforms are affected. You can access the field notices from <https://www.cisco.com/c/en/us/support/web/tsd-products-field-notice-summary.html#%7Etab-product-categories>.

System Requirements

The following are the minimum system requirements:



Note There is no change in the system requirements from the earlier releases.

- Memory: 4 GB DDR3 up to 32 GB
- Hard Drive: 200 GB or higher (Optional). The hard drive is only required for running services such as Cisco ISR-WAAS.
- Flash Storage: 4 GB to 32 GB
- NIMs and SM-Xs: Modules (Optional)
- NIM SSD (Optional)

For more information, see the [Cisco 4000 Series ISRs Data Sheet](#).



Note For more information on the Cisco WAAS IOS-XE interoperability, refer to the WAAS release notes: <https://www.cisco.com/c/en/us/support/routers/wide-area-application-services-waas-software/products-release-notes-list.html>.

Determining the Software Version

You can use the following commands to verify your software version:

- For a consolidated package, use the **show version** command
- For individual sub-packages, use the **show version installed** command

Upgrading to a New Software Release

To install or upgrade, obtain a Cisco IOS XE 17.8.x consolidated package (image) from Cisco.com. You can find software images at <http://software.cisco.com/download/navigator.html>. To run the router using individual sub-packages, you also must first download the consolidated package and extract the individual sub-packages from a consolidated package.



Note When you upgrade from one Cisco IOS XE release to another, you may see *%Invalid IPv6 address* error in the console log file. To rectify this error, enter global configuration mode, and re-enter the missing IPv6 alias commands and save the configuration. The commands will be persistent on subsequent reloads.

For more information on upgrading the software, see the [Installing the Software](#) section of the Software Configuration Guide for the Cisco 4000 Series ISRs.

Recommended Firmware Versions

The following table lists the recommended ROMMON and CPLD versions for Cisco IOS XE 17.2.x onwards releases.

Table 1: Recommended Firmware Versions

Cisco 4000 Series ISRs	Existing ROMMON	Cisco Field-Programmable Devices	CCO URL for the CPLD Image
Cisco 4461 ISR	16.12(2r)	21102941	isr_4400v2_cpld_update_v2.0.SPA.bin isr4002hwprogrammable040100SPA.pkg
Cisco 4451-X ISR	16.12(2r)	19042950	isr4400_cpld_update_v2.0.SPA.bin
Cisco 4431 ISR	16.12(2r)	19042950	isr4400_cpld_update_v2.0.SPA.bin
Cisco 4351 ISR	16.12(2r)	19040541	isr4300_cpld_update_v2.0.SPA.bin
Cisco 4331 ISR	16.12(2r)	19040541	isr4300_cpld_update_v2.0.SPA.bin
Cisco 4321 ISR	16.12(2r)	19040541	isr4300_cpld_update_v2.0.SPA.bin
Cisco 4221 ISR	16.12(2r)	19042420	isr4200_cpld_update_v2.0.SPA.bin



Note Cisco 4461 ISR may require two upgrade packages to upgrade to 21102941. See [CPLD-4-1 Release Notes](#).

Upgrading Field-Programmable Hardware Devices

The hardware-programmable firmware is upgraded when Cisco 4000 Series ISR contains an incompatible version of the hardware-programmable firmware. To do this upgrade, a hardware-programmable firmware package is released to customers.

Generally, an upgrade is necessary only when a system message indicates one of the field-programmable devices on the Cisco 4000 Series ISR needs an upgrade, or a Cisco technical support representative suggests an upgrade.

From Cisco IOS XE Release 3.10S onwards, you must upgrade the CPLD firmware to support the incompatible versions of the firmware on the Cisco 4000 Series ISR. For upgrade procedures, see the [Upgrading Field-Programmable Hardware Devices for Cisco 4000 Series ISRs](#).

Feature Navigator

You can use Cisco Feature Navigator to find information about feature, platform, and software image support. To access Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.

New and Changed Information

New and Changed Hardware Features

There are no new hardware features for this release.

New and Changed Software Features

Table 2: New Software Features in Cisco IOS XE 17.8.1a

Feature	Description
Configuring Supplementary Voice Features	From the Cisco IOS XE 17.8.1a release, you can configure your hardware to use the SIP Line Side features such as Directed Call Park, Call Pick Up, Call Transfer, and so on. To provision these features, configure the outbound VOIP Dial-Peer, Pots Dial-Peer, Voice Card, and SIP in your hardware by performing the procedures explained in the Configuring the Supplementary Features.
Download AnyConnect Profiles with IPsec IKEv2 VPN	This feature allows you to configure Internet Protocol Security (IPSec)-Internet Key Exchange (IKEv2) VPN to download AnyConnect profiles over SSL, for IOS-XE headends.
Support for Bidirectional Debugging	You can now enable bidirectional debugging of traffic using the debug platform condition match command.
Cisco Unified Border Element (CUBE) Features	
mTLS Client CN-SAN validation	It is now possible to verify a client through the validation of the common name or subject alternate name fields in its certificate.
Unified Secure SRST: SHA2-Cipher-only Mode	To ensure that only the most robust cipher suites are used, Secure SRST (SCCP) may now be configured to only use TLS 1.2 Cipher Suites. Secure SIP SRST now supports the granular control of cipher suites used for both signaling (TLS) and media (SRTP).
Unified Secure SRST: SIP OAuth Client Registration	IP Phones, Jabber clients, and the Webex app may now failover and register to Secure SIP SRST using OAuth authentication.
VRF-aware Listen Port per Tenant	SIP trunks configured using the CUBE tenant feature may now be configured with a specific listen port, allowing more flexibility in routing inbound calls to the correct trunk. This feature may be used together with VRF interface binding to further control the partition and routing of calls.
Programmability Features	
IPsec YANG model	This feature introduces a YANG model for the show platform hardware qfp active feature ipsec state command. This model displays the Cisco Quantum Flow Processor (QFP) IPsec state information. You can view the different states and the number of messages exchanged for each state in QFP IPsec. With this information, you can troubleshoot issues related to IPsec flows. For more information about YANG models, see https://github.com/YangModels/yang/tree/master/vendor/cisco/xe .

Feature	Description
YANG Model Version 1.1	Cisco IOS XE Cupertino 17.8.1a uses the YANG version 1.0; however, you can download the YANG version 1.1 from GitHub at https://github.com/YangModels/yang/tree/master/vendor/cisco/xfolder . For inquiries related to the migrate_yang_version.py script or the Cisco IOS XE YANG migration process, send an email to xe-yang-migration@cisco.com .

Configure the Router for Web User Interface

This section explains how to configure the router to access Web User Interface. Web User Interface requires the following basic configuration to connect to the router and manage it.

- An HTTP or HTTPS server must be enabled with local authentication.
- A local user account with privilege level 15 and accompanying password must be configured.
- Vty line with protocol SSH/Telnet must be enabled with local authentication. This is needed for interactive commands.
- For more information on how to configure the router for Web User Interface, see [Cisco 4000 Series ISRs Software Configuration Guide, Cisco IOS XE 17](#).

Resolved and Open Bugs

This section provides information about the bugs in Cisco 4000 Series Integrated Services Routers and describe unexpected behavior. Severity 1 bugs are the most serious bugs. Severity 2 bugs are less serious. Severity 3 bugs are moderate bugs. This section includes severity 1, severity 2, and selected severity 3 bugs.

The open and resolved bugs for this release are accessible through the [Cisco Bug Search Tool](#). This web-based tool provides you with access to the Cisco bug tracking system, which maintains information about bugs and vulnerabilities in this product and other Cisco hardware and software products. Within the [Cisco Bug Search Tool](#), each bug is given a unique identifier (ID) with a pattern of CSCxxNNNNN, where x is any letter (a-z) and N is any number (0-9). The bug IDs are frequently referenced in Cisco documentation, such as Security Advisories, Field Notices and other Cisco support documents. Technical Assistance Center (TAC) engineers or other Cisco staff can also provide you with the ID for a specific bug. The [Cisco Bug Search Tool](#) enables you to filter the bugs so that you only see those in which you are interested.

In addition to being able to search for a specific bug ID, or for all bugs in a product and release, you can filter the open and/or resolved bugs by one or more of the following criteria:

- Last modified date
- Status, such as fixed (resolved) or open
- Severity
- Support cases

You can save searches that you perform frequently. You can also bookmark the URL for a search and email the URL for those search results.



Note If the bug that you have requested cannot be displayed, this may be due to one or more of the following reasons: the bug ID does not exist, the bug does not have a customer-visible description yet, or the bug has been marked Cisco Confidential.

Resolved and Open Bugs in Cisco 4000 Series Integrated Services Routers

Resolved Bugs - Cisco IOS XE 17.8.1a

All resolved bugs for this release are available in the [Cisco Bug Search Tool](#).

Bug ID	Description
CSCwb23043	MACsec not working on subinterfaces using dot1q >255.
CSCvz34380	Multiple Cisco Products Snort Modbus Denial of Service Vulnerability
CSCwa92411	Slowness issues caused by intermittent traffic drop on device ingress from GRE tunnel.
CSCwa92082	RG B2B (Box to Box), Interchassis HA, STBY is stuck in STANDBY COLD-BULK on device.
CSCwa13553	QFP core due to NAT scaling issue.
CSCwa15132	DMVPN over DMVPN with IPSEC - return packets are dropped with BadIpChecksum.
CSCwb11389	NAT translation stops suddenly (ip nat inside doesn't work).
CSCvz98373	ZBFW: FirewallPolicy drops seen with RTSP traffic in steady state.
CSCwa26412	ZBFW: OG lookups are missing from device for optimized policy.
CSCwa66916	SCCP auto-configuration issues with multiple protocols.
CSCvy78501	AAR not working properly as configured SLA classes are not shown under app-route stats.
CSCwa36699	Prefetch CRL download fails.
CSCvz74773	Discrepancies in CLI and GUI interface details (Truncating interface numbers).
CSCvx21819	Keychain MACsec key input value 0 should be restricted.
CSCvt15177	Certificate Signing Request made by IOS-XE never shows the Subject Alternate Name.
CSCwa93930	alarms alarm bfd-state-change syslog command is getting rejected while reconfiguring the device.
CSCwa67398	NAT translations do not work for FTP traffic on device.
CSCwb02851	Device get crashed consistently with memory corruption with PPPoE dailer interface flap.

Bug ID	Description
CSCwa84448	Intersite cloudsec enabled packets with <60 byte across device getting dropped when PTP is enabled.
CSCwa57462	The router reloads unexpectedly due to Cellular CNM process.
CSCwa51443	Incorrect check of the TCP sequence number causing return ICMP error packets to drop (ThousandEyes).
CSCwa78020	ZBFW dropping packets as Input VPN ID set to 0 instead of 99.
CSCvz80101	Policy XML pruning without ConfD dependency.
CSCvz34668	Static mapping for the hub lost on one of the spokes.
CSCwa15085	Router crash due to Stuck Thread.
CSCwa47219	Crash on ipv4_nat_get_all_mapping_stats due to NULL pointer of mapping_hash_table.
CSCwa46760	Memory Utilisation value sent 0.6 always to device; shows wrong value 60%.

Open Bugs - Cisco IOS XE 17.8.1a

All open bugs for this release are available in the [Cisco Bug Search Tool](#).

Bug ID	Description
CSCvz65764	Peer MSS value showing incorrect.
CSCwb23632	Command show sdwan utd file reputation incorrectly shows "Not connected to AMP cloud".
CSCwb40139	Device fails to load bootstrap configuration with '@' in the admin password.
CSCvy31609	%SELINUX-5-MISMATCH: R0/0: audispd: type=AVC msg=audit(1620855824.156:105): avc: denied{read write}
CSCwb11389	NAT translation stops suddenly (ip nat inside doesn't work).
CSCwa84919	"Revocation-check curl none" does not failover.
CSCwb42807	After Enforce Software Version (ZTP) completed successfully, it automatically rolled back.
CSCwb04815	NHRP process taking more CPU with ip nhrp redirect configured.
CSCwa72273	ZBFW dropping return packets post upgrade.
CSCwa64955	Device loses control connections after installing new enterprise hardware wan edge cert.
CSCwa49721	HUB with firewall configured incorrectly dropping return packets when routing between VRFs.
CSCwb38501	Support IGMP on voice VLAN.

Bug ID	Description
CSCwb25137	[XE NAT] Source address translation for multicast traffic fails with route-map.
CSCwb18223	SNMP v2 community name encryption problem.
CSCwb16723	Traceroute not working with NAT.
CSCwb55683	Large number of IPsec tunnel flapping occurs when underlay is restored.
CSCwb12647	Device crash for stuck threads in cpp on packet processing.
CSCwb24123	Registration of spoke fails with dissimilar capabilities to HUB.
CSCvz28950	DMVPN phase 2 connectivity issue between two spokes.
CSCwb21645	NAT traffic gets dropped when default route changes from OMP to NAT DIA route.
CSCwb01477	Logging message "%IOSXE_INFRA-6-PROCPATH_CLIENT_HOG: IOS shim client 'fman stats bipc'".
CSCwa08847	ZBFW policy stops working after modifying the zone pair.
CSCvw50622	NHRP network resolution not working with link-local IPv6 address.
CSCwb29362	Evaluation of IOS-XE for OpenSSL CVE-2022-0778 and CVE-2021-4160.
CSCwb32635	Daemon file is incomplete when running admin-tech.
CSCwa74499	ZBFW seeing the SIP ALG incorrectly dropping traffic and resetting connection.
CSCwa68540	FTP data traffic broken when UTD IPS enabled in both service VPN.
CSCwa48122	SIP OAuth http request to fetch keys from CUCM fails after bootup as interface is down.

Related Documentation

- [Release Notes for Previous Versions of Cisco 4000 Series ISRs](#)
- [Hardware Installation Guide for Cisco 4000 Series Integrated Services Routers](#)
- [Configuration Guides for Cisco 4000 Series ISRs](#)
- [Command Reference Guides for Cisco 4000 Series ISRs](#)
- [Product Landing Page for Cisco 4000 Series ISRs](#)
- [Datasheet for Cisco 4000 Series ISRs](#)
- [Upgrading Field-Programmable Hardware Devices for Cisco 4000 Series ISRs](#)
- [Field Notices](#)
- [Cisco Bulletins](#)

Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco Marketplace](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

Documentation Feedback

To provide feedback about Cisco technical documentation, use the feedback form available in the right pane of every online document.

Troubleshooting

For the most up-to-date, detailed troubleshooting information, see the Cisco TAC website at <https://www.cisco.com/en/US/support/index.html>.

Go to **Products by Category** and choose your product from the list, or enter the name of your product. Look under **Troubleshoot and Alerts** to find information for the issue that you are experiencing.

