



Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Open Caveats – Cisco IOS XE Dublin 17.11.1a, on page 1](#)
- [Resolved Caveats – Cisco IOS XE Dublin 17.11.1a, on page 2](#)
- [Cisco Bug Search Tool, on page 3](#)

Open Caveats – Cisco IOS XE Dublin 17.11.1a

Identifier	Headline
CSCwe42290	netconf intermittent connection issue due to checksum issue.
CSCwe34672	High CPU utilization on ptp_uea process
CSCwe54549	Unable to detect few SFPs.
CSCwe53791	EFP—Low throughput for rate step 900mbps+ when max-throughput command is disabled.
CSCwe38904	Frame loss seen for 64 bytes packet size for rate step 2333333/all kbps.

Resolved Caveats – Cisco IOS XE Dublin 17.11.1a

Identifier	Headline
CSCwc80493	APS - K2 byte not reflecting proper value during LRDI and LAIS conditions.
CSCwd04198	A900-IMASER14A/S: when configurations are pasted in a specific order, line config is missing
CSCwc41115	APS 1+1 Uni - Tx K2 to reflect Rx K1 channel number
CSCwd26330	IMA3G does not generate FEBE's when BPV, P-bit, C-bit error are detected on the T3 port
CSCwc79322	Memory leak on ptpd_uea process
CSCwc76004	Wrong timestamp in TWAMP test packet with PTP active
CSCwd90840	mcast data traffic is getting dropped over vpls
CSCwe27336	Error logs during reload in ASR920-24SZ-M variant
CSCwd28121	E1 loopback syslog and alarm reporting issues
CSCwd38074	Alarm reporting to IOS and L-bit propagation missing with STS1e-ct3-e1 mode
CSCwd48164	EVPN statd resource leak after protocol flaps
CSCwd44817	After router reload E1 framing gets changed to unframed in SDH VC12 mode with channe-group config
CSCwd11926	Need support for dual options in CLI for setting clock rate for x21
CSCwd16666	Only in 3GMS OC3 port with network loop Bert pattern is not syncing
CSCwd40951	CEM getting removed successfully even with wrong T1 number provided from same T3/E3
CSCwc77502	Unexpected reload due to MLDPv6
CSCwd67723	In IMA32D/IMA8D card, sometimes change in E1 controller config(after ctrlr flap)results in IM reboot
CSCwc84627	ASR-920-12SZ-IM goes continous reboot for a PCIE bus error
CSCwd78618	IMASER14A/S does not boot as expected.
CSCwd26357	rs485 with half-duplex configuration when reloaded, it gets into default full-duplex mode

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>

