



## Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



**Note** The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Resolved Caveats – Cisco IOS XE Bengaluru 17.5.1, on page 1](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.5.1, on page 2](#)
- [Cisco Bug Search Tool, on page 2](#)

## Resolved Caveats – Cisco IOS XE Bengaluru 17.5.1

Caveat ID Number	Description
<a href="#">CSCvs50029</a>	Interface flaps and input errors seen with optics GLC-FE-100BX-D in the router
<a href="#">CSCvv21542</a>	Command to change from dynamic to static FAN algorithm for the router
<a href="#">CSCvv23077</a>	config failure is seen from 16_9_4 to 17_3_1 images upgrade
<a href="#">CSCvv42595</a>	REP flapping randomly and frequently due to port down
<a href="#">CSCvv72192</a>	IMA2Z IM, XFP and SFP+ are present and then XFP is removed LED still shows as green
<a href="#">CSCvv99456</a>	ACL entries with FRAGMENT keywords are not working on the router
<a href="#">CSCvw64784</a>	RSP2 CEM ACR: Not able to reuse same clock id on another controller After deleted clock id.

Caveat ID Number	Description
<a href="#">CSCvw93411</a>	Interface counters are not incrementing after 2yrs, 22+ weeks on the router
<a href="#">CSCvx24923</a>	FPGA commit for reload or brom select issue
<a href="#">CSCvr43362</a>	NCS 4202: Fan speed control measures for overheating router

## Open Caveats – Cisco IOS XE Bengaluru 17.5.1

Caveat ID Number	Description
<a href="#">CSCvw38827</a>	Observing RSP2A-64 and RSP2A-128 logs in Cisco RSP2 HA router with CEM
<a href="#">CSCvx42526</a>	A900-IMA2Z IM is impacted during SSO

## Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>