



# Release Notes for Cisco Wireless Controllers and Lightweight Access Points, Cisco Wireless Release 8.8.120.0 and 8.8.125.0

**First Published:** 2019-03-29

**Last Modified:** 2020-10-05

## About the Release Notes

This release notes document describes what is new or changed in this release, instructions to upgrade to this release, and open and resolved caveats for this release. Unless otherwise noted, in this document, Cisco Wireless Controllers are referred to as *controllers*, and Cisco lightweight access points are referred to as *access points* or *APs*.

### Content Hub

Explore the [Content Hub](#), the all-new product documentation portal in which you can use faceted search to locate content that is most relevant to you, create customized PDFs for ready reference, benefit from context-based recommendations, and much more.

Get started with the Content Hub at <https://content.cisco.com/> to craft a personalized documentation experience.

Do provide feedback about your experience with the Content Hub.

## Revision History

**Table 1: Revision History**

Modification Date	Modification Details
October 05, 2020	Removed references to the Bluetooth Low Energy (BLE) USB Dongle feature in the <i>What's New in Release 8.8.120.0</i> section.
July 02, 2019	Included Release 8.8.125.0 <ul style="list-style-type: none"><li>• Updated Open Caveats</li><li>• Updated Resolved Caveats</li></ul>

## Supported Cisco Wireless Controller Platforms

The following Cisco Wireless Controller platforms are supported in this release:

- Cisco 3504 Wireless Controller

- Cisco 5520 Wireless Controller
- Cisco 8540 Wireless Controller
- Cisco Virtual Wireless Controller (vWLC) on the following platforms:
  - VMware vSphere Hypervisor (ESXi) Version 5.x and 6.x
  - Hyper-V on Microsoft Servers 2012 and later versions (Support introduced in Release 8.4)
  - Kernel-based virtual machine (KVM) (Support introduced in Release 8.1. After KVM is deployed, we recommend that you do not downgrade to a Cisco Wireless release that is earlier than Release 8.1.)
- Cisco Wireless Controllers for High Availability for Cisco 3504 WLC, Cisco 5520 WLC, and Cisco 8540 WLC.
- Cisco Mobility Express Solution

## Supported Cisco Access Point Platforms

The following Cisco AP platforms are supported in this release:

- Cisco Aironet 700 Series Access Points
- Cisco Aironet 700W Series Access Points
- Cisco AP803 Integrated Access Point
- Integrated Access Point on Cisco 1100, 1101, and 1109 Integrated Services Routers
- Cisco Aironet 1700 Series Access Points
- Cisco Aironet 1800 Series Access Points
- Cisco Aironet 1810 Series OfficeExtend Access Points
- Cisco Aironet 1810W Series Access Points
- Cisco Aironet 1815 Series Access Points
- Cisco Aironet 1830 Series Access Points
- Cisco Aironet 1850 Series Access Points
- Cisco Aironet 2700 Series Access Points
- Cisco Aironet 2800 Series Access Points
- Cisco Aironet 3700 Series Access Points
- Cisco Aironet 3800 Series Access Points
- Cisco Aironet 4800 Series Access Points
- Cisco ASA 5506W-AP702
- Cisco Aironet 1530 Series Access Points

- Cisco Aironet 1540 Series Access Points
- Cisco Aironet 1560 Series Access Points
- Cisco Aironet 1570 Series Access Points
- Cisco Industrial Wireless 3700 Series Access Points

**Note**

- Cisco AP803 is an integrated access point module on the Cisco 800 Series Integrated Services Routers (ISRs). For more information about the stock-keeping units (SKUs) for the AP803 Cisco ISRs, see: <http://www.cisco.com/c/en/us/products/routers/800-series-routers/brochure-listing.html>.
- For more information about Integrated Access Point on Cisco 1100 ISR, see the product data sheet: <https://www.cisco.com/c/en/us/products/collateral/routers/1000-series-integrated-services-routers-ist/datasheet-c78-739512.html>.

For information about Cisco Wireless software releases that support specific Cisco access point modules, see the "[Software Release Support for Specific Access Point Modules](#)" section in the *Cisco Wireless Solutions Software Compatibility Matrix* document.

## What's New in Release 8.8.125.0

There are no new features that are introduced in this release. For more information about updates in this release, see the Caveats section in this document.

**Note**

For complete listing of all the documentation published for Cisco Wireless Release 8.8, see the Documentation Roadmap:

<https://www.cisco.com/c/en/us/td/docs/wireless/doc-roadmap/doc-roadmap-release-88.html>

## What's New in Release 8.8.120.0

This section provides a brief introduction to the new features and enhancements that are introduced in this release.

**Note**

For complete listing of all the documentation published for Cisco Wireless Release 8.8, see the Documentation Roadmap:

<https://www.cisco.com/c/en/us/td/docs/wireless/doc-roadmap/doc-roadmap-release-88.html>

## Support for –P Domain for Cisco Wireless LAN Solutions

The Cisco Wireless LAN Solution supports –P domain for Japan.

For the current approvals and regulatory domain information see <https://www.cisco.com/c/dam/assets/prod/wireless/wireless-compliance-tool/index.html>



**Caution** Cisco 3802P -Q Japan domain access points fail to join the Cisco controller running 8.8.111.0 or 8.8.120.0 release software. For more information, see [CSCvp05117](#). For further assistance with this issue contact Cisco Technical Assistance Center (TAC).

## Support for Workgroup Bridges (WGB) on Cisco Wave 2 Access Points

In this release, Cisco Wave 2 APs can operate as Workgroup Bridges. The following Wave 2 APs support the WGB mode:

- Cisco Aironet 2800 Series Access Points
- Cisco Aironet 3800 Series Access Points
- Cisco Aironet 1560 Series Access Points

For more information, see the [Cisco Wave 2 Access Points as Workgroup Bridges](#) section in the *Cisco Wireless Controller Configuration Guide*.

## Software Release Types and Recommendations

*Table 2: Release Types*

Release Type	Description	Benefit
Maintenance Deployment (MD)	Software releases that provide bug-fix support and ongoing software maintenance. These releases are categorized as Maintenance Deployment (MD).  These releases are long-living releases with ongoing software maintenance.	Provides you with a software release that offers stability and long support duration with periodic maintenance releases (MRs).
Early Deployment (ED)	Software releases that provide new features and new hardware platform support in addition to bug fixes. These releases are categorized as Early Deployment (ED).  These releases are short-lived releases.	Allows you to deploy the latest features and new hardware platforms or modules.

For detailed release recommendations, see the *Guidelines for Cisco Wireless Software Release Migration Bulletin* at:

<http://www.cisco.com/c/en/us/products/collateral/wireless/8500-series-wireless-controllers/bulletin-c25-730741.html>.

**Table 3: Upgrade Path to Cisco Wireless Release 8.8.x**

Current Software Release	Upgrade Path to Release 8.8.x
8.2.x	You must upgrade to an 8.5.x release and then upgrade to Release 8.8.x.
8.3.x	You must upgrade to an 8.5.x release and then upgrade to Release 8.8.x.
8.4.x	You must upgrade to an 8.5.x release and then upgrade to Release 8.8.x.
8.5.x	You can upgrade directly to Release 8.8.x.
8.6.x	You can upgrade directly to Release 8.8.x.
8.7.x	You can upgrade directly to Release 8.8.x.

## Upgrading Cisco Wireless Release

This section describes the guidelines and limitations that you must be aware of when you are upgrading the Cisco Wireless release and the procedure to upgrade.



### Caution

Before you upgrade to this release, we recommend that you go through the following documents to understand various issues related to Cisco Wave 1 AP flash and the solution to address them:

- Field Notice: <https://www.cisco.com/c/en/us/support/docs/field-notices/703/fn70330.html>
- Understanding Various AP-IOS Flash Corruption Issues: <https://www.cisco.com/c/en/us/support/docs/wireless-mobility/wireless-lan-wlan/213317-understanding-various-ap-ios-flash-corru.html>

## Guidelines and Limitations

- Legacy clients that require RC4 or 3DES encryption types are not supported in Local EAP authentication.
- If you downgrade from Release 8.8.x to Release 8.7, FlexConnect IPv6 ACLs are shown to be in their FlexConnect group.
- If you have an AVC profile with *default-class* setting and you downgrade from Release 8.8.x to an earlier release, the *default-class* setting is still present in the controller, although the earlier releases do not support this setting.

- If you want to downgrade from Release 8.8.x to Release 8.6.101.0 and if you have Wave 2 APs in Flex+Bridge mode, ensure that these APs are changed to Bridge mode before you perform the downgrade; else, the APs will have incorrect configuration after the downgrade process.
- If you downgrade to Release 8.0.140.0 or 8.0.15x.0, and later upgrade to a later release and also have the multiple country code feature configured, then the configuration file could get corrupted. When you try to upgrade to a later release, special characters are added in the country list causing issues when loading the configuration. For more information, see [CSCve41740](#).




---

**Note** Upgrade and downgrade between other releases does not result in this issue.

---

- After downloading the new software to the Cisco APs, it is possible that a Cisco AP may get stuck in an upgrading image state. In such a scenario, it might be necessary to forcefully reboot the controller to download a new controller software image or to reboot the controller after the download of the new controller software image. You can forcefully reboot the controller by entering the **reset system forced** command.
- It is not possible to download some of the older configurations from the controller because of the Multicast and IP address validations. See the "Restrictions on Configuring Multicast Mode" section in the *Cisco Wireless Controller Configuration Guide* for detailed information about platform support for global multicast and multicast mode.
- When a client sends an HTTP request, the controller intercepts it for redirection to the login page. If the HTTP GET request that is intercepted by the controller is longer than 2000 bytes, the controller drops the packet. Track the Caveat ID [CSCuy81133](#) for a possible enhancement to address this restriction.
- When downgrading from one release to an earlier release, you might lose the configuration from your current release. The workaround is to reload the previous controller configuration files that are saved in the backup server, or to reconfigure the controller.
- When you upgrade controller to an intermediate release, wait until all the APs that are associated with the controller are upgraded to the intermediate release before you install the latest controller software. In large networks, it can take some time to download the software on each AP.
- You can upgrade to a new release of the controller software or downgrade to an earlier release even if FIPS is enabled.
- When you upgrade to the latest software release, the software on the APs associated with the controller is also automatically upgraded. When an AP is loading software, each of its LEDs blinks in succession.
- Controllers support standard SNMP MIB files. MIBs can be downloaded from the software download page on Cisco.com.
- The controller software that is factory-installed on your controller and is automatically downloaded to the APs after a release upgrade and whenever an AP joins a controller. We recommend that you install the latest software version available for maximum operational benefit.
- Ensure that you have a TFTP, HTTP, FTP, or SFTP server available for the software upgrade. Follow these guidelines when setting up a server:
  - Ensure that your TFTP server supports files that are larger than the size of controller software image. Some TFTP servers that support files of this size are tftpd32 and the TFTP server within Cisco

Prime Infrastructure. If you attempt to download the controller software image and your TFTP server does not support files of this size, the following error message appears:

```
TFTP failure while storing in flash
```

- If you are upgrading through the distribution system network port, the TFTP or FTP server can be on the same subnet or a different subnet because the distribution system port is routable.
- The controller Bootloader stores a copy of the active primary image and the backup image. If the primary image becomes corrupted, you can use the Bootloader to boot with the backup image.

With the backup image stored before rebooting, from the **Boot Options** menu, choose **Option 2: Run Backup Image** to boot from the backup image. Then, upgrade with a known working image and reboot controller.

- You can control the addresses that are sent in the Control and Provisioning of Wireless Access Points (CAPWAP) discovery responses when NAT is enabled on the Management Interface, using the following command:

```
config network ap-discovery nat-ip-only {enable | disable}
```

The following are the details of the command:

**enable**—Enables use of NAT IP only in a discovery response. This is the default. Use this command if all the APs are outside the NAT gateway.

**disable**—Enables use of both NAT IP and non-NAT IP in a discovery response. Use this command if APs are on the inside and outside the NAT gateway, for example, Local Mode and OfficeExtend APs are on the same controller.




---

**Note** To avoid stranding of APs, you must disable AP link latency (if enabled) before you use the disable option in the **config network ap-discovery nat-ip-only** command. To disable AP link latency, use the **config ap link-latency disable all** command.

---

- Do not power down controller or any AP during the upgrade process. If you do this, the software image might get corrupted. Upgrading controller with a large number of APs can take as long as 30 minutes, depending on the size of your network. However, with the increased number of concurrent AP upgrades supported, the upgrade time should be significantly reduced. The APs must remain powered, and controller must not be reset during this time.
- After you perform the following functions on controller, reboot it for the changes to take effect:
  - Enable or disable LAG.
  - Enable a feature that is dependent on certificates (such as HTTPS and web authentication).
  - Add a new license or modify an existing license .




---

**Note** Reboot is not required if you are using Right-to-Use licenses.

---

- Increase the priority of a license.

- Enable HA.
  - Install the SSL certificate.
  - Configure the database size.
  - Install the vendor-device certificate.
  - Download the CA certificate.
  - Upload the configuration file.
  - Install the Web Authentication certificate.
  - Make changes to the management interface or the virtual interface.
- From Release 8.3 or a later release, ensure that the configuration file that you back up does not contain the < or > special characters. If either of the special characters is present, the download of the backed up configuration file fails.

## Upgrading Cisco Wireless Software (GUI)

### Procedure

- 
- Step 1** Upload your controller configuration files to a server to back up the configuration files.
- Note** We highly recommend that you back up your controller configuration files prior to upgrading the controller software.
- Step 2** Follow these steps to obtain controller software:
- a) Browse to the Software Download portal at: <https://software.cisco.com/download/home>.
  - b) Search for the controller model.
  - c) Click **Wireless LAN Controller Software**.
  - d) The software releases are labeled as described here to help you determine which release to download. Click a controller software release number:
    - Early Deployment (ED)—These software releases provide new features and new hardware platform support as well as bug fixes.
    - Maintenance Deployment (MD)—These software releases provide bug fixes and ongoing software maintenance.
    - Deferred (DF)—These software releases have been deferred. We recommend that you migrate to an upgraded release.
  - e) Click the filename `<filename.aes>`.
  - f) Click **Download**.
  - g) Read the Cisco End User Software License Agreement and click **Agree**.
  - h) Save the file to your hard drive.
  - i) Repeat steps *a* through *h* to download the remaining file.
- Step 3** Copy the controller software file `<filename.aes>` to the default directory on your TFTP, FTP, or SFTP server.



- Step 4** (Optional) Disable the controller 802.11 networks.
- Note** For busy networks, controllers on high utilization, and small controller platforms, we recommend that you disable the 802.11 networks as a precautionary measure.
- Step 5** Choose **Commands** > **Download File** to open the **Download File to Controller** page.
- Step 6** From the **File Type** drop-down list, choose **Code**.
- Step 7** From the **Transfer Mode** drop-down list, choose **TFTP**, **FTP**, or **SFTP**.
- Step 8** In the **IP Address** field, enter the IP address of the TFTP, FTP, or SFTP server.
- Step 9** If you are using a TFTP server, the default value of 10 retries for the **Maximum Retries** field, and 6 seconds for the **Timeout** field should work correctly without any adjustment. However, you can change these values, if required. To do so, enter the maximum number of times the TFTP server attempts to download the software in the **Maximum Retries** field and the amount of time (in seconds) for which the TFTP server attempts to download the software, in the **Timeout** field.
- Step 10** In the **File Path** field, enter the directory path of the software.
- Step 11** In the **File Name** field, enter the name of the software file *<filename.aes>*.
- Step 12** If you are using an FTP server, perform these steps:
- In the **Server Login Username** field, enter the username with which to log on to the FTP server.
  - In the **Server Login Password** field, enter the password with which to log on to the FTP server.
  - In the **Server Port Number** field, enter the port number on the FTP server through which the download occurs. The default value is 21.
- Step 13** Click **Download** to download the software to the controller.
- A message indicating the status of the download is displayed.
- Note** Ensure that you choose the **File Type** as **Code** for both the images.
- Step 14** After the download is complete, click **Reboot**.
- Step 15** If you are prompted to save your changes, click **Save and Reboot**.
- Step 16** Click **OK** to confirm your decision to reboot the controller.
- Step 17** If you have disabled the 802.11 networks, reenable them.
- Step 18** (Optional) To verify that the controller software is installed on your controller, on the controller GUI, click **Monitor** and view the **Software Version** field under **Controller Summary**.

---

## CIMC Utility Upgrade for 5520 and 8540 Controllers

The AIR-CT5520-K9 and AIR-CT8540-K9 controller models are based on Cisco UCS server C series, C220 and C240 M4 respectively. These controller models have CIMC utility that can edit or monitor low-level physical parts such as power, memory, disks, fan, temperature, and provide remote console access to the controllers.

We recommend that you upgrade the CIMC utility to Version 3.0(4d) that has been certified to be used with these controllers. Controllers that have older versions of CIMC installed are susceptible to rebooting without being able to access FlexFlash, with the result that the manufacturing certificates are unavailable, and thus SSH and HTTPS connections will fail, and access points will be unable to join. See: [CSCvo33873](#).

The CIMC 3.0(4d) images are available at the following locations

**Table 4: CIMC Utility Software Image Information**

Controller	Link to Download the CIMC Utility Software Image
Cisco 5520 Wireless Controller	<a href="https://software.cisco.com/download/home/286281345/type/283850974/release/3.0%25284d%2529">https://software.cisco.com/download/home/286281345/type/283850974/release/3.0%25284d%2529</a>
Cisco 8540 Wireless Controller	<a href="https://software.cisco.com/download/home/286281356/type/283850974/release/3.0%25284d%2529">https://software.cisco.com/download/home/286281356/type/283850974/release/3.0%25284d%2529</a>

For information about upgrading the CIMC utility, see the "Updating the Firmware on Cisco UCS C-Series Servers" chapter in the *Cisco Host Upgrade Utility 3.0 User Guide*:

[https://www.cisco.com/c/en/us/td/docs/unified\\_computing/ucs/c/sw/lomug/2-0-x/3\\_0/b\\_huu\\_3\\_0\\_1/b\\_huu\\_2\\_0\\_13\\_chapter\\_011.html](https://www.cisco.com/c/en/us/td/docs/unified_computing/ucs/c/sw/lomug/2-0-x/3_0/b_huu_3_0_1/b_huu_2_0_13_chapter_011.html)

### Updating Firmware Using the Update All Option

This section mentions specific details when using CIMC utility with Cisco 5520 or 8540 controllers. For general information about the software and UCS chassis, see *Release Notes for Cisco UCS C-Series Software, Release 3.0(4)* at:

[https://www.cisco.com/c/en/us/td/docs/unified\\_computing/ucs/release/notes/b\\_UCS\\_C-Series\\_Release\\_Notes\\_3\\_0\\_4.html](https://www.cisco.com/c/en/us/td/docs/unified_computing/ucs/release/notes/b_UCS_C-Series_Release_Notes_3_0_4.html)

**Table 5: Open Caveats for Release 3.0(4d)**

Caveat ID	Description
<a href="#">CSCvj80941</a>	After upgrading CIMC to 3.04d, only after power reset, UCS-based controller is coming up.
<a href="#">CSCvj80915</a>	Not able to logon to the CIMC GUI with the username and password that are configured from the controller.

Table 6: Resolved Caveats for Release 3.0(4d)

Caveat ID	Description
<a href="#">CSCvd86049</a>	<p><b>Symptom:</b> The system will stop working or reboot during OS operation with PROCHOT, MEMHOT, and DMI Timeout-related events reported in the System Event Log (SEL).</p> <p><b>Conditions:</b> C220-M4 or C240-M4</p> <p><b>Workaround:</b> No workaround is available.</p> <p>This bug fix changes the default BIOS option for ASPM (Active State Power Management) from 'L1 only' to 'Disabled', and the ASPM setting can no longer be modified. This change was made to help increase system stability and eliminate some system crash scenarios.</p>
<a href="#">CSCvf78458</a>	<p><b>Symptom:</b> The system will stop working or reboot during OS operation with PROCHOT, MEMHOT, and DMI Timeout-related events reported in the System Event Log (SEL).</p> <p><b>Conditions:</b> C220-M4 or C240-M4</p> <p><b>Workaround:</b> No workaround is available.</p> <p>This bug fix changes the BIOS option "Package C-State limit" default value from C6 Retention to C0/C1 to help increase system stability and eliminate some crash scenarios.</p> <p>Once upgraded, reset the BIOS settings to default or manually change Package C-State limit to C0/C1.</p>

## Interoperability with Other Clients

This section describes the interoperability of controller software with other client devices.

The following table describes the configuration used for testing the client devices.

Table 7: Test Bed Configuration for Interoperability

Hardware or Software Parameter	Hardware or Software Configuration Type
Release	8.8.x.
Cisco Wireless Controller	Cisco 5520 Wireless Controller
Access Points	AIR-CAP3802E-B-K9, AIR-AP1852E-B-K9

Hardware or Software Parameter	Hardware or Software Configuration Type
Radio	802.11ac, 802.11a, 802.11g, 802.11n (2.4 GHz or 5 GHz)
Security	Open, PSK (WPA-TKIP-WPA2-AES), 802.1X (WPA-TKIP-WPA2-AES) (EAP-FAST, EAP-TLS)
RADIUS	Cisco ACS 5.3, Cisco ISE 2.2, Cisco ISE 2.3
Types of tests	Connectivity, traffic (ICMP), and roaming between two APs

The following table lists the client types on which the tests were conducted. Client types included laptops, handheld devices, phones, and printers.

**Table 8: Client Types**

Client Type and Name	Driver / Software Version
<b>Laptops</b>	
Acer Aspire 15 Windows 8 Home	Qc Atheros Qca9377 11.0.0.492
Acer Aspire E15 Windows 8	Qc Atheros Qca9377 15.1.1.1
Acer Aspire E 15 Windows 8.1	QC Atheros Qca9377 11.0.0.492
Acer Aspire E15 Windows 8.1 Pro	Qc Atheros Qca9377 11.0.0.492
Dell Inspiron 15 7569 Windows 10 Home	Ntel Ac 3165 18.32.0.5
Dell Latitude 6430 Windows 8.1 Pro	Intel 6205w8 15.16.0.2
Dell Latitude E5430 Windows 7	Intel Centrino N 6205 15.17.0.1
Dell Latitude E5450 Windows 7 Professional	Intel 7260 18.33.6.2
Dell Latitude E5540 Windows 7	Intel Dualband Ac7260 1.566.0.0
Dell Latitude E6430 Windows 7 Professional	Intel Centrino Ultn6300 15.9.2.1
Dell Latitude E6430 Windows 7 Professional	Intel 6250 15.11.0.7
Dell Latitude E6430 Windows 7 Professional	Intel 3160 6.30.223.215
Dell Latitude E7450 Windows 7 Professional	Broadcom 1560 15.1.1.1
Dell Latitude Windows 8.1 Pro	Intel Ac7260 18.33.3.2
Fujitsu Lifebook E556 Windows 10 Pro	Intel 8260 11.0.0.492
Lenovo Yoga 460 Windows 10 Pro	Intel Ac8260 19.1.0.4
Macbook Air Mac OS Sierra 10.12.3	Broadcom Bcm43xx 1.0 6.30.225.29.1
Macbook Air MacOS Sierra 10.12.6	Broadcom Bcm43xx 1.0 7.21.171.68.1a4
Macbook Air OS X Yosemite (10.10.5)	Broadcom Bcm43xx 1.0 7.15.166.24.3
Macbook Mac OS Sierra 10.12 Beta	Broadcom Bcm43xx 1.0 7.21.149.34.1a7

<b>Client Type and Name</b>	<b>Driver / Software Version</b>
Macbook Pro Mac OS Sierra 10.12.4	Broadcom Bcm43xx 1.0 7.21.171.68.1a4
Macbook Pro OS X 10.8.5	Broadcom Bcm43xx 1.0 5.106.98.100.17
Macbook Pro Retina Mac OS Sierra 10.12.3	Broadcom Bcm43xx 1.0 7.15.166.24.3
<b>Tablets</b>	
Apple iPad	iOS 9.3.1
Apple iPad mini	iOS 12.0
Apple iPad mini 2	iOS 10.3.1
Apple iPad Air	iOS 10.1.1
Apple iPad Air 2	iOS 10.2.1
<b>Mobile Phones</b>	
Apple iPhone 4S	iOS 8.0
Apple iPhone 5	iOS 10.3.1
Apple iPhone 5C	iOS 9.3.2
Apple iPhone 6 Plus	iOS 12.0
Apple iPhone SE	iOS 10.3.1
AT100	Toshiba Android 4.0.4
Cisco 7925G-EX	CP7925G-1.4.8.4.LOADS
Cisco 7926G	CP7925G-1.4.8.4.LOADS
Cisco 8821	sip8821.11-0-4-14
ET1	Android VERSION 2.3.4
ET5	Android 5.1.1
LG-D855	LG Android 5.0
Mediapad X1 7.0	Huawei Android 4.4.2
Moto X 2nd Gen	Motorola Android 5.0
One Plus One	One Plus Android 4.3
One Plus Three	One Plus Android 6.0.1
Samsung Galaxy S4	Samsung Android 4.2.2
Samsung Galaxy S4	Samsung Android 5.0.1
Samsung Galaxy S6	Samsung Android 7.0
Samsung Galaxy S6	Samsung Android 6.0.1
Samsung Galaxy S8	Samsung Android 7.0
Samsung Tab Pro	Samsung Android 4.4.2

Client Type and Name	Driver / Software Version
SM-P600	Samsung Android 4.4.2
SM-T520	Samsung Android 4.4.2
TC510K	Zebra Android 6.0.1
TC8000	Zebra Android 4.4.3
8742	Spectralink Android 5.1.1
8744	Spectralink Android 5.1.1 2.5.0

## Key Features Not Supported in Cisco WLC Platforms

This section lists the features that are not supported on various Cisco WLC platforms:



**Note** In a converged access environment that has Cisco WLCs running AireOS code, High Availability Client SSO and native IPv6 are not supported.

### Key Features Not Supported in Cisco 3504 WLC

- Cisco WLAN Express Setup Over-the-Air Provisioning
- Mobility controller functionality in converged access mode
- VPN Termination (such as IPsec and L2TP)

### Key Features Not Supported in Cisco 5520 and 8540 WLCs

- Internal DHCP Server
- Mobility controller functionality in converged access mode
- VPN termination (such as IPsec and L2TP)
- Fragmented pings on any interface

### Key Features Not Supported in Cisco Virtual WLC

- Cisco Umbrella
- Software-defined access
- Domain-based ACLs
- Internal DHCP server
- Cisco TrustSec
- Access points in local mode

- Mobility or Guest Anchor role
- Wired Guest
- Multicast



---

**Note** FlexConnect locally switched multicast traffic is bridged transparently for both wired and wireless on the same VLAN. FlexConnect APs do not limit traffic based on IGMP or MLD snooping.

---

- FlexConnect central switching in large-scale deployments



---

**Note**

- FlexConnect central switching is supported in only small-scale deployments, wherein the total traffic on Cisco WLC ports is not more than 500 Mbps.
- FlexConnect local switching is supported.

---

- Central switching on Microsoft Hyper-V deployments
- AP and Client SSO in High Availability
- PMIPv6
- Datagram Transport Layer Security (DTLS)
- EoGRE (Supported only in local switching mode)
- Workgroup bridges
- Client downstream rate limiting for central switching
- SHA2 certificates
- Cisco WLC integration with Lync SDN API
- Cisco OfficeExtend Access Points

## Key Features Not Supported in Access Point Platforms

This section lists the features that are not supported on various Cisco Aironet AP platforms:

### Key Features Not Supported in Cisco Aironet 1800i, 1810 OEAP, 1810W, 1815, 1830, 1850, 2800, 3800, and 4800 Series APs

For detailed information about feature support on Cisco Aironet Wave 2 APs, see:

[https://www.cisco.com/c/en/us/td/docs/wireless/controller/technotes/8-7/b\\_feature\\_matrix\\_for\\_802\\_11ac\\_wave2\\_access\\_points.html](https://www.cisco.com/c/en/us/td/docs/wireless/controller/technotes/8-7/b_feature_matrix_for_802_11ac_wave2_access_points.html).

Table 9: Key Features Not Supported in Cisco Aironet 1800i, 1810 OEAP, 1810W, 1815, 1830, 1850, 2800, 3800, and 4800 Series APs

Operational Modes	<ul style="list-style-type: none"> <li>• Autonomous Bridge mode</li> <li>• Mesh mode</li> <li>• LAG behind NAT or PAT environment</li> </ul>
Protocols	<ul style="list-style-type: none"> <li>• Full Cisco Compatible Extensions (CCX) support</li> <li>• Rogue Location Discovery Protocol (RLDP)</li> <li>• Telnet</li> <li>• Internet Group Management Protocol (IGMP)v3</li> </ul>
Security	<ul style="list-style-type: none"> <li>• CKIP, CMIC, and LEAP with Dynamic WEP</li> <li>• Static WEP for CKIP</li> <li>• WPA2 + TKIP</li> </ul> <p><b>Note</b> WPA +TKIP and TKIP + AES protocols are supported.</p>
Quality of Service	Cisco Air Time Fairness (ATF)
FlexConnect Features	<ul style="list-style-type: none"> <li>• Split Tunneling</li> <li>• PPPoE</li> <li>• Multicast to Unicast (MC2UC)</li> </ul> <p><b>Note</b> VideoStream is supported</p> <ul style="list-style-type: none"> <li>• Traffic Specification (TSpec) <ul style="list-style-type: none"> <li>• Cisco Compatible eXtensions (CCX)</li> <li>• Call Admission Control (CAC)</li> </ul> </li> <li>• VSA/Realm Match Authentication</li> <li>• SIP snooping with FlexConnect in local switching mode</li> </ul>



**Note** For Cisco Aironet 1850 Series AP technical specifications with details on currently supported features, see the [Cisco Aironet 1850 Series Access Points Data Sheet](#).



## Key Features Not Supported in Cisco Aironet 1800i, 1810 OEAP, and 1810W Series APs

*Table 10: Key Features Not Supported in Cisco Aironet 1800i, 1810 OEAP and 1810W Series APs*

Operational Modes	<ul style="list-style-type: none"> <li>• Workgroup Bridge (WGB) mode</li> <li>• Mobility Express</li> </ul>
FlexConnect Features	Local AP authentication
Location Services	Data RSSI (Fast Locate)

## Key Features Not Supported in Cisco Aironet 1830, 1850, and 1815 Series APs

*Table 11: Key Features Not Supported in Cisco Aironet 1830, 1850, and 1815 Series APs*

Operational Modes	<ul style="list-style-type: none"> <li>• Workgroup Bridge (WGB) mode</li> <li>• Mobility Express is not supported in Cisco 1815t APs.</li> </ul>
FlexConnect Features	Local AP Authentication
Location Services	Data RSSI (Fast Locate)

## Key Features Not Supported in Mesh Networks

- Load-based call admission control (CAC). Mesh networks support only bandwidth-based CAC or static CAC
- High availability (Fast heartbeat and primary discovery join timer)
- AP acting as supplicant with EAP-FASTv1 and 802.1X authentication
- AP join priority (Mesh APs have a fixed priority)
- Location-based services

## Key Features Not Supported in Cisco Aironet 1540 Mesh APs

- Dynamic Mesh backhaul data rate.



**Note** We recommend that you keep the Bridge data rate of the AP as auto.

- Background scanning
- Noise-tolerant fast convergence

## Key Features Not Supported on Cisco Aironet 1560 APs

- MAC Authentication FlexConnect Local Authentication
- Noise-tolerant fast convergence
- Static WEP

## Caveats

### Open Caveats

**Table 12: Open Caveats for Release 8.8.125.0**

Caveat ID Number	Description
<a href="#">CSCvk57014</a>	AP: Sometimes creates empty radio core files without any information
<a href="#">CSCvm63736</a>	Erratic multicast throughput
<a href="#">CSCvn87656</a>	Cisco Wave 2 APs reloads unexpectedly in the context of vendor driver @ click_packet_type_event_hook
<a href="#">CSCvo51266</a>	EAP TLS failure with WGB
<a href="#">CSCvo59784</a>	AP usage shows discrepancy through pages
<a href="#">CSCvp43376</a>	IP Phone cannot associate after modify WLAN configure/profile, delete client, idle timeout etc.
<a href="#">CSCvp68494</a>	Cisco 2800 AP reloads unexpectedly due to exception when having MU-MIMO clients in network

**Table 13: Open Caveats for Release 8.8.120.0**

Caveat ID Number	Description
<a href="#">CSCvb70551</a>	Cisco Wave 2 APs reboot due to kernel panic-not syncing: Out of Memory
<a href="#">CSCvg50680</a>	Cisco 3800/2802/1562 AP still advertise RSN IE after WLAN is changed to OPEN
<a href="#">CSCvg96533</a>	Cisco 3800, 2800 APs FIQ/NMI reset
<a href="#">CSCvi02106</a>	Cisco 2800, 3800, 1560 APs: when connected to a Cisco Switch CDP-4-DUPLEX_MISMATCH log is seen
<a href="#">CSCvi10888</a>	Intermittently stops transmitting Beacon for 12 and 85 seconds
<a href="#">CSCvj30568</a>	Cisco 1832 AP stopped working due to beacon stuck
<a href="#">CSCvj79841</a>	Cisco 3802 AP unexpected reboot
<a href="#">CSCvj81526</a>	AP name is "AP0000.0000.0000" on new/factory reset APs

Caveat ID Number	Description
<a href="#">CSCvk42225</a>	Max client reached on AP. Sending association response failure with reason code 17
<a href="#">CSCvm11861</a>	Cisco Wave 2 APs FIQ/NMI reloads unexpectedly on the radio driver
<a href="#">CSCvm13837</a>	vWLC reloads unexpectedly while fetching memory statistics during longevity run
<a href="#">CSCvm33978</a>	Apple iPad devices are getting profiled as Apple device
<a href="#">CSCvm58235</a>	Cisco 2802E AP with DART connector - custom RF profile not always applied properly to XOR
<a href="#">CSCvm63975</a>	WLC loses config if specific countries are enabled together
<a href="#">CSCvm65411</a>	Cisco 2700 AP radio resets with FC71 code
<a href="#">CSCvm68341</a>	Cisco controller is sending duplicate interim accounting packets to ISE
<a href="#">CSCvm72007</a>	Incorrect VLAN mapping when using MAC filtering and PSK
<a href="#">CSCvm81901</a>	Cisco 3800 AP does not acknowledge the client frames
<a href="#">CSCvn14292</a>	Cisco 3800 AP reloads unexpectedly on 8.2.170.2
<a href="#">CSCvn15777</a>	Cisco 5508 WLC reloads unexpectedly with high CPU util on emWeb process
<a href="#">CSCvn37957</a>	WLC FTIE not saved sending Association Response FT 802.11r
<a href="#">CSCvn41324</a>	Standby WLC keeps unjoined AP statistics entry even if statistics is cleared on Active WLC
<a href="#">CSCvn43971</a>	AAA override pmk-cache can result in unwanted L3 inter-controller roaming
<a href="#">CSCvn48626</a>	CAP1552H 15.3(3)JD6 Autonomous Status LED not lighting. It is unlit (Off).
<a href="#">CSCvn56211</a>	Cisco 702W AP radio resets, tracebacks and other radio buffer errors
<a href="#">CSCvn57308</a>	WLC/AP do not send M1 message to clients
<a href="#">CSCvn59061</a>	Cisco 8510 controller on on 8.3.141.10 DP crash at broffu_fp_dapi_cmd.c:4588
<a href="#">CSCvn59160</a>	WLC logs "NMSP cloud service update. Received CMX service Link Check" even when CMX is not used
<a href="#">CSCvn62176</a>	Cisco 3802 series APs unable to associate clients when using UNII-1 Channels
<a href="#">CSCvn89221</a>	Unable to add netuser. Error message displayed - User already exists in the list of Management users
<a href="#">CSCvo09245</a>	WLC sends incomplete Accounting packets using client's MAC as username after Flexconnect AP failover
<a href="#">CSCvo18656</a>	Several AP configurations are changed after switchover
<a href="#">CSCvo18663</a>	'Native VLAN Inheritance' is changed after controller switchover

Caveat ID Number	Description
<a href="#">CSCvo24010</a>	2.4 GHz Rogue clients stay in containment pending
<a href="#">CSCvo37232</a>	WLC - certain WLANs configuration is not listed in 'show run-config'
<a href="#">CSCvo42865</a>	Cisco controller reloads unexpectedly at task "TransferTask" while uploading WebAdmin certificate
<a href="#">CSCvo55603</a>	Cisco 4800 series access points not requesting UPoE power when connected to Cisco 94xx switch.
<a href="#">CSCvo64729</a>	vWLC on Microsoft Hyper-V not passing centrally switched traffic
<a href="#">CSCvo74306</a>	Cisco 1815W APs: Per-user BW contract not working with web policy
<a href="#">CSCvo84924</a>	Cisco Wave 2 AP unexpectedly reloads frequently after upgrading to 8.8.111.0
<a href="#">CSCvo87763</a>	Cisco 1815 ME AP dropping DHCP behind RLAN
<a href="#">CSCvo89811</a>	WLC CLI : Index 4 is missing in "config ap ethernet "
<a href="#">CSCvo90764</a>	AP4800: AP recurrent unexpected reloads found in multiple places
<a href="#">CSCvo94878</a>	Cisco Wave 2 APs: Reloads unexpectedly when PC is at find_get_entries+0x64/0x15c
<a href="#">CSCvp01439</a>	Cisco 1815 AP leaking RLAN VLAN traffic when port looped
<a href="#">CSCvp05117</a>	P-Q domain Wave 2 APs cannot join the controller and the AP reloads unexpectedly

## Resolved Caveats

*Table 14: Resolved Caveats in Release 8.8.125.0*

Caveat ID Number	Description
<a href="#">CSCvj69298</a>	Data Plane reloads unexpectedly due to RPE/Double bit errors
<a href="#">CSCvj79841</a>	Cisco 3802 AP reboots unexpectedly
<a href="#">CSCvk79765</a>	apstatEngineMsgQ MSGQ_RUNNING_HIGH or MSGQ_SEND_FAILED Queue Utilization Issues
<a href="#">CSCvk79850</a>	Extend 'config flexconnect arp-cache' CLI support to fabric AP
<a href="#">CSCvm18273</a>	Handling of Cisco 702W AP reloads due to memory limitation from 8.5release and other memleak fixes
<a href="#">CSCvm65360</a>	Cisco controller redirects to internal webauth login page after successful external webauth login
<a href="#">CSCvm81901</a>	Cisco 3800 AP does not acknowledge the client frames
<a href="#">CSCvm88213</a>	Cisco Wave 2 APs do not forward DHCP Offer OTA to TKIP client

Caveat ID Number	Description
<a href="#">CSCvm91854</a>	Cisco 8540 controller becomes inaccessible with systemDb corruption
<a href="#">CSCvn53435</a>	C3702AP on 8.5.140.0: %DOT11-2-RADIO_RX_BUF: 1E72C72C leads to unexpected reloads with reason 44
<a href="#">CSCvo28124</a>	Local switching WLANs is changed to central switching in some scenarios
<a href="#">CSCvp05117</a>	P-Q domain Wave 2 APs cannot join the controller and the AP reloads unexpectedly
<a href="#">CSCvp05891</a>	In AP SSO, FT 802.1x/PSK auth break in Flex Wave 2 AP when mobility MAC different from burned in MAC
<a href="#">CSCvp26465</a>	Cisco AireOS HA: The mobility hash keys are not getting synced UP in AireOS
<a href="#">CSCvp35686</a>	Cisco 5508/ 5520 controller running 8.5.140.0 dropping all wireless clients
<a href="#">CSCvp36540</a>	Cisco 2802, 3802 APs: System memory is running low
<a href="#">CSCvp49290</a>	Cisco 5520 controller running 8.8 release: LSC device certificate cannot be installed
<a href="#">CSCvp52994</a>	WLC fails to learn AAA VLAN, fails to send Central Switched VLAN on second Add mobile
<a href="#">CSCvp57188</a>	Cisco 4800 AP: memory leak in kmalloc-512 and kmalloc-1024 in 8.8.X.X code
<a href="#">CSCvp64806</a>	AP reloads due to power fluctuations when connected to CAT9400 switches.
<a href="#">CSCvp71391</a>	WLC lobby ambassador GUI become unresponsive with Form submit action failed due to Cross Site Attack
<a href="#">CSCvp73499</a>	Cisco 3800 AP transmits ACK at lower RSSI
<a href="#">CSCvp91931</a>	702 AP as WGB keeps sending a new association req every 7 seconds when connected to 2800, 3800 APs

**Table 15: Resolved Caveats for 8.8.120.0**

Caveat ID Number	Description
<a href="#">CSCvi06408</a>	Wave 1 AP failed to send DHCP packet to wired side under VLAN Override
<a href="#">CSCvi77141</a>	HA_send_usmDbSpamSetRadSlotBand, ErrType:Apply Config failed on Standby
<a href="#">CSCvi82746</a>	Cisco controller reloads unexpectedly with Task Name SISF BT Process
<a href="#">CSCvi84734</a>	Cisco 702w AP: client intermittently cannot connect- decrypt errors
<a href="#">CSCvj48316</a>	AP3700: process "QoS stats process" causes unexpected reloads
<a href="#">CSCvj72136</a>	Cisco 2800, 3800 APs loose its ability to reach the default gateway
<a href="#">CSCvj80129</a>	Cisco Wave 2 AP uses invalid CAPWAP-Data keep-alive source port
<a href="#">CSCvj97430</a>	Mobility Express AP - Loop detected that causes AP reboot

Caveat ID Number	Description
<a href="#">CSCvj97602</a>	WLC Client RSSI and SNR values to be updated as part of Assoc & reassoc request processing
<a href="#">CSCvk00885</a>	DHCP Address Assignment gets disabled after any successive WLAN config in WLC GUI
<a href="#">CSCvk36887</a>	Some clients cannot associate because their entry is not getting deleted at the WLC.
<a href="#">CSCvk41603</a>	WLC - Unable to add/delete DCA channels in RF-Profile while Channel width configured as 80 MHz.
<a href="#">CSCvk68688</a>	Client traffic seen on the 5508 Standby Hot WLC causing MAC flapping on switch
<a href="#">CSCvk76386</a>	Reaper Reset due to too much CPU while SW Watchdog is disabled - various processes
<a href="#">CSCvk79597</a>	Frequent DFS detection
<a href="#">CSCvm11060</a>	WLC: After soft-roam of client, client is not able to see new Apple TV from associated AP-Grp VLAN
<a href="#">CSCvm51648</a>	Cisco WLC open auth guest clients unable to pass traffic and PEM state struck in STATICIP_NOL3SEC
<a href="#">CSCvm54487</a>	WLC sends Accounting Start without Framed-IP-address while WLAN has DHCP required
<a href="#">CSCvm62619</a>	Cisco controller reloads unexpectedly with task emweb after 'debug flexconnect' command is typed
<a href="#">CSCvm65858</a>	2800 APs using Flexible Radio Assignment has admin status and clean air status down
<a href="#">CSCvm69246</a>	Cisco controller applying wrong interface policy to re-associated client after SSO
<a href="#">CSCvm73244</a>	AP3800 in sniffer mode not capturing ACK,RTS in 8.7 and 8.8 <a href="#">CSCvf74377</a>
<a href="#">CSCvm80592</a>	Cisco 2800 AP reloads unexpectedly with ERROR TAMD device 'ap-tam' heartbeat failure
<a href="#">CSCvm83223</a>	AP1832: Kernel panic: PC is at _raw_spin_lock+0x44/0x84
<a href="#">CSCvm84941</a>	Cisco 1600, 1700 APs: memory leak due to packets accumulation
<a href="#">CSCvm90337</a>	Cisco 18xx APs unexpectedly reload due to 'radio failure(radio recovery failed)'
<a href="#">CSCvn03560</a>	Decrypt errors seen on Cisco 702 AP
<a href="#">CSCvn03915</a>	After controller upgrades it reloads unexpectedly due to kernel panic
<a href="#">CSCvn04046</a>	Cisco 2800,3800 AP does not map the DSCP to the correct WMM UP Value for FlexConnect Local Switching
<a href="#">CSCvn05881</a>	Cisco Phone 8821 has roaming issues with 2802/3802 access points MIC mismatch

Caveat ID Number	Description
<a href="#">CSCvn07126</a>	Cisco FlexConnect - Cisco 2802 AP's lowers the priority UP on QoS on the downlink transmit
<a href="#">CSCvn11947</a>	Cisco 1815w:RLAN port traffic will get stuck at TX direction after end device restarts several times
<a href="#">CSCvn13314</a>	Cisco 2802, 3802 APs: Default SSID "IP Cheetah" broadcasted during AP boot up
<a href="#">CSCvn17267</a>	702AP: WGB is disconnectig from root AP 'parent lost: Too many retries' RTS when root AP is offchanl
<a href="#">CSCvn18615</a>	APs could not authenticate with ISE 2.5.0.311 when EAP method is set as EAP-FAST
<a href="#">CSCvn20446</a>	Wireless client moves from local switching SSID to central switching SSID DHCP traffic gets dropped
<a href="#">CSCvn23565</a>	Cisco 702w AP enables POE in LAN 4 before joining Cisco controller after reboot
<a href="#">CSCvn25524</a>	Cisco 5520, 8540 controllers: Throughput is low with Port 2 with 1 Gig SFP
<a href="#">CSCvn27111</a>	Cisco WLC on 8.8.114.54 reloads unexpectedly due "pmalloc detected memory corruption spamAP Task4"
<a href="#">CSCvn27144</a>	Unable to restore 802.11ac MCS parameter
<a href="#">CSCvn27902</a>	%SAFEC-3-SAFEC_ERROR observed while decoding iPSK key from RADIUS
<a href="#">CSCvn32314</a>	Cisco 2800 AP on 8.8.114.54 reloads unexpectedly due to WCPD
<a href="#">CSCvn42184</a>	Cisco 1562 ME WLC Console is flooded with "/usr/sbin/nginx-helper: line 115: retry++: not found" msg
<a href="#">CSCvn47094</a>	CLI not taking all the commands sent via "paste" action
<a href="#">CSCvn49888</a>	Cisco 702, 1532 AP has tracebacks and beacons stuck with load 8.5.140.0
<a href="#">CSCvn50968</a>	Invalid web-auth https-redirect command in startup-config
<a href="#">CSCvn53514</a>	AP Syslog Facility does not work on IOS AP
<a href="#">CSCvn54782</a>	IGMP snooping needs to be enabled for Local Mode Local switching RLAN
<a href="#">CSCvn55904</a>	WLC modified FlexACLs rules are not populated on the Flex AP
<a href="#">CSCvn61436</a>	Cisco 5520 controller reloads unexpectedly on taskname : NFV9_Task
<a href="#">CSCvn66293</a>	3802 AP relays CDP Packets from wireless devices using Cisco IP Communicator to the switch
<a href="#">CSCvn66715</a>	3800 AP stops passing traffic under client with Intel NIC 8260/8265 load in MU-MIMO deployment
<a href="#">CSCvn68423</a>	Passive client config is lost upon WLC Reload or HA failover

Caveat ID Number	Description
<a href="#">CSCvn68501</a>	WLC LSC : Device certificate can't be installed and showing as "Not Present"
<a href="#">CSCvn68752</a>	Cisco 1542/1562 APs Failed to get ARP entry for WLC
<a href="#">CSCvn71004</a>	WLC Mbuf allocation problem / Mbuf Max reached
<a href="#">CSCvn98214</a>	Cisco 1830 AP: core-radio1FW found during WGB association, WGB did not join
<a href="#">CSCvn98598</a>	FT 802.1X clients cannot authenticate after ME primary AP / N+1 WLC failover
<a href="#">CSCvo04251</a>	dot1x_aaa_eapresp_supp: sending MDNS request to ISE flooding when running "debug client [macaddr]"
<a href="#">CSCvo05093</a>	Cisco controller reloads unexpectedly with task name radiusTransportThread
<a href="#">CSCvo06832</a>	Sensor test failed using Open as well as EAP authentication
<a href="#">CSCvo41016</a>	Cisco controller reloads unexpectedly when adding 4096 bit key size device cert for LSC
<a href="#">CSCvo48759</a>	AP deauths associated clients with reason code 7, Class 3 frame received from nonassociated STA
<a href="#">CSCvo60307</a>	Cisco controller reloads unexpectedly at Client Profiler Task
<a href="#">CSCvo71753</a>	AP side: Multicast Traffic stops working when enabling Inline Tagging on CTS

## Related Documentation

### Wireless Products Comparison

- Use this tool to compare the specifications of Cisco wireless access points and controllers:  
<https://www.cisco.com/c/en/us/products/wireless/wireless-lan-controller/product-comparison.html>
- Product Approval Status:  
[https://prdapp.cloudapps.cisco.com/cse/prdapp/jsp/externalsearch.do?action=externalsearch&page=EXTERNAL\\_SEARCH](https://prdapp.cloudapps.cisco.com/cse/prdapp/jsp/externalsearch.do?action=externalsearch&page=EXTERNAL_SEARCH)
- Wireless LAN Compliance Lookup:  
<https://www.cisco.com/c/dam/assets/prod/wireless/wireless-compliance-tool/index.html>

### Cisco Wireless Controller

For more information about the Cisco WLCs, lightweight APs, and mesh APs, see these documents:

- The quick start guide or installation guide for your particular Cisco WLC or access point
- [Cisco Wireless Solutions Software Compatibility Matrix](#)
- [Cisco Wireless Controller Configuration Guide](#)



- [Cisco Wireless Controller Command Reference](#)
- [Cisco Wireless Controller System Message Guide](#)

For all Cisco WLC software related documentation, see:

<http://www.cisco.com/c/en/us/support/wireless/wireless-lan-controller-software/tsd-products-support-series-home.html>

### **Cisco Mobility Express**

- [Cisco Mobility Express Release Notes](#)
- [Cisco Mobility Express User Guide](#)
- [Cisco Aironet Universal AP Priming and Cisco AirProvision User Guide](#)

### **Cisco Aironet Access Points for Cisco IOS Releases**

- [Release Notes for Cisco Aironet Access Points for Cisco IOS Releases](#)
- [Cisco IOS Configuration Guides for Autonomous Aironet Access Points](#)
- [Cisco IOS Command References for Autonomous Aironet Access Points](#)

### **Open Source Used in Controller and Access Point Software**

Click this link to access the documents that describe the open source used in controller and access point software:

<https://www.cisco.com/c/en/us/about/legal/open-source-documentation-responsive.html>

### **Cisco Prime Infrastructure**

[Cisco Prime Infrastructure Documentation](#)

### **Cisco Mobility Services Engine**

[Cisco Mobility Services Engine Documentation](#)

### **Cisco Connected Mobile Experiences**

[Cisco Connected Mobile Experiences Documentation](#)

## **Communications, Services, and Additional Information**

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco Marketplace](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).

- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

### **Cisco Bug Search Tool**

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

---

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2019 Cisco Systems, Inc. All rights reserved.