

# SG350XG: Device Does Not Join the Stack After Reload when Changing from Set ID to Auto Unit ID

## Date Identified

May 23, 2017

## Date Resolved

September 8, 2017

## Products Affected

| Model  | Firmware Version | Fixed In |
|--------|------------------|----------|
| SG350X | 2.2.0.x          | 2.3.5.63 |

## Problem Description

In some cases, if the unit-ID setting of a unit in a stack is changed from set ID to auto ID, the device does not join the stack after reload.

## Resolution

This issue is fixed when you upgrade to the firmware version 2.3.5.63. To upgrade, click [here](#) for instructions.