


-R (Russia)	Not Affected	Not Affected	Not Affected	Not Affected	Not Affected	Not Affected	Not Affected
-Q/Q1 (Japan)	Not Affected	Not Affected	Not Affected	Not Affected	Not Affected	VID 04 or later	VID 02 or later
All Other Reg Domains	VID 07 or later	VID 07 or later	Not Affected	VID 03 or later	VID 03 or later	VID 04 or later	VID 02 or later

The affected APs require these controller software versions:

- [8.10.181.0*](#) or later
- [17.3.6*](#) or later
- 17.6.4 or later
- 17.9.2 or later

 **Note:** As of June 2024, replacement APs delivered via Return Material Authorization (RMA), for the affected PIDs, can require the newer software.

* 8.10.181.0 is deferred due to Cisco bug ID [CSCwd37092](#). See [Recommended AireOS Wireless LAN Controller Releases](#). Customers with 9800 series controllers should consult [Recommended Cisco IOS XE Releases for Catalyst 9800 Wireless LAN Controllers](#).



Note: Only registered Cisco users can access internal tools and bug information.

Bug Assistant Tool

If you have an Access Point Serial Number (SN) or Product Identifier (PID), and Country/Version Identifier (VID) information, use the [Self Service Tool](#) to validate the applicability of [Field Notice 72424](#) .

 **Note:** Only registered Cisco users can access internal tools and information.

Related Information

- Cisco bug ID [CSCwc47544](#)
- [Field Notice 72424](#)
- [Cisco Wireless Solutions Software Compatibility Matrix](#)
- [Cisco Technical Support & Downloads](#)