End-of-Sale and End-of-Life Announcement for the 16-Port 10/100 Ethernet Modules and Gigabit Ethernet Daughter Card for Cisco 2600/2800/2900/3600/3700/3800/3900 Series Routers

EOL7259

Cisco announces the end-of-sale and end-of life dates for the 16-Port 10/100 Ethernet Modules and Gigabit Ethernet Daughter Card for Cisco 2600/2800/2900/3600/3700/3800/3900 Series Routers. The last day to order the affected product(s) is November 15, 2011. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1.   End-of-Life Milestones and Dates for the 16-Port 10/100 Ethernet Modules and Gigabit Ethernet Daughter Card for Cisco 2600/2800/2900/3600/3700/3800/3900 Series Routers

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 15, 2010
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 15, 2011
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 13, 2012
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	November 14, 2014
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	November 14, 2012
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 14, 2012
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	February 13, 2016
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 30, 2016

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Table 2.   Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
GE-DCARD-ESW	1 GE (1000BaseT) daughtercard for Etherswitch Modules	See the Product Migration Options section below for detailed information on replacing this product.		
GE-DCARD-ESW=	1 1000BaseT daughtercard for Etherswitch NM	See the Product Migration Options section below for detailed information on replacing this product.		
NM-16ESW	1 16 port 10/100 EtherSwitch NM	See the Product Migration Options section below for detailed information on replacing this product.		

NM-16ESW-1GIG	1 16 port 10/100 EtherSwitch NM with 1 GE (1000BaseT) port	See the Product Migration Options section below for detailed information on replacing this product.		
NM-16ESW-1GIG=	1 16 port 10/100 EtherSwitch NM + 1 Gig Port	See the Product Migration Options section below for detailed information on replacing this product.		
NM-16ESW=	1 16 port 10/100 EtherSwitch NM	See the Product Migration Options section below for detailed information on replacing this product.		

Product Migration Options

Customers using Cisco 2900,3900,and 3900 E-Series Routers are encouraged to migrate to the Cisco Enhanced EtherSwitch modules. Information about this product can be found at: http://www.cisco.com/en/US/prod/collateral/routers/ps10536/data_sheet_c78-553980_ps10537_Products_Data_Sheet.html. Customers using Cisco 2800 and 3800 Series Routers are encouraged to migrate to the Cisco EtherSwitch modules. Information about this product can be found at: http://www.cisco.com/en/US/prod/collateral/routers/ps259/product_data_sheet09186a00801aca3e.html. There are no migration options for those customers using Cisco 2600,3600,or 3700 Series Routers.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

For More Information

For more information about the Cisco Enhanced EtherSwitch Service Modules for Cisco 2900 and 3900 Series Routers, visit http://www.cisco.com/en/US/prod/collateral/routers/ps10536/data_sheet_c78-553980_ps10537_Products_Data_Sheet.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.