End-of-Sale and End-of-Life Announcement for the Select Cisco Integrated Services Router (ISR) G1 Modules and Cables

EOL10632 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Select Cisco Integrated Services Router (ISR) G1 Modules and Cables. The last day to order the affected product(s) is March 31, 2016. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1.   End-of-Life Milestones and Dates for the Select Cisco Integrated Services Router (ISR) G1 Modules and Cables

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 1, 2015
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 31, 2016
Last Ship Date: OS SW, HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 29, 2016
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	March 31, 2017
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	March 31, 2017
End of New Service Attachment Date: OS SW, HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	March 31, 2017
End of Service Contract Renewal Date: OS SW, HW	The last date to extend or renew a service contract for the product.	June 26, 2020
Last Date of Support: OS SW, HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 31, 2021

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Table 2.   Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
ACS-2500ASYN=	AUX/Console Part Cable Kit	There is currently no replacement product available for this product.	-	-
ACS-IAD2400RM-19=	19 inch Rack Mount Bracket for Cisco IAD24xx	There is currently no replacement product available for this product.	-	-
ACS-IAD2435RM-19=	IAD2435 19 Rack Bracket	There is currently no replacement product available for this product.	-	-
C1841-FIPS-SHIELD=	FIPS Opacity Shield for Cisco 1841	There is currently no replacement product available for this product.	-	-
CAB-449FC	RS-449 Cable, DCE, Female, 10 Feet	CAB-SS-449FC	RS-449 Cable, DCE Female to Smart Serial, 10 Feet	-
CAB-449MT	RS-449 Cable, DTE, Male, 10 Feet	CAB-SS-449MT	RS-449 Cable, DTE Male to Smart Serial, 10 Feet	-
FL-PAYG-U-SRST=	PayGrow SEC to VSEC Upgrade Lic - Adv IP Svcs and FL-SRST-36	FL-CME-SRST-5	Communication Manager Express or SRST - 5 seat license	-
FL-PAYG-U-VG=	PayGrow Voice Gateway Software license upgrade to AdvIPServ	There is currently no replacement product available for this product.	-	-
HWIC-2SHDSL	2-pair G.SHDSL HWIC	EHWIC-4SHDSL-EA	Double Wide EHWIC with multimode 4 pair G.SHDSL EFM and ATM	-
HWIC-2SHDSL=	2-pair G.SHDSL HWIC	EHWIC-4SHDSL-EA	Double Wide EHWIC with multimode 4 pair G.SHDSL EFM and ATM	-
MEM-243-1X128D	128MB DRAM Memory for IAD2430 series	There is currently no replacement product available for this product.	-	-
MEM-243-1X128F	128MB Flash Memory for IAD2430 series	There is currently no replacement product available for this product.	-	-
MEM2811-256U512D	256 to 512MB DDR DRAM factory upgrade for the Cisco 2811	There is currently no replacement product available for this product.	-	-
MEM2811-256U512D=	256 to 512 MB DDR DRAM Distribution Upgrade for Cisco 2811	There is currently no replacement product available for this product.	-	-
MEM2811-256U768D	256 to 768MB DDR DRAM factory upgrade for the Cisco 2811	There is currently no replacement product available for this product.	-	-
MEM2811-256U768D=	256 to 768MB DDR DRAM Distribution Upgrade for Cisco 2811	There is currently no replacement product available for this product.	-	-
MEM2811-512D=	512MB DIMM DDR DRAM for the Cisco 2811	There is currently no replacement product available for this product.	-	-
MEM2821-512D=	512MB DIMM DDR DRAM for the Cisco 2821	There is currently no replacement product available for this product.	-	-
MEM2851-512D=	512MB DIMM DDR DRAM for the Cisco 2851	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
MEMUSB-128FT	128MB USB Flash Token for Cisco 1800/2800/3800 series	There is currently no replacement product available for this product.	-	-
MEMUSB-128FT=	128MB USB Flash Token for Cisco 1800/2800/3800 series	There is currently no replacement product available for this product.	-	-
NM-8CE1T1-PRI	8 port channelized T1/E1 and PRI network module	NIM-8CE1T1-PRI	8 port Multiflex Trunk Voice/Channelized Data T1/E1 Module	-
NM-8CE1T1-PRI=	8 port channelized T1/E1 and PRI network module	NIM-8CE1T1-PRI=	8 port Multiflex Trunk Voice/Channelized Data T1/E1 Module	-
NME-RVPN-SEC1-G2=	Module for loading Russian VPN sofware security level 1	There is currently no replacement product available for this product.	-	-
NME-RVPN-SEC2-G2=	Module for loading Russian VPN sofware security level 2	There is currently no replacement product available for this product.	-	-
PWR-2811-AC-IP	Cisco 2811 AC/IP power supply	There is currently no replacement product available for this product.	-	-
PWR-2811-AC-IP=	Cisco 2811 AC/IP power supply	There is currently no replacement product available for this product.	-	-
S184ASK9-15103T	Cisco 1841 IOS ADVANCED SECURITY	There is currently no replacement product available for this product.	-	-
S186UAISK9-15102T	Cisco 1861 IOS SPSK9-AISK9 FEAT SET FACTORY UPG	There is currently no replacement product available for this product.	-	-
S186UAISK9-15103T	Cisco 1861 IOS SPSK9-AISK9 FEAT SET FACTORY UPG	There is currently no replacement product available for this product.	-	-
S243CHK9-12415T=	Cisco 2430 Series IOS IP PLUS/IPSEC 64BIT/FW/VOICE	There is currently no replacement product available for this product.	-	-
S28NASK9-12401	Cisco 2800 IOS ADVANCED SECURITY	There is currently no replacement product available for this product.	-	-
SL-IAD880-AIS=	Cisco IAD 880 Advanced IP Services Software License	There is currently no replacement product available for this product.	-	-
SM-2GE-SFP-CU	2 port GE SFP service module	EHWIC-1GE-SFP-CU	EHWIC 1 port dual mode SFP(100M/1G) or GE(10M/100M/1G)	-
SM-2GE-SFP-CU=	2 port GE SFP service module	EHWIC-1GE-SFP-CU=	EHWIC 1 port dual mode SFP(100M/1G) or GE(10M/100M/1G) Spare	-
SM-32A	32 port Asynchronous Module	HWIC-16A	16-Port Async HWIC	-
SM-32A=	32 port Asynchronous Module	HWIC-16A=	16-Port Async HWIC	-

Product Migration Options

Customers are encouraged to migrate to the Cisco ISR G2 modules and cables.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at
http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Select Cisco Integrated Services Router (ISR) G1 Modules and Cables through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to:
http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:
http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:
http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:
http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

CISCO

Printed in USA

C51-735924-01   11/15