ıı|ıı|ıı
CISCO

End-of-Sale and End-of-Life Announcement for the Cisco UCS 6324 Fabric Interconnect

Contents

Overview

EOL15533

Cisco announces the end-of-sale and end-of-life dates for the Cisco UCS 6324 Fabric Interconnect. The last day to order the affected product(s) is January 30, 2025. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1.   End-of-Life Milestones and Dates for the Cisco UCS 6324 Fabric Interconnect

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 31, 2024
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 30, 2025
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 30, 2025
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 30, 2026
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 30, 2026
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 30, 2026
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	April 27, 2029

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Product part numbers

Table 2.   Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-FI-M-6324-UPG	UCS 6324 In-Chassis FI with 4 UP, 1x40G Exp Port, 16 10Gb	UCSX-S9108-100G	UCS X-Series Direct Fabric Interconnect 9108 100G	-
UCS-MINI-Z0001	Cisco Unified Computing System	There is currently no replacement product available for this product.	-	-
TR-FSA1-MINI	UCS-FSA1-MINI Tracer	There is currently no replacement product available for this product.	-	-
TR-MINI-SEED-5108	UCS 5108 Blade Server AC2 Chassis w/FI 6324,No Blades Tracer	There is currently no replacement product available for this product.	-	-
TR-SP-MINI	UCS-SP-MINI Tracer	There is currently no replacement product available for this product.	-	-
UCS-FI-M-6324=	UCS 6324 In-Chassis FI with 4 UP, 1x40G Exp Port, 16 10Gb	UCSX-S9108-100G=	UCS X-Series Direct Fabric Interconnect 9108 100G	-
UCS-FI-M-6324	UCS 6324 In-Chassis FI with 4 UP, 1x40G Exp Port, 16 10Gb	UCSX-S9108-100G	UCS X-Series Direct Fabric Interconnect 9108 100G	-
UCS-SP-MINI-2-5108	UCS SP Select 2nd Mini AC2 Chassis w. I/O Mod, FI p.lic,QSFP	There is currently no replacement product available for this product.	-	-
UCS-6324-40G	6324 Fabric Interconnect License for 40G Scalability Port	There is currently no replacement product available for this product.	-	-
UCS-6324-40G=	6324 Fabric Interconnect License for 40G Scalability Port	There is currently no replacement product available for this product.	-	-
UCS-FI-M-6324++=	TAA UCS 6324 In-Chassis FI with 4UP, 1x40G Exp Port, 16 10Gb	UCSX-S9108-100G=	UCS X-Series Direct Fabric Interconnect 9108 100G	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-FI-M-6324-BR	UCS 6324 In-Chassis FI with 4 UP, 1x40G Exp Port, 16 10Gb	UCSX-S9108-100G	UCS X-Series Direct Fabric Interconnect 9108 100G	-
UCS-FI-M-6324-U-BR	UCS 6324 In-Chassis FI with 4 UP, 1x40G Exp Port, 16 10Gb	UCSX-S9108-100G	UCS X-Series Direct Fabric Interconnect 9108 100G	-

Product migration options

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.