Cisco UCS Director Software Versions 5.0, 5.1, 5.2, 5.3 and 5.4

Cisco announces the end-of-life dates for Cisco UCS Director Software Version 5.0 through 5.4 software releases

Software maintenance support for 5.0, 5.1, 5.2, 5.3 and 5.4 software releases end on July 10, 2020. No patches or maintenance releases will be provided for Cisco UCS Director 5.0.x, 5.1.x, 5.2.x, 5.3.x. and 5.4.x releases after that date.

Starting July 10, 2018 only sev1 and security vulnerability issues will be addressed, and it may be necessary to upgrade to later software release to correct a reported problem.

Software maintenance requires an active service contract.

Product Migration Options

Current Cisco UCS Director 5.0.x through 5.4.x customers can upgrade to latest Cisco UCS Director 6.x release

Install and upgrade guides can be found here: http://www.cisco.com/c/en/us/support/servers-unified-computing/ucs-director/products-installation-guides-list.html.

Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

© 2017 Cisco and/or its affiliates. All rights reserved. This document is Cisco Public Information.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-738907-00 04/17

© 2017 Cisco and/or its affiliates. All rights reserved. This document is Cisco Public Information.