End-of-Sale and End-of-Life Announcement for the Cisco Prisma Optical Passive Components (Select PIDs only)

EOL11853

Cisco announces the end-of-sale and end-of-life dates for the Cisco Prisma Optical Passive Components (Select PIDs only). The last day to order the affected product(s) is November 30, 2017. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions.

Table 1.   End-of-Life Milestones and Dates for the Cisco Prisma Optical Passive Components (Select PIDs only)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	June 1, 2017
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 30, 2017
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 28, 2018
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	November 30, 2018
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	November 30, 2018
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 30, 2018
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	February 25, 2022
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete[**]. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	November 30, 2022

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
1030016	LGX-DWDM-MXDX 1X20 ITU2039 DTP-UG-EXP-LA	OPLGX-MD20-2039-LQ	Single-wide LGX-MXDX-20 ch-ITU 20-39 using quad LC/APC	-
1030191	LGX-Dual-CWDM-MXDX 8CH Type B DTP-Express-LC/APC(47-61)	There is currently no replacement product available for this product.	-	-
1030192	LGX-Dual-CWDM-MXDX 8CH Type C DTP-Express-LC/APC(4351, 5761)	There is currently no replacement product available for this product.	-	-
4000669	(JMPR-9SS-2-S-SA-SA-015)Jmpr, SM Sx, 2mm, Std, SA-SA, 15m	There is currently no replacement product available for this product.	-	-
4000686	(JMPR-9SS-2-S-LP-LP-001)Jmpr, SM Sx, 2mm, Std, LP-LP, 1m	There is currently no replacement product available for this product.	-	-
4000687	(JMPR-9SS-2-S-LP-LP-003)Jmpr, SM Sx, 2mm, Std, LP-LP, 3m	There is currently no replacement product available for this product.	-	-
4000688	(JMPR-9SS-2-S-LP-LP-005)Jmpr, SM Sx, 2mm, Std, LP-LP, 5m	There is currently no replacement product available for this product.	-	-
4000689	(JMPR-9SS-2-S-LP-LP-010)Jmpr, SM Sx, 2mm, Std, LP-LP, 10m	There is currently no replacement product available for this product.	-	-
4003300	Mx/DMx, 1x2, Dual Node Tray, SA	There is currently no replacement product available for this product.	-	-
4004349	DWDM Mx/DMx, 1:8, ITU43-50, 100GHz, LGX, SA, 2slot	There is currently no replacement product available for this product.	-	-
4004352	DWDM Mx/DMx, 1:8, ITU16-23, 100GHz, LGX, SA, 2slot	There is currently no replacement product available for this product.	-	-
4004353	BWDM Mx/DMx, 5Band, ITU16-23, 25-32, 34-41, 43-50, 52-59, LGX, SA	There is currently no replacement product available for this product.	-	-
4004354	DWDM Mx/DMx, 40CH, ITU16-59, skips 24/33/42/51, 100GHz, LC	There is currently no replacement product available for this product.	-	-
4004872	Opt Add/Drop Mux, Fltr, CWDM 1450nm, SA	There is currently no replacement product available for this product.	-	-
4004873	Opt Add/Drop Mux, Fltr, CWDM 1430nm, SA	There is currently no replacement product available for this product.	-	-
4005094	BWDM Mx/DMx, 2Band, ITU16-23, 25-59, LGX, SA	There is currently no replacement product available for this product.	-	-
4005126	(JMPR-6MD-2-S-LP-LP-010)Jmpr, 62.5MM Dx, 2mm, Std, LP-LP, 10m	There is currently no replacement product available for this product.	-	-
4005606	BWDM Mx/DMx, 2Band, ITU25-32, 16-23/34-59, LGX, SA	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4005607	BWDM Mx/DMx, 2Band, ITU34-41, 16-32/43-59, LGX, SA	There is currently no replacement product available for this product.	-	-
4005608	BWDM Mx/DMx, 2Band, ITU43-50, 16-41/52-59, LGX, SA	There is currently no replacement product available for this product.	-	-
4005870	(JMPR-6MD-3-S-LP-LP-001)Jmpr, 62.5MM Dx, 3mm, Std, LP-LP, 1m	There is currently no replacement product available for this product.	-	-
4005873	(JMPR-6MD-3-S-LP-LP-020)Jmpr, 62.5MM Dx, 3mm, Std, LP-LP, 20m	There is currently no replacement product available for this product.	-	-
4006513	Mx/DMx, 1x2, Sgl Node Tray, SA	There is currently no replacement product available for this product.	-	-
4009095	Opt Add/Drop Mux, LGX, CWDM, 1430nm	There is currently no replacement product available for this product.	-	-
4009096	Opt Add/Drop Mux, LGX, CWDM, 1450nm	There is currently no replacement product available for this product.	-	-
4010857	(CAS-MXDX-1x4-20nm-900-SA-14701530)CWDM Mx/DMx, 1x4, 1470-1530	There is currently no replacement product available for this product.	-	-
4010858	(CAS-MXDX-1x4-20nm-900-SA-15501610)CWDM Mx/DMx, 1x4, 1550-1610	There is currently no replacement product available for this product.	-	-
4013017	(JMPR-9SD-2-S-LP-LP-002)Jmpr, SM Dx, 2mm, Std, LP-LP, 2m	There is currently no replacement product available for this product.	-	-
4013033	(JMPR-9SD-3-S-SA-LP-003)Jmpr, SM Dx, 3mm, Std, SA-LP, 3m	There is currently no replacement product available for this product.	-	-
4014316	DWDM Mx/DMx, 1x4, ITU21-27, 200GHz, LGX, SA, 1slot	There is currently no replacement product available for this product.	-	-
4014318	DWDM Mx/DMx, 1x8, ITU43-57, 200GHz, LGX, SA, 2slot	There is currently no replacement product available for this product.	-	-
4014977	(JMPR-9SD-3-S-SA-LP-010)Jmpr, SM Dx, 3mm, Std, SA-LP, 10m	There is currently no replacement product available for this product.	-	-
4014978	(JMPR-9SD-3-S-SA-LP-015)Jmpr, SM Dx, 3mm, Std, SA-LP, 15m	There is currently no replacement product available for this product.	-	-
4014979	(JMPR-9SD-3-S-SA-LP-020)Jmpr, SM Dx, 3mm, Std, SA-LP, 20m	There is currently no replacement product available for this product.	-	-
4014980	(JMPR-9SD-3-S-SA-LP-030)Jmpr, SM Dx, 3mm, Std, SA-LP, 30m	There is currently no replacement product available for this product.	-	-
4014981	(JMPR-9SD-3-S-SA-LP-040)Jmpr, SM Dx, 3mm, Std, SA-LP, 40m	There is currently no replacement product available for this product.	-	-
4020939	Service Cbl, 6Fiber, SA, 30ft	There is currently no replacement product available for this product.	-	-
4021049	LGX-MXDX-1X2-OBAND-EF-SA, 1x2 Dnstrm Hub, Ch E/F	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
4021051	LGX-MXDX-1X6-OBAND-AF-SA, 1x6 Dnstrm Hub, Ch A/B/C/D/E/F	There is currently no replacement product available for this product.	-	-
4021218	CAS-DMUX-1X2-OBAND-EF-SA, 1x2 Dnstrm Out Plnt, Ch E/F	There is currently no replacement product available for this product.	-	-
4021220	CAS-DMUX-1X6-OBAND-AF-SA, 1x6 Dnstrm Out Plnt, Ch A/B/C/D/E/F	There is currently no replacement product available for this product.	-	-
4021225	OADM-FILTER-OBAND-E-SA, 1CH Fltr for Node/Splicing Encl	There is currently no replacement product available for this product.	-	-
4021226	OADM-FILTER-OBAND-F-SA, 1CH Fltr for Node/Splicing Encl	There is currently no replacement product available for this product.	-	-
4032472	Service Cable, 4 MPO Conn, 32 Fbr SC/APC-100 Ft	There is currently no replacement product available for this product.	-	-
4032473	Service Cbl, 48 Fiber, 4 Ribbon Cbl, 4 MPO Conn, 100Ft LC/APC	There is currently no replacement product available for this product.	-	-
4036573	(RM-CPLR-1RU-2X32-EVEN-SA)Opt Cplr, 2x32, 1RU, Even, SA	There is currently no replacement product available for this product.	-	-
4038730	(RM-CPLR-1RU-Dual 2X16-EVEN-SA) Cplr, Dual 2x16, 1RU, Even, SA	There is currently no replacement product available for this product.	-	-
4040560	CYL-BWDM-2035/4459 900-NC	There is currently no replacement product available for this product.	-	-
OPLGX-MD16-2162-LA	LGX-MXDX-16CH-IWDM-LC/APC-DTP	OPLGX-MD16-2162-LQ	Single-wide LGX-MXDX-16CH-IWDM-quad LC/APC-DTP	-

Product Migration Options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:
http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Prisma Optical Passive Components (Select PIDs only) through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:
http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

**For more information about the Cisco Product Warranties, go to:
http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:
http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Printed in USA

C51-739157-00   05/17