

End-of-Sale and End-of-Life Announcement for the Cisco 3G and Cisco LTE 1.0 Wireless WAN Enhanced High-Speed WAN Interface Cards (EHWICs) for Cisco 1900, 2900, and 3900 Series Integrated Services Routers

EOL11099

Cisco announces the end-of-sale and end-of-life dates for the Cisco 3G and Cisco LTE 1.0 Wireless WAN Enhanced High-Speed WAN Interface Cards (EHWICs) for Cisco 1900, 2900, and 3900 Series Integrated Services Routers. The last day to order the affected product(s) is January 28, 2017. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco 3G and Cisco LTE 1.0 Wireless WAN Enhanced High-Speed WAN Interface Cards (EHWICs) for Cisco 1900, 2900, and 3900 Series Integrated Services Routers

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 30, 2016
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 28, 2017
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 28, 2017
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 28, 2018
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 28, 2018
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 28, 2018
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	April 25, 2021
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 31, 2022

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
C1921-3G-G-K9	C1921 w/3.5G HWIC (non-US) HSPA/UMTS 900/1900/2100MHz
C1921-3G-G-SEC/K9	C1921 w/3.5G HWIC (non-US) HSPA/UMTS 900/1900/2100MHz w/SEC
C1921-SHDSL-4G/K9	Cisco1921/K9, 2GE, HWIC-2SHDSL, EHWIC-4G-LTE-G, 512MB DR, 256MBFL
C1921-VAG-4G/K9	Cisco1921, 2GE, EHWIC-DSL-VA-A, EHWIC-4G-LTE-G, 512MBDR, 256MBFI

Product Migration Options

There is no replacement available for the Cisco 3G and Cisco LTE 1.0 Wireless WAN Enhanced High-Speed WAN Interface Cards (EHWICs) for Cisco 1900, 2900, and 3900 Series Integrated Services Routers at this time.

Cisco LTE NIM and LTE 2.0 EHWIC configuration options are available with all existing modular 4000 Series ISRs and ISR G2 routers.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco 3G and Cisco LTE 1.0 Wireless WAN Enhanced High-Speed WAN Interface Cards (EHWICs) for Cisco 1900, 2900, and 3900 Series Integrated Services Routers through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)