

Product Bulletin EOL5053

End-of-Sale and End-of-Life Announcement for the SSL VPN Module for Cisco Catalyst 6500 and Cisco 7600 Series

Cisco Systems[®] announces the end-of-sale and end-of life dates for the SSL VPN Module for Cisco Catalyst 6500 and Cisco 7600 Series. The last day to order the SSL VPN Module for Cisco Catalyst 6500 and Cisco 7600 Series is May 29, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the SSL VPN Module for Cisco Catalyst 6500 and Cisco 7600 Series. Table 2 lists the product part numbers affected by this announcement.

The recommended replacement for the Cisco WebVPN Module and the SSL VPN Module is the Cisco ASA 5500 Series, VPN Edition, which enables organizations to gain the connectivity and cost benefits of Internet transport without compromising the integrity of corporate security policies. By converging IP Security (IPsec) and Secure Sockets Layer (SSL) VPN (Cisco WebVPN) services with comprehensive threat defense technologies, the Cisco ASA 5500 Series delivers highly customizable network access tailored to meet the requirements of diverse deployment environments.

Table 1. End-of-Life Milestones and Dates for the SSL VPN Module for Cisco Catalyst 6500 and Cisco 7600 Series.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 28, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 29, 2007
Last Ship Date: HW, OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 27, 2007
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 28, 2008
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 28, 2008
End of New Service Attachment Date: HW, OS SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 28, 2008
End of Service Contract Renewal Date: HW, OS SW	The last date to extend or renew a service contract for the product.	August 24, 2011
Last Date of Support: HW, OS SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 27, 2012

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement'Product Part Number	Replacement Product Description
SC-SVC-WVPN-11-K9	WebVPN Module software 1.1 for Catalyst 6500 and 7600	ASA5550-SSL2500-K9	ASA 5550 SSL VPN 2500 user bundle
SC-SVC-WVPN-11-K9=	WebVPN Module software 1.1 for Catalyst 6500 and 7600	ASA5550-SSL2500-K9	ASA 5550 SSL VPN 2500 user bundle
WS-SVC-WEBVPN-K9	SSL VPN Module for Catalyst 6500	ASA5550-SSL2500-K9	ASA 5550 SSL VPN 2500 user bundle
WS-SVC-WEBVPN-K9=	SSL VPN Module for Catalyst 6500	ASA5550-SSL2500-K9	ASA 5550 SSL VPN 2500 user bundle

PRODUCT MIGRATION OPTIONS

Customers are encouraged to migrate to the Cisco ASA 5550 Adaptive Security Appliance, VPN Edition. Information about this product can be found at: http://www.cisco.com/en/US/products/ps6120/index.html

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: http://www.cisco.com/go/tradein/. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program.'Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html

FOR MORE INFORMATION

For more information about the Cisco ASA 5550 Adaptive Security Appliance, VPN Edition, visit, contact your local account representative, or send an e-mail to.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod end of life.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



Corporate Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com

Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 526-4100 Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: 31 0 20 357 1000

Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

European Headquarters

Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883 Asia Pacific Headquarters Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com

Tel: +65 6317 7777 Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco.com Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, Pro-Connect, RateMUX, ScriptShare, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in USA C51-373865-00 10/06