

# End-of-Sale and End-of-Life Announcement for the Cisco Select UCS and HCI accessories

---

# Contents

|                           |    |
|---------------------------|----|
| Overview                  | 3  |
| End-of-life milestones    | 3  |
| Product Part Numbers      | 4  |
| Product Migration Options | 10 |
| For more information      | 10 |

## Overview

### EOL15359

Cisco announces the end-of-sale dates for the Cisco Select UCS and HCI accessories. The last day to order the affected product(s) is June 27, 2024. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Select UCS and HCI accessories

| Milestone                            | Definition  | Date           |
|--------------------------------------|---|----------------|
| <b>End-of-Life Announcement Date</b> | The date the document that announces the end of sale and end of life of a product is distributed to the general public.                   | March 28, 2024 |
| <b>End-of-Sale Date Accessory</b>    | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.             | June 27, 2024  |
| <b>Last Ship Date Accessory</b>      | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | June 27, 2024  |

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

## Product Part Numbers

**Table 2.** Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description                          | Replacement Product Part Number                                       | Replacement Product Description                            | Additional Information |
|---------------------------------|--|---|--|------------------------|
| <b>HCI-M-V5D200G</b>            | Cisco VIC 15238 2x 40/100/200G mLOM C-Series | HCI-M-V5D200GV2   | Cisco VIC 15237 2x 40/100/200G mLOM C-Series w/Secure Boot | -                      |
| <b>HCI-M-V5D200G=</b>           | Cisco VIC 15238 2x 40/100/200G mLOM C-Series | HCI-M-V5D200GV2=  | Cisco VIC 15237 2x 40/100/200G mLOM C-Series w/Secure Boot | -                      |
| <b>HCI-M-V5D200G-M6</b>         | Cisco VIC 15238 2x 40/100/200G mLOM C-Series | HCI-M-V5D200GV2M6   | Cisco VIC 15237 2x 40/100/200G mLOM C-Series w/Secure Boot | -                      |
| <b>HCI-M-V5D200G-M6=</b>        | Cisco VIC 15238 2x 40/100/200G mLOM C-Series | HCI-M-V5D200GV2M6=  | Cisco VIC 15237 2x 40/100/200G mLOM C-Series w/Secure Boot | -                      |
| <b>HCI-M-V5Q50G</b>             | Cisco VIC 15428 4x 10/25/50G mLOM C-Series   | HCI-M-V5Q50GV2  | Cisco VIC 15427 4x 10/25/50G mLOM C-Series w/Secure Boot   | -                      |
| <b>HCI-M-V5Q50G=</b>            | Cisco VIC 15428 4x 10/25/50G mLOM C-Series   | HCI-M-V5Q50GV2=   | Cisco VIC 15427 4x 10/25/50G mLOM C-Series w/Secure Boot   | -                      |
| <b>HCI-M-V5Q50G-M6</b>          | Cisco VIC 15428 4x 10/25/50G mLOM C-Series   | HCI-M-V5Q50GV2-M6   | Cisco VIC 15427 4x 10/25/50G mLOM C-Series w/Secure Boot   | -                      |
| <b>HCI-M-V5Q50G-M6=</b>         | Cisco VIC 15428 4x 10/25/50G mLOM C-Series   | HCI-M-V5Q50GV2-M6=  | Cisco VIC 15427 4x 10/25/50G mLOM C-Series w/Secure Boot   | -                      |
| <b>HCI-SD76T6S1X-EV</b>         | 7.6TB 2.5in Enter Value 6G SATA Samsung SSD  | See Product Migration Options section for details.                    | Coming soon  | -                      |
| <b>TR-FSA1-5108-AC2</b>         | UCS-FSA1-5108-AC2 Tracer                     | There is currently no replacement product available for this product. | -  | -                      |
| <b>TR-FSA1-ENTRY-FIA</b>        | UCS-FSA1-ENTRY-FIA Tracer                    | There is currently no replacement product available for this product. | -  | -                      |
| <b>TR-FSA1-FI48P</b>            | UCS-FSA1-FI48P Tracer                        | There is currently no replacement product available for this product. | -  | -                      |

| End-of-Sale Product Part Number | Product Description                      | Replacement Product Part Number                                       | Replacement Product Description | Additional Information |
|---------------------------------|--|---|---------------------------------|------------------------|
| <b>TR-FSA1-SAS</b>              | UCS-FSA1-SAS Tracer                      | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-HANA-MAPR-01</b>          | UCS-HANA-MAPR-01 Tracer                  | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA3-P</b>             | Big Data v3 Performance Optimized Tracer | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA4-C1</b>            | UCS-SL-CPA4-C1 Tracer                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA4-C2</b>            | UCS-SL-CPA4-C2 Tracer                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA4-H</b>             | UCS-SL-CPA4-H Tracer                     | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA4-P1</b>            | UCS-SL-CPA4-P1 Tracer                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA4-P2</b>            | UCS-SL-CPA4-P2 Tracer                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA4-P3</b>            | UCS-SL-CPA4-P3 Tracer                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SL-CPA4-S</b>             | UCS-SL-CPA4-S Tracer                     | There is currently no replacement product available for this product. | -                               | -                      |
| <b>TR-SP-5108-AC4</b>           | UCS-SP-5108-AC4 Tracer                   | There is currently no replacement product available for this product. | -                               | -                      |

| End-of-Sale Product Part Number | Product Description       | Replacement Product Part Number | Replacement Product Description                                       | Additional Information |
|---------------------------------|---------------------------|---------------------------------|---|------------------------|
| <b>TR-SP-5108-DC</b>            | UCS-SP-5108-DC Tracer     |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-5108-DC3</b>           | UCS-SP-5108-DC3 Tracer    |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-5108-DC4</b>           | UCS-SP-5108-DC4 Tracer    |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-FIO-10PS-4</b>         | UCS-SP-FIO-10PS-4 Tracer  |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-FIO-13MP-2</b>         | UCS-SP-FIO-13MP-2 Tracer  |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-H1P8TB-4X</b>          | UCS-SP-H1P8TB-4X Tracer   |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-H4TB-4X</b>            | UCS-SP-H4TB-4X Tracer     |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-MINI-2-5108</b>        | UCS-SP-MINI-2-5108 Tracer |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-SD-1P6TB-4X</b>        | UCS-SP-SD-1P6TB-4X Tracer |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-SD-3P8TB-4X</b>        | UCS-SP-SD-3P8TB-4X Tracer |                                 | There is currently no replacement product available for this product. | -                      |
| <b>TR-SP-SM-DISKEXP1</b>        | UCS-SP-SM-DISKEXP1 Tracer |                                 | There is currently no replacement product available for this product. | -                      |

| End-of-Sale Product Part Number | Product Description                               | Replacement Product Part Number                                       | Replacement Product Description | Additional Information |
|---------------------------------|---|---|---------------------------------|------------------------|
| <b>UCSC-AIRBAF-C220L</b>        | Air Baffle Replacement Kit for C220 M3 LFF Server | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-AIRBAF-C220L=</b>       | Air Baffle Replacement Kit for C220 M3 LFF Server | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-BAFF-C220M4</b>         | C220 M4 Air Baffle, Plastic Kit                   | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-CMA-EXT</b>             | 2inch Cable Extender for CMA                      | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-CMA-EXT=</b>            | 2inch Cable Extender for CMA                      | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-FAN-C220M4</b>          | C220 M4 Fan Module (one)                          | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-FAN-C220M4=</b>         | C220 M4 Fan Module (one)                          | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-OCP-QD10GC</b>          | Qlogic QL41132HORJ dual port 10GBase-T OCP 1.0    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-OCP-QD10GC=</b>         | Qlogic QL41132HORJ dual port 10GBase-T OCP 1.0    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-OCP-QD25GF</b>          | Qlogic QL41232HOCU dual port 25G SFP28 OCP 1.0    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-OCP-QD25GF=</b>         | Qlogic QL41232HOCU dual port 25G SFP28 OCP 1.0    | There is currently no replacement product available for this product. | -                               | -                      |

| End-of-Sale Product Part Number | Product Description                                     | Replacement Product Part Number                                       | Replacement Product Description | Additional Information |
|---------------------------------|---|---|---------------------------------|------------------------|
| <b>UCSC-O-M5S100GF</b>          | MELLANOX MCX545B-ECAN 1x100Gb QSFP28 IB/ENET OCP2.0 NIC | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-O-M5S100GF=</b>         | MELLANOX MCX545B-ECAN 1x100Gb QSFP28 IB/ENET OCP2.0 NIC | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-BD32GF</b>         | Emulex LPe32002 Dual-Port 32G FC HBA                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-BD32GF=</b>        | Emulex LPe32002 Dual-Port 32G FC HBA                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-BS32GF</b>         | Broadcom LPe32000 Single-Port 32G FC HBA                | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-BS32GF=</b>        | Broadcom LPe32000 Single-Port 32G FC HBA                | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-QD25GF</b>         | Qlogic QL41212H dual-port 25G NIC                       | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-QD25GF=</b>        | Qlogic QL41212H dual-port 25G NIC                       | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-QD40GF</b>         | Qlogic QL45412H dual port 40G NIC                       | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-QD40GF=</b>        | Qlogic QL45412H dual port 40G NIC                       | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIE-QS100GF</b>        | Qlogic QLE45611HLCU single port 100G NIC                | There is currently no replacement product available for this product. | -                               | -                      |



| End-of-Sale Product Part Number | Product Description                               | Replacement Product Part Number                                       | Replacement Product Description | Additional Information |
|---------------------------------|---|---|---------------------------------|------------------------|
| <b>UCSC-PCIE-QS100GF=</b>       | Qlogic QLE45611HLCU single port 100G NIC          | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIF-240M4</b>          | C240 M4 PCIe Riser Blanking Panel                 | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PCIF-240M4=</b>         | C240 M4 PCIe Riser Blanking Panel                 | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-P-M5S100GF</b>          | MELLANOX CX-5 MCX515A-CCAT 1x100GbE QSFP PCIe NIC | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-P-M5S100GF=</b>         | MELLANOX CX-5 MCX515A-CCAT 1x100GbE QSFP PCIe NIC | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PSU-BLKP1U</b>          | Power Supply Blanking Panel for C220 M4 servers   | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-PSU-BLKP1U=</b>         | Power Supply Blanking Panel for C220 M4 servers   | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSX-GPU-H100-80D</b>        | VOID, NOT USED                                    | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-GPU-M10</b>             | NVIDIA M10 PCIE 225W 32GB                         | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-GPU-M10-CH</b>          | Disti: NVIDIA M10 PCIE 225W 32GB                  | There is currently no replacement product available for this product. | -                               | -                      |

| End-of-Sale Product Part Number | Product Description       | Replacement Product Part Number                                       | Replacement Product Description | Additional Information |
|---------------------------------|---------------------------|---|---------------------------------|------------------------|
| <b>UCSC-GPU-M10-PROMO</b>       | NVIDIA M10 PCIE 225W 32GB | There is currently no replacement product available for this product. | -                               | -                      |
| <b>UCSC-GPU-M10=</b>            | NVIDIA M10                | There is currently no replacement product available for this product. | -                               | -                      |

## Product Migration Options

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

### For more information

For more information about the Cisco End-of-Life Policy, go to:

<https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to:

<https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)