

# Contents

[Introduction](#)  
[Prerequisites](#)  
[Requirements](#)  
[Components Used](#)  
[Configure](#)  
[Network Diagram](#)  
[Configurations](#)  
[Verify](#)  
[Troubleshoot on Client](#)  
[Related Information](#)

## Introduction

This document describes Prefix Delegation configuration example in scenarios where Layer 2 Tunnelling Protocol Network Server (LNS) delegates an IPv6 prefix to the Client router over Virtual Private Dialup Network (VPDN) Tunnel built between the Layer 2 Tunnelling Protocol Access Concentrator (LAC) and LNS.

## Prerequisites

### Requirements

Cisco recommends that you have knowledge of End-to-End Layer 1 connectivity that is UP

### Components Used

This document is not restricted to specific software and hardware versions.


The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, make sure that you understand the potential impact of any command.

## Configure

**Note:** Use the [Command Lookup Tool](#) (registered customers only) in order to obtain more information on the commands used in this section.

## Network Diagram

This document uses this network setup:



## Configurations

### Client Configuration:

An example of the configuration on the Client router is shown here:

### LAC Configuration:

An example of the configuration on the LAC is shown here:

### LNS Configuration:

An example of the configuration on the LNS is shown here:

```
!
vpdn enable
!
vpdn-group 1
accept-dialin
protocol l2tp
virtual-template 1
terminate-from hostname LAC
vpn vrf test
lcp renegotiation on-mismatch
no l2tp tunnel authentication
!
username test@cisco.com password cisco
interface Ethernet1/0
 ip vrf forwarding test
 ip address 192.168.1.2 255.255.255.0
 negotiation auto
 cdp enable
end interface Virtual-Template1 ip address 10.1.1.1 255.255.255.0 ipv6 enable
ipv6 dhcp server AAA
peer default ip address pool local
peer default ipv6 pool PPPOE_POOL6
no keepalive
ppp authentication chap ! ipv6 dhcp pool AAA
prefix-delegation pool DHCPv6Pool
!
ipv6 local pool PPPOE_POOL6 2001:DB8:5AB:10::/60 64
!
ip local pool local 10.1.1.2 10.1.1.100
!
ipv6 local pool DHCPv6Pool 2A02:838F:F880::/42 56
!
```

## Verify

```
Client#show ipv6 interface brief FastEthernet0/2
FastEthernet0/2 [up/up]
 FE80::205:FF:FE77:2C1B
2A02:838F:F880::1
```

```
Client#show ipv6 interface brief dialer1
Dialer1 [up/up]
 FE80::1234
2001:DB8:5AB:10::1234
```

## Troubleshoot on Client

These #debugs assist in debugging the issue:

```
FastEthernet0/2 [up/up]
```

```

FE80::205:FF:FE77:2C1B
2A02:838F:F880::1

Client#show ipv6 interface brief dialer1
Dialer1                  [up/up]
  FE80::1234
2001:DB8:5AB:10::1234
Client#show ipv6 interface brief FastEthernet0/2
FastEthernet0/2           [up/up]
  FE80::205:FF:FE77:2C1B
2A02:838F:F880::1

Client#show ipv6 interface brief dialer1
Dialer1                  [up/up]
  FE80::1234
2001:DB8:5AB:10::1234

```

This a snippet of debug ipv6 dhcp detail on the Client router after PPP Negotiation has been completed and respective Virtual-Access is UP.

```

*Jun 27 15:08:53.019: %LINEPROTO-5-UPDOWN: Line protocol on Interface Virtual-Access2, changed
state to up
*Jun 27 15:09:03.711: IPv6 DHCP: detailed packet contents
*Jun 27 15:09:03.711:   src FE80::1234
*Jun 27 15:09:03.711:   dst FF02::1:2 (Dialer1)
*Jun 27 15:09:03.711:   type REQUEST(3), xid 1849347
*Jun 27 15:09:03.711:   option ELAPSED-TIME(8), len 2
*Jun 27 15:09:03.711:     elapsed-time 3202
*Jun 27 15:09:03.711:   option CLIENTID(1), len 10
*Jun 27 15:09:03.711:     00030001000500772C1B
*Jun 27 15:09:03.711:   option ORO(6), len 6
*Jun 27 15:09:03.711:     IA-PD,DNS-SERVERS,DOMAIN-LIST
*Jun 27 15:09:03.711:   option SERVERID(2), len 10
*Jun 27 15:09:03.711:     000300017CAD74F9EB00
*Jun 27 15:09:03.711:   option IA-PD(25), len 41
*Jun 27 15:09:03.711:     IAID 0x000B0001, T1 0, T2 0
*Jun 27 15:09:03.711:   option IAPREFIX(26), len 25
*Jun 27 15:09:03.711:     preferred 0, valid 0, prefix 2A02:838F:F880::/56
*Jun 27 15:09:03.711: IPv6 DHCP: Sending REQUEST to FF02::1:2 on Dialer1
*Jun 27 15:09:03.711: IPv6 DHCP: Received REPLY from FE80::7EAD:74FF:FEF9:EB00 on Dialer1
*Jun 27 15:09:03.711: IPv6 DHCP: detailed packet contents
*Jun 27 15:09:03.711:   src FE80::7EAD:74FF:FEF9:EB00 (Dialer1)
*Jun 27 15:09:03.711:   dst FE80::1234 (Dialer1)
*Jun 27 15:09:03.711:   type REPLY(7), xid 1849347
*Jun 27 15:09:03.711:   option SERVERID(2), len 10
*Jun 27 15:09:03.711:     000300017CAD74F9EB00
*Jun 27 15:09:03.711:   option CLIENTID(1), len 10
*Jun 27 15:09:03.711:     00030001000500772C1B
*Jun 27 15:09:03.711:   option IA-PD(25), len 41
*Jun 27 15:09:03.711:     IAID 0x000B0001, T1 302400, T2 483840
*Jun 27 15:09:03.711:   option IAPREFIX(26), len 25
*Jun 27 15:09:03.711:     preferred 604800, valid 2592000, prefix 2A02:838F:F880::/56
*Jun 27 15:09:03.711: IPv6 DHCP: Processing options
*Jun 27 15:09:03.711: IPv6 DHCP: Adding prefix 2A02:838F:F880::/56 to my-prefix1
*Jun 27 15:09:03.711: IPv6 DHCP: T1 set to expire in 302400 seconds
*Jun 27 15:09:03.711: IPv6 DHCP: T2 set to expire in 483840 seconds
*Jun 27 15:09:03.711: IPv6 DHCP: DHCPv6 changes state from REQUEST to OPEN (REPLY_RECEIVED) on Dialer1

```

## Related Information

- [IPv6 Access Service: DHCPv6 Prefix Delegation](#)

- [Technical Support & Documentation - Cisco Systems](#)