

SG350XG: Some Functions in the Web-based Utility are not Responding

Date Identified

May 23, 2017

Date Resolved

N/A

Product Affected

SG350XG	2.2.0.x

Problem Description

Some of the functions in the web-based utility of the switch are not working when using the Apple Safari browser. These functions in the utility that do not respond include the **Reboot** and **Logout** buttons, as well as the **Stop** button of Locate Device page.

Workaround

Use other browsers such as Google Chrome, Mozilla Firefox, or Microsoft Edge.