

Access Point Service Packs (APSPs) for Field Notice 74035 (CSCwf67316)

Contents

This table provides links to the Access Point Service Packs (APSPs) to address Field Notice 74035. These APSPs apply only to Cisco IOS® XE 17.3.7, 17.6.5 and 17.9.3, and will be superseded by the 17.3.8, 17.6.6 and 17.9.4 releases. The APSPs provide fixes only for the following AP series: 2800, 2800, 4800, 1560, IW6300, ESW6300.

For more details see:

[Field Notice 74035](#)

[CSCwf67316: 2800/3800/4800/1560/IW6300 may not detect radar on the required levels after CAC time](#)

Release	APSP Image	
17.3.7	9800-40: https://software.cisco.com/download/home/286316412/type/286325254/release/17.3.7 Image name: C9800-universalk9_wlc.17.03.07.CSCwf84244.SPA.apsp.bin	https://www.cisco.com
	9800-80: https://software.cisco.com/download/home/286321396/type/286325254/release/17.3.7 Image name: C9800-universalk9_wlc.17.03.07.CSCwf84244.SPA.apsp.bin	
	9800-L: https://software.cisco.com/download/home/286323430/type/286325254/release/17.3.7 Image name: C9800-L-universalk9_wlc.17.03.07.CSCwf84244.SPA.apsp.bin	
	9800-CL: https://software.cisco.com/download/home/286322605/type/286325254/release/17.3.7 Image name: C9800-CL-universalk9.17.03.07.CSCwf84244.SPA.apsp.bin	
	9800-SW (EWC-Switch): https://software.cisco.com/download/home/286313994/type/286325254/release/17.3.7 Image name: cat9k_iosxe.17.03.07.CSCwf84244.SPA.apsp.bin	
	EWC C9105: https://software.cisco.com/download/home/286324858/type/286325254/release/17.3.7 Image name: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip EWC C9115:	

	<p>https://software.cisco.com/download/home/286321056/type/286325254/release/17.3.7 Image name: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9117: https://software.cisco.com/download/home/286321061/type/286325254/release/17.3.7 Image name: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9120: https://software.cisco.com/download/home/286323294/type/286325254/release/17.3.7 Image name: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9124: https://software.cisco.com/download/home/286326614/type/286325254/release/17.3.7 Image name: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9130: https://software.cisco.com/download/home/286323998/type/286325254/release/17.3.7 Image name: C9800-AP-universalk9.17.03.07.CSCwf84244.SPA.apsp.zip</p>	
17.6.5	<p>9800-40: https://software.cisco.com/download/home/286316412/type/286325254/release/17.6.5 Image name: C9800-universalk9_wlc.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-80: https://software.cisco.com/download/home/286321396/type/286325254/release/17.6.5 Image name: C9800-universalk9_wlc.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-L: https://software.cisco.com/download/home/286323430/type/286325254/release/17.6.5 Image name: C9800-L-universalk9_wlc.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-CL: https://software.cisco.com/download/home/286322605/type/286325254/release/17.6.5 Image name: C9800-CL-universalk9.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>9800-SW (EWC-Switch): https://software.cisco.com/download/home/286313994/type/286325254/release/17.6.5 Image name: cat9k_iosxe.17.06.05.CSCwf84244.SPA.apsp.bin</p> <p>EWC C9105: https://software.cisco.com/download/home/286324858/type/286325254/release/17.6.5 Image name: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9115: https://software.cisco.com/download/home/286321056/type/286325254/release/17.6.5 Image name: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9117: https://software.cisco.com/download/home/286321061/type/286325254/release/17.6.5 Image name: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9120: https://software.cisco.com/download/home/286323294/type/286325254/release/17.6.5 Image name: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p>	https://www.cisco.com

	<p>EWC C9124: https://software.cisco.com/download/home/286326614/type/286325254/release/17.6.5 Image name: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9130: https://software.cisco.com/download/home/286323998/type/286325254/release/17.6.5 Image name: C9800-AP-universalk9.17.06.05.CSCwf84244.SPA.apsp.zip</p>	
<p>17.9.3</p>	<p>9800-40: https://software.cisco.com/download/home/286316412/type/286325254/release/17.9.3 Image name: C9800-universalk9_wlc.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-80: https://software.cisco.com/download/home/286321396/type/286325254/release/17.9.3 Image name: C9800-universalk9_wlc.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-L: https://software.cisco.com/download/home/286323430/type/286325254/release/17.9.3 Image name: C9800-L-universalk9_wlc.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-CL: https://software.cisco.com/download/home/286322605/type/286325254/release/17.9.3 Image name: C9800-CL-universalk9.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>9800-SW (EWC-Switch): https://software.cisco.com/download/home/286313994/type/286325254/release/17.9.3 Image name: cat9k_iosxe.17.09.03.CSCwf84244.SPA.apsp.bin</p> <p>EWC C9105: https://software.cisco.com/download/home/286324858/type/286325254/release/17.9.3 Image name: C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9115: https://software.cisco.com/download/home/286321056/type/286325254/release/17.9.3 Image name: C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9117: https://software.cisco.com/download/home/286321061/type/286325254/release/17.9.3 Image name: C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9120: https://software.cisco.com/download/home/286323294/type/286325254/release/17.9.3 Image name: C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9124: https://software.cisco.com/download/home/286326614/type/286325254/release/17.9.3 Image name: C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip</p> <p>EWC C9130: https://software.cisco.com/download/home/286323998/type/286325254/release/17.9.3 Image name: C9800-AP-universalk9.17.09.03.CSCwf84244.SPA.apsp.zip</p>	<p>https://www.cisco.com</p>