

Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats.

The *Open Caveats* section lists open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.



Note


The *Caveats* section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- Cisco Bug Search, on page 1
- Open Caveats for Cisco 1x2 / Compact Shelf RPD Software 2.2, on page 2
- Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 2.2, on page 2


Cisco Bug Search

Use the Cisco Bug Search Tool to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.



You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.



Open Caveats for Cisco 1x2 / Compact Shelf RPD Software 2.2

Caveat ID Number	Description
CSCvg02212	RPHY: Interleaves are not support for Annex B

Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 2.2

Caveat ID Number	Description
CSCve18110	rpd stuck at init(clock)
CSCve19967	RPD SSD download fail due to Cannot allocate memory
CSCve73662	Dummy info in show cable rpd identification or version
CSCve75751	D31:RxMER is wrong when modem online
CSCve88972	RPD grouping take long time to choose primary
CSCve94405	Failed to IPv6 SSD from RPD side
CSCve96162	RPHY: Support for pre-equalization and ingress noise cancellation on RPD
CSCvf06301	RPHY: modem p-online after change the RPD ds controller profile
CSCvf06396	Should not print out system file path msg after SSH login to RPD
CSCvf09983	1RU shelf: small rate downstream packets drop in low or high temperature
CSCvf10050	RPD may take long time to be operational
CSCvf17069	OFDM power is changed after mute and no-mute the channel
CSCvf23411	Re-config the QAM channel will impact the existing Pilot channel setting
CSCvf33966	traffic loss erratically when no and add back the OOB profile

Caveat ID Number	Description
CSCvf38677	RPD cannot be online after double failure until a reset
CSCvf58658	RPHY: after cBR changed equalization and inc_enable, show cli can not update on node side.
CSCvf60415	RPHY - RPD does not come online when using Interleaver depth > 1
CSCvf70748	RPHY: interop l2tp session id duplicated when multiple SCQAM and OFDM channels
CSCvf67474	RPD stuck and not keep rebooting
CSCvf11078	Pilot tone power level can not be adjusted in expected range

Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 2.2