

# Cisco TelePresence Collaboration Endpoint (CE) RoomOS 1.0: Denial of Service (DoS) Vulnerability

CVE-2022-20783



**Severity:** High  
**CVE ID:** CVE-2022-20783  
**Published:** 2022-04-20 16:00  
**Product:** Cisco TelePresence Collaboration Endpoint (CE) RoomOS 1.0: Final  
**CVSS Score:** 7.5  
**Workarounds:** No workarounds available  
**Cisco ID:** CSCvz55702

**Summary:** A Denial of Service (DoS) vulnerability exists in Cisco TelePresence Collaboration Endpoint (CE) RoomOS 1.0. An attacker can exploit this vulnerability to cause a denial of service on the affected device.

**Impact:**

Cisco TelePresence Collaboration Endpoint (CE) RoomOS 1.0 is vulnerable to a Denial of Service (DoS) attack. An attacker can exploit this vulnerability to cause a denial of service on the affected device. The vulnerability is caused by a buffer overflow in the CE's SIP stack.

The vulnerability is caused by a buffer overflow in the CE's SIP stack. An attacker can exploit this vulnerability to cause a denial of service on the affected device.

For more information, please refer to the following link:  
<https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-ce-roomos-dos-c65x2Qf2>

**References:**

<https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-ce-roomos-dos-c65x2Qf2>

RoomOS 1.0 is vulnerable to a Denial of Service (DoS) attack. An attacker can exploit this vulnerability to cause a denial of service on the affected device. The vulnerability is caused by a buffer overflow in the CE's SIP stack.

For more information, please refer to the following link:  
<https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-ce-roomos-dos-c65x2Qf2>







å^©ç””è!ç´,,

æœ-ã,çãf%ãfã,ã,ã,ã,ãfãç,,iàçè”¼ã@ã,,ã@ã”ã—ã|ã”æãã¼ã—ã|ãŠã,Šã€  
æœ-ã,çãf%ãfã,ã,ã,ã,ãfã@æf...å±ãŠã,^ã³ãfãfã,ã@ã½ç””ã«é-çã™ã,«è²-ä»ã@ä,€  
ã¼ãÿã€ã,ã,ã,ãæœ-ãf%ã,ãfãfãfãfã@ãt...ã¹ã,ã^ãŠãã—ã«ã%ãæ’ã—ã  
æœ-ã,çãf%ãfã,ã,ã,ã,ãfã@è”~èç°ãt...ã¹ã«é-çã—ã|æf...å±é...ãçjã@ URL  
ã,çœç•¥ã—ã€ããç<-ã@è»çè¼%ã,,,æ,,è”³ã,æ-½ã—ãÿã’ã^ã€ã½”ç¼ãÇç@çç  
ã”ã@ãf%ã,ãfãfãfãfã@æf...å±ãæã,ã,ã,ã,³è£½ã”ã@ã,ãfãf%ãf!ãf¼ã,ã,ã³¼è±jã

## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。