

Cisco Small Business RV160x/RV260x語言選擇使用者介面錯誤

缺陷引用ID:CSCvn27058

識別日期

2018年11月11日

解決日期

2018年12月13日

受影響的產品

型號	韌體版本	修復位置
RV160x、RV260x	1.0.00.14	1.0.00.15

問題描述


當作業系統或瀏覽器語言設定為時，圖形使用者介面(GUI)中的錯誤會異常顯示單詞；

- 德語
- 法文
- 義大利文
- 西班牙文

解析

步驟1. 下載最新的韌體1.0.00.15或更高版本[[RV160 Link](#)] [[RV260 Link](#)]。

步驟2. 登入到路由器的管理介面後，您可以使用快速連結。



或者，也可以使用邊欄導航連結，按一下**Administration**，然後載入**File Management**頁面。



Status and Statistics



Administration

File Management

Reboot

Diagnostic


Certificate

Configuration
Management




System Configuration

步驟3. 按一下**browse**按鈕，導覽至下載的韌體檔案的位置。



步驟4.按一下檔案將其選中，然後按一下開啟。



步驟5.按一下Upgrade按鈕，韌體開始更新。



File Management

System Information

Device Model: RV160W
PID VID: RV160W-A-K9 V01
Current Firmware Version: 1.0.00.15
Latest Version Available on Cisco.com: -
Firmware Last Updated: 2019-Jan-10, 14:08:32

Manual Upgrade

File Type: Firmware Image Language File

Upgrade From: cisco.com PC USB

Firmware Image Format: *.img (Maximum size: 100MB)

[Browse...](#)

RV16X_26X-v1.0.00.15-2018-11-19-22-20-20-PM.img

Reset all configurations/settings to factory defaults

[Upgrade](#)

The device will be automatically rebooted after the upgrade is complete.

升級韌體可防止錯誤再次出現。