

# لرباكل GRE ق فن نيوكت

## المحتويات

- [المقدمة](#)
- [قبل البدء](#)
- [الاصطلاحات](#)
- [المتطلبات الأساسية](#)
- [المكونات المستخدمة](#)
- [النظرة الأساسية](#)
- [التكوين](#)
- [الرسم التخطيطي للشبكة](#)
- [التكوينات](#)
- [التحقق من الصحة](#)
- [استكشاف الأخطاء وإصلاحها](#)
- [معلومات ذات صلة](#)

## المقدمة

يحتوي هذا المستند على أوصاف وتكوينات وعمليات تحقق لتغليف التوجيه العام (GRE) في بيئة كبلية. GRE هو بروتوكول إنشاء أنفاق مطور من قبل Cisco يمكنه تضمين مجموعة متنوعة من أنواع حزم بروتوكولات طبقة الشبكة داخل أنفاق IP.

## قبل البدء

### الاصطلاحات

للحصول على مزيد من المعلومات حول اصطلاحات المستندات، راجع [اصطلاحات تلميح Cisco التقنية](#).

### المتطلبات الأساسية

لا توجد متطلبات أساسية خاصة لهذا المستند.

### المكونات المستخدمة

تستند المعلومات الواردة في هذا المستند إلى إصدارات البرامج والمكونات المادية أدناه.

- مودم الكبل uBR924 الذي يشغل برنامج Cisco IOS © الإصدار 12.1(5)T4
- ملاحظة: على الرغم من أنه من الممكن تكوين أنفاق GRE في منصات مودم كبل Cisco الأخرى، مثل على uBR904 باستخدام إصدارات مختلفة من Cisco IOS، فإن الدعم الرسمي لهذه الميزة هو على Cisco IOS T4(5)12.1 لـ uBR920 (ومن 12.1(3) Cisco IOS) لـ uBR910.

إصدار برنامج IOS من Cisco	النظام الأساسي لمودم الكبل
T4(5)12.1	uBR920
من 12.1(3) وما بعده	uBR910

لتشغيل هذا التكوين، يلزمك توفر [اتصال IP](#) بين أجهزة مودم الكبل.

تم إنشاء المعلومات المقدمة في هذا المستند من الأجهزة الموجودة في بيئة معملية خاصة. بدأت جميع الأجهزة المستخدمة في هذا المستند بتكوين ممسوح (افتراضي). إذا كنت تعمل في شبكة مباشرة، فتأكد من فهمك للتأثير المحتمل لأي أمر قبل استخدامه.

## النظرية الأساسية

يوفر الاتصال النفقي طريقة لتضمين الحزم من بروتوكول خارجي داخل بروتوكول نقل. يتم تنفيذ الاتصال النفقي كواجهة افتراضية لتوفير واجهة بسيطة للتكوين. لا يتم ربط واجهة النفق ببروتوكولات نقل أو ركاب معينة، ومع ذلك، فهي بنية تم تصميمها لتوفير الخدمات الضرورية لتنفيذ أي مخطط تضمين قياسي من نقطة إلى نقطة. تكون الأنفاق إرتباطات من نقطة إلى نقطة، ويجب عليك تكوين نفق منفصل لكل إرتباط.

تقوم GRE بإنشاء إرتباط ظاهري من نقطة إلى نقطة بموجهات Cisco عند نقاط بعيدة عبر شبكة IP البينية. من خلال توصيل الشبكات الفرعية متعددة البروتوكولات في بيئة أساسية أحادية البروتوكول، تتيح أنفاق IP باستخدام GRE إمكانية توسيع الشبكة عبر بيئة أساسية أحادية البروتوكول. نظام توصيل مودم الكبل (CMTS) هو أي موجه كبل وحدة الاستقبال والبت عبر الكبلات (DOCSIS) متوافق مع مواصفات واجهة خدمة البيانات المنقولة عبر الكبلات، مثل Cisco uBR7246، أو uBR7223، أو uBR7246VXR.

## التكوين


في هذا القسم، تُقدّم لك معلومات تكوين الميزات الموضحة في هذا المستند.

### الرسم التخطيطي للشبكة

يستخدم هذا المستند إعداد الشبكة الموضح في الرسم التخطيطي أدناه.

يقوم هذا الإعداد بإنشاء نفق بين مودم الكبل uBR924-ddd5 و uBR924-b5db باستخدام المثال التالي وحدتي uBR924s و uBR7246VXR. بالنسبة لهذا الإعداد، أسماء أجهزة مودم الكبل هي uBR924-ddd5 و uBR924-b5db، وهي تستخدم الإصدار T4(5)12.1 من Cisco IOS. يتم إنشاء واجهات النفق ديناميكياً في وضع التكوين العام من خلال إصدار الأمر `interface tunnel 0`.

**ملاحظة:** لا يلزم توصيل أجهزة مودم كبل uBR900 بـ CMTS نفسه uBR7200 أو شبكة مزود الخدمة نفسه طالما كان هناك اتصال IP بين أجهزة مودم الكبل.



## التكوينات





```

!
ip default-gateway 10.1.4.1
    ip classless
    no ip http server
    no ip http cable-monitor
!
snmp-server packetsize 4096
    snmp-server manager
!
    voice-port 0
    input gain -2
!
    voice-port 1
    input gain -2
!
!
    line con 0
    exec-timeout 0 0
    transport input none
    line vty 0 4
    password ww
    login
!
    end
#ubr924-b5db

```

## التحقق من الصحة

يوفر هذا القسم معلومات يمكنك استخدامها للتأكد من أن التكوين يعمل بشكل صحيح.

يتم دعم بعض أوامر العرض بواسطة أداة مترجم الإخراج، والتي تتيح لك عرض تحليل إخراج أمر العرض.

تحقق من صحة تكوين (7246VXR CMTS)، ومن اتصال أجهزة مودم الكبلات. يتم عرض تكوين CMTS أدناه.

```

7246VXR#show run
...Building configuration

Current configuration : 4579 bytes
!
Last configuration change at 13:22:17 PDT Mon Feb 26 2001 !
NVRAM config last updated at 13:22:46 PDT Mon Feb 26 2001 !
!
    version 12.1
    no service single-slot-reload-enable
    no service pad
    service timestamps debug datetime msec localtime
    service timestamps log datetime localtime
    no service password-encryption
    service linenumbers
    service udp-small-servers max-servers no-limit
!
    hostname 7246VXR
!
    logging buffered 1000000 debugging
    logging rate-limit console 10 except errors
    enable password cable
!

```

```

        cable qos profile 8
        cable qos profile 10
        cable qos profile 10 grant-size 1500
cable qos profile 12 guaranteed-upstream 100000
        no cable qos permission create
        no cable qos permission update
        cable qos permission modems
        cable time-server
        clock timezone PDT -8
        clock summer-time PDT recurring
        clock calendar-valid
        ip subnet-zero
        no ip finger
        !
        interface Ethernet2/0
ip address 172.16.30.4 255.255.255.192
        no ip mroute-cache
        half-duplex
        !

interface Cable4/0
ip address 172.16.29.1 255.255.255.224 secondary
        ip address 10.1.4.1 255.255.255.0
        no keepalive
cable downstream rate-limit token-bucket shaping
        cable downstream annex B
        cable downstream modulation 64qam
cable downstream interleave-depth 32
cable downstream frequency 55500000
cable upstream 0 frequency 40000000
cable upstream 0 power-level 0
        no cable upstream 0 shutdown
        cable upstream 1 shutdown
        cable upstream 2 shutdown
        cable upstream 3 shutdown
        cable upstream 4 shutdown
        cable upstream 5 shutdown
        cable dhcp-giaddr policy
cable helper-address 172.16.30.2
        !
        interface Cable5/0
ip address 172.16.29.225 255.255.255.224 secondary
        ip address 10.1.5.1 255.255.255.0
        load-interval 30
        no keepalive
cable downstream rate-limit token-bucket shaping
        cable downstream annex B
        cable downstream modulation 64qam
cable downstream interleave-depth 32
cable downstream frequency 62000000
cable upstream 0 frequency 25008000
        cable upstream 0 power-level 0
        no cable upstream 0 shutdown
        no cable upstream 1 shutdown
        cable dhcp-giaddr policy
        !
        router eigrp 202
        redistribute connected
        redistribute static
        network 10.0.0.0
        network 172.16.0.0
        no auto-summary
        no eigrp log-neighbor-changes
        !

```

```

router rip
version 2
redistribute connected
redistribute static
network 10.0.0.0
network 172.16.0.0
no auto-summary
!
ip default-gateway 172.16.30.1
ip classless
ip route 0.0.0.0 0.0.0.0 172.16.30.1
ip route 172.16.30.0 255.255.255.0 Ethernet2/0
ip http server
ip http authentication local
!
access-list 188 permit tcp any any eq www log
access-list 188 permit ip any any
route-map docsis permit 10
!
snmp-server engineID local 00000009020000E01ED77E40
snmp-server community public RO
snmp-server community private RW

line con 0
exec-timeout 0 0
transport input none
line aux 0
speed 19200
line vty 0 4
session-timeout 60
exec-timeout 0 0
!
ntp clock-period 17179973
end

```

```

7246VXR#show cable modem

```

Interface	Prim Online	Timing	Rec	QoS	CPE	IP address	MAC address
		Sid	State	Offset	Power		
<b>Cable4/0/U0 69</b>	<b>online</b>	<b>2812</b>	<b>0.25 5</b>	<b>0</b>	<b>10.1.4.3</b>	<b>0002.1685.b5db</b>	
Cable4/0/U0 70	online	2288	0.00 5	0	10.1.4.6	0010.7bed.9b23	
Cable4/0/U0 71	online	2289	0.50 5	0	10.1.4.2	0010.7bed.9b45	
Cable4/0/U0 72	online	2812	0.00 5	0	10.1.4.4	0002.fdfa.0a63	
<b>Cable4/0/U0 73</b>	<b>online</b>	<b>2812</b>	<b>-0.75 5</b>	<b>0</b>	<b>10.1.4.5</b>	<b>0004.2752.ddd5</b>	
Cable4/0/U0 74	online	2813	0.25 5	0	10.1.4.7	0001.64ff.e47d	

إذا لم تظهر حالة أجهزة مودم الكبل على الإنترنت ، فارجع إلى [أستكشاف أخطاء أجهزة مودم كبل uBR التي لا تظهر](#) [المستند على الإنترنت وإصلاحها](#).

```

7246VXR#show ip interface brief

```

Interface	IP-Address	OK?	Method	Status	Protocol
FastEthernet0/0	192.168.7.253	YES	NVRAM	up	down
Ethernet2/0	172.16.30.4	YES	manual	up	up
<b>Ethernet2/1</b>	<b>unassigned</b>	<b>YES</b>	<b>NVRAM</b>	<b>administratively down</b>	<b>down</b>
Ethernet2/2	unassigned	YES	NVRAM	administratively down	down
Ethernet2/3	unassigned	YES	NVRAM	administratively down	down
Cable3/0	10.1.3.1	YES	manual	up	up
<b>Cable4/0</b>	<b>10.1.4.1</b>	<b>YES</b>	<b>manual</b>	<b>up</b>	<b>up</b>
Cable5/0	10.1.5.1	YES	manual	up	up

```

7246VXR#show ip route
Codes: C - connected, S - static, I - IGRP, R - RIP, M - mobile, B - BGP
D - EIGRP, EX - EIGRP external, O - OSPF, IA - OSPF inter area
N1 - OSPF NSSA external type 1, N2 - OSPF NSSA external type 2

```

E1 - OSPF external type 1, E2 - OSPF external type 2, E - EGP  
i - IS-IS, L1 - IS-IS level-1, L2 - IS-IS level-2, ia - IS-IS inter area  
candidate default, U - per-user static route, o - ODR - \*  
P - periodic downloaded static route

Gateway of last resort is 172.16.30.1 to network 0.0.0.0

is variably subnetted, 4 subnets, 3 masks 172.16.0.0/16  
C 172.16.29.224/27 is directly connected, Cable5/0  
C 172.16.29.0/27 is directly connected, Cable4/0  
S 172.16.30.0/24 is directly connected, Ethernet2/0  
C 172.16.30.0/26 is directly connected, Ethernet2/0  
is subnetted, 1 subnets 9.0.0.0/24  
R 9.9.9.0 [120/1] via 10.1.4.5, 00:00:09, Cable4/0  
R 192.168.20.0/24 [120/1] via 10.1.4.5, 00:00:09, Cable4/0  
is variably subnetted, 5 subnets, 2 masks 10.0.0.0/8  
C 10.1.3.0/24 is directly connected, Cable3/0  
R 10.5.5.0/24 [120/1] via 10.1.4.4, 00:00:01, Cable4/0  
R 10.0.0.0/8 [120/1] via 172.16.30.10, 00:00:24, Ethernet2/0  
C 10.1.5.0/24 is directly connected, Cable5/0  
C 10.1.4.0/24 is directly connected, Cable4/0  
is subnetted, 1 subnets 11.0.0.0/24  
R 11.11.11.0 [120/1] via 10.1.4.3, 00:00:15, Cable4/0  
S\* 0.0.0.0/0 is directly connected

من جانب أجهزة مودم الكبل، تحقق من إصدار sh من كلا الجهازين، كما هو موضح أدناه.

```
ubr924-ddd5#sh ver
Cisco Internetwork Operating System Software
(IOS (tm) 920 Software (UBR920-K1V4Y556I-M), Version 12.1(5)T4, RELEASE SOFTWARE (fc1
TAC Support: http://www.cisco.com/cgi-bin/ibld/view.pl?i=support
.Copyright (c) 1986-2001 by cisco Systems, Inc
Compiled Fri 02-Feb-01 10:55 by ccai
Image text-base: 0x800100A0, data-base: 0x806DB770
```

```
(ROM: System Bootstrap, Version 12.0(6r)T3, RELEASE SOFTWARE (fc1
(ROM: 920 Software (UBR920-K1V4Y556I-M), Version 12.1(5)T4, RELEASE SOFTWARE (fc1
```

```
ubr924-ddd5 uptime is 2 hours, 1 minute
System returned to ROM by reload at 12:45:25 - Fri Feb 23 2001
System restarted at 12:46:07 - Fri Feb 23 2001
"System image file is "flash:ubr920-k1v4y556i-mz.121-5.T4
```

```
.cisco uBR920 CM (MPC850) processor (revision 4.d) with 15872K/1024K bytes of memory
Processor board ID FAA0444Q14Z
.Bridging software
(Ethernet/IEEE 802.3 interface(s) 1
(Cable Modem network interface(s) 1
(3968K bytes of processor board System flash (Read/Write
(1536K bytes of processor board Boot flash (Read/Write
```

Configuration register is 0x2102

```
ubr924-b5db#show ver
Cisco Internetwork Operating System Software
(IOS (tm) 920 Software (UBR920-K1V4Y556I-M), Version 12.1(5)T4, RELEASE SOFTWARE (fc1
TAC Support: http://www.cisco.com/cgi-bin/ibld/view.pl?i=support
.Copyright (c) 1986-2001 by cisco Systems, Inc
Compiled Fri 02-Feb-01 10:55 by ccai
Image text-base: 0x800100A0, data-base: 0x806DB770
```

```
(ROM: System Bootstrap, Version 12.0(6r)T3, RELEASE SOFTWARE (fc1
```



ubr924-b5db uptime is 1 hour, 53 minutes  
System returned to ROM by reload at 12:55:34 - Fri Feb 23 2001  
System restarted at 12:56:15 - Fri Feb 23 2001  
"System image file is "flash:ubr920-k1v4y556i-mz.121-5.T4

.cisco uBR920 CM (MPC850) processor (revision 3.e) with 15872K/1024K bytes of memory  
Processor board ID FAA0422Q04F  
.Bridging software  
(Ethernet/IEEE 802.3 interface(s 1  
(Cable Modem network interface(s 1  
(3968K bytes of processor board System flash (Read/Write  
(1536K bytes of processor board Boot flash (Read/Write

Configuration register is 0x2102

يظهر النفق / ما دامت الشروط التالية موجودة:

• تم تكوينه بعناوين IP صالحة.

• هناك مسار في جدول التوجيه إلى عنوان IP لوجهة النفق، وليس عنوان IP المعين إلى الطرف البعيد من النفق.  
يجب أن يكون هذا صحيحا بغض النظر عما إذا كان يمكنك اختبار اتصال عنوان الوجهة أم لا. مسار ثابت غير صحيح أو مسار افتراضي يشير إلى الإتجاه الخاطئ سيُجلب النفق، ومع ذلك، لن يعمل النفق.

الخطوة الأولى للتحقق من عمل النفق هي التحقق من تشغيل النفق. قم بإصدار الأمر **show ip interface brief** و**show interface tunnel 0** على كل من أجهزة مودم الكبل. يتم عرض عينة من مخرجات الأمر أدناه.

```
ubr924-ddd5#show ip interface brief
Interface                IP-Address      OK? Method Status        Protocol
Ethernet0                9.9.9.9         YES manual up            up
Tunnel0                  192.168.20.1   YES manual up            up
cable-modem0             10.1.4.5        YES unset  up            up
```

```
ubr924-ddd5#show interface tunnel 0
Tunnel0 is up, line protocol is up
Hardware is Tunnel
Internet address is 192.168.20.1/24
,MTU 1514 bytes, BW 9 Kbit, DLY 500000 usec
reliability 255/255, txload 1/255, rxload 1/255
Encapsulation TUNNEL, loopback not set
(Keepalive set (10 sec
Tunnel source 9.9.9.9 (Ethernet0), destination 11.11.11.11
Tunnel protocol/transport GRE/IP, key disabled, sequencing disabled
Checksumming of packets disabled
Last input 00:15:25, output 00:14:27, output hang never
Last clearing of "show interface" counters never
Queueing strategy: fifo
Output queue 0/0, 2 drops; input queue 0/75, 0 drops
minute input rate 0 bits/sec, 0 packets/sec 5
minute output rate 0 bits/sec, 0 packets/sec 5
packets input, 21024 bytes, 0 no buffer 146
Received 0 broadcasts, 0 runts, 0 giants, 0 throttles
input errors, 0 CRC, 0 frame, 0 overrun, 0 ignored, 0 abort 0
packets output, 57392 bytes, 0 underruns 172
output errors, 0 collisions, 0 interface resets 0
output buffer failures, 0 output buffers swapped out 0
```

```
ubr924-b5db#show ip interface brief
Interface                IP-Address      OK? Method Status        Protocol
```

```

Ethernet0          11.11.11.11      YES manual up      up
Tunnel0           192.168.20.2    YES manual up      up
cable-modem0     10.1.4.3        YES NVRAM up        up

```

```

ubr924-b5db#show interface tunnel 0
Tunnel0 is up, line protocol is up
      Hardware is Tunnel
      Internet address is 192.168.20.2/24
      ,MTU 1514 bytes, BW 9 Kbit, DLY 500000 usec
      reliability 255/255, txload 1/255, rxload 1/255
      Encapsulation TUNNEL, loopback not set
      (Keepalive set (10 sec
Tunnel source 11.11.11.11 (Ethernet0), destination 9.9.9.9
Tunnel protocol/transport GRE/IP, key disabled, sequencing disabled
      Checksumming of packets disabled
      Last input 00:16:42, output 00:17:40, output hang never
      Last clearing of "show interface" counters never
      Queueing strategy: fifo
      Output queue 0/0, 5 drops; input queue 0/75, 0 drops
      minute input rate 0 bits/sec, 0 packets/sec 5
      minute output rate 0 bits/sec, 0 packets/sec 5
      packets input, 19144 bytes, 0 no buffer 118
      Received 0 broadcasts, 0 runts, 0 giants, 0 throttles
      input errors, 0 CRC, 0 frame, 0 overrun, 0 ignored, 0 abort 0
      packets output, 49624 bytes, 0 underruns 164
output errors, 0 collisions, 0 interface resets 0
output buffer failures, 0 output buffers swapped out 0

```

دقت أن يعمل النفق أن يؤشر النفق غاية عنوان. سيقوم هذا بالتحقق من اتصال IP فقط، وليس التشغيل الفعلي للنفق.

```

From ubr924-ddd5 we ping 11.11.11.11
ubr924-ddd5#ping 11.11.11.11

.Type escape sequence to abort
:Sending 5, 100-byte ICMP Echos to 11.11.11.11, timeout is 2 seconds
!!!!
Success rate is 100 percent (5/5), round-trip min/avg/max = 12/14/17 ms
ubr924-ddd5#

```

يتم إختبار الاتصال من uBR924-b5db عنوان الوجهة 9.9.9.9.

```

ubr924-b5db#ping 9.9.9.9

.Type escape sequence to abort
:Sending 5, 100-byte ICMP Echos to 9.9.9.9, timeout is 2 seconds
!!!!
Success rate is 100 percent (5/5), round-trip min/avg/max = 12/14/16 ms
#ubr924-b5db

```

للتحقق من عمل النفق، قم بإصدار الأمر `show ip route x.x.x.x`، حيث يكون `x.x.x.x` عنوان IP المعين إلى الطرف البعيد من النفق. في هذه الحالة، سيكون هو عنوان التكرار الحلقي للموجه البعيد. إذا كان المسار الوحيد الموضح هو إلى واجهة النفق، فسيثبت إختبار الاتصال بهذا العنوان أن النفق يعمل.

إذا كان هناك مخطط عنوان IP يعلن عن الموجهات إلى مقطع النفق عبر الشبكة، فسيكون هناك أكثر من موجه إلى الطرف البعيد لواجهة النفق. وإذا كان هذا هو الحال، فمن الصعب جدا التحقق من ان النفق يعمل. عادة في هذه الحالة، لا تحتاج إلى مسارات متكررة إلى شبكة النفق. يجب إتخاذ خطوات لمنع الإعلان عن الموجهات بواسطة

بروتوكول توجيه عبر الشبكة. إن يكون النفق يكون استعملت أن ينقل حركة مرور من بروتوكول مختلف من IP، ال نفسه أساسى تدقيق طريقة يطبق.

```
From ubr924-ddd5 we get
ubr924-ddd5#show ip route 192.168.20.2
Routing entry for 192.168.20.0/24
(Known via "connected", distance 0, metric 0 (connected, via interface
:Routing Descriptor Blocks
directly connected, via Tunnel0 *
Route metric is 0, traffic share count is 1
```

```
From ubr924-b5db we get
ubr924-b5db#show ip route 192.168.20.1
Routing entry for 192.168.20.0/24
(Known via "connected", distance 0, metric 0 (connected, via interface
:Routing Descriptor Blocks
directly connected, via Tunnel0 *
Route metric is 0, traffic share count is 1
```

للتحقق من إمكانية وصول PC1 إلى PC2 والعكس بالعكس، قم بإجراء اختبارات اتصال موسعة على أجهزة مودم الكبلات، وكذلك اختبارات الاتصال من أجهزة الكمبيوتر.

قم بإجراء اختبار اتصال موسع على uBR924-b5db من واجهة إيثرنت (11.11.11.11) إلى واجهة إيثرنت الخاصة ب (uBR924-ddd5 (9.9.9.9).


```
ubr924-b5db#ping ip
Target IP address: 9.9.9.9
ubr924-ddd5 Ethernet's IP address. Repeat count [5]: Datagram size [100]: Timeout in ---!
seconds [2]: Extended commands [n]: y Source address or interface: 11.11.11.11
ubr924-b5db Ethernet's IP address. Type of service [0]: Set DF bit in IP header? [no]: ---!
Validate reply data? [no]: Data pattern [0xABCD]: Loose, Strict, Record, Timestamp,
Verbose[none]: Sweep range of sizes [n]: Type escape sequence to abort. Sending 5, 100-byte ICMP
!!!!!! :Echos to 9.9.9.9, timeout is 2 seconds
Success rate is 100 percent (5/5), round-trip min/avg/max = 12/16/28 ms
#ubr924-b5db
```

قم بإجراء العكس لاختبار اتصال الجانب الآخر.


```
ubr924-ddd5#ping ip
Target IP address: 11.11.11.11
ubr924-b5db Ethernet's IP address. Repeat count [5]: Datagram size [100]: Timeout in ---!
seconds [2]: Extended commands [n]: y Source address or interface: 9.9.9.9
ubr924-ddd5 Ethernet's IP address. Type of service [0]: Set DF bit in IP header? [no]: ---!
Validate reply data? [no]: Data pattern [0xABCD]: Loose, Strict, Record, Timestamp,
Verbose[none]: Sweep range of sizes [n]: Type escape sequence to abort. Sending 5, 100-byte ICMP
!!!!!! :Echos to 11.11.11.11, timeout is 2 seconds
Success rate is 100 percent (5/5), round-trip min/avg/max = 12/14/16 ms
ubr924-ddd5#
```

الاختبار الأخير هو اختبار الاتصال من PC1 إلى PC2، و PC2 إلى PC1.

PC1 له عنوان 9.9.9.1 IP.



PC2 له عنوان IP و 11.11.11.1.



إختبار الاتصال من PC1 إلى PC2.

```
MS-DOS Prompt
Auto
Microsoft(R) Windows 95
(C)Copyright Microsoft Corp 1981-1996.
C:\WINDOWS>ping 11.11.11.1
Pinging 11.11.11.1 with 32 bytes of data:
Reply from 11.11.11.1: bytes=32 time=17ms TTL=125
Reply from 11.11.11.1: bytes=32 time=14ms TTL=125
Reply from 11.11.11.1: bytes=32 time=18ms TTL=125
Reply from 11.11.11.1: bytes=32 time=14ms TTL=125
C:\WINDOWS>_
```

إختبار الاتصال من PC2 إلى PC1.

```
MS-DOS Prompt
8 x 13
Microsoft(R) windows 98
(C)Copyright Microsoft Corp 1981-1998.
C:\WINDOWS>ping 9.9.9.1
Pinging 9.9.9.1 with 32 bytes of data:
Reply from 9.9.9.1: bytes=32 time=16ms TTL=29
Reply from 9.9.9.1: bytes=32 time=15ms TTL=29
Reply from 9.9.9.1: bytes=32 time=13ms TTL=29
Reply from 9.9.9.1: bytes=32 time=12ms TTL=29
Ping statistics for 9.9.9.1:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 12ms, Maximum = 16ms, Average = 14ms
C:\WINDOWS>_
```

## استكشاف الأخطاء وإصلاحها

لا تتوفر حاليًا معلومات محددة لاستكشاف الأخطاء وإصلاحها لهذا التكوين.

## معلومات ذات صلة

- [أستكشاف أخطاء أجهزة مودم كبل uBR وإصلاحها غير متوفرة عبر الإنترنت](#)
- [الدعم الفني - Cisco Systems](#)

ةمچرتل هذه لوج

ةللأل تاي نقتل نمة ومة مادختساب دن تسمل اذة Cisco تمةرت  
ملاعلاء انء مء مء نمة دختسمل معد و تمة مء دقتل ةر شبل او  
امك ةق قء نوك ت نل ةللأل ةمچرت لصف أن ةظحال مء ءرء. ةصاأل مء تءل ب  
Cisco ةللخت. فرتمة مچرت مء دقء ةللأل ةل فارتحال ةمچرتل عم لاعل او  
ىل إلمءءاد ءوچرلاب ةصوء و تامةرتل هذه ةقء نء اهءل وئس م Cisco  
Systems (رفوتم طبارل) ةلصلأل ةزىلچنلأل دن تسمل