

جمانرب عاطخاً فاشكتسأ Bootflash و System Image Recovery دادرتسا (ماظنلا ڦروص دادرتسا) احallas او CGOS نم CGR 1000

المحتويات

[المقدمة](#)

[معلومات أساسية](#)

[المتطلبات الأساسية](#)

[المتطلبات](#)

[المكونات المستخدمة](#)


[خطوات الاسترداد](#)

المقدمة

يصف هذا المستند خطوات أستكشاف المشكلات لاستعادة ذاكرة التمهيد المؤقتة (bootflash) وصورة النظام على CGR 1000.

معلومات أساسية

يستخدم CGR1000 ذاكرة البطاقة الرقمية الآمنة (SD) من Cisco لعرض صور المخزنة وصور النظام والتكوينات، وما إلى ذلك. في عمليات *occas* نادرة، تتعرض بطاقة SD للتلف. ونتيجة لذلك، تتلف صورة kickstart وأو صورة النظام. وهذا يمنع CGR من التمهيد. ويرد في الشكل المحدد تسلسل التمهيد. الغرض من مخطط الإجراء الوارد في هذه المقالة هو إستعادة CGR من حالة ذاكرة بطاقة SD تالفة.



المتطلبات الأساسية

1. خادم بروتوكول نقل الملفات البسيط (TFTP)المثبت على الكمبيوتر المحلي
2. إعداد خادم TFTP للحصول على صورة Kickstart وصورة النظام

المتطلبات

توصي Cisco بأن تكون لديك معرفة بالمواضيع التالية:

1. كبل وحدة التحكم

2- إتفاقية مناهضة التعذيب(5)

المكونات المستخدمة

يقتصر هذا المستند على إصدار CGOS الذي يتم تشغيله على CGR 1120 وCGR1240 فقط. تم إنشاء المعلومات الواردة في هذا المستند من الأجهزة الموجودة في بيئه معملية خاصة. بدأت جميع الأجهزة المستخدمة في هذا المستند بتكون ممسوح (افتراضي). إذا كانت شبكتك مباشرة، فتأكد من فهمك للتأثير المحتمل لأي أمر.

خطوات الاسترداد

1. إعداد كبل وحدة التحكم باستخدام برنامج.
2. قم بتوصيل كبل CAT5 من بطاقة واجهة الشبكة (NIC) الخاصة بالكمبيوتر المحلي إلى CGR ETH 2/2 . هذه هي الواجهة الوحيدة التي تعمل في وقت عملية الاسترداد.
3. قم بإعداد بطاقة واجهة الشبكة (NIC) الخاصة بالكمبيوتر المحلي لتكون في الشبكة الفرعية نفسها الخاصة بـ.CGR

على سبيل المثال، بطاقة واجهة الشبكة (NIC) الخاصة بالكمبيوتر هي 192.0.2.1 شبكة فرعية 0.255.255.255.0 بالنسبة ل CGR ستكون 192.0.2.2 شبكة فرعية 0.255.255.255.0

4. في جلسة PuTTY، ترى:

```
"<loader"

IOFPGA @ 0xd0000000 version=0x30020700, datecode=0xc080d17 CPLD version 0x14
(Reset Reason = 0(0
!!! Scratch pad test passed

BIOS Version: Build # 12 - Wed 06/27/2012
CGR Loader Version: 1.00.01

Filesystem type is ext2fs, partition type 0x83
Filesystem type is ext2fs, partition type 0x83

GNU GRUB  version 0.97
```

CGR Loader Version 1.00.01

5. قم بإعداد عنوان IP الخاص ب 2/2 ETH باستخدام الأمر "set ip"

```
set ip 192.0.2.2 255.255.255.0
```

<loader

6. قم بإعداد عنوان البوابة ليكون هو بطاقة واجهة الشبكة (NIC) الخاصة بالكمبيوتر المحلي باستخدام الأمر "gw".

```
set gw 192.0.2.1
```

```
Correct gateway addr 192.0.2.1
          Address: 192.0.2.2
          Netmask: 255.255.255.0
          Server: 0.0.0.0
          Gateway: 192.0.2.1
```

7. قم بتمهيد صورة kickstart من خادم TFTP المحلي باستخدام الأمر "://boot tftp".

```
          .INIT: Checking all filesystems ..... done
          Warning: switch is starting up with default configuration
                    ...Creating boot config file
etc/rc.d/rcS.d/S26check-flash: line 528: /mnt/bootloader/boot/grub/menu.lst.local: No such file/
                                         or directory
cp: cannot stat `/mnt/cfg/0/boot/grub/menu.lst.local': No such file or directory
WARNING: image sync is going to be disabled after a loader netboot
          Loading system software
          INIT: Sending processes the TERM signal [H [J
          INIT: Sending processes the TERM signal
          INIT: Sending processes the KILL signal
```

8. بمجرد تمهيد الصورة لأعلى، ستري مخرجات مماثلة لهذا المخرج.

```
? #(Router(boot
      :Exec commands
clear      Reset functions
config    Enter configuration mode
```

```

copy      Copy from one file to another
delete    Delete a file or directory
dir       Directory listing for files
exit      Exit from the EXEC
find      Find a file below the current directory
format    Format disks
init      Initialize internal disk
load      Load system image
mkdir    Create new directory
move      Move files
no       Disable debugging functions
pwd      View current directory
reload   Reboot this supervisor module
rmdir    Remove existing directory
show     Show running system information
sleep    Sleep for the specified number of seconds
ssh      SSH to another system
tail     Display the last part of a file
telnet   Telnet to another system

```

9. قم بتنسيق بطاقة SD التالفة باستخدام الأمر "تنسيق".

```

.:This command is going to erase the contents of your bootflash
Do you want to continue? (y/n) [n] y

```

```

:Formatting bootflash
Formatting started at: Fri Feb 20 23:56:00 UTC 2015
(mke2fs 1.35 (28-Feb-2004)
Formatting finished at: Fri Feb 20 23:56:52 UTC 2015
Formatting completed

```

10. قم بتشغيل نظام داخلي (الخيار خطوة: هذا الأمر ينسق بطاقة SD ويمحو كل شيء).

```

Router(boot)# init system
This command is going to erase your startup-config, licenses as well as the contents of your
.:bootflash

```

```

Do you want to continue? (y/n) [n] y
Initializing the system
mount: /dev/mmcblk0p4 already mounted or /bootflash busy
mount: according to mtab, /dev/mmcblk0p4 is already mounted on /bootflash
ERROR: cannot mount filesystem
'/cp: omitting directory `/bootflash
Partitioning failed

```

11. إعداد واجهة الإدارة (يلزم هذا لنسخ وصورة النظام إلى ذاكرة التمهيد المؤقتة).

```

Router(boot)# configure terminal
Router(boot)(config)# interface mgmt0
Router(boot)(config-if)#ip address 192.0.2.2 255.255.255.0
Router(boot)(config-if)#no shut

```

12. انسخ بعد التشغيل وصورة النظام إلى ذاكرة التمهيد المؤقتة.

```

:Router(boot)# copy tftp://192.0.2.1/cgr1000-uk9-kickstart.5.2.1.CG4.3.SPA.bin bootflash
.....Trying to connect to tftp server
.....Connection to server Established. Copying Started

```

```

TFTP get operation was successful
....(Copy complete, now saving to disk (please wait

```

```
:Router(boot)# copy tftp://192.0.2.1/cgr1000-uk9.5.2.1.CG4.3.SPA.bin bootflash
.....Trying to connect to tftp server
.....Connection to server Established. Copying Started
```

TFTP get operation was successful
...(Copy complete, now saving to disk (please wait

13. تأكيد من أن Kickstart صورة النظام موجودان على "dir" مع

```
Router(boot)#dir
Feb 21 00:39:59 2015 cgr1000-uk9-kickstart.5.2.1.CG4.3.SPA.bin    29167616
                Feb 21 00:42:06 2015 cgr1000-uk9.5.2.1.CG4.3.SPA.bin    143332283
                                Feb 23 17:55:52 2015 fpga.log      372
                                Feb 23 18:39:54 2015 mts.log      1905
```

```
//:Usage for bootflash
bytes used 691462144
bytes free 8859394048
bytes total 9550856192
```

14. قم بتمهيد صورة النظام باستخدام الأمر ".load bootflash"

```
Router(boot)# load bootflash:cgr1000-uk9.5.2.1.CG4.3.SPA.bin
```

```
Loading system software
(Uncompressing bootflash:/cgr1000-uk9.5.2.1.CG4.3.SPA.bin.....done. (in 37 seconds
...Loading plugin 0: core_plugin
```

```
INIT: Switching to runlevel: 3
INIT: Sending processes the TERM signal
#(Router(boot
```

:INIT

```
... System is coming up ... Please wait
```

```
Feb 21 00:47:56 %% VDC-1 %% %COPP-2-COPP_NO_POLICY: Control-plane is unprotected. System is 2015
... coming up ... Please wait
```

```
Feb 21 00:47:58 %% VDC-1 %% %VDC_MGR-2-VDC_ONLINE: vdc 1 has come online 2015 Feb 21 2015
00:47:58 Router %% VDC-1 %% %PLATFORM-2-
```

```
INPUT_POWER_SOURCE_TRANSITION: Three Phase and DC Input Status Alert: L1 Phase ON, L2 Phase
OFF, L3 Phase OFF, DC Input Absent
```

15. بمجرد تمهيد CGR في صورة النظام، تحتاج إلى تثبيت Kickstart صورة النظام باستخدام "تثبيت كافة bootflash:<kickstart-image> bootflash"

```

cgr1120# install all kickstart bootflash:cgr1000-uk9-kickstart.5.2.1.CG4.3.SPA.bin system
bootflash:cgr1000-uk9.5.2.1.CG4.3.SPA.bin

Verifying image bootflash:/cgr1000-uk9-kickstart.5.2.1.CG4.3.SPA.bin for boot variable
.  "kickstart
    SUCCESS --

."Verifying image bootflash:/cgr1000-uk9.5.2.1.CG4.3.SPA.bin for boot variable "system
    SUCCESS --

.Verifying image type
    SUCCESS --

.Extracting "system" version from image bootflash:/cgr1000-uk9.5.2.1.CG4.3.SPA.bin
    SUCCESS --

.Extracting "kickstart" version from image bootflash:/cgr1000-uk9-kickstart.5.2.1.CG4.3.SPA.bin
    SUCCESS --

.Extracting "bios" version from image bootflash:/cgr1000-uk9.5.2.1.CG4.3.SPA.bin
    SUCCESS --

.Checking for Battery Power Mode
    SUCCESS --

.Checking for Module Power Status
    SUCCESS --

.Checking for WPAN upgrade compatibility
    SUCCESS --

.Performing module support checks
    SUCCESS --

 NOTIFYING SERVICES ABOUT SYSTEM UPGRADE
    SUCCESS --


:Compatibility check is done
-----+-----+-----+-----+-----+-----+
Module  bootable      Impact   Install-type  Reason
-----+-----+-----+-----+-----+-----+
yes     disruptive     reset    Hitless upgrade is not supported  1


:Images will be upgraded according to following table
-----+-----+-----+-----+-----+-----+
Module  Image          Running-Version(pri:alt)      New-Version  Upg-Required
-----+-----+-----+-----+-----+-----+
system           5.2(1)CG4(3)        5.2(1)CG4(3)      no         1
kickstart        5.2(1)CG4(3)        5.2(1)CG4(3)      no         1
bios    v16.1.0(10/15/2013):v12.1.0(06/27/2012)  v16.1.0(10/15/2013)  no         1
fpga              2.07.00          2.07.00          no         1


.Switch will be reloaded for disruptive upgrade
Do you want to continue with the installation (y/n)? [n] y

```

هـ لـ وـ لـ جـ رـ تـ لـ اـ هـ ذـ هـ

ةـ يـ لـ آـ لـ اـ تـ اـ يـ نـ قـ تـ لـ اـ نـ مـ مـ جـ مـ وـ عـ مـ اـ دـ خـ تـ سـ اـ بـ دـ نـ تـ سـ مـ لـ اـ اـ ذـ هـ تـ مـ جـ رـ تـ
لـ اـ عـ لـ اـ ءـ اـ حـ نـ اـ عـ يـ مـ جـ يـ فـ نـ يـ مـ دـ خـ تـ سـ مـ لـ لـ مـ عـ دـ ئـ وـ تـ حـ مـ يـ دـ قـ تـ لـ ةـ يـ رـ شـ بـ لـ اـ وـ
اـ مـ كـ ةـ قـ يـ قـ دـ نـ وـ كـ تـ نـ لـ ةـ يـ لـ آـ ةـ مـ جـ رـ تـ لـ ضـ فـ اـ نـ اـ ةـ ظـ حـ اـ لـ مـ ئـ جـ رـ يـ .ـ صـ اـ خـ لـ اـ مـ هـ تـ غـ لـ بـ
يـ لـ خـ تـ .ـ فـ رـ تـ حـ مـ مـ جـ رـ تـ مـ اـ هـ دـ قـ يـ يـ تـ لـ اـ ةـ يـ فـ اـ رـ تـ حـ اـ لـ اـ ةـ مـ جـ رـ تـ لـ اـ عـ مـ لـ اـ حـ لـ اـ وـ
ىـ لـ إـ أـ مـ ئـ اـ دـ عـ وـ جـ رـ لـ اـ بـ يـ صـ وـ تـ وـ تـ اـ مـ جـ رـ تـ لـ اـ هـ ذـ هـ ةـ قـ دـ نـ عـ اـ هـ تـ يـ لـ وـ ئـ سـ مـ
(رـ فـ وـ تـ مـ طـ بـ اـ رـ لـ اـ)ـ يـ لـ صـ أـ لـ اـ يـ زـ يـ لـ جـ نـ إـ لـ اـ دـ نـ تـ سـ مـ لـ اـ).