

End-of-Sale and End-of-Life Announcement for the Cisco DWDM X2 Modules

EOL10788

Cisco announces the end-of-sale and end-of-life dates for the Cisco DWDM X2 Modules. The last day to order the affected product(s) is August 1, 2016. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco DWDM X2 Modules

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 1, 2016
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 1, 2016
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 30, 2016
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	August 1, 2017
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 1, 2017
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	October 27, 2020
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 31, 2021

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
DWDM-X2-30.33	DWDM X2 1530.33 nm (100 GHz ITU grid)
DWDM-X2-30.33=	DWDM X2 1530.33 nm X2 (100 GHz ITU grid)
DWDM-X2-31.12	DWDM X2 1531.12 nm (100 GHz ITU grid)
DWDM-X2-31.12=	DWDM X2 1531.12 nm X2 (100 GHz ITU grid)
DWDM-X2-31.90	DWDM X2 1531.90 nm (100 GHz ITU grid)
DWDM-X2-31.90=	DWDM X2 1531.90 nm X2 (100 GHz ITU grid)
DWDM-X2-32.68	DWDM X2 1532.68 nm (100 GHz ITU grid)
DWDM-X2-32.68=	DWDM X2 1532.68 nm X2 (100 GHz ITU grid)

End-of-Sale Product Part Number	Product Description
DWDM-X2-34.25	DWDM X2 1534.25 nm (100 GHz ITU grid)
DWDM-X2-34.25=	DWDM X2 1534.25 nm X2 (100 GHz ITU grid)
DWDM-X2-35.04	DWDM X2 1535.04 nm (100 GHz ITU grid)
DWDM-X2-35.04=	DWDM X2 1535.04 nm X2 (100 GHz ITU grid)
DWDM-X2-35.82	DWDM X2 1535.82 nm (100 GHz ITU grid)
DWDM-X2-35.82=	DWDM X2 1535.82 nm X2 (100 GHz ITU grid)
DWDM-X2-36.61	DWDM X2 1536.61 nm (100 GHz ITU grid)
DWDM-X2-36.61=	DWDM X2 1536.61 nm X2 (100 GHz ITU grid)
DWDM-X2-38.19	DWDM X2 1538.19 nm (100 GHz ITU grid)
DWDM-X2-38.19=	DWDM X2 1538.19 nm X2 (100 GHz ITU grid)
DWDM-X2-38.98	DWDM X2 1538.98 nm (100 GHz ITU grid)
DWDM-X2-38.98=	DWDM X2 1538.98 nm X2 (100 GHz ITU grid)
DWDM-X2-39.77	DWDM X2 1539.77 nm (100 GHz ITU grid)
DWDM-X2-39.77=	DWDM X2 1539.77 nm X2 (100 GHz ITU grid)
DWDM-X2-40.56	DWDM X2 1540.56 nm (100 GHz ITU grid)
DWDM-X2-40.56=	DWDM X2 1540.56 nm X2 (100 GHz ITU grid)
DWDM-X2-42.14	DWDM X2 1542.14 nm (100 GHz ITU grid)
DWDM-X2-42.14=	DWDM X2 1542.14 nm X2 (100 GHz ITU grid)
DWDM-X2-42.94	DWDM X2 1542.94 nm (100 GHz ITU grid)
DWDM-X2-42.94=	DWDM X2 1542.94 nm X2 (100 GHz ITU grid)
DWDM-X2-43.73	DWDM X2 1543.73 nm (100 GHz ITU grid)
DWDM-X2-43.73=	DWDM X2 1543.73 nm X2 (100 GHz ITU grid)
DWDM-X2-44.53	DWDM X2 1544.53 nm (100 GHz ITU grid)
DWDM-X2-44.53=	DWDM X2 1544.53 nm X2 (100 GHz ITU grid)
DWDM-X2-46.12	DWDM X2 1546.12 nm (100 GHz ITU grid)
DWDM-X2-46.12=	DWDM X2 1546.12 nm X2 (100 GHz ITU grid)
DWDM-X2-46.92	DWDM X2 1546.92 nm (100 GHz ITU grid)
DWDM-X2-46.92=	DWDM X2 1546.92 nm X2 (100 GHz ITU grid)
DWDM-X2-47.72	DWDM X2 1547.72 nm (100 GHz ITU grid)
DWDM-X2-47.72=	DWDM X2 1547.72 nm X2 (100 GHz ITU grid)
DWDM-X2-48.51	DWDM X2 1548.51 nm (100 GHz ITU grid)
DWDM-X2-48.51=	DWDM X2 1548.51 nm X2 (100 GHz ITU grid)
DWDM-X2-50.12	DWDM X2 1550.12 nm (100 GHz ITU grid)
DWDM-X2-50.12=	DWDM X2 1550.12 nm X2 (100 GHz ITU grid)
DWDM-X2-50.92	DWDM X2 1550.92 nm (100 GHz ITU grid)
DWDM-X2-50.92=	DWDM X2 1550.92 nm X2 (100 GHz ITU grid)
DWDM-X2-51.72	DWDM X2 1551.72 nm (100 GHz ITU grid)
DWDM-X2-51.72=	DWDM X2 1551.72 nm X2 (100 GHz ITU grid)
DWDM-X2-52.52	DWDM X2 1552.52 nm (100 GHz ITU grid)
DWDM-X2-52.52=	DWDM X2 1552.52 nm X2 (100 GHz ITU grid)
DWDM-X2-54.13	DWDM X2 1554.13 nm (100 GHz ITU grid)
DWDM-X2-54.13=	DWDM X2 1554.13 nm X2 (100 GHz ITU grid)
DWDM-X2-54.94	DWDM X2 1554.94 nm (100 GHz ITU grid)
DWDM-X2-54.94=	DWDM X2 1554.94 nm X2 (100 GHz ITU grid)

End-of-Sale Product Part Number	Product Description
DWDM-X2-55.75	DWDM X2 1555.75 nm (100 GHz ITU grid)
DWDM-X2-55.75=	DWDM X2 1555.75 nm X2 (100 GHz ITU grid)
DWDM-X2-56.55	DWDM X2 1556.55 nm (100 GHz ITU grid)
DWDM-X2-56.55=	DWDM X2 1556.55 nm X2 (100 GHz ITU grid)
DWDM-X2-58.17	DWDM X2 1558.17 nm (100 GHz ITU grid)
DWDM-X2-58.17=	DWDM X2 1558.17 nm X2 (100 GHz ITU grid)
DWDM-X2-58.98	DWDM X2 1558.98 nm (100 GHz ITU grid)
DWDM-X2-58.98=	DWDM X2 1558.98 nm X2 (100 GHz ITU grid)
DWDM-X2-59.79	DWDM X2 1559.79 nm (100 GHz ITU grid)
DWDM-X2-59.79=	DWDM X2 1559.79 nm X2 (100 GHz ITU grid)
DWDM-X2-60.61	DWDM X2 1560.61 nm (100 GHz ITU grid)
DWDM-X2-60.61=	DWDM X2 1560.61 nm X2 (100 GHz ITU grid)

Product Migration Options

There is no replacement available for the Cisco DWDM X2 Modules at this time.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco DWDM X2 Modules through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products/products end-of-life policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod warranties listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-736658-00 02/16