

# End-of-Sale and End-of-Life Announcement for the Cisco Select 819, 886, 887, 897, 898 and 899 models



# Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	5
For more information	6

## Overview

### EOL13227 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select 819, 886, 887, 897, 898 and 899 models. The last day to order the affected product(s) is April 29, 2020. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-Life Milestones and Dates for the Cisco Select 819, 886, 887, 897, 898 and 899 models

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 30, 2019
<b>End-of-Sale Date: HW</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 29, 2020
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 28, 2020
<b>End of SW Maintenance Releases Date: HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	April 29, 2021
<b>End of Vulnerability/Security Support: HW</b>	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	April 29, 2023
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	April 29, 2021
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 29, 2021
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	July 25, 2024
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2025

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

## Product part numbers

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
C819G-LTE-LA-K9	C819 M2M FDD and TDD LTE for APAC, ANZ, LATAM, SMS/GPS	C1101-4PLTEP	ISR 1101 4P GE Ethernet and LTE Secure Router with Pluggable	-
C819G-LTE-LA-K9	C819 M2M FDD and TDD LTE for APAC, ANZ, LATAM, SMS/GPS	C1111-4PLTELA	ISR 1100 4P Dual GE WAN w/ LTE Adv SMS/GPS LATAM and APAC	-
C819G-LTE-LA-K9	C819 M2M FDD and TDD LTE for APAC, ANZ, LATAM, SMS/GPS	P-LTEA-LA	CAT6 LTE Advanced Pluggable for APAC, LATAM and ANZ	-
C886VA-K9	Cisco 880 Series Integrated Services Routers	C1116-4P	ISR 1100 4 Ports DSL Annex B/J and GE WAN Router	-
C886VA-K9	Cisco 880 Series Integrated Services Routers	C926-4P	Cisco 926 VDSL2/ADSL2+ over ISDN and 1GE Sec Router	-
C886VAJ-K9	Cisco 880 Series Integrated Services Routers	C1117-4P	ISR 1100 4 Ports DSL Annex A/M and GE WAN Router	-
C886VAJ-K9	Cisco 880 Series Integrated Services Routers	C927-4P	Cisco 927 VDSL2/ADSL2+ over POTs and 1GE/SFP Sec Router	-
C887VAM-K9	Cisco 880 Series Integrated Services Routers	C1117-4PM	ISR 1100 4 Ports DSL Annex M and GE WAN Router	-
C887VAM-K9	Cisco 880 Series Integrated Services Routers	C927-4PM	Cisco 927 Annex M over POTs and 1GE Sec Router	-
C897VAG-LTE-LA-K9	C897 GE SFP VDSL2/ADSL2+ over POTS, FDD and TDD LTE, HSPA+	C1113-8PLTELA	ISR 1100 G.FAST GE SFP Router w/ LTE Adv LATAM & APAC	-
C897VAG-LTE-LA-K9	C897 GE SFP VDSL2/ADSL2+ over POTS, FDD and TDD LTE, HSPA+	C1127-8PLTEP	ISR 1100 8P xDSL GE SFP Router Pluggable SMS/GPS	-
C897VAG-LTE-LA-K9	C897 GE SFP VDSL2/ADSL2+ over POTS, FDD and TDD LTE, HSPA+	C1127X-8PLTEP	ISR 1100X 8P xDSL GE SFP Router Pluggable SMS/GPS	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
C897VAG-LTE-LA-K9	C897 GE SFP VDSL2/ADSL2+ over POTS, FDD and TDD LTE, HSPA+	P-LTEA-LA	CAT6 LTE Advanced Pluggable for APAC, LATAM and ANZ	-
C898EA-K9	Cisco 898 G.SHDSL ATM/EFM Multi-mode & 1GE/SFP Sec Router	C1118-8P	ISR 1100 8 Ports Dual GE WAN Ethernet Router G.SHDSL	-
C898EA-K9	Cisco 898 G.SHDSL ATM/EFM Multi-mode & 1GE/SFP Sec Router	C1128-8PLTEP	ISR 1100 8P GE G.SHDSL Router Pluggable SMS/GPS	-
C899G-LTE-LA-K9	C899 FDD and TDD LTE, APAC, ANZ, LATAM, HSPA+, SMS/GPS	C1111-8PLTELA	ISR 1100 8P Dual GE Router w/ LTE Adv SMS/GPS LATAM & APAC	-
C899G-LTE-LA-K9	C899 FDD and TDD LTE, APAC, ANZ, LATAM, HSPA+, SMS/GPS	C1121-8PLTEP	ISR 1100 8P Dual GE SFP Router Pluggable SMS/GPS	-
C899G-LTE-LA-K9	C899 FDD and TDD LTE, APAC, ANZ, LATAM, HSPA+, SMS/GPS	C1121X-8PLTEP	ISR 1100X 8P Dual GE SFP Router Pluggable SMS/GPS	-
C899G-LTE-LA-K9	C899 FDD and TDD LTE, APAC, ANZ, LATAM, HSPA+, SMS/GPS	P-LTEA-LA	CAT6 LTE Advanced Pluggable for APAC, LATAM and ANZ	-
CISCOUTM1100	Unified Threat Management 1100 Bundle	There is currently no replacement product available for this product.	-	-

## Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

[https://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco Select 819, 886, 887, 897, 898 and 899 models through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to:

<https://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

---

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For more information

For more information about the Cisco End-of-Life Policy, go to:

[https://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](https://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[https://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](https://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)