

# End-of-Sale and End-of-Life Announcement for the Cisco 32GB DDR3-1066MHz RDIMM/PC3-8500/2x16GB Kit LV

### EOL8170

Cisco announces the end-of-sale and end-of life dates for the Cisco 32GB DDR3-1066MHz RDIMM/PC3-8500/2x16GB Kit LV. The last day to order the affected product(s) is May 4, 2012. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the CIsco 32GB DDR3-1066MHz RDIMM/PC3-8500/2x16GB Kit LV

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	February 3, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 4, 2012
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 2, 2012
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	May 4, 2013
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 4, 2013
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	July 30, 2016
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 31, 2017

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
A02-M332GB3-2-L	32GB DDR3-1066MHz RDIMM/PC3-8500/2x16GB 4R Kit/Low Volt	UCS-MR-2X164RX-C=	2X16GB DDR3-1333-MHz RDIMM/PC3-10600/quad rank/x4/1.35v	_
A02-M332GB3-2-L=	32GB DDR3-1066MHz RDIMM/PC3-8500/2x16GB 4R Kit/Low Volt	UCS-MR-2X164RX-C	2X16GB DDR3-1333-MHz RDIMM/PC3-10600/quad rank/x4/1.35v	_

## **Product Migration Options**

Customers are encouraged to migrate to the Cisco 2X16GB DDR3-1333-MHz RDIMM/PC3-10600/quad rank. Information about this product can be found at:

http://www.cisco.com/en/US/products/ps10280/prod\_eol\_notices\_list.html.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html

### For More Information

For more information about the Cisco 2X16GB DDR3-1333-MHz RDIMM/PC3-10600/Quad Rank, visit <a href="http://www.cisco.com/en/US/products/ps10280/prod">http://www.cisco.com/en/US/products/ps10280/prod</a> eol notices list.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products\_end-of-life\_policy.html

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod\_warranties\_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

# Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <a href="http://www.cisco.com/web/feeds/products/end">http://www.cisco.com/web/feeds/products/end</a> of <a href="life-rss.xml">life-rss.xml</a>

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

# cisco.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-697992-00 01/12