

## End-of-Sale and End-of-Life Announcement for the Cisco 16-Socket Server SAP Resale

EOL12959

Cisco announces the end-of-sale and end-of-life dates for the Cisco 16-Socket Server SAP Resale. The last day to order the affected product(s) is May 31, 2019. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 16-Socket Server SAP Resale

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	March 1, 2019
<b>End-of-Sale Date: HW</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 31, 2019
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 29, 2019
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	May 30, 2020
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 30, 2020
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	August 26, 2023
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 31, 2024

HW = Hardware OS SW = Operating System Software App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
<b>C16-2PDU</b>	AddOn-Bullion 2PDU
<b>C16-CB16</b>	AddOn-Bullion 8 Module Connecting Box CB16
<b>C16S10-32G-YR-BRNZ</b>	Bullion 10 socket-32GB-Per Year Support -Bronze
<b>C16S10-32G-YR-GD</b>	Bullion 10 socket-32GB-Per Year Support -Gold
<b>C16S10-32G-YR-GDA</b>	Bullion Appliance 10 socket-32GB-Per Year Support -Gold
<b>C16S10-32G-YR-SV</b>	Bullion 10 socket-32GB-Per Year Support -Silver
<b>C16S10-32G-YR-SVA</b>	Bullion Appliance 10 socket-32GB-Per Year Support -Silver

End-of-Sale Product Part Number	Product Description
<b>C16S10-64G-YR-BRNZ</b>	Bullion 10 socket-64GB-Per Year Support -Bronze
<b>C16S10-64G-YR-GD</b>	Bullion 10 socket-64GB-Per Year Support -Gold
<b>C16S10-64G-YR-GDA</b>	Bullion Appliance 10 socket-64GB-Per Year Support -Gold
<b>C16S10-64G-YR-SV</b>	Bullion 10 socket-64GB-Per Year Support -Silver
<b>C16S10-64G-YR-SVA</b>	Bullion Appliance 10 socket-64GB-Per Year Support -Silver
<b>C16S10-7.5T32G-C</b>	Bullion 10 socket-7.5TB 32GB DIMM 8880V4 -Copper
<b>C16S10-7.5T32G-C-R</b>	Appl RedHat-Bullion 10 skt-7.5TB 32GB DIMM 8880V4 -Copper
<b>C16S10-7.5T32G-C-S</b>	Appl SUSE -Bullion 10 socket-7.5TB 32GB DIMM 8880V4 -Copper
<b>C16S10-7.5T32G-O</b>	Bullion 10 skt-7.5TB 32GB DIMM 8880V4 -Optical
<b>C16S10-7.5T32G-O-R</b>	Appl RedHat-Bullion 10 skt-7.5TB 32GB DIMM 8880V4 -Optical
<b>C16S10-7.5T32G-O-S</b>	Appl SUSE -Bullion 10 skt-7.5TB 32GB DIMM 8880V4 -Optical
<b>C16S10-L10T64G-C</b>	Bullion 10 socket-10TB 64GB DIMM 8890V4 -Copper
<b>C16S10-L10T64G-C-R</b>	Appl RedHat-Bullion 10 socket-10TB 64GB DIMM 8890V4 -Copper
<b>C16S10-L10T64G-C-S</b>	Appl SUSE -Bullion 10 socket-10TB 64GB DIMM 8890V4 -Copper
<b>C16S10-L10T64G-O</b>	Bullion 10 socket-10TB 64GB DIMM 8890V4 -Optical
<b>C16S10-L10T64G-O-R</b>	Appl RedHat-Bullion 10 socket-10TB 64GB DIMM 8890V4 -Optical
<b>C16S10-L10T64G-O-S</b>	Appl SUSE -Bullion 10 socket-10TB 64GB DIMM 8890V4 -Optical
<b>C16S12-32G-YR-BRNZ</b>	Bullion 12 socket-32GB-Per Year Support -Bronze
<b>C16S12-32G-YR-GD</b>	Bullion 12 socket-32GB-Per Year Support -Gold
<b>C16S12-32G-YR-GDA</b>	Bullion Appliance 12 socket-32GB-Per Year Support -Gold
<b>C16S12-32G-YR-SV</b>	Bullion 12 socket-32GB-Per Year Support -Silver
<b>C16S12-32G-YR-SVA</b>	Bullion Appliance 12 socket-32GB-Per Year Support -Silver
<b>C16S12-64G-YR-BRNZ</b>	Bullion 12 socket-64GB-Per Year Support -Bronze
<b>C16S12-64G-YR-GD</b>	Bullion 12 socket-64GB-Per Year Support -Gold
<b>C16S12-64G-YR-GDA</b>	Bullion Appliance 12 socket-64GB-Per Year Support -Gold
<b>C16S12-64G-YR-SV</b>	Bullion 12 socket-64GB-Per Year Support -Silver
<b>C16S12-64G-YR-SVA</b>	Bullion Appliance 12 socket-64GB-Per Year Support -Silver
<b>C16S12-9T-32G-C</b>	Bullion 12 socket-9TB 32GB DIMM 8880V4 -Copper
<b>C16S12-9T-32G-C-R</b>	Appl RedHat-Bullion 12 socket-9TB 32GB DIMM 8880V4 -Copper
<b>C16S12-9T-32G-C-S</b>	Appl SUSE -Bullion 12 socket-9TB 32GB DIMM 8880V4 -Copper
<b>C16S12-9T-32G-O</b>	Bullion 12 socket-9TB 32GB DIMM 8880V4 -Optical
<b>C16S12-9T-32G-O-R</b>	Appl RedHat-Bullion 12 socket-9TB 32GB DIMM 8880V4 -Optical
<b>C16S12-9T-32G-O-S</b>	Appl SUSE -Bullion 12 socket-9TB 32GB DIMM 8880V4 -Optical
<b>C16S12-L12T64G-C</b>	Bullion 12 socket-12TB 64GB DIMM 8890V4 -Copper
<b>C16S12-L12T64G-C-R</b>	Appl RedHat-Bullion 12 socket-12TB 64GB DIMM 8890V4 -Copper
<b>C16S12-L12T64G-C-S</b>	Appl SUSE -Bullion 12 socket-12TB 64GB DIMM 8890V4 -Copper
<b>C16S12-L12T64G-O</b>	Bullion 12 socket-12TB 64GB DIMM 8890V4 -Optical
<b>C16S12-L12T64G-O-R</b>	Appl RedHat-Bullion 12 socket-12TB 64GB DIMM 8890V4 -Optical
<b>C16S12-L12T64G-O-S</b>	Appl SUSE -Bullion 12 socket-12TB 64GB DIMM 8890V4 -Optical
<b>C16S14-105T32G-C</b>	Bullion 14 skt-10.5TB 32GB DIMM 8880V4 -Copper
<b>C16S14-105T32G-C-R</b>	Appl RedHat-Bullion 14 skt-10.5TB 32GB DIMM 8880V4 -Copper
<b>C16S14-105T32G-C-S</b>	Appl SUSE -Bullion 14 skt-10.5TB 32GB DIMM 8880V4 -Copper
<b>C16S14-105T32G-O</b>	Bullion 14 skt-10.5TB 32GB DIMM 8880V4 -Optical

End-of-Sale Product Part Number	Product Description
<b>C16S14-105T32G-O-R</b>	Appl RedHat-Bullion 14 skt-10.5TB 32GB DIMM 8880V4 -Optical
<b>C16S14-105T32G-O-S</b>	Appl SUSE -Bullion 14 skt-10.5TB 32GB DIMM 8880V4 -Optical
<b>C16S14-32G-YR-BRNZ</b>	Bullion 14 socket-32GB-Per Year Support -Bronze
<b>C16S14-32G-YR-GD</b>	Bullion 14 socket-32GB-Per Year Support -Gold
<b>C16S14-32G-YR-GDA</b>	Bullion Appliance 14 socket-32GB-Per Year Support -Gold
<b>C16S14-32G-YR-SV</b>	Bullion 14 socket-32GB-Per Year Support -Silver
<b>C16S14-32G-YR-SVA</b>	Bullion Appliance 14 socket-32GB-Per Year Support -Silver
<b>C16S14-64G-YR-BRNZ</b>	Bullion 14 socket-64GB-Per Year Support -Bronze
<b>C16S14-64G-YR-GD</b>	Bullion 14 socket-64GB-Per Year Support -Gold
<b>C16S14-64G-YR-GDA</b>	Bullion Appliance 14 socket-64GB-Per Year Support -Gold
<b>C16S14-64G-YR-SV</b>	Bullion 14 socket-64GB-Per Year Support -Silver
<b>C16S14-64G-YR-SVA</b>	Bullion Appliance 14 socket-64GB-Per Year Support -Silver
<b>C16S14-L14T64G-C</b>	Bullion 14 socket-14TB 64GB DIMM 8890V4 -Copper
<b>C16S14-L14T64G-C-R</b>	Appl RedHat-Bullion 14 socket-14TB 64GB DIMM 8890V4 -Copper
<b>C16S14-L14T64G-C-S</b>	Appl SUSE -Bullion 14 socket-14TB 64GB DIMM 8890V4 -Copper
<b>C16S14-L14T64G-O</b>	Bullion 14 socket-14TB 64GB DIMM 8890V4 -Optical
<b>C16S14-L14T64G-O-R</b>	Appl RedHat-Bullion 14 socket-14TB 64GB DIMM 8890V4 -Optical
<b>C16S14-L14T64G-O-S</b>	Appl SUSE -Bullion 14 socket-14TB 64GB DIMM 8890V4 -Optical
<b>C16S16-12T-32G-C</b>	Bullion 16 socket-12TB 32GB DIMM 8880V4 -Copper
<b>C16S16-12T-32G-C-R</b>	Appl RedHat-Bullion 16 socket-12TB 32GB DIMM 8880V4 -Copper
<b>C16S16-12T-32G-C-S</b>	Appl SUSE -Bullion 16 socket-12TB 32GB DIMM 8880V4 -Copper
<b>C16S16-12T-32G-O</b>	Bullion 16 socket-12TB 32GB DIMM 8880V4 -Optical
<b>C16S16-12T-32G-O-R</b>	Appl RedHat-Bullion 16 socket-12TB 32GB DIMM 8880V4 -Optical
<b>C16S16-12T-32G-O-S</b>	Appl SUSE -Bullion 16 socket-12TB 32GB DIMM 8880V4 -Optical
<b>C16S16-32G-YR-BRNZ</b>	Bullion 16 socket-32GB-Per Year Support -Bronze
<b>C16S16-32G-YR-GD</b>	Bullion 16 socket-32GB-Per Year Support -Gold
<b>C16S16-32G-YR-GDA</b>	Bullion Appliance 16 socket-32GB-Per Year Support -Gold
<b>C16S16-32G-YR-SV</b>	Bullion 16 socket-32GB-Per Year Support -Silver
<b>C16S16-32G-YR-SVA</b>	Bullion Appliance 16 socket-32GB-Per Year Support -Silver
<b>C16S16-64G-YR-BRNZ</b>	Bullion 16 socket-64GB-Per Year Support -Bronze
<b>C16S16-64G-YR-GD</b>	Bullion 16 socket-64GB-Per Year Support -Gold
<b>C16S16-64G-YR-GDA</b>	Bullion Appliance 16 socket-64GB-Per Year Support -Gold
<b>C16S16-64G-YR-SV</b>	Bullion 16 socket-64GB-Per Year Support -Silver
<b>C16S16-64G-YR-SVA</b>	Bullion Appliance 16 socket-64GB-Per Year Support -Silver
<b>C16S16-L12T32G-C</b>	Bullion 16 socket-12TB 32GB DIMM 8890V4 -Copper
<b>C16S16-L12T32G-C-R</b>	Appl RedHat-Bullion 16 socket-12TB 32GB DIMM 8890V4 -Copper
<b>C16S16-L12T32G-C-S</b>	Appl SUSE -Bullion 16 socket-12TB 32GB DIMM 8890V4 -Copper
<b>C16S16-L12T32G-O</b>	Bullion 16 socket-12TB 32GB DIMM 8890V4 -Optical
<b>C16S16-L12T32G-O-R</b>	Appl RedHat-Bullion 16 socket-12TB 32GB DIMM 8890V4 -Optical
<b>C16S16-L12T32G-O-S</b>	Appl SUSE -Bullion 16 socket-12TB 32GB DIMM 8890V4 -Optical
<b>C16S16-L12T64G-C</b>	Bullion 16 socket-12TB 64GB DIMM 8890V4 -Copper
<b>C16S16-L12T64G-C-R</b>	Appl RedHat-Bullion 16 socket-12TB 64GB DIMM 8890V4 -Copper
<b>C16S16-L12T64G-C-S</b>	Appl SUSE -Bullion 16 socket-12TB 64GB DIMM 8890V4 -Copper

End-of-Sale Product Part Number	Product Description
<b>C16S16-L12T64G-O</b>	Bullion 16 socket-12TB 64GB DIMM 8890V4 -Optical
<b>C16S16-L12T64G-O-R</b>	Appl RedHat-Bullion 16 socket-12TB 64GB DIMM 8890V4 -Optical
<b>C16S16-L12T64G-O-S</b>	Appl SUSE -Bullion 16 socket-12TB 64GB DIMM 8890V4 -Optical
<b>C16S16-L16T64G-C</b>	Bullion 16 socket-16TB 64GB DIMM 8890V4 -Copper
<b>C16S16-L16T64G-C-R</b>	Appl RedHat-Bullion 16 socket-16TB 64GB DIMM 8890V4 -Copper
<b>C16S16-L16T64G-C-S</b>	Appl SUSE -Bullion 16 socket-16TB 64GB DIMM 8890V4 -Copper
<b>C16S16-L16T64G-O</b>	Bullion 16 socket-16TB 64GB DIMM 8890V4 -Optical
<b>C16S16-L16T64G-O-R</b>	Appl RedHat-Bullion 16 socket-16TB 64GB DIMM 8890V4 -Optical
<b>C16S16-L16T64G-O-S</b>	Appl SUSE -Bullion 16 socket-16TB 64GB DIMM 8890V4 -Optical
<b>C16S16-L64G-Y-BRNZ</b>	Bullion 16 socket-L 64GB-Per Year Support -Bronze
<b>C16S16-L64G-YR-GD</b>	Bullion 16 socket-L 64GB-Per Year Support -Gold
<b>C16S16-L64G-YR-GDA</b>	Bullion Appliance 16 socket-L 64GB-Per Year Support -Gold
<b>C16S16-L64G-YR-SV</b>	Bullion 16 socket-L 64GB-Per Year Support -Silver
<b>C16S16-L64G-YR-SVA</b>	Bullion Appliance 16 socket-L 64GB-Per Year Support -Silver
<b>C16S2-80-1.5-32G</b>	AddOn-Bullion S2 1,5TB 32GB DIMM 8880V4
<b>C16S2-90-1.5-32G</b>	AddOn-Bullion S2 1,5TB 32GB DIMM 8890V4
<b>C16S2-90-2T-64G</b>	AddOn-Bullion S2 2TB 64GB DIMM 8890V4
<b>C16S8-32G-YR-BRNZ</b>	Bullion 8 socket-32G-Per Year Support -Bronze
<b>C16S8-32G-YR-GD</b>	Bullion 8 socket-32G-Per Year Support -Gold
<b>C16S8-32G-YR-GDA</b>	Bullion Appliance 8 socket-32G-Per Year Support -Gold
<b>C16S8-32G-YR-SV</b>	Bullion 8 socket-32G-Per Year Support -Silver
<b>C16S8-32G-YR-SVA</b>	Bullion Appliance 8 socket-32G-Per Year Support -Silver
<b>C16S8-64G-YR-BRNZ</b>	Bullion 8 socket-64GB-Per Year Support -Bronze
<b>C16S8-64G-YR-GD</b>	Bullion 8 socket-64GB-Per Year Support -Gold
<b>C16S8-64G-YR-GDA</b>	Bullion Appliance 8 socket-64GB-Per Year Support -Gold
<b>C16S8-64G-YR-SV</b>	Bullion 8 socket-64GB-Per Year Support -Silver
<b>C16S8-64G-YR-SVA</b>	Bullion Appliance 8 socket-64GB-Per Year Support -Silver
<b>C16S8-6T-32G-C</b>	Bullion 8 socket-6TB 32GB DIMM 8880V4 -Copper
<b>C16S8-6T-32G-C-R</b>	Appl RedHat-Bullion 8 socket-6TB 32GB DIMM 8880V4 -Copper
<b>C16S8-6T-32G-C-S</b>	Appl SUSE -Bullion 8 socket-6TB 32GB DIMM 8880V4 -Copper
<b>C16S8-6T-32G-O</b>	Bullion 8 socket-6TB 32GB DIMM 8880V4 -Optical
<b>C16S8-6T-32G-O-R</b>	Appl RedHat-Bullion 8 socket-6TB 32GB DIMM 8880V4 -Optical
<b>C16S8-6T-32G-O-S</b>	Appl SUSE -Bullion 8 socket-6TB 32GB DIMM 8880V4 -Optical
<b>C16S8-L-6T-32G-C</b>	Bullion 8 socket-6TB 32GB DIMM 8890V4 -Copper
<b>C16S8-L-6T-32G-C-R</b>	Appl RedHat-Bullion 8 socket-6TB 32GB DIMM 8890V4 -Copper
<b>C16S8-L-6T-32G-C-S</b>	Appl SUSE -Bullion 8 socket-6TB 32GB DIMM 8890V4 -Copper
<b>C16S8-L-6T-32G-O</b>	Bullion 8 socket-6TB 32GB DIMM 8890V4 -Optical
<b>C16S8-L-6T-32G-O-R</b>	Appl RedHat-Bullion 8 socket-6TB 32GB DIMM 8890V4 -Optical
<b>C16S8-L-6T-32G-O-S</b>	Appl SUSE -Bullion 8 socket-6TB 32GB DIMM 8890V4 -Optical
<b>C16S8-L-8T-64G-C</b>	Bullion 8 socket-8TB 64GB DIMM 8890V4 -Copper
<b>C16S8-L-8T-64G-C-R</b>	Appl RedHat-Bullion 8 socket-8TB 64GB DIMM 8890V4 -Copper
<b>C16S8-L-8T-64G-C-S</b>	Appl SUSE -Bullion 8 socket-8TB 64GB DIMM 8890V4 -Copper
<b>C16S8-L-8T-64G-O</b>	Bullion 8 socket-8TB 64GB DIMM 8890V4 -Optical

End-of-Sale Product Part Number	Product Description
<b>C16S8-L-8T-64G-O-R</b>	Appl RedHat-Bullion 8 socket-8TB 64GB DIMM 8890V4 -Optical
<b>C16S8-L-8T-64G-O-S</b>	Appl SUSE -Bullion 8 socket-8TB 64GB DIMM 8890V4 -Optical

## Product Migration Options

There is no replacement available for the Cisco 16-Socket Server SAP Resale at this time.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco End-of-Life Policy, go to:

[https://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](https://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[https://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](https://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)