

End-of-Sale and End-of-Life Announcement for the Cisco Select Unified Computing System and Hyperflex Accessories



Contents

- Overview 3
- End-of-life milestones 3
- Product part numbers 3
- Product migration options 6
- For more information 6

Overview

EOL14611 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select Unified Computing System and Hyperflex Accessories. The last day to order the affected product(s) is May 11, 2022. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Select Unified Computing System and Hyperflex Accessories

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 9, 2022
End-of-Sale Date Accessory	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 11, 2022
Last Ship Date Accessory	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 11, 2022

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-MR-X64G2RT-H	64GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	UCS-MR-X64G2RW	64GB RDIMM DRx4 3200 (16Gb)	-
UCS-SP-X64G2RT-H	UCS SP 64GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	There is currently no replacement product available for this product.	-	-
HX-MR-X64G2RT-H	64GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	HX-MR-X64G2RW	64GB RDIMM DRx4 3200 (16Gb)	-
HX-SP-M64G2-RTH	SP 64GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-X32G2RT-H	32GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	UCS-MR-X32G2RW	32GB RDIMM DRx4 3200 (8Gb)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HX-MR-X32G2RT-H	32GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	HX-MR-X32G2RW	32GB RDIMM DRx4 3200 (8Gb)	-
PLHC-MR-X32G2RT-H	Cisco+ 32GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	UCS-MR-X32G2RW	32GB RDIMM DRx4 3200 (8Gb)	-
HX-SP-M32G2-RTH	SP 32GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-SP-M32G2RT-H	UCS SP 32GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-X32G2RT-HS	32GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	UCS-MR-X32G2RW-S	32GB RDIMM DRx4 3200 (8Gb)	-
UCS-MR-X64G2RT-HS	64GB DDR4-2933-MHz RDIMM/2Rx4/1.2v	There is currently no replacement product available for this product.	-	-
UCS-MR-X64G2RT-HM	64GB DDR4-2933-MHz RDIMM/2Rx4	UCS-MR-X64G2RW-M	64GB 3200MHZ RDIMM (16Gb)	-
HX-MR-X64G2RT-HM	64GB DDR4-2933-MHz RDIMM/2Rx4	HX-MR-X64G2RW-M	64GB 3200MHZ RDIMM (16Gb)	-
HX-ML-128G4RT-H	128GB DDR4-2933-MHz LRDIMM/4Rx4/1.2v	HX-ML-128G4RW	128GB LRDIMM QRx4 3200 (16Gb)	-
UCS-ML-128G4RT-H	128GB DDR4-2933-MHz LRDIMM/4Rx4/1.2v	UCS-ML-128G4RW	128GB LRDIMM QRx4 3200 (16Gb)	-
UCS-MR-X16G1RT-H	16GB DDR4-2933-MHz RDIMM/1Rx4/1.2v	UCS-MR-X16G1RW	16GB RDIMM SRx4 3200 (8Gb)	-
UCS-SP-M16G1RT-H	UCS SP 16GB DDR4-2933-MHz RDIMM/1Rx4/1.2v	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HX-SP-M16G1-RTH	SP 16GB DDR4-2933-MHz RDIMM/1Rx4/1.2v	There is currently no replacement product available for this product.	-	-
HX-MR-X16G1RT-H	16GB DDR4-2933-MHz RDIMM/1Rx4/1.2v	HX-MR-X16G1RW	16GB RDIMM SRx4 3200 (8Gb)	-
UCS-ML-128G4RT-HM	128GB DDR4-2933-MHz LRDIMM/4Rx4	UCS-ML-128G4RW-M	128GB 3200MHZ LRDIMM(16Gb)	-
HX-ML-128G4RT-HM	128GB DDR4-2933-MHz LRDIMM/4Rx4	HX-ML-128G4RW-M	128GB 3200MHZ LRDIMM(16Gb)	-
UCS-MR-X32G2RTHM	32GB RDIMM DRx4 2933 (8Gb)	UCS-MR-X32G2RW-M	32GB 3200MHZ RDIMM(8Gb)	-
HX-MR-X32G2RTHM	32GB RDIMM DRx4 2933 (8Gb)	HX-MR-X32G2RW-M	32GB 3200MHZ RDIMM(8Gb)	-
UCS-MR-X16G1RTHM	16GB RDIMM SRx4 2933 (8Gb)	UCS-MR-X16G1RW-M	16GB 3200MHZ RDIMM(8Gb)	-
HX-MR-X16G1RTHM	16GB RDIMM SRx4 2933 (8Gb)	HX-MR-X16G1RW-M	16GB 3200MHZ RDIMM(8Gb)	-

Product migration options

Cisco goes through a very rigorous process to ensure that customers receive support. However in rare occasions, due to component supplier limitations, there may be a need for customer to migrate to a part that is an upgrade of something comparable or better than what they previously bought. This may require customer to upgrade to a different Software and OS version or even the closest generation of an equivalent server that may be currently shipping at the time.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)