

End-of-Sale and End-of-Life Announcement for the Cisco SPA232D Multi-Line DECT ATA and SPA302D Multi-Line DECT Handset

EOL10611 - Amended

Cisco announces the end-of-sale Cisco SPA232D Multi-Line DECT ATA and SPA302D Multi-Line DECT Handset. The last day to order the affected product(s) is December 19, 2015. Customers will continue to receive phone support from the Cisco Small Business Support Center (SBSC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active product warranties, support will be available as stated in the product warranty terms and conditions.

Table 1. End-of-Life Milestones and Dates for the Cisco SPA232D Multi-Line DECT ATA and SPA302D Multi-Line DECT Handset

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	September 19, 2015
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 19, 2015
End of Phone Support: HW	The last date to receive phone support as part of the product warranty. After this date, all phone support services for the product are available with additional charges or support fees. In some cases, support may not be available.	December 18, 2016
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 18, 2016
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	December 31, 2020

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Note: The products listed in this End-of-Life bulletin have now passed their End of Software Maintenance milestones. No new firmware loads will be released for these phones.

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
SPA232D	Analog Telephone Adapter with DECT Base Station	There is currently no replacement product available for this product.	-	-
SPA232D-G1	Multi-Line DECT ATA	There is currently no replacement product available for this product.	-	-
SPA232D-G1-1	Multi-Line DECT ATA	There is currently no replacement product available for this product.	-	-
SPA232D-G7	Multi-Line DECT ATA	There is currently no replacement product available for this product.	-	-
SPA232D-G7-1	Multi-Line DECT ATA	There is currently no replacement product available for this product.	-	-
SPA232D-R1	Multi-Line DECT ATA	There is currently no replacement product available for this product.	-	-
SPA232D-R7	Multi-Line DECT ATA	There is currently no replacement product available for this product.	-	-
SPA232D-RC	Analog Telephone Adapter with DECT Base Station	There is currently no replacement product available for this product.	-	-
SPA232D-XU	Multi-Line DECT ATA, SRPT Removed	There is currently no replacement product available for this product.	-	-
SPA302D-G1	Mobility Enhanced Cordless Handset	CP-6825-3PC-NA-K9=	Cisco IP DECT 6825 Handset, 3PCC, US and Canada	-
SPA302D-G1-1	Mobility Enhanced Cordless Handset	CP-6825-3PC-NA-K9=	Cisco IP DECT 6825 Handset, 3PCC, US and Canada	-
SPA302D-G7	Mobility Enhanced Cordless Handset	CP-6825-3PC-AU-K9=	Cisco IP DECT 6825 Handset, 3PCC, AUS and New Zealand	-
SPA302D-G7	Mobility Enhanced Cordless Handset	CP-6825-3PC-CE-K9=	Cisco IP DECT 6825 Handset, 3PCC, EU and APAC	-
SPA302D-G7	Mobility Enhanced Cordless Handset	CP-6825-3PC-UK-K9=	Cisco IP DECT 6825 Handset, 3PCC, United Kingdom	-
SPA302D-G7-1	Mobility Enhanced Cordless Handset	CP-6825-3PC-AU-K9=	Cisco IP DECT 6825 Handset, 3PCC, AUS and New Zealand	-
SPA302D-G7-1	Mobility Enhanced Cordless Handset	CP-6825-3PC-CE-K9=	Cisco IP DECT 6825 Handset, 3PCC, EU and APAC	-
SPA302D-G7-1	Mobility Enhanced Cordless Handset	CP-6825-3PC-UK-K9=	Cisco IP DECT 6825 Handset, 3PCC, United Kingdom	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
SPA302DKIT-G1	Multi-Line DECT Handset with Base Station	CP-6825-3PC-BUN-NA	Cisco IP DECT Bundle, Handset and Base, 3PCC, US and CAN	-
SPA302DKIT-G7	Multi-Line DECT Handset with Base Station	CP-6825-3PC-BUN-AU	Cisco IP DECT Bundle, Handset and Base, 3PCC, AUS and NZ	-
SPA302DKIT-G7	Multi-Line DECT Handset with Base Station	CP-6825-3PC-BUN-CE	Cisco IP DECT Bundle, Handset and Base, 3PCC, EMEA	-
SPA302DKIT-G7	Multi-Line DECT Handset with Base Station	CP-6825-3PC-BUN-UK	Cisco IP DECT Bundle, Handset and Base, 3PCC, UK	-
SPA302DKIT-XU	Multi-Line DECT Handset with Base Station, SRTP Removed	There is currently no replacement product available for this product.	-	-

Product Migration Options

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

** For more information about the Cisco Product Warranties, go to:

https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)