What Does the "#%BGP-3-INSUFCHUNKS: Insufficient chunk pools for aspath" Error Message Mean?

Document ID: 13757

Cisco no longer maintains or updates this document. Though the document resides on Cisco.com, Cisco cannot guarantee the document's accuracy. Please consider this fact if you decide to use this information for support purposes.

Contents

Introduction

Prerequisites

Requirements
Components Used
Conventions

%BGP-3-INSUFCHUNKS Error Message

Related Information

Introduction

This document explains the Cisco IOS® %BGP-3-INSUFCHUNKS error message and the possible situations in which the message can be safely ignored.

Prerequisites

Requirements

Cisco recommends that you have knowledge of how to configure Border Gateway Protocol (BGP) on Cisco routers.

Components Used

The information in this document is based on certain versions of Cisco IOS® as described later in the document.

Conventions

Refer to Cisco Technical Tips Conventions for more information on document conventions.

%BGP-3-INSUFCHUNKS Error Message

If the autonomous system (AS) path length is less than 50 ASs (100 bytes), the router uses chunk memory allocation. If the AS path length is longer than 50 ASs, the router uses regular memory allocation and returns the #%BGP-3-INSUFCHUNKS: Insufficient chunk pools for aspath error message every time it encounters this situation. The router should continue working normally despite this error message.

This problem has a Cisco bug ID of CSCdr07279 (registered customers only). The fix for CSCdr07279 allows the router to use chunk memory allocation for an AS path of up to 125 ASs. Once the path exceeds this length, the router returns the error message only once.

The fix for CSCdr07279 was integrated into these Cisco IOS Software releases:

- 12.0(9.6)ST
- 12.0(10.1)S
- 12.0(10.3)SC
- 12.1(1.3)
- 12.1(1.3)T
- 12.1(1.3)E
- 12.1(1.3)EC
- 12.1(3)DB
- 12.1(3)DC

Related Information

- BGP AS_PATH Attribute
- Border Gateway Protocol (BGP) Support Page
- Technical Support & Documentation Cisco Systems

Contacts & Feedback | Help | Site Map

© 2014 – 2015 Cisco Systems, Inc. All rights reserved. Terms & Conditions | Privacy Statement | Cookie Policy | Trademarks of Cisco Systems, Inc.

Updated: Apr 12, 2005 Document ID: 13757