



## Resolved Issues

For your convenience, the release notes list the resolved issues for this version.

If you have a support contract, you can use the [Cisco Bug Search Tool](#) to obtain up-to-date bug lists. You can constrain searches to bugs affecting specific platforms and versions. You can also search by bug status, bug ID, and for specific keywords.



---

**Important** Bug lists are auto-generated *once* and are not subsequently updated. Depending on how and when a bug was categorized or updated in our system, it may not appear in the release notes. You should regard the [Cisco Bug Search Tool](#) as the source of truth.

---

- [Version 6.7.0 Resolved Issues, on page 1](#)

## Version 6.7.0 Resolved Issues

*Table 1: Version 6.7.0 Resolved Issues*

Bug ID	Headline
<a href="#">CSCuq33233</a>	Clustering: Overlapping PAT IPs in NAT rules prevent xlates from replicating
<a href="#">CSCvd09106</a>	Editing SNMP/Syslog/Email Alert Configuration causes in use count to increase
<a href="#">CSCvf34107</a>	False positive alerts for High Unmanaged Disk usage on /Volume
<a href="#">CSCvg01007</a>	https pdf attachment issues
<a href="#">CSCvg74990</a>	Need to update Online documentation for Archive Inspection feature limitations
<a href="#">CSCvh65500</a>	Firepower 2100 Client in FTP active mode is not able to establish control channel with the Server
<a href="#">CSCvi47847</a>	Shell application not detected through Firepower
<a href="#">CSCvi51189</a>	ENH: FDM should allow custom non-UDP/TCP 443 port for webvpn/AnyConnect
<a href="#">CSCvi92162</a>	DOC: Need explanation about App and URL inspection of HTTPS traffic on each Firepower version

<b>Bug ID</b>	<b>Headline</b>
<a href="#">CSCvi96835</a>	No validation err when changing host thats part of a group object used in a routing policy, to Range
<a href="#">CSCvj87597</a>	Import fails when Flex Config contains a Security Zone.
<a href="#">CSCvj91418</a>	Cisco FTD Software SMB Protocol Preprocessor Detection Engine Low System Memory DoS Vuln
<a href="#">CSCvk16568</a>	AppID stop processing traffic if Application ID has been detected
<a href="#">CSCvk21405</a>	shell application not pin holing new connection from server
<a href="#">CSCvk40714</a>	Unable to configure SSH option for Remote Storage
<a href="#">CSCvk56513</a>	Tor not blocked when traffic is passed through proxy.
<a href="#">CSCvk62871</a>	Firepower 2100 FTP Client in passive mode is not able to establish data channel with the Server
<a href="#">CSCvm69294</a>	Standby FMC sending Flood of SNMP traps
<a href="#">CSCvm99989</a>	SNMP OID for SystemUpTime show incorrect value
<a href="#">CSCvn08417</a>	ENH: FlexConfig should not blacklist crypto commands
<a href="#">CSCvn49854</a>	Subsequent HTTP requests not retrieving URL and XFF
<a href="#">CSCvn73530</a>	Scheduled deployment task on KP devices were stuck for more than 50+ hours.
<a href="#">CSCvn78597</a>	Firepower block page not displayed on MS IE11 and Edge for HTTPS blocked sites when proxy is enabled
<a href="#">CSCvn94888</a>	FTD registered to FMC returns "Service Unavailable"
<a href="#">CSCvo33348</a>	Mysql traffic on non standard port is not correctly classified
<a href="#">CSCvp06526</a>	Manage the sfhassd thread CPU affinity to match the Snort CPU affinity
<a href="#">CSCvp29817</a>	Fail to update login history when converting TempID to RealID. 1x log per ID, history lost
<a href="#">CSCvp80474</a>	OpenSSL vulnerability CVE-2019-1559 on SFOS
<a href="#">CSCvq23896</a>	TLS 1.3 traffic whitelisted by SSL preprocessor when pending for AppID
<a href="#">CSCvq39888</a>	Cisco Firepower Threat Defense Software Non-Standard Protocol Detection Bypass Vuln
<a href="#">CSCvq39955</a>	Cisco Firepower Threat Defense Software Stream Reassembly Bypass Vulnerability
<a href="#">CSCvq54551</a>	Failed to load error on Intelligence Page for FMC for CAC User
<a href="#">CSCvq67965</a>	ENH:Need the ability to disable auto negotiation in SFP - Fp2k

Bug ID	Headline
<a href="#">CSCvq76964</a>	Fault Related to Unhealthy module FlexFlash Controller 1 old Firmware
<a href="#">CSCvq95058</a>	IPSEC SA is deleted by failover which is caused by link down
<a href="#">CSCvr01675</a>	Multiple Cisco Products Snort HTTP Detection Engine File Policy Bypass Vulnerability
<a href="#">CSCvr09399</a>	Dynamic flow-offload can't be disabled
<a href="#">CSCvr09468</a>	ASA traceback and reload for the CLI "Show nat pool"
<a href="#">CSCvr13762</a>	NGFWHA Missing EO UUID on FMC
<a href="#">CSCvr39217</a>	Fxos Snmp-user is not persistent after reboot
<a href="#">CSCvr49729</a>	Fail-to-Wire ports showing down for FPR2100, FTW configuration API takes long to finish
<a href="#">CSCvr49833</a>	Cisco Firepower 2100 Series Security Appliances ARP Denial of Service Vulnerability
<a href="#">CSCvr55535</a>	Phase 3 of policy deployment takes a long time due to only working on 10 packages at a time
<a href="#">CSCvr57051</a>	Policy deployment failed with error "Can't use an undefined value as a HASH reference "
<a href="#">CSCvr66067</a>	Provide the backup and restore steps for FMC in high availability deployment mode
<a href="#">CSCvr66798</a>	DNS Application Detector sometimes fails to detect DNS traffic
<a href="#">CSCvr68885</a>	FXOS fault F0479 Virtual Interface link state is down
<a href="#">CSCvr74896</a>	Cannot update Security intelligence when AC Policy is imported to FMC with cloud feeds disabled
<a href="#">CSCvr74901</a>	AppAG encoding for FXOS logical device bootstrap
<a href="#">CSCvr86077</a>	ASA Traceback/pagefault in Datapath due to re_multi_match_ascii
<a href="#">CSCvr86213</a>	CD is required to ignore Cluster-Msg-Delivery-Confirmation in Cluster Node Release Lina State
<a href="#">CSCvr98881</a>	Traceback: FTD ZeroMQ memory assertion
<a href="#">CSCvs05066</a>	Snort file mempool corruption leads to performance degradation and process failure.
<a href="#">CSCvs06043</a>	TunnelClient for CSM_CCMservice on ngfwManager not reading ACK sent from CSM_CCM service on FMC
<a href="#">CSCvs13950</a>	REST API Network Object Validation
<a href="#">CSCvs19968</a>	Fix consoled from getting stuck and causing HA FTD policy deployment errors.
<a href="#">CSCvs21705</a>	admin user is not authorized to access the device routing configuration inside the domain.

Bug ID	Headline
<a href="#">CSCvs29494</a>	Hub and spoke VPN, dynamic crypto map, auto-generated PSK is the same for static and dynamic peers
<a href="#">CSCvs31114</a>	Warning about not supported bypass revocation checking for FTD 6.5 and higher
<a href="#">CSCvs33392</a>	Known Key SSL decryption and connections can fail when servers are using unsupported TLS options
<a href="#">CSCvs34851</a>	Continuous link flapping leading to snm_log corefile
<a href="#">CSCvs37266</a>	Reviewed intrusion events belonging to a subdomain show the reviewer as Unknown
<a href="#">CSCvs39253</a>	Firepower 7000 & 8000 cannot send emails on version 6.4
<a href="#">CSCvs39368</a>	DME process may traceback due to memory leak on Firepower 4100/9300
<a href="#">CSCvs39388</a>	FTD not sending system syslog messages in CC mode
<a href="#">CSCvs41883</a>	Deployment fails after upgrading to 6.4.0.x if ND policy refs are missing
<a href="#">CSCvs42203</a>	hostname transmission: Hostname is null, Device sends hostname as "none" to SA
<a href="#">CSCvs42388</a>	Gratuitous logging of string: "Memory stats information for preprocessor is NULL"
<a href="#">CSCvs42577</a>	user download may fail due to password not sent
<a href="#">CSCvs42799</a>	After FXOS upgrade, App Instance failed to start with Checksum Verification Fail
<a href="#">CSCvs44109</a>	FMC: PPPoE password restrictions are too strict; should match the underlying code
<a href="#">CSCvs44149</a>	Reconciliation report not displaying all the networks when adding a large object group
<a href="#">CSCvs52227</a>	Firewall engine debug logs being produced in syslog without actually enabling debugs.
<a href="#">CSCvs59866</a>	Remove unsupported fast mode lacppolicy configuration from FXOS on Firepower 2100
<a href="#">CSCvs64510</a>	Deployment failure with message (Can't call method "binip" on unblessed reference)
<a href="#">CSCvs68576</a>	Deploy failure when deleting auto nat rule due to double negate
<a href="#">CSCvs71578</a>	FMC upgrade [6.2.3.10 to 6.4.0] got stuck at 400_run_troubleshoot.sh, upgrade was hung
<a href="#">CSCvs72390</a>	Cisco Firepower Management Center Cross-Site Scripting Vulnerability
<a href="#">CSCvs74586</a>	Firepower FTD transparent does not decode non-ip packets
<a href="#">CSCvs74747</a>	FTD registration state shows "pending" after a backup is restored
<a href="#">CSCvs76604</a>	SNMP not working over Management Interface in 6.6.0-1430
<a href="#">CSCvs81871</a>	Remove CCL MTU Pop-Up Warning When Editing Data Interfaces
<a href="#">CSCvs85348</a>	Object validation is validating interfaces from different devices.

Bug ID	Headline
<a href="#">CSCvs85640</a>	Unable to suppress Audit logs on the FMC
<a href="#">CSCvs86765</a>	rule impact regeneration should not be terminated on single rule errors
<a href="#">CSCvs90447</a>	FXOS 8x1G FTW continuous link flap
<a href="#">CSCvs91270</a>	Inspect Interruption - Error in deployment page.
<a href="#">CSCvs92044</a>	FXOS L3 Egress Object Resource Leak due to Port-Channel Member Interface Flaps
<a href="#">CSCvs92077</a>	wrong impact flag for local rules with impact flag not red
<a href="#">CSCvs94061</a>	NTP script error leading to clock drift and traffic interruption
<a href="#">CSCvs98373</a>	FMC is unable to detect classic licenses intermittently
<a href="#">CSCvt01397</a>	Deployment is marked as success although LINA config was not pushed
<a href="#">CSCvt03320</a>	VLAN interfaces should be configurable for DHCP-related configuration on an FMC
<a href="#">CSCvt04377</a>	When vlan encapsulation is exceeded decoding errors are depleting disk space.
<a href="#">CSCvt06091</a>	FXOS displays a WSP-Q40GLR4L transceiver from show interface as type QSFP-40G-LR4
<a href="#">CSCvt06743</a>	FTW watch-dog kick delays which might cause inline sets to go down/Bypass-Fail
<a href="#">CSCvt08514</a>	SFDataCorrelator:FPReplicationCommunicationRabbit unable to connect without restarting sfiproxy
<a href="#">CSCvt10420</a>	DomainSearchNameValidator class needs updated regex for DOMAIN_NAME_PATTERN
<a href="#">CSCvt10604</a>	Validation Check when two objects with different mask but same network is used in route without ECMP
<a href="#">CSCvt11885</a>	Running the migration script exits with an out of memory error
<a href="#">CSCvt15062</a>	FTD 2100: Packet drops during the transition of BYPASS to NON-BYPASS when device is rebooted
<a href="#">CSCvt16642</a>	FMC not sending some audit messages to remote syslog server
<a href="#">CSCvt16723</a>	log rotation for ngfw-onbox logs NOT happening at expected log size
<a href="#">CSCvt17448</a>	OSPF multicast mac getting removed from l2-table causing OSPF to fail
<a href="#">CSCvt18337</a>	Failover got disabled on HA node after upgrade
<a href="#">CSCvt20235</a>	Firepower 4100 series all FTW interfaces link flap at the same time but occur rarely
<a href="#">CSCvt20709</a>	Wrong direction in SSL-injected RESET causes it to exit through wrong interface, causing MAC flap

Bug ID	Headline
<a href="#">CSCvt21986</a>	Inconsistent allocation of cores for snort and lina between instances
<a href="#">CSCvt22254</a>	Auto Deploy fails after Restore if FDM cannot reach update server
<a href="#">CSCvt25599</a>	Deprecated Flexconfig should block deployment not just warn
<a href="#">CSCvt25647</a>	sru and tid update failures caused by missing rabbitmq device accounts
<a href="#">CSCvt26530</a>	FTD failed over due to 'Inspection engine in other unit has failed due to snort failure'
<a href="#">CSCvt34160</a>	"Link not connected" error after reboot when using WSP-Q40GLR4L transceiver on FPR9K-NM-4X40G
<a href="#">CSCvt34894</a>	Snort consumes excessive memory which is leading to performance problems.
<a href="#">CSCvt34973</a>	SFNotificationd may cause excessive logging in 'messages' files
<a href="#">CSCvt35053</a>	Cisco Firepower Management Center Software Cross-Site Scripting Vulnerabilities
<a href="#">CSCvt35134</a>	FPR4100/9300: Packet drops during the transition of BYPASS to NON-BYPASS when device is rebooted
<a href="#">CSCvt35233</a>	Excessive logging from the daq modules process_snort_verdict verdict blacklist
<a href="#">CSCvt35366</a>	Excessive logging of lua detector invalid LUA (null)
<a href="#">CSCvt35730</a>	FDM deployment error if 2nd tunnel has overlapping crypto ACL
<a href="#">CSCvt35897</a>	Cisco Adaptive Security Appliance Software and Firepower Threat Defense Software DoS Vuln
<a href="#">CSCvt37881</a>	Block page for https not working
<a href="#">CSCvt37913</a>	serviceability - when breaking FMC HA EOs authority stays with former primary
<a href="#">CSCvt38279</a>	Erase disk0 on ISA3000 causes file system not supported
<a href="#">CSCvt39292</a>	LDAPS External users can't 'sudo su' on Firepower 4110
<a href="#">CSCvt39349</a>	Registration of device should be allowed as long as deploy status = DEPLOYED or FAILED
<a href="#">CSCvt39897</a>	FP 4120 svc_sam_dcosAG crashed with crash type:139
<a href="#">CSCvt40306</a>	ASA:BVI interface of standby unit stops responding after reload
<a href="#">CSCvt45206</a>	Event search may fail when searching events that existed before upgrade
<a href="#">CSCvt46784</a>	clish configure ssh-accesslist command fails silently if iptables is corrupt
<a href="#">CSCvt46999</a>	EventHandler does not process connection events after CLI command to enable/disable ramdisk
<a href="#">CSCvt48260</a>	Standby unit traceback at fover_parse and boot loop when detecting Active unit

Bug ID	Headline
<a href="#">CSCvt50528</a>	Warning Message for default settings with Installation of Certificates in ASA/FTD - CLI
<a href="#">CSCvt51039</a>	Handling license cleanup
<a href="#">CSCvt52604</a>	Interfaces page from Objects section of the FMC does not load (domains page is likely affected also)
<a href="#">CSCvt52607</a>	Reduce SSL HW mode flow table memory usage to reduce the probability of Snort going in D state
<a href="#">CSCvt52844</a>	AMP cloud lookup using legacy port on upgraded FDM, 6.6.0-1621
<a href="#">CSCvt54267</a>	Cisco Firepower Management Center Software Denial of Service Vulnerability
<a href="#">CSCvt54279</a>	FDM: Deploy fails with: Missing license for object: Sensitive_data requires the URLFILTERING license
<a href="#">CSCvt54943</a>	extra "Local Disk 3" displayed on FPR9300 (improved solution)
<a href="#">CSCvt59770</a>	FTD: Failure to retrieve certificate via SCEP will cause outage
<a href="#">CSCvt61196</a>	ASA on multicontext mode, deleting a context does not delete the SSH keys.
<a href="#">CSCvt61229</a>	Deployment should not fail for special characters in rule comments
<a href="#">CSCvt61370</a>	Events may stop coming from a device due to a communication deadlock
<a href="#">CSCvt63293</a>	Disk Usage Health monitor not working for any appliance without 2 Hard Drives
<a href="#">CSCvt64642</a>	FMC -Deployment Failure- Anyconnect - "Certificate Map" using "DC (Domain Component)" to match cert.
<a href="#">CSCvt64822</a>	Cisco Adaptive Security Appliance Software SSL/TLS Denial of Service Vulnerability
<a href="#">CSCvt67638</a>	restore is failing with error unable to extract metadata
<a href="#">CSCvt68486</a>	FXOS: svc_sam_dcosAG process crash on FirePower 4100/9300
<a href="#">CSCvt69260</a>	connection event shows old device name
<a href="#">CSCvt70879</a>	"clear configure access-list" on ACL used for vpn-filter breaks access to resources
<a href="#">CSCvt72683</a>	NAT policy configuration after NAT policy deployment on FP 8130 is not seen
<a href="#">CSCvt73808</a>	Handling for longer header length messages going from DAQ to Oct driver
<a href="#">CSCvt75677</a>	Configuring logical name as TRUE or FALSE on interface disappears all static routes from FMC UI
<a href="#">CSCvt78809</a>	Instance start failed due to VNIC configuration error
<a href="#">CSCvt79471</a>	GET to ../deployment/deployabledevices fails with 500 internal error on 6.2.3.13 FMC.

Bug ID	Headline
<a href="#">CSCvt79777</a>	duplicate ip addresses in sfipproxy.conf
<a href="#">CSCvt79863</a>	FTD upgrade incorrectly declared successful despite failure due to IO errors
<a href="#">CSCvt79988</a>	Policy deployment failure due to snmp configuration after upgrading FMC to 6.6
<a href="#">CSCvt80104</a>	Memcached software needs to be upgraded to address CVE-2018-1000115
<a href="#">CSCvt80172</a>	Supervisor software needs to be upgraded to address CVE-2017-11610
<a href="#">CSCvt83121</a>	Cisco ASA and FTD Software OSPFv2 Link-Local Signaling Denial of Service Vulnerability
<a href="#">CSCvt83133</a>	Unable to access anyconnect webvpn portal from google chrome using group-url
<a href="#">CSCvt85815</a>	Policy Deployment fails after enabling "Sensitive Data Detection"
<a href="#">CSCvt86807</a>	Web Analytics (Google Analytics) is re-enabled after major upgrade
<a href="#">CSCvt89587</a>	Deployment failing with error : Input line size exceeded available buffer
<a href="#">CSCvt91258</a>	FDM: None of the NTP Servers can be reached - Using Data interfaces as Management Gateway
<a href="#">CSCvt93177</a>	Disable Full Proxy to Light Weight Proxy by Default. (FP2LWP) on FTD Devices
<a href="#">CSCvt93999</a>	FMC shouldn't allow a second upgrade on same device if upgrade is going on
<a href="#">CSCvt94383</a>	Invalid gid permissions causing HA sync and device registration issues
<a href="#">CSCvu01083</a>	Add RabbitMQ log cleaning exception to avoid process restart
<a href="#">CSCvu02594</a>	Snort taking long time to terminate, because of too many async sessions
<a href="#">CSCvu05216</a>	cert map to specify CRL CDP Override does not allow backup entries
<a href="#">CSCvu08802</a>	FTD HA configuration lost on FMC after FMC upgrade from 6.4.0.7 to 6.5.0.4
<a href="#">CSCvu09379</a>	During reimage FMC will get stuck in a loop when using FTP transfer without password
<a href="#">CSCvu09496</a>	DNS data collected and exported multiple times while same DNS policy referenced in many ACP's
<a href="#">CSCvu09723</a>	FDM: Default Action's logging doesn't reflect on LINA side
<a href="#">CSCvu10900</a>	Tons of ssl-certs-unified.log files, contributing to 9GB in troubleshoot
<a href="#">CSCvu11868</a>	"Link not connected" error after reboot when using QSFP-40G-LR4 transceiver on FPR9K-NM-4X40G
<a href="#">CSCvu12307</a>	FTD-HA: "ERROR: The specified AnyConnect Client image does not exist."
<a href="#">CSCvu12608</a>	ASA5506/5508/5516 devices not booting up properly / Boot loop
<a href="#">CSCvu13287</a>	FDM unable to import certificate with no subject or issuer - fails upgrade as well



Bug ID	Headline
<a href="#">CSCvu14647</a>	Unable to stop config database error during FMC HA sync
<a href="#">CSCvu14772</a>	In jQuery versions greater than or equal to 1.0.3 and before 3.5.0, pa
<a href="#">CSCvu15611</a>	FTD-HA: Standby failed to join HA "CD App Sync error is App Config Apply Failed"
<a href="#">CSCvu16201</a>	Data Correlator terminated unexpectedly on FMC during CheckClientAppVulnerability
<a href="#">CSCvu22377</a>	An extra whitespace in cluster group name of FTD causing Slave to be kicked out.
<a href="#">CSCvu23289</a>	Disk filled by numerous neostore.transaction.db.* files, causing neo4j issues
<a href="#">CSCvu26658</a>	SFDataCorrelator can drop events during backup operations
<a href="#">CSCvu29660</a>	Block exhaustion snapshot not created when available blocks goes to zero
<a href="#">CSCvu30549</a>	Document all 3 URL entry options for "Manual URL Filtering"
<a href="#">CSCvu30572</a>	Document syntax and semantics of URL when "Enter URL" textbox of "Add Rule" is used
<a href="#">CSCvu30585</a>	Document "URL Object" format and feature operation
<a href="#">CSCvu30588</a>	Document "URL List and Feeds Object" format and feature operation of "Security Intelligence"
<a href="#">CSCvu30756</a>	User Identity does not correctly handle identical sessions in different netmaps
<a href="#">CSCvu31167</a>	DOC: File policy automatically enables inline normalization with Normalize TCP Payload option
<a href="#">CSCvu32449</a>	FDM: AnyConnect "Validation failed due to duplicate name:"
<a href="#">CSCvu36539</a>	Upgrade will fail if a smart licensed device is upgraded from 6.2.2 -> 6.4.0 -> 6.6.0.
<a href="#">CSCvu40531</a>	FXOS LACP packet logging to pktmgr.out and lacp.out fills up /opt/cisco/platform/logs to 100%
<a href="#">CSCvu43827</a>	ASA & FTD Cluster unit traceback in thread Name "cluster config sync" or "fover_FSM_thread"
<a href="#">CSCvu53585</a>	Elektra onbox policy deployment failure after upgrade to 6.6.0
<a href="#">CSCvu54000</a>	Firepower 4100 FTP Client in EPSV passive mode is not able to establish data channel with the Server
<a href="#">CSCvu54221</a>	Add hardware requirement for FMC HA
<a href="#">CSCvu54706</a>	Cisco Firepower Management Center CWE-772 - Slow HTTP POST vulnerability
<a href="#">CSCvu55469</a>	FTD - Connection idle timeout doesn't reset
<a href="#">CSCvu57825</a>	Snort down: Reconfiguring Detection Error

Bug ID	Headline
<a href="#">CSCvu57834</a>	syslog-ng process utilizing 100% CPU
<a href="#">CSCvu58153</a>	Display RADIUS port representation as little-endian instead of big-endian
<a href="#">CSCvu60923</a>	Editing the IP in a Radius Server Group object results in unintended values for the IP address
<a href="#">CSCvu65085</a>	[DOC] Route-map object Set Clauses do not include EIGRP k-values.
<a href="#">CSCvu65890</a>	FMC unable to switch from MD5 and DES under SNMP3 settings despite not being supported
<a href="#">CSCvu65936</a>	FDM 6.6.0 upgrade(or)configImport fail with EtherChannelInterface as failoverlink validation failure
<a href="#">CSCvu66119</a>	URL rules are incorrectly promoted on series 3 resulting in traffic matching the wrong rule.
<a href="#">CSCvu70529</a>	Binary rules (SO rules) are not loaded when snort reloads
<a href="#">CSCvu75581</a>	Cisco ASA and FTD Web Services Interface Cross-Site Scripting Vulnerabilities
<a href="#">CSCvu77689</a>	FTP to FileZilla miscategorized as SMTP
<a href="#">CSCvu79129</a>	FTD-API/FDM: Smart License Base License is Lost
<a href="#">CSCvu82272</a>	Upgrade on Firepower Management Center may fail due to inactive stale entries of managed devices
<a href="#">CSCvu82578</a>	Light Theme UI FMC - SFR Module long delay loading Interfaces Page
<a href="#">CSCvu82743</a>	Encoded Rule Plugin SID: value, GID: 3 not registered properly. Disabling this rule
<a href="#">CSCvu82918</a>	HA sync fails on standby with unexpected error
<a href="#">CSCvu83389</a>	ASA drops GTPV1 Forward relocation Request message with Null TEID
<a href="#">CSCvu83629</a>	Number Of URLs in Security Intelligence for URL List file may not appear in new UI (Ligth Theme)
<a href="#">CSCvu84556</a>	Site to Site Dynamic crypto map deployed below RA VPN Dynamic Crypto map
<a href="#">CSCvu85127</a>	Unable to deploy if device with same UUID is trying to connect
<a href="#">CSCvu85381</a>	HA Re-formation fails following a policy deploy failure on standby
<a href="#">CSCvu87879</a>	Deployment gets stuck when HA continually changes state due to interface monitoring
<a href="#">CSCvu88005</a>	FMC REST API user permission for GET taskstatus
<a href="#">CSCvu91292</a>	Snort restarts repeatedly when new custom apps are identified using nmap
<a href="#">CSCvu96927</a>	Not able to remove FQDN object once it is assigned within a NAT group

Bug ID	Headline
<a href="#">CSCvu98197</a>	HTTPS connections matching 'Do not decrypt' SSL decryption rule may be blocked
<a href="#">CSCvv02925</a>	OSPF neighbourship is not establishing
<a href="#">CSCvv09180</a>	NTP "Server Status" is blank in Firepower Chassis Manager when more than one NTP server configured
<a href="#">CSCvv10901</a>	vFTD on VMware documentation should recommend disabling hyperthreading
<a href="#">CSCvv10948</a>	FDM upgrade - There are no visible pending changes on UI -- but upgrade is not starting
<a href="#">CSCvv11981</a>	Lina side of changes required for bug CSCvr98881 in unified-logging.
<a href="#">CSCvv12988</a>	tomcat does not recover gracefully after getting killed during backup
<a href="#">CSCvv13672</a>	CPU load graph may show incomplete CPU data for longer time period selected
<a href="#">CSCvv14442</a>	FMC backup restore fails if it contains files/directories with future timestamps
<a href="#">CSCvv15013</a>	FXOS sending additional internal VLAN TAG leading to ARP update failure on devices.
<a href="#">CSCvv16245</a>	Cisco Firepower Management Center Software Common Access Card Authentication Bypass Vuln
<a href="#">CSCvv17893</a>	Bad uip snapshot and log file causes FTD to repeatedly requests catchup, and exhausts file handlers
<a href="#">CSCvv18936</a>	CAC login button doesn't appear on new UI, after session timeout
<a href="#">CSCvv21045</a>	Database doesn't accept any new connections causing event processing to stop
<a href="#">CSCvv21782</a>	6.6.1: Prefilter Policy value shown as Invalid ID for all the traffic in ASA SFR Platform
<a href="#">CSCvv23370</a>	Observed traceback in FPR2130 while running webVPN, SNMP related traffic.
<a href="#">CSCvv26683</a>	"configure high-availability disable" command when executed from CLI causes exception in next HAJoin
<a href="#">CSCvv27113</a>	ProcessMetadata for intrusion event uses wrong local_sid constraint to lookup entry
<a href="#">CSCvv29851</a>	FMC - High Availabilty page not loading after Migration from Virtual to Physical device
<a href="#">CSCvv31197</a>	File names not showing up correctly for the file events for decrypted ssl traffic
<a href="#">CSCvv33013</a>	FDM: Unable to add the secret key with the character ^ @ _
<a href="#">CSCvv34888</a>	WR6, WR8 and LTS18 commit id update in CCM layer(sprint 92)
<a href="#">CSCvv36915</a>	"Show NTP" command does not work on multi-instance FTD
<a href="#">CSCvv38482</a>	FDM UI fails to load after an upgrade

Bug ID	Headline
<a href="#">CSCvv40316</a>	FDM - Unable to add the BGP 11th neighbor using smart CLI routing object
<a href="#">CSCvv43864</a>	Preview change log is blank when changes are made to the policy
<a href="#">CSCvv45500</a>	Version 6.6.0.1 FTD Upgrade with FDM Suspends HA
<a href="#">CSCvv46984</a>	Upgrade to 660 fails in HA standby device managed through data interface
<a href="#">CSCvv52591</a>	DMA memory leak in <code>ctm_hw_malloc_from_pool</code> causing management and VPN connections to fail
<a href="#">CSCvv55066</a>	FPR1010: Internal-Data0/0 and data interfaces are flapping during SMB file transfer
<a href="#">CSCvv57476</a>	CSS Styles loading issue in Chrome 85, IE and Edge browsers
<a href="#">CSCvv58604</a>	Reset not sent when traffic matches AC-policy configured with block/reset and SSL inspection
<a href="#">CSCvv64302</a>	DOC: Documentation incorrectly states Logging Events to Ramdisk is not enabled on lower end devices
<a href="#">CSCvv69708</a>	DOC: FTD Improve Platform Settings DNS Resolution configuration guide
<a href="#">CSCvv70096</a>	Snort 2: Memory Leak in SSL Decrypt & Resign Processing
<a href="#">CSCvv73540</a>	Create a monitor to drop file cache once it exceeds a certain limit
<a href="#">CSCvv74951</a>	Disable memory cgroups when running the system upgrade scripts
<a href="#">CSCvv79705</a>	Upgrade to 6.6.0 or 6.6.1 failed on <code>800_post/100_ftd_onbox_data_import.sh</code>
<a href="#">CSCvv91486</a>	Memory leak during reload in stream
<a href="#">CSCvv99517</a>	FMC: Unable to save interface config and "An internal error occurred while processing your request"
<a href="#">CSCvw07003</a>	Unable to edit Site-to-Site VPN configuration by a leaf domain admin user
<a href="#">CSCvw07352</a>	SFDataCorrelator log spam, metadata fails after Sybase connection status 0
<a href="#">CSCvw17084</a>	In Firepower Module 6.3, app status is down after restore