


# Cisco Enterprise

## NFV, NaaS, Cloud Managed Network (CMN), SD-WAN, Cloud Managed Network (CMN) - CLI Command Injection



**CVSS Score: 4.2**  
Cisco ID: [CSCvi09723](#)  
No workarounds available

[CVE-2018-0324](#)

**CVSS Score: 4.2**  
Cisco ID: [CSCvi09723](#)  
No workarounds available

### Summary

Cisco Enterprise

NFV, NaaS, Cloud Managed Network (CMN), SD-WAN, Cloud Managed Network (CMN) - CLI Command Injection  
The vulnerability allows an attacker to execute arbitrary commands on the device through a CLI interface. This can be exploited to gain administrative access and execute any command on the device.

For more details, see the Cisco Security Advisory: <https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180516-nfvis-cli-command-injection>

### References

[Cisco Security Advisory: cisco-sa-20180516-nfvis-cli-command-injection](#)

Cisco Enterprise  
NFV, NaaS, Cloud Managed Network (CMN), SD-WAN, Cloud Managed Network (CMN) - CLI Command Injection  
Bug ID: CSCvi09723

**CVSS Score: 4.2**  
Cisco ID: [CSCvi09723](#)  
No workarounds available

For more details, see the Cisco Security Advisory: <https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180516-nfvis-cli-command-injection>

å>žéç-

ã"ãè,,†å¼±æ€šã«ã³¼å‡|ã™ã,å>žéç-ã-ã,ã,šã¾ã>ã,"ã€,

ä;Ⓝæ£æ, ^ãçã,½ãf•ãf^ã, |ã,šã,ç

ä;Ⓝæ£æ, ^ãçã,½ãf•ãf^ã, |ã,šã,ç

ãfãfãf¼ã,¹ãè©³ç°ã«ã»ã,,ã|ã-ã€æœ-ã,çãf%ããfã,ã,¶ã,¶ãfã,šéfã Cisco  
Bug ID å,å,ç...šãããããã,ã€,

ã,½ãf•ãf^ã,ã,šã,çãⓃã,çãffãf-ã,°ãf-ãf¼ãf%ãã,æœè"Žã™ã,«ésã«ã-ã€[ã,ã,¹ã,³ãⓃã,»ã,ãf  
Security Advisories and Alerts[¼%]

ãfšãf¼ã,ãšã...¥æ%ãšããã,ã,ã,¹ã,³è£½å"ãⓃã,çãf%ããfã,ã,¶ã,¶ãfã,ã@šæœÿçš,,ã«ã,ç  
ã,½ãfãf¼ã,ãfãfã,çç°èãã-ã|ãããããã,ã€,

ã,,ãšã,çãⓃãå'å^ã,,ã€ã,çãffãf-ã,°ãf-ãf¼ãf%ãã™ã,ãfããã,ã,ã,¹ã«ãã^ããfãfçã  
Technical Assistance

Center¼TAC¼ã,,ã-ããã-ã¥ç,,ã-ã|ã,,ã,ãfãfãfãfãfãfã,¹ãf-ãfãfã,ããfãf¼ã«

ä,æ£å^©ç"" ä°<ã¾ã"ã...-ã¼ç™°èj"

Cisco Product Security Incident Response

Team¼PSIRT¼ã-ã€æœ-ã,çãf%ããfã,ã,¶ã,¶ãfã«è~¼ãã,ã,çã|ã,,ã,«è,,†å¼±æ€šã»

å†°å...,

ã"ãè,,†å¼±æ€šã-ã€Orange

GroupãⓃã,»ã,ãfãfãfãfã,£ãããf¼ããã«ã,^ã£ã|ã,ã,¹ã,³ã«ã±ãšãã,çã¾ã-ãÿã€,

## URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180516-nfvis-cli-command-injection>

æ''è",å±¥æ'

ãfãf¼ã,ãfšãf³	èª-æ~Ž	ã,»ã,ã,ãfšãf³	ã,¹ãfãf¼ã,
1.1	[Source]ã,»ã,ã,ãfšãf³ãⓃã,ãf-ã,ãffãf^ã,ãœæ'ã€,	å†°å...	Final
1.0	å^å>žå...-é-ãfãfãf¼ã,¹	-	Final



## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。