

Cisco RV110W, RV130W, RV215W

High severity vulnerability in Cisco RV110W, RV130W, and RV215W routers allowing remote code execution via a specially crafted HTTP request.



Severity: High
CVE ID: CVE-2018-0426
Published: 2018-09-05 16:00
Version: 1.0 (Final)
CVSS Score: 7.5
Workarounds: No workarounds available
Related IDs: CSCvj42750, CSCvj42752, CSCvj23233

Remote code execution vulnerability in Cisco RV110W, RV130W, and RV215W routers.

Impact

Cisco RV110W Wireless-N VPN, Cisco RV130W Wireless-N VPN, and Cisco RV215W Wireless-N VPN are affected.

The vulnerability allows an attacker to execute arbitrary code on the device via a specially crafted HTTP request. This could lead to a complete compromise of the router.

CVSS Score: 7.5 (High)

For more details, visit: <https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180905-rv-routers-traversal>

References

https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20180905-rv-routers-traversal

ç „

æœ-ã, çãf%ãf ã,ã,¶ã, ¶ãfã ç,; äç è ¼ã @ã,,ã @ã ã —ã |ã "æ ä¾ã —ã |ã Šã,Šã€
æœ-ã, çãf%ããf ã,ã,¶ã, ¶ãfã @æf...ã ±ã Šã, ^ã ³ãfã³ã, _ã @½ç "ã «é-çã ™ã, <è²-ä»ã @ã, €
ã ¾ã ÿã€ã, .ã, ³ã æœ-ãf%ãã,ãfãf;ãf³ãf^ã @ãt...ã ¹ã, 'ã ^ã Šã ^ã —ã «ã%ãæ'ã —ã
æœ-ã, çãf%ããf ã,ã,¶ã, ¶ãfã @è ~èç °ãt...ã ¹ã «é-çã —ã |æf...ã ±é... äçã @ URL
ã, çœ ç ¥ã —ã € ã ç <-ã @è» ç è ¼%ã,,,æ,, è ³ã, 'æ-½ã —ã ÿã 'ã ^ã € ã ½"ç ¾ã Çç @çç
ã "ã @ãf%ãã,ãfãf;ãf³ãf^ã @æf...ã ±ã _ã €ã, .ã, ³ã, è £½ã "ã @ã, "ã³ãf%ããf!ãf¼ã, ¶ã, 'ã ¾è±;ã

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。